



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 1660R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BALANCER (CONSISTENT)	MISSING	12.00	12.00
1	BELLY PAN (CONSISTENT)	CUT	35.00	35.00
1	BOARD FOOTREST LH (CONSISTENT)	CUT	55.00	55.00
1	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT (CONSISTENT)	GRAZED	208.00	208.00
1	COVER SIDE CENTRE LH (WHITE) (CONSISTENT)	CUT	32.00	32.00
1	MID BOLT RING NUT (CONSISTENT)	NECESSARY	1.50	1.50
1	WINDSHIELD (CONSISTENT)	SCRATCHED	60.00	60.00
	LESS 10% DISCOUNT		-	-40.35
			403.50	363.15
<u>SPECIAL NETT ITEMS</u>				
1	PROTECTOR EXHAUST (SN) (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	38.00	-
1	STICKER (CERTIS CISCO) WINDSHIELD NEW (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT (SN) (CONSISTENT)	SCRATCHED	12.00	10.00
			110.00	70.00
<u>LABOUR</u>				
	TRANSPORT CHARGES.		35.00	35.00
	LABOUR.		70.00	70.00
			105.00	105.00
GRAND TOTAL			618.50	538.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				430.00

Report Ref No. CC4/ASM19004345/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.