



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545 Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

08/02/2018

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPAXA.
Asher,

Accident date: 07/02/2018

Estimated repair cost for vehicle no: SGT4135E TOYOTA WISH 1.8 A '07

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid <i>Dented</i>		\$1,315.20 <i>-1270</i>
2	2	Rear Boot Lid Hinge <i>gap</i>	\$141.40	\$282.80 <i>+</i>
3	2	Rear Boot Lid Shock Absorber <i>gap</i>	\$371.85	\$743.70 <i>+</i>
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$51.10 <i>-</i>
5	1	Rear Boot Lid Centre Chrome Moulding <i>gap</i>		\$274.45 <i>+</i>
6	4	Rear Boot Lid Centre Chrome Moulding Clip <i>gap</i>	\$6.50	\$39.00 <i>+</i>
7	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 <i>+</i>
8	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$374.45 <i>✓</i>
9	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$381.90 <i>-</i>
10	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$781.45 <i>+</i>
11	1	Rear Boot Lid Windscreen Top Seal		\$125.00 <i>-</i>
12	2	Rear Boot Lid Windscreen Side Moulding <i>gap</i>	\$65.00	\$130.00 <i>-</i>
13	1	Rear Boot Lid Camera (Special Nett) <i>new</i>		\$550.00 <i>+</i>
14	2	Rear Tail Lamp <i>cracked</i>	\$387.40	\$774.80 <i>✓</i>
15	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 <i>-</i>
16	1	Rear Bumper <i>Deformed</i>		\$625.20 <i>-</i>
17	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>-30</i>
18	2	Rear Bumper Bracket <i>new new LH Dented</i>	\$88.60	\$177.20 <i>+88.60</i>
19	2	Rear Bumper Side Retainer <i>new</i>	\$132.10	\$264.20 <i>-50.</i>
20	2	Rear Bumper Side Reflector <i>new new</i>	\$141.45	\$282.90 <i>+</i>
21	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00 <i>200.00</i>
22	2	Rear Fender Inner Trim Board <i>gap</i>	\$471.45	\$942.90 <i>+</i>
23	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 <i>+</i>
24	1	Rear End Panel Outer <i>Dented.</i>		\$519.80 <i>✓</i>
25	1	Rear End Panel Inner <i>Repair</i>		\$780.50 <i>+</i>
26	1	Rear End Panel Top Garnish <i>Deformed.</i>		\$374.45 <i>-</i>
27	1	Rear Floor Panel <i>Repair</i>		\$980.30 <i>+</i>
28	2	Rear Floor Panel Top Cover <i>new new</i>	\$282.10	\$564.20 <i>+</i>

29	1	Rear Floor Panel Inner Garnish		\$291.40	+
30	1	Rear Floor Panel & End Panel Sealant		\$450.00	+
31	1	Rear Exhaust		\$961.20	+
32	2	Rear Exhaust Mounting	\$67.60	\$135.20	+
33	1	Rear Centre Exhaust		\$1,714.20	+
34	1	Rear Spare Tyre Bracket		\$194.85	+

4838.70 SN: 200
3629.02

Subtotal:- \$15,700.35

Labour charges

To remove & refit cushion		\$280.00 80
To remove & refit reverse sensor		\$100.00 60
To remove & refit camera		\$180.00 60
To remove & refit rear windscreen		\$120.00 ✓
Gum		\$50.00 ✓
To remove & refit rear & centre exhaust	2160	\$380.00 x
To check wiring		\$100.00 30
Tuff kote		\$150.00 60
Panel beating		\$1,200.00 800
Spray painting		\$1,200.00 900
	Subtotal:-	<u>\$3,760.00</u>
	Total:-	<u>\$19,460.35</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5989.02
A/S: 4 8K
06 Days

4.8K