15/5/2010	mm Retor.	CC 4/ ASM 1900	4352,	B fa 352 LKK: 103172
INS. CASE OWNER:	Mr. (Ym	ASSIGNM		9 11/3/19
a Surve or	Mrs. Our	DOI:	13/2012	Date / Time : V(\5 \9
A 1000/000/000		1910		Registered in Merimen:
Pre-assign / CCU / I	FTE O/F 122	210		
Insured Vehicle No.	XE177	51	Claim No.	: _ sqm01612 6x
Name of Insured	WAR I BOTT	Ares Pl	Policy No.	8
Q Q		115 V 11 -	Make / Model	*
Insured Tel No.	180	HP: 0/3/19	Place of Accide	
Excess Sec II :SS		D.O.A: 815114	Place of Accide	iit .
Is driver the owner?	(YES / (10)	Nature of Accident :		- Davis OL DEPORTATION (NO
1f NO, Driver Name		Ω		XT: YES / NO; TP GIA REPORT, YES / NO y: % Final? Yes / No
Driver Tel N	(0)(0)	(V/L:YES/NO)	Insured Liability	y: % Final? Yes/No
SIH 4Pd0.	<u> </u>			
INSRS:	/ INSRS:	6	INSRS:	INSRS:
WSP: TOPAN	NSP:		WSP:	WSP:
Tel: Liability:	Tel: Liability	, H H	Tel: Liability:	Tel: Liability:
RMKS:	RMKS:	1/4 -1/1	RMKS:	RMKS:
Date/ Time				
b v D	CALULANC CLIMBIT	mosen by the	011/10	STAGE DATE / PIC
7/4	XE 1373K - X	0.12 19 11 + 441 10011.	1111	Non-Reporting ltr (1st): Non-Reporting ltr (2nd):
-MV	VELLISH- V			Non-Reporting ltr (200). Non-Reporting ltr (Final):
	7000 100			Notification ltr (if non-pickup):
	laget WA.			Call OI: After call itr to OI: > 11/4/17 - 52
51/6/19	FILE PASS TO LIM TG T	TO FINAUSE		Documentation Check List: Handler Typist
2/1/1	11. 9 1100 10 0100 10			Notification ltr (if non-pickup)
	mandate already	Seek, pendig works	op revut on	After call itr to OI:
	(ob			Authorisation To Act: Release Voucher:
18/9	mandale above	wed . (to offer to).	MWW.	Final Repair Bill:
18/1	Offer > sence (2)	\$6983.50 OU DON TO 1	00 , DN	Car Rental Invoice:
2763545	John Chending DV	CNI		Towing Invoice
20/9 -	DV IN UTILE P	acs Admin to close) .	LTA/GIA:
	1			Medical Bill:
				Mandate/Reject Instruction:
				LOD
				Payment Breakdown Form:
PRELIMINARY ADVICE	Date/Time:	Sent By:		Post-Repair Photos: Others:
FINALIZATION	Date/Time:	Confirm with:		Confirm by: Wiv Um.
Repair Cost: UL	ss - 5750 (8	days) Reduction: \$733\ 8	\$ % 50	Email Call
FINAL SETTLEMENT	Date/Time: 18/9/19 / 10pm	Confirm with Rach		Email Call
Final Liability		/ Assessed) BOLA S/N No. : 27	CON MAN	If NO or B 28, Ass. Lia:
Repair Cost: (WIN)	ss 4152.50	M Y han	40 ×04	That arms
Loss of Rental (LOR):	S\$ 000.00 (days) (5 00 days)		P0224016
Loss of Use (LOU): Loss of Income (LOI);	S\$ - (\$ x			PL ST IT
LOR only LOU only	LOR + LOU L	OR + LOI [Tick only one	e]	
GIA/LTA Search	ss 31-00	0		N. Christophy N. C. and the control of the control
Medical:	S\$	(a = Tand Indoneside	et Y	Claim status: Normal/Reject/Private Settle Report Format:
Disbursement:	SS =	(e.g. Tow/ Independe	in)	3) Survey fee: #3tt -
Legal Cost Total:	ss 6983.50	Global Sum SS:		10
FINAL PAYMENT	Date/Time:	Confirm with:		Email Call
Payee 1:	ss 6983 50	Name 1: Tovque	5 Pte Ltd	7
Payee 2: (Strike if N. 4.)	55	Name 2:		
Payee 3: (Strile if N.A.)	S\$	Name 3:		

Weekend (\$

TOTAL

Lump Sum / I.B.I: (\$



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No

: SJH4690X

Estimation No. : E19030013

Make & Model

: TOYOTA, COROLLA AXIO 1.5X A, NZE1416085483

DOA

: 09/03/2019

Year of Manufacture : 2008

No	Description			+11	Qty	U/P	Amt
	Section: List Items		N. S. Sir			-	
1	Rear bumper		100		1.00	10.00 491	₩ 0.00 C
2	Rear bumper retainer long (LH)			1.00	1000 00	90 0005
3	Rear bumper retainer long (RH)	(0)		1.00	V0.00 . 8ª	10 0.00
4	Rear bumper retainer short (LF	1)			1.00	Vo.00 89	10 000
5	Rear bumper retainer short (RI	4)			1.00	V0.00 89	
6	Reverse sensor				4.00 3	62000 00 1-W	8.00000
7	Rear bumper bracket (LH)				1.00 2	0.00 99.	90 0.002
8	Rear bumper bracket (RH)	277			1.00	0.00 84	90 0.00 ?
9	Bootlid				1.00	33.5	70 0.00 BT
10	Bootlid emblem - Logo				1.00 3	50 0.00 85	
11	Bootlid emblem - Axio	D.		56		5,50 0.00 38	and the second s
12	Bootlid emblem - X	Parts	4689.68			4.50 0.00 58	
13	Bootlid lock	S/N	345.00			Z-20 0.00 755	
14	Bootlid lock catch	Labour	2190.00		1.00	0.00	N -00.0
.5	Bootlid key lock	carron		410	1.00	0.00	0.00 NI
6	Bootlid rubber beading		7224.68		1.00 /82	-10 0.00 148	70.00 Cu7
7	Bootlid hinge (LH)	20%	1444,94		1.00	0.00 178	
8	Bootlid hinge (RH)	10	- 444 174		1.00	0.00 178	
9	License lamp garnish		5779,74		1.00	VO.00167.	-
0	License lamp (LH)	FD 1			1.00	0.00 97.0	(00.0
1	License lamp (RH)	5750/	k.		1.00	0.00 92.0	6.866
2	Bootlid insulator	01110	25% AAA		1.00 200	100.0031010	
3	rom tomp (Err)		TO 10 MAIN			.00 0.00 467.	10000
4	Tail lamp (RH)	= 6861				00 0.00 467.5	7 6 0
5	Tail lamp gasket (LH)				1.00	0.00	0.001
6	Tall lamp gasket (RH) S/N	= 450			1.00	-0.00	0.00 7 1 1
7	Tail lamp inner panel (LH)	u = 219	0		1.00 /83 Co	・80.00 25年) ntinue on next	0 0.00 ? B

P+5+1 = 9501 - 20% 4/5 = \$7600.



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No Make & Model : SJH4690X

: TOYOTA, COROLLA AXIO 1.5X

A,NZE1416085483

Year of Manufacture . 2000

Estimation No. : E19030013 DOA : 09/03/2019

No	Description			Qty	U/P	Amt
28	Tall lamp inner panel (RH)		* ***			5/k2+ 0.00 2 B
29	End panel					85.800.00 ? D
30	End panel top garnish					15,10 0.00 DL
31	Spare tyre panel	35		1.00		145.70 0.00 7 F
32	Spare tyre top panel	(E)(3)	The Contract of the Contract o	54.56 POSS#0451		98-20 0.00 ? a
33	Rear fender (LH)					811-20 0.00 DD
34	Rear fender inner shield (LH)			1.00		9110 0.00 DD
35	Rear fender air vent			1.00	0.00	NA -00-0
6	Rear fender inner trim (LH)		€			18.80 0.007)
7	Rear fender inner trim (RH)					18.80 0.00? Ja
8	Fu g lid			1.00	0.00	0.00; J
9	Rear windscreen			1.00	0.00	-0.00 NN
0	Rear windscreen moulding			1.00	√ 0.00 N	
1	Rear exhaust muffler			1.00	A # 0.000 CO. (5.7% D.)	
2	Rear exhaust heat shield	107	20 10	1.00	0.00	-0.00 P N
3	Rear chassis member (LH)			1.00	0.00	0.00 R
		@ 25%	6252.98 1563.23	Discount	Amt (0.00%) subtotal	S\$ 0.00 S\$ 0.00 S\$ 0.00
	Section: Special Nett Items	101	4689.68 .			
	Rear number plate & casing			1.00	45.00	45.00 SER
	Rear bumper clip set			1.00		
	Tail lamp clip set			1.00	30.00	30.00 TNE
	Bootlid insulator clip set		1 .	1.00	45.00 30	
	End panel top garnish clip set			1.00	30.00	
	Rear fender inner trim clip set (Li	H)		1.00		30.00 NEC
	Rear fender inner trim clip set (R			1.00	50.00 30	10.00
	End panel sealant	16		1:00	50.00 30.	00 50.00 } 7N

we are



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No Make & Model : SJH4690X

: TOYOTA, COROLLA AXIO 1.5X

A,NZE1416085483

: 2008

Year of Manufacture Estimation No. : E19030013 DOA : 09/03/2019

No	Description			Qty	U/P	Amt
52	Tail lamp panel sealant	=375	1/2	1.00	50.00 36	50.00 Z 250.
53	Spare tyre panel sealant			1.00	50.00 3	50.00 J 'AL
54	Spare tyre panel insulator matt			1.00	280.00	280.00 7 NN
55	Rear windscreen sealant			1.00	50.00 3	010050.00 NE C
56	Rear windscreen tinted			1.00	200.00	(un { 00.000
57	Exhaust mounting set			1.00	150.00	-150.00
	1		345,00	Discoun	t (0.00%)	\$ 1,130.00 \$\$ 0.00
				\$	Subtotal S	\$ 1,130.00
	Section: Labour Items			200220		60.00
58	To R&R rear bumper reverse sensor			1.00	80.00	80:00 50:00

		Section: Labour Items				60.00
5	8	To R&R rear bumper reverse sensor		1.00	80.00	00 00
	9	To check wiring & lighting system		1.00	80.00	80:00 5 A OU
	60	To supply undercoating / putty on parts replaced		1.00	80.00	Хии 00.08
	51	To perform anti rust treatment on affected areas		1.00	60.00	60.00 NECV
	2	To R&R rear trims, seats & garnish	29	1.00	180.00	180.00 100.00
	33	To R&R rear windscreen	25 N	1.00	200.00	200.00 120.00
	54	To R&R fuel tank to cut & weld		1.00	300.00	4 NN 80.00€
	55	To R&R rear exhaust assy		1.00	200.00	X414 00.005
	66	To straighten rear chassis member		1.00	400.00	400.00 NNX
	57	To repair,replace & realign damaged areas		1.00	1,600.00	1,600.00 1000 .00
	68	To spray painting on affected areas		1.00	1,200.00	1,200.00 800.00
	59	To perform water seepage test after repair		1.00	150.00	-150.00 NNX
	70	Sundries		1.00	50.00	50.00
-					Amt 5	\$ 4,580.00 2/90 0

[전문 12] [전문 전문 전문 기계 12] [전문 전문 전문 기계 12] [전문 전문 전	
LKK Auto Consultants hence notify	7
the Repairer of the following:	1 1
 To resurvey before/after spray painting 	
 To display damaged part(s) during resurvey 	R
 Parts prices are subject to confirmation 	
. Third party survey is on a "Without Prejudice" basi	s I
No lilegal modification(s) is allowed	-19
 Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company 	00

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	11/3/19 16 oolus
Acknowledged by Repairer	
Signature:	
Date:	Resurvey ou
	1027

1/3(19)	16 00MS	Special Nett Items	S\$ 1,130.00
Labour Items Subtotal	5\$ 4,580.00		
Resurvey on 12/3/19	Total	5\$ 5,710.00	
237	Min	PAGE 3 0F 3	

7372.50

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	7901C
Vehicle No.:	SJH4690X
Vehicle to be Exported:	No.
Intended Deregistration Date:	09 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model;	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1NZD084385
Chassis No.:	NZE1416085483
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,717.00
Original Registration Date:	08 Aug 2008
First Registration Date:	08 Aug 2008
Transfer Count:	2
Actual ARF Paid:	\$8,183.00
Intended PARF Rebate Details	Forfeited
PARF Eligibility: PARF Eligibility Expiry Date:	Forteled
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	\$0.00
COE Expiry Date:	07 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$15,085.00
Total Rebate Amount: Message	\$15,085.00
	enewed. The vehicle must be de-registered upon COE expiry or when the

The information contained herein is correct as at 09 Mar 2019

vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

OK

Aug dep 5,5 to fyr 458/mil

1000 mil

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Singapore NRIC
Owner ID:	7901C
/ehicle Details	
/ehicle No.:	SJH4690X
/ehicle to be Exported:	Yes
ntended Deregistration Date:	11 Mar 2019
/ehicle Make:	TOYOTA
/ehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
ngine No.:	1NZD084385
Chassis No.:	NZE1416085483
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,717.00
Original Registration Date:	08 Aug 2008
irst Registration Date:	08 Aug 2008
Fransfer Count:	2
Actual ARF Paid: ntended PARF Rebate Details	\$8,183.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	07 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$15,067.00
Total Rebate Amount: Message	\$15,067.00
Please note that the 5-year COE for this vehicle cannot be	further renewed. The vehicle must be de-registered upon COE expiry or when the ever is earlier.

The information contained herein is correct as at 11 Mar 2019

SGCARMART.COM

Login Sign up

dealers

New Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

competed to buy my car!



Sell ur Car for More Cash Highest Price or Get \$100 Free Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Ways of Selling

Direct Owner

YONG LEE SENG MOTOR PTE LTD

Post an Ad

Advertiser Login

« Back (1 2 3) Next »

Stock GTR Oct 08, \$175k Negotiable

Sort by Date Posted ▼ 20 results/page

Basic Search 🔉

*

54 vehicles

Price Any price Depre Any depre ▼ Mileage Any

Reg Date After 2008 OMV Anv

Eng Cap Any

Veh Type All types

Past Owners Any

Fuel Any fuel

Category All categories

Scheme All schemes

Dealer Any Dealer ▼ Location Any

Gear Any Gear

Status Available

3

Make & Model

Toyota Corolla Axio 1.5A X

\$25,800

Price

Depreciation

Reg Date

Eng Cap Mileage Veh Type

Status

(COE till 11/2023)

\$5,530 /VT

07-Nov-2008

108,000 km 1.496 cc

Sedan

Available

SECURITION AND ADDRESS.

STATE OF THE PARTY OF THE PARTY

Available

Available

Well Maintained, Super Low Genuine Mileage Done, Well Groomed Inside Out, No Repairs Needed, Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency, We Pr...

Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota Posted: 09-Mar-2019

toyota axio



Toyota Corolla Axio 1.5A X (COE till 03/2024)

\$29,800

\$5,970 /vr

05-Mar-2009

1,496 cc

140,000 km

Available Sedan

Well Maintained By Previous Owner. Best Fuel Saving Unit, Toyota Japan Model. 160 Point Check Done. Most Of The Wear And Tear Has Been Done Up. Please Call Our Sales Consultant For More Enquiries Now.

Inchcape Pre-Owned

Posted: 09-Mar-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota



Toyota Corolla Axio 1.5A X

\$26,800

\$5,350 /yr

06-Feb-2009

1,496 cc

109,845 km

Sedan

(New 5-yr COE) Reliable, Very Well Maintained By Careful Owner. Stable Good Road Holding And Best Fuel Saving! 100% Loan Available. Bank Or In House Loan. Low Maintenance Cost! Flexible Loan, Low Monthly Installment .

Posted: 08-Mar-2019 Tays: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Axio 1.5A X

\$26,800

\$5,350 /yr

09-Mar-2009

1,496 cc

91,000 km

Sedan

(New 5-yr COE) 100% Loan Available, We Only Select The Best Unit To Sell, Best Effiency Car To Own, Trade In Welcomed. Buy With A Peace Of Mind As Car Is Good

1axis

Taga: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota Posted: 08-Mar-2019



Dynamics Mechanic Pte Ltd - Repair & Servicing

DM-Dynamics Mechanic Garage, the only Boutique Garage in Singapore. They are a fully equipped garage serving JDM (Japanese) and Continental vehicles.

More info about this shop



Toyota Corolla Axio 1.5A X (New 10-yr COE)

\$39,888

\$3,990 /vr

11-Mar-2009

1.496 cc

Sedan

Available

Fosted: 08-Mar-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota

Toyota Corolla Axio 1.5A X

\$14,800

N.A


17-Aug-2009

1,496 cc

Available

New Arrivals, 2 Owners Reliable Axio, Vi Usage Or Future COE Renewal, Call Nov

inal Paint Work Elegant Gold Paint With Grey Leather Interior, Good For Short Terms





No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT


Vehicle No Make & Model : SJH4690X

: TOYOTA,COROLLA AXIO 1.5X A,NZE1416085483

: 2008

Year of Manufacture Estimation No. : E19030013 DOA : 09/03/2019

No	Description	Qty	U/P	Amt
	Section: List Items			
1	Rear bumper	1.00	0.00	0.00 (
2	Rear bumper retainer long (LH)	1.00	0.00	0.00)
3	Rear bumper retainer long (RH)	1.00	0.00	0.00 (
4	Rear bumper retainer short (LH)	1.00	0.00	0.00
5	Rear bumper retainer short (RH)	1.00	0.00	0.00
5	Reverse sensor	4.00	0.00	0.00 (
,	Rear bumper bracket (LH)	1.00	0.00	0.007
3	Rear bumper bracket (RH)	1.00	0.00	0.00
9	Bootlid	1.00	0.00	0.00 F
.0	Bootlid emblem - Logo	1.00	0.00	0.00)
.1	Bootlid emblem - Axio	1.00	0.00	0.00
12	Bootlid emblem - X	1.00	0.00	0.00
.3	Bootlid lock	1.00	0.00	0.00B
.4	Bootlid lock catch	1.00	0.00	0.00
.5	Bootlid key lock	1.00	0.00	0.00
.6	Bootlid rubber beading	1.00	0.00	0.00 €
7	Bootlid hinge (LH)	1.00	0.00	0.00
.8	Bootlid hinge (RH)	1.00	0.00	0.00
19	License lamp garnish	1.00	0.00	0.00
20	License lamp (LH)	1.00	0.00	0.00)
21	License lamp (RH)	1.00	0.00	0.00
22	Bootlid insulator	1.00	0.00	0.00
23	Tail lamp (LH)	1.00	0.00	0.00 }
4	Tail lamp (RH)	1.00	0.00	0.00
25	Tail lamp gasket (LH)	1.00	0.00	0.00 ر
26	Tail lamp gasket (RH)	1.00	0.00	0.00
27	Tail lamp inner panel (LH)	1.00	0.00	0.00



: 09/03/2019



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

DOA

ESTIMATION REPORT Estimation No. : E19030013

Vehicle No Make & Model : SJH4690X

: TOYOTA, COROLLA AXIO 1.5X

A,NZE1416085483

Year of Manufacture

49

50

51

End panel sealant

Rear fender inner trim clip set (LH)

Rear fender inner trim clip set (RH)

: 2008

No	Description	Qty	U/P	Amt
28	Tail lamp inner panel (RH)	1.00	0.00	0.00 ?
29	End panel	1.00	0.00	0.00 ?
30	End panel top garnish	1.00	0.00	0.00 DL V
31	Spare tyre panel	1.00	0.00	0.00 ?
32	Spare tyre top panel	1.00	0.00	0.00 ?
33	Rear fender (LH)	1.00	0.00	0.00 DDV
34	Rear fender inner shield (LH)	1.00	0.00	0.00 NN
35	Rear fender air vent	1.00	0.00	0.00 ?
36	Rear fender inner trim (LH)	1.00	0.00	0.007
37	Rear fender inner trim (RH)	1.00	0.00	0.00?
38	Fug lid	1.00	0.00	0.00 NN)
39	Rear windscreen	1.00	0.00	0.00 NN>
40	Rear windscreen moulding	1.00	0.00	0.00 NEC
41	Rear exhaust muffler	1.00	0.00	-0.00 2 NY
42	Rear exhaust heat shield	1.00	0.00	0.00 NN
43	Rear chassis member (LH)	1.00	0.00	0.00 R
			Amt (0.00%) Subtotal	S\$ 0.00 S\$ 0.00 S\$ 0.00
	Section: Special Nett Items			
44	Rear number plate & casing	1.00	45.00	45.00 SCR
45	Rear bumper clip set	1.00	50.00	50.00 7
46	Tail lamp clip set	1.00	30.00	30.00 YNE
47	Bootlid insulator clip set	1.00	45.00	45.00
48	End panel top garnish clip set	1.00	30.00	30.00 NE

50.00

50.00

50.00

1.00

1.00

1.00

50.00

50,00

50.00



No.8 Kakl Buklt Ave 4, Premier @ Kaki Buklt, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No Make & Model : SJH4690X

: 2008

: TOYOTA, COROLLA AXIO 1.5X

A,NZE1416085483

Year of Manufacture

Estimation No.: E19030013 DOA

: 09/03/2019

No	Description	Qty	U/P	Amt
52	Tail lamp panel sealant	1.00	50.00	50.00 7 5
53	Spare tyre panel sealant	1.00	50.00	50.00,
54	Spare tyre panel insulator matt	1.00	280.00	280.00 7
55	Rear windscreen sealant	1.00	50.00	50.00 NEC
56	Rear windscreen tinted	1.00	200.00	200.00 (NN)
57	Exhaust mounting set	1.00	150.00	·150.00
			1 000	

Amt S\$ 1,130.00 Discount (0.00%) S\$ 0.00 Subtotal S\$ 1,130.00

	Section: Labour Items			60.00
58	To R&R rear bumper reverse sensor	1.00	80.00	80.00
59	To check wiring & lighting system	1.00	80.00	80:00 50.00
60	To supply undercoating / putty on parts replaced	1.00	80.00	80:00 NNX
61	To perform anti rust treatment on affected areas	1.00	60.00	60.00 NEC√
62	To R&R rear trims, seats & garnish	1.00	180.00	180.00 00 · 00
63	To R&R rear windscreen	1.00	200.00	200.00 120 · 00
64	To R&R fuel tank to cut & weld	1.00	300.00	-300.00 NNX
65	To R&R rear exhaust assy	1.00	200.00	200.00 NNX
66	To straighten rear chassis member	1.00	400.00	400.00 HNX
67	To repair, replace & realign damaged areas	1.00	1,600.00	1,600.00 1000 .00
68	To spray painting on affected areas	1.00	1,200.00	1,200.00 800 00
69	To perform water seepage test after repair	1.00	150.00	150.00
70	Sundries	1.00	50.00	50.00 NNX

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

? Photo Dump Sum pepair Repair days 8 Discount (0.00%)

\$\$ 0.00 List Items Subtotal 11/3/19 16 oolus Special Nett Items 5\$ 1,130.00 Subtotal Labour Items Subtotal S\$ 4,580.00 Total S\$ 5,710.00

PAGE 3 OF 3

Amt 5\$ 4,580.00

Subtotal 5\$ 4,580.00

5\$ 0.00

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

A

Policyholder's Signature Date & Time: M

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





No.8 Kakl Bukit Ave 4, Premler @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No Make & Model

24

25

26

27

Tail lamp (RH)

Tail lamp gasket (LH)

Tail lamp gasket (RH)

Tail lamp inner panel (LH)

: SJH4690X

: TOYOTA, COROLLA AXIO 1.5X

A,NZE1416085483

Year of : 2008 Manufacture

Estimation No. : E19030013

DOA

: 09/03/2019

No	Description	Qty	U/P	Amt
	Section: List Items			
1	Rear bumper	1.00	0.00	0.00 CRU V
2	Rear bumper retainer long (LH)	1.00	0.00	0.00)
3	Rear bumper retainer long (RH)	1.00	0.00	0.00
4	Rear bumper retainer short (LH)	1.00	0.00	0.00 PR
5	Rear bumper retainer short (RH)	1.00	0.00	0.00
6	Reverse sensor	4.00	0.00	0.00 CUTV
7	Rear bumper bracket (LH)	1.00	0.00	0.007
8	Rear bumper bracket (RH)	1.00	0.00	0.00 BTV
9	Bootlid	1.00	0.00	0.00 BTV
10	Bootlid emblem - Logo	1.00	0.00	0.00)
11	Bootlid emblem - Axio	1.00	0.00	0.00 NEC
12	Bootlid emblem - X	1.00	0.00	0.00
13	Bootlid lock	1.00	0.00	0.00BTV
14	Bootlid lock catch	1.00	0.00	XNN-00.0
15	Bootlid key lock	1.00	0.00	X 4 1 00.0
16	Bootlid rubber beading	1.00	0.00	0.00 CUTV
17	Bootlid hinge (LH)	1.00	0.00	0.00
18	Bootlid hinge (RH)	1.00	0.00	0.00 KNX
19	License lamp garnish	1.00	0.00	0.00 ? CRA!
20	License lamp (LH)	1.00	0.00	0.00)
21	License lamp (RH)	1.00	0.00	0.00 NNX
22	Bootlid insulator	1.00	0.00	0.00 CUTV
23	Tail lamp (LH)	1.00	0.00	0.00 200

0.00

0.00

0.00

0.00

1.00

1.00

1.00

1.00

0.00

0.00 3 BTV





No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No Make & Model : SJH4690X

: 2008

: TOYOTA, COROLLA AXIO 1.5X

A,NZE1416085483

Year of Manufacture Estimation No. : E19030013 DOA

: 09/03/2019

No	Description		Qty	U/P	Amt
28	Tail lamp inner panel (RH)		1.00	0.00	0.00 ?BTv
29	End panel		1.00	0.00	0.00 ? DD
30	End panel top garnish		1.00	0.00	0.00 DLV
31	Spare tyre panel		1.00	0.00	-0.00 ? R
32	Spare tyre top panel		1.00	0.00	0.00 ? 007
33	Rear fender (LH)		1.00	0.00	0.00 DDV
34	Rear fender inner shield (LH)		1.00	0.00	- 00.00 NN
35	Rear fender air vent		1.00	0.00	0.00 > N N
36	Rear fender inner trim (LH)		1.00	0.00	0.007)
37	Rear fender inner trim (RH)		1.00	0.00	0.00?](11
38	Fug lid		1.00	0.00	XNH 00.0
39	Rear windscreen		1.00	0.00	0:00 NNX
40	Rear windscreen moulding		1.00	0.00	0.00 NEC
41	Rear exhaust muffler		1.00	0.00	-0.00 P NN
42	Rear exhaust heat shield		1.00	0.00	-0.00 NN)
43	Rear chassis member (LH)	8075	1.00	0.00	-0.00 R X
			Discou	Amt unt (0.00%) Subtotal	S\$ 0.00 S\$ 0.00 S\$ 0.00
	Section: Special Nett Items				
14	Rear number plate & casing		1.00	45.00	45.00 SCR1
15	Rear bumper clip set		1.00	50.00	30 50.00 7
16	Tail lamp clip set		1.00	30.00	30.00 YNEC
17	Bootlid insulator clip set		1.00	45.00	30 45.00
18	End panel top garnish clip set		1.00	30.00	30.00 NEC
19	Rear fender inner trim clip set (LH)		1.00	50.00	30 50,00)
0	Rear fender inner trim clip set (RH)		1.00	50.00	30 50:00 7 7NE
1	End panel sealant		1.00	50.00	50.00
				Continue on	next page



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No

: SJH4690X

: TOYOTA, COROLLA AXIO 1.5X Make & Model

: 2008

A,NZE1416085483

Year of Manufacture Estimation No. : E19030013 DOA : 09/03/2019

No	Description	Qty	U/P	Amt
52	Tail lamp panel sealant	1.00	50.00	50.00-2 250.0
53	Spare tyre panel sealant	1.00	50.00	50.00
54	Spare tyre panel insulator matt	1.00	280.00	280.00 7 NNX
55	Rear windscreen sealant	1.00	50.00	50.00 NEC
56	Rear windscreen tinted	1.00	200.00	X NN { 00.000
57	Exhaust mounting set	1.00	150.00	-150.00

Amt 5\$ 1,130.00 375.00 Discount (0.00%) S\$ 0.00 Subtotal S\$ 1,130.00

Amt 5\$ 4,580.00 219 b

Subtotal 5\$ 4,580.00

\$\$ 0.00

	Section: Labour Items			
58	To R&R rear bumper reverse sensor	1.00	80.00	80.00
59	To check wiring & lighting system	1.00	80.00	80.00 50 OV
60	To supply undercoating / putty on parts replaced	1.00	80.00	X44 00.08
61	To perform anti rust treatment on affected areas	1.00	60.00	60.00 NECV
62	To R&R rear trims, seats & garnish	1.00	180.00	180.00 100.00
63	To R&R rear windscreen	1.00	200.00	200.00 120.00
64	To R&R fuel tank to cut & weld	1.00	300.00	-300.00 NNX
65	To R&R rear exhaust assy	1.00	200.00	200.00 NNX
66	To straighten rear chassis member	1.00	400.00	XUH 00.00+
67	To repair,replace & realign damaged areas	1.00	1,600.00	1,600.00 1000.00
68	To spray painting on affected areas	1.00	1,200.00	1,200.00 800.00
69	To perform water seepage test after repair	1.00	150.00	150.00
70	Sundries	1.00	50.00	-50.00 NNX

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

? Photo D Lump Sun pepair Repair days 8 Discount (0.00%)

List Items Subtotal 5\$ 0.00 11/3/19 16 oolus Special Nett Items S\$ 1,130.00 Subtotal Labour Items Subtotal SS 4,580.00 5\$ Total Resurvey on 12/3/19 5,710.00 PAGE 3 OF 3

Nivitha (LKK Auto)

From:

Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent:

Monday, 11 March 2019 12:10 PM

To:

assignments

Subject:

FW: Accident involving SJH4690X & XE1773K on 08/03/2019 (PRE-REPAIR SURVEY

REQUEST)

Attachments:

image001.emz; image012.wmz; 20190309114522557.pdf; 20190309114530329.pdf

12.17pmD11/3/19 Vehicle In Lucas SURO Mr. Lim. Requirer agreed Mr. Lim. to Survy.

Hi team

Kindly assist. Tp smart.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Torque 5 Assessment <assessment@torque5.com>

Sent: Saturday, 9 March, 2019 11:27 AM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Cc: 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com

Subject: Accident involving SJH4690X & XE1773K on 08/03/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Lee Yee Ling, to notify you of the aforesaid accident involving our client's vehicle SJH 4690 X and your insured's vehicle XE 1773 K on 08/03/2019.

Please find enclose our client's GIA report for your necessary action.

This serves as a NOTICE that we are claiming against XE 1773 K for damages, costs and disbursements.

Please let us know within 2 working days from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least ten (10) motor surveyors.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: Lucas (8131 6518)

Contact Email: assessment@torque5.com

VEH IN (Date & Time)

: 08/03/2019

PRS ARRANGEMENT (Date & Time)

: 11/03/2019

PRS ACKNOWLEDGEMENT

Appointed Surveyor (Name & Signature)

Date & Time of Inspection

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA



report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards, Lucas Chow Assessor | Motor Claims Department

Hotline

(65) 6452 4457 | Fax (65) 6452 4584

Mobile

(65) 8131 6518

Email

lucas.chow@torque5.com

Address

8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54 Premier @ KB, Singapore 415875

www.torque5.com















Menu



<MANDATE IA> - S9M01GI2 [ACCIDENT INVOLVING XE 1773K(OI) & SJH 4690X(TP) ON 08/03/2019]

Туре

Question

Message

· Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$6,659.95(if claim LOU) -\$7,159.95(if claim LOR). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Jia Le - 06 June 2019



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 06/06/2019

Survey Details:

Date of loss	8-Mar-19
Date of appointment	11-Mar-19
Date of survey	11-Mar-19
Location of survey	TORQUE 5 PTE LTD

Vehicle Details:

Claim Type:		Third party
Vehicle number		SJH 4690X
Make and Model		TOYOTA COROLLA AXIO 1.5X
Date of registration	8/8/20	
Excess		
Market Value	\$	23,000.00
Parf Rebate	\$	15,067.00
Nett Loss	\$	7,933.00

Repair details:

Initial Estimate	\$ 14,081.88

Proposed/Revised repair cost:

Parts	\$ 5,034.68
Check items (estimate)	\$
Labour	\$ 2,190.00
Total	\$ 7,224.68
Lump Sum(if applicable)	\$ 5,750.00

Number of days for repair	8



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

recommendation repair days + 1 sun + 1 PRS	

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 6,152.50	\$ 6,152.50
Loss of use (10days x \$50)	NIL	\$ 500.00
Loss of rental (10days x		39
\$100.00)	\$ 1,000.00	NIL
Loss of income	NIL	NIL
LTA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 7,159.95	\$ 6,659.95



HUB Logistics Pte Ltd

Main Office: 2 Clementi Loop,#01-04 LogisHub@Clementi, Singapore 129809

Warehouse: #01-03/04/05/05A, #03-03, #04-04

Tel: (65)6262 0313 Fax: (65)6262 0318

Website: www.hublogistics.com.sg

Website: www.hublogistics.com.sg Email: enquiry@hublogistics.com.sg Co. Reg No.: 200403197G

TO WHOM IT MAY CONCERN

RE: CERTIFICATION OF EMPLOYMENT

This is to certify that Mr Nagarajan Senthil Murugan of FIN No.: G7988510Q has been employed by HUB Logistics Pte Ltd as Prime Mover Driver since 10th October 2018. His Monthly Salary is \$2,600.00.

He is being assigned to drive vehicle number XE1773K during his employment.

Kindly give us a call if you need further clarification.

Thank you.

Your faithfully,

Jane Teo HR/Admin Manager

HUB Logistics Pte Ltd

Hsiao Tong (LKKAuto)

From:

jane@hubdistributors.com

Sent:

Thursday, 11 April 2019 5:35 PM

To:

'David Neo'; Hsiao Tong (LKKAuto)

Cc:

'Alvin Ea'

Subject:

RE: ACCIDENT INVOLVING XE 1773K(AXA) & SJH 4690X ALONG/AT BKE BEFORE

EXIT 8 SLE (CTE/TPE) ON 08/03/2019

Attachments:

11042019173318.pdf

Dear Ms Chew,

Hereby attached the document for your kind attention.

Thank you.



From: David Neo <davidneo@hublogistics.com.sg>

Sent: Thursday, 11 April 2019 4:44 PM

To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>

Cc: jane@hubdistributors.com; 'Alvin Ea' <alvinea@hublogistics.com.sg>

Subject: RE: ACCIDENT INVOLVING XE 1773K(AXA) & SJH 4690X ALONG/AT BKE BEFORE EXIT 8 SLE (CTE/TPE) ON

08/03/2019

Hi Ms Chew,

Our HR Ms Jane will reply with Letters that u needed once is ready.

Tks.

Hi Jane,

Pls kindly send the letter to Ms Chew once ready. Tks.



Name	Changes to Telephone Number	
Janet (Accounts)	6262 0313 Ext. 26	
Shazana (CS)	6463 1648 Ext. 105	
Rhinadel (CS)	6463 1648 Ext. 106	
Yusni (Control)	6463 1648 Ext. 107	
David	6463 1648 Ext. 108	= -
Alvin	6463 1648 Ext. 108	





Since 1989

David Neo

Assistant Manager (Haulage)

davidneo@hublogistics.com.sg

T: +65 6463 1648 ext 107

M: +65 9680 6673

No. 2 Clementi Loop, Logishub@Clementi #01-04/05/05A, #03-03 & #04-04. Singapore 129809

HUB Distributors Services • HUB Logistics • HUB Express



Our range of services include:

Warehousing & Storage, Third-party Logistics (3PL), Local Transportation, Van Delivery Services, Door-to-Door Services, Customs Declaration & Clearance, Ocean/Air Freight Services, Container Haulage, Machinery Shifting, Project Cargo Services Police / Cisco Escort

Please kindly drop us a call if you do not receive a reply from us within 2 hours Office Hours: 8 am to 5 pm (Mondays to Fridays) and 8 am to 12 pm (Saturday) Emails that are sent and received after office hours will be replied the next working day

All business are transacted with HUB are in accordance with Standard Trading Terms and Conditions of Singapore Logistics Association. A copy is available upon request.

This email and any attachements may contain confidential or privileged information. Unauthorized use, review, distribution and copying of this email and any attachment herein are prohibited. If you receive this email or had been transmitted in error, please delete/notify us immediately by reply email. Thank You.



A Please consider the environment before printing this email

From: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Sent: Thursday, April 11, 2019 11:55 AM To: davidneo@hublogistics.com.sg

Subject: ACCIDENT INVOLVING XE 1773K(AXA) & SJH 4690X ALONG/AT BKE BEFORE EXIT 8 SLE (CTE/TPE) ON

08/03/2019

11 April 2019

M/S HUB LOGISTICS PTE LTD Attn: Mr David

Dear Sir/ Mdm

OUR REF

: CC4/ASM19004352/Bfg3

YOUR REF

: XE 1773K

ACCIDENT INVOLVING XE 1773K(AXA) & SJH 4690X ALONG/AT BKE BEFORE EXIT 8 SLE (CTE/TPE) ON 08/03/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from TORQUE 5 PTE LTD acting on behalf of the owner of SJH 4690X against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your driver favour as it is a head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license or vocational license (if any)
- Authorisation Letter/ Employment Letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: $\frac{\text{chewht@lkkauto.com}}{\text{email: chewht@lkkauto.com}} \mid \text{fax: 6741-4108}$ Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK AUTO CONSULTANTS PTE LTD (TP) *

Menu



pls proceed DS

Type

Question

Message

Menu



Pls upload parts price before proceeding DS with quantum as proposed

Type

Question

Message

LKK AUTO CONSULTANTS PTE LTD (TP) +

Menu



pls proceed DS

Туре

Q Question

Message

Cecilia Chong (LKK Auto)

From:

Torque 5 Claims <claims@torque5.com>

Sent:

Friday, 13 September 2019 2:19 PM

To:

Asher Sng (LKKAuto); Vic (LKKAuto); Cecilia Chong (LKK Auto); Poh Kin (LKKAuto); Hsiao

Tong (LKKAuto)

Cc:

claims@torque5.com

Subject:

Accident Involving SJH 4690 X & XE 1773 K on 08/03/2019. Our Ref: SJH4690X

Attachments:

SJH 4690X - 08032019 LOD.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

Attached is the Final repair bill, Rental agreement, LTA fee & GIA fee of the above mentioned vehicle.

Claim amount as per below:-

Repair Cost

\$ 6,152.50

Loss of Rental for 08 Days x \$100/- per day

\$ 800.00

LTA/GIA fee

\$ 31.00

TOTAL:

\$ 6,983.50

The above settlement is in respect of our client's claim for damages pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation of his personal injuries.

Kindly acknowledge by replying to this email and let us have your offer soon.

Your assistance is greatly appreciated.



Thank you.

Warmest Regards, Rachel Wu

Claims Officer | Motor Claims Department

Hotline

(65) 6452 4457 EXT 112 | Fax (65) 6452 4584

Address

8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54 Premier @ KB, Singapore 415875

www.torque5.com



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna	ationale Des	Experts En Autom	obile
AXA INSURANCE P	TE LTD	Ref :	CC4/ASM19004	4352/Bga3s2
8 SHENTON WAY #; AXA TOWERSINGA ATTN: PETER WAN	PORE 068811	Date :		
1.	Policy Particula			M
Insured Veh.	XE 1773K		nspected	SJH 4690X
Policy No.	P1795175	Cover	age (\$)	0.00
Claim No.	S9M01GI2	Exces	s (\$)	0.00
Assign From	PETER WANG	Assig	n Date	11/03/2019
2.	Vehicle Pa	rticulars 8	& Condition	
Make & Mode	TOYOTA COROLLA AXIO	c.c		1496
Engine No.	HIDDEN	Year	of Reg.	2008
Chassis No.	NZE1416085483	Colou	r	GREY

_	D	Size	Make	Balance
3.		Size	onditions of Tyres	Polonia
3.	CO Horses Days			THE RESERVE AND THE RESERVE AND THE PARTY OF
	General	FAIR		
	Brakes	IN ORDER	Modification	SPORTS RIM
	Odometer	172890	Steering	IN ORDER
	Chassis No.	NZE1416085483	Colour	GREY
	Eligine No.	HIDDEN	Year of Reg.	2008

Size	Make	Balance
205/50 R16	BRIDGESTONE	7 mm
205/50 R16	BRIDGESTONE	7 mm
205/50 R16	BRIDGESTONE	7 mm
205/50 R16	BRIDGESTONE	7 mm
	205/50 R16 205/50 R16 205/50 R16	205/50 R16 BRIDGESTONE 205/50 R16 BRIDGESTONE 205/50 R16 BRIDGESTONE

4.	Description of Damag
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/03/2019	Inspection Date	11/03/2019	
	Survey held at	TORQUE 5 PTE LTD		W1000000000000000000000000000000000000	
	839	8 KAKI DI IKIT AVENI JE A			

O MAMI DUINT AVENUE A
8 KAKI BUKIT AVENUE 4
#01-50 PREMIER @ KAKI BUKIT
SINGAPORE 415875

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
1	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair		
	ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 4690X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	CRUSHED	496.20	496.20
1	REAR BUMPER RETAINER LONG (LH) (CONSISTENT)	BROKEN	89.90	89.90
1	REAR BUMPER RETAINER LONG (RH) (CONSISTENT)	BROKEN	89.90	89.90
1	REAR BUMPER RETAINER SHORT (LH) (CONSISTENT)	BROKEN	89.90	89.90
1	REAR BUMPER RETAINER SHORT (RH) (CONSISTENT)	BROKEN	89.90	89.90
4	REVERSE SENSOR @ \$362.00 (CONSISTENT)	сит	1,448.00	200.00
1	REAR BUMPER BRACKET (LH) (CONSISTENT)	BENT	89.90	89.90
1	REAR BUMPER BRACKET (RH) (CONSISTENT)	BENT	89.90	89.90
1	BOOTLID (CONSISTENT)	BENT	698.70	698.70
1	BOOTLID EMBLEM - LOGO (CONSISTENT)	NECESSARY	85.20	34.50
1	BOOTLID EMBLEM - AXIO (CONSISTENT)	NECESSARY	58.00	45.50
1	BOOTLID EMBLEM - X (CONSISTENT)	NECESSARY	58.00	34.50
1	BOOTLID LOCK (CONSISTENT)	BENT	755.40	192.20
1	BOOTLID LOCK CATCH (NPA) (CONSISTENT)	NOT NECESSARY		
1	BOOTLID KEY LOCK (NPA) (CONSISTENT)	NOT NECESSARY		
1	BOOTLID RUBBER BEADING (CONSISTENT)	сит	198.70	187.10
1	BOOTLID HINGE (LH) (CONSISTENT)	NOT NECESSARY	128.10	1000000
1	BOOTLID HINGE (RH) (CONSISTENT)	NOT NECESSARY	128.10	
1	LICENSE LAMP GARNISH (CONSISTENT)	CRACKED	167.10	167.10
1	LICENSE LAMP (LH) (CONSISTENT)	NOT NECESSARY	92.00	
1	LICENSE LAMP (RH) (CONSISTENT)	NOT NECESSARY	92.00	
1	BOOTLID INSULATOR (CONSISTENT)	сит	310.00	200.00
1	TAIL LAMP (LH) (CONSISTENT)	BROKEN	467.50	321.00
1	TAIL LAMP (RH) (CONSISTENT)	BROKEN	467.50	321.00
1	TAIL LAMP GASKET (LH) (NPA) (CONSISTENT)	NOT NECESSARY	5-	
- 1	TAIL LAMP GASKET (RH) (NPA) (CONSISTENT)	NOT NECESSARY		
536	TAIL LAMP INNER PANEL (LH) (CONSISTENT)	BENT	254.20	183.80
1	TAIL LAMP INNER PANEL (RH) (CONSISTENT)	BENT	254.20	183.80
1	END PANEL (CONSISTENT)	DENTED	485.80	394.60
1	END PANEL TOP GARNISH (CONSISTENT)	DISLODGE	215.10	182.50

Report Ref No. CC4/ASM19004352/Bga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,345.20	
1	SPARE TYRE TOP PANEL (CONSISTENT)	CUT	598.20	380.90
1	REAR FENDER (LH) (CONSISTENT)	DENTED	981.20	845.10
1	REAR FENDER INNER SHIELD (LH) (CONSISTENT)	NOT NECESSARY	229.10	
1	REAR FENDER AIR VENT (NPA) (CONSISTENT)	NOT NECESSARY	(c .	
1	REAR FENDER INNER TRIM (LH) (CONSISTENT)	CUT	498.80	266.50
1	REAR FENDER INNER TRIM (RH) (CONSISTENT)	CUT	498.80	266.50
1	FUEL LID (NPA) (CONSISTENT)	NOT NECESSARY	(S *	9
1	REAR WINDSCREEN (NPA) (CONSISTENT)	NOT NECESSARY	1	
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	112.00	112.00
1	REAR EXHAUST MUFFLER (NPA) (CONSISTENT)	NOT NECESSARY	1/2	5.
1	REAR EXHAUST HEAT SHIELD (NPA) (CONSISTENT)	NOT NECESSARY		
1	REAR CHASSIS MEMBER (LH) (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	S
	LESS 25% DISCOUNT		-	-1,563.22
	And the artificial standards of control and control and standard for		11,662.50	4,689.68
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE & CASING (SN) (CONSISTENT)	SCRATCHED	45.00	45.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	SET TAIL LAMP CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET BOOTLID INSULATOR CLIP (SN) (CONSISTENT)	NECESSARY	45.00	30.00
1	SET END PANEL TOP GARNSIH CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET REAR FENDER INNER TRI CLIP (LH) (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	SET REAR FENDER INNER TRI CLIP (RH) (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	30.00
ា	TAIL LAMP PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	SPARE TYRE PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	SPARE TYRE PANEL INSULATOR MATT (SN) (CONSISTENT)	NOT NECESSARY	280.00	2
1	REAR WIDNSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN TINTED (SN) (CONSISTENT)	NOT NECESSARY	200.00	5

Report Ref No. CC4/ASM19004352/Bga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET EXHAUST MOUNTING (SN) (CONSISTENT)	NOT NECESSARY	150.00	
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	50.00	
	te. 565		1,180.00	345.00
	LABOUR			
	TO R&R REAR BUMPER REVERSE SENSOR.		80.00	60.00
	TO CHECK WIRING & LIGHTING SYSTEM.		80.00	50.00
	TO SUPPLY UNDERCOATING / PUTTY ON PARTS REPLACED.	NOT NECESSARY	80.00	6.7
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.		60.00	60.00
	TO R&R REAR TRIMS, SEATS & GARNISH.		180.00	100.00
	TO R&R REAR WINDSCREEN.		200.00	120.00
	TO R&R FUEL TANK TO CUT & WELD.	NOT NECESSARY	300.00	
	TO R&R REAR EXHAUST ASSY.	NOT NECESSARY	200.00	
	TO STRAIGHTEN REAR CHASSIS MEMBER.	NOT NECESSARY	400.00	
	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL AND REAR CHASSIS MEMBER (LH).		1,600.00	1,000.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	800.00
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR.	NOT NECESSARY	150.00	
	According to the American Committee of the Committee of t	AW 00 40140	4,530.00	2,190.00
	GRAND TOTAL		17,372.50	7,224.68

RECOMMENDED COST OF LUMP SUM REPAIRS	5,750.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM19004352/Bga3s2



LIM TEOW GUAN

Automotive Assessor

Amont

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.