



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJH4690X
Make & Model : TOYOTA, COROLLA AXIO 1.5X
A, NZE1416085483
Year of Manufacture : 2008

Estimation No. : E19030013
DOA : 09/03/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper	1.00	0.00	0.00 CRU ✓
2	Rear bumper retainer long (LH)	1.00	0.00	0.00
3	Rear bumper retainer long (RH)	1.00	0.00	0.00
4	Rear bumper retainer short (LH)	1.00	0.00	0.00 } ? BR ✓
5	Rear bumper retainer short (RH)	1.00	0.00	0.00
6	Reverse sensor	4.00	0.00	0.00 CuTV ✓
7	Rear bumper bracket (LH)	1.00	0.00	0.00
8	Rear bumper bracket (RH)	1.00	0.00	0.00 } ? BT ✓
9	Bootlid	1.00	0.00	0.00 BT ✓
10	Bootlid emblem - Logo	1.00	0.00	0.00
11	Bootlid emblem - Axio	1.00	0.00	0.00
12	Bootlid emblem - X	1.00	0.00	0.00 } NEC ✓
13	Bootlid lock	1.00	0.00	0.00 BT ✓
14	Bootlid lock catch	1.00	0.00	0.00 NN ✓
15	Bootlid key lock	1.00	0.00	0.00 NN ✓
16	Bootlid rubber beading	1.00	0.00	0.00 CuTV ✓
17	Bootlid hinge (LH)	1.00	0.00	0.00 } NN ✓
18	Bootlid hinge (RH)	1.00	0.00	0.00 }
19	License lamp garnish	1.00	0.00	0.00 ? CRA ✓
20	License lamp (LH)	1.00	0.00	0.00 } NN ✓
21	License lamp (RH)	1.00	0.00	0.00 }
22	Bootlid insulator	1.00	0.00	0.00 CuTV ✓
23	Tail lamp (LH)	1.00	0.00	0.00 } BR ✓
24	Tail lamp (RH)	1.00	0.00	0.00 }
25	Tail lamp gasket (LH)	1.00	0.00	0.00 } NN ✓
26	Tail lamp gasket (RH)	1.00	0.00	0.00 }
27	Tail lamp inner panel (LH)	1.00	0.00	0.00 ? BT ✓

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJH4690X
Make & Model : TOYOTA, COROLLA AXIO 1.5X
 A, NZE1416085483
Year of Manufacture : 2008

Estimation No. : E19030013
DOA : 09/03/2019

No	Description	Qty	U/P	Amt
28	Tail lamp inner panel (RH)	1.00	0.00	0.00 ? BTV
29	End panel	1.00	0.00	0.00 ? DDV
30	End panel top garnish	1.00	0.00	0.00 DLV
31	Spare tyre panel	1.00	0.00	0.00 ? RX
32	Spare tyre top panel	1.00	0.00	0.00 ? CUTV
33	Rear fender (LH)	1.00	0.00	0.00 DDV
34	Rear fender inner shield (LH)	1.00	0.00	0.00 NNX
35	Rear fender air vent	1.00	0.00	0.00 ? NNX
36	Rear fender inner trim (LH)	1.00	0.00	0.00 ? } CUTV
37	Rear fender inner trim (RH)	1.00	0.00	0.00 ? }
38	Fuel lid	1.00	0.00	0.00 NNX
39	Rear windscreen	1.00	0.00	0.00 NNX
40	Rear windscreen moulding	1.00	0.00	0.00 NECV
41	Rear exhaust muffler	1.00	0.00	0.00 ? NNX
42	Rear exhaust heat shield	1.00	0.00	0.00 NNX
43	Rear chassis member (LH)	1.00	0.00	0.00 RX
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

44	Rear number plate & casing	1.00	45.00	45.00 SCRV
45	Rear bumper clip set	1.00	50.00	30 50.00
46	Tail lamp clip set	1.00	30.00	30.00 } NEC
47	Bootlid insulator clip set	1.00	45.00	30 45.00
48	End panel top garnish clip set	1.00	30.00	30.00 NECV
49	Rear fender inner trim clip set (LH)	1.00	50.00	30 50.00
50	Rear fender inner trim clip set (RH)	1.00	50.00	30 50.00 } ? NEC
51	End panel sealant	1.00	50.00	50.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJH4690X
Make & Model : TOYOTA, COROLLA AXIO 1.5X
A, NZE1416085483
Year of Manufacture : 2008

Estimation No. : E19030013
DOA : 09/03/2019

No	Description	Qty	U/P	Amt
52	Tail lamp panel sealant	1.00	50.00	50.00
53	Spare tyre panel sealant	1.00	50.00	50.00
54	Spare tyre panel insulator matt	1.00	280.00	280.00
55	Rear windscreen sealant	1.00	50.00	50.00
56	Rear windscreen tinted	1.00	200.00	200.00
57	Exhaust mounting set	1.00	150.00	150.00
				Amt S\$ 1,130.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,130.00

Section: Labour Items

58	To R&R rear bumper reverse sensor	1.00	80.00	80.00
59	To check wiring & lighting system	1.00	80.00	80.00
60	To supply undercoating / putty on parts replaced	1.00	80.00	80.00
61	To perform anti rust treatment on affected areas	1.00	60.00	60.00
62	To R&R rear trims, seats & garnish	1.00	180.00	180.00
63	To R&R rear windscreen	1.00	200.00	200.00
64	To R&R fuel tank to cut & weld	1.00	300.00	300.00
65	To R&R rear exhaust assy	1.00	200.00	200.00
66	To straighten rear chassis member	1.00	400.00	400.00
67	To repair, replace & realign damaged areas	1.00	1,600.00	1,600.00
68	To spray painting on affected areas	1.00	1,200.00	1,200.00
69	To perform water seepage test after repair	1.00	150.00	150.00
70	Sundries	1.00	50.00	50.00
				Amt S\$ 4,580.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,580.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

? Photo
Lump Sum repair
Repair days 8

Repairer
11/3/19 1600hrs

Resurvey on 12/3/19
1237

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 1,130.00
Labour Items Subtotal	S\$ 4,580.00
Total	S\$ 5,710.00