



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 1455T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP) (CONSISTENT)	DENTED	200.00	200.00
1	TOWING EYE COVER (WCP) (CONSISTENT)	NOT NECESSARY	25.00	-
1	L/F BUMPER BRACKET (WCP) (CONSISTENT)	BROKEN	35.00	35.00
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	15.00	15.00
1	L/F WING (WCP) (CONSISTENT)	DENTED	170.00	170.00
1	L/F WING CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	12.00	-
1	L/F WHEELHOUSE COVER (WCP) (CONSISTENT)	NOT NECESSARY	45.00	-
	COST PLUS 15%		80.55	63.00
			617.55	483.00
	<u>LABOUR</u>			
	APPLY ANTI RUST COAT ANTI RUST COAT.	NOT NECESSARY	80.00	-
	TOTAL LABOUR.		108.00	108.00
	PAINT WORK: LABOUR COST.	NOT NECESSARY	144.00	-
	PAINT WORK: MATERIAL COST.	NOT NECESSARY	84.14	-
			416.14	108.00
GRAND TOTAL			1,033.69	591.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			450.00
---	--	--	---------------

Report Ref No. CC4/ASM19004353/Eba3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.