



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19004353/Eba3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 21-09-2020



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-------------|----------------|------------|
| Insured Veh. | SGY 128B | Veh. Inspected | SJJ 1455T |
| Policy No. | GA107839/1 | Coverage (\$) | 0.00 |
| Claim No. | S9M01GEX | Excess (\$) | 0.00 |
| Assign From | RICHARD ANG | Assign Date | 11/03/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------------|--------------|------------|
| Make & Model | TOYOTA RUSH | c.c | 1495 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | J200E0023187 | Colour | RED |
| Odometer | 128595 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 215/60 R16 | MICHELIN | 7 mm |
| L/H Front Tyre | 215/60 R16 | MICHELIN | 7 mm |
| R/H Rear Tyre | 215/60 R16 | MICHELIN | 7 mm |
| L/H Rear Tyre | 215/60 R16 | MICHELIN | 7 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 29/01/2019 | Inspection Date | 28/01/2019 |
| Survey held at | SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457. | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|