

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7828H

DATE 11/3/2019 14:56

MAKE :

*Like*

*L/Sum*

MODEL : HYUNDAI i40

*AXA*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Under Cover X			\$ 228.00
	<b>SUB TOTAL</b>			<b>\$ 803.00</b>
	<b>LESS 20%</b>			<b>\$ 160.60</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 642.40</b>
	Rear Bumper Rubber Mat ✓			\$ 50.00
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				<b>\$ 300.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>400.00</del> <i>200</i>
	Spray Painting Charge			\$ <del>300.00</del> <i>200</i>
	Wiring Charge			\$ <del>30.00</del> <i>X</i>
	Remove/Refix Reverse Sensor			\$ <del>80.00</del> <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 810.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,752.40</b>

Nett  
Nett  
Nett

*Kahin 700k*  
*12/3/19 1020h*  
*2 hrs*  
*L/S*  
*Atta Repair phd*

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplier's part(s) must be resurveyed and is subject to the insurer's liability insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.