

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	8		TO FURNISH AND APPLY UNDER-SEALING & RUST PROOFING COATS ON ACCIDENT AFFECTED AREA.	60	0		Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIZE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BITRN	DISC QUNTK	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	38	1			AIR CON DISCHARGE PIPE			Serviceable	0		20		0	Reviewing	
	39	1			AIR CON ELECTRIC FAN ASSY			Replaced	338.3		20		270.64	Reviewing	
	40	1			RADIATOR ASSY			Replaced	1276		20		1020.8	Reviewing	
	41	1			RADIATOR UPPER SUPPORT BRACKET			Replaced	9.25		20		7.4	Reviewing	
	42	2			RADIATOR LOWER SUPPORT MOUNTING			Replaced	32.5		20		52	Reviewing	
	43	1			RADIATOR ELECTRIC FAN ASSY			Replaced	338.3		20		270.64	Reviewing	
	44	1			RADIATOR SPARE TANK ASSY			Reused	0		20		0	Reviewing	
	45	1			RADIATOR INLET HOSE			Reused	0		20		0	Reviewing	
	46	1			RADIATOR OUTLET HOSE			Reused	0		20		0	Reviewing	
	47	1			AIR CLEANER BOX ASSY			Reused	0		20		0	Reviewing	
	48	1			ALTERNATOR ASSY			Replaced	1101.5		20		881.2	Reviewing	
	49	1			WASHER TANK ASSY			Replaced	115.1		20		92.08	Reviewing	
	50	1			WASHER TANK NECK HOSE			Replaced	62.5		20		50	Reviewing	
	51	1			WASHER TANK TOP COVER			Replaced	42.6		20		34.08	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BITTIN	DISC QUANTITY	SALY AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		12	1			RH HEADLAMP LOWER SUPPORT BRACKET			Replaced	36.9		20		29.52	Reviewing	
		13	1			LH HEADLAMP ASSY			Replaced	657.9		20		526.32	Reviewing	
		14	1			LH HEADLAMP LOWER SUPPORT BRACKET			Replaced	36.9		20		29.52	Reviewing	
		15	2			HEADLAMP CLIP			Replaced	3.5		20		5.6	Reviewing	
		16	1			FRONT RH FENDER PANEL			Repair	0		20		0	Reviewing	
		17	1			FRONT RH FENDER INNER PANEL			Repair	0		20		0	Reviewing	
		18	1			FRONT RH FENDER MUD SHIELD			Reused	0		20		0	Reviewing	
		19	1			FRONT LH FENDER PANEL			Repair	0		20		0	Reviewing	
		20	1			FRONT LH FENDER INNER PANEL			Repair	0		20		0	Reviewing	
		21	1			FRONT LH FENDER MUD SHIELD			Reused	0		20		0	Reviewing	
		22	2			SETS FRONT FENDER MUD SHIELD CLIP			Replaced	17.5		20		28	Reviewing	
		23	1			FRONT BUMPER COVER			Replaced	660.9		20		528.72	Reviewing	
		24	1			FRONT BUMPER TOW HOOK COVER			Reused	0		20		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0	0	License Type		
Market Value	0	0	License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	Singapore	
			Address type	Personal Correspondence	
			Gender	Unknown	
			Marital status	Unknown	
			Identification #	S8214220G	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
PAY Daniel	3/12/19 9:13 AM	9067.5	9067.5	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Re-Inspection details.msg	Letters and Correspondence	Third Party	PAY Daniel	March 12, 2019
 TP LOD.pdf	Legal	Letter of Demand/Notice of Proceedings	KUMAR Shailendra	September 25, 2018
 LKKPreRepairInspection[4].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 28, 2018
 LKKPhoto[2].pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 27, 2018
 LKKPhotoIn6-1.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 26, 2018
 GA204850-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TEO Kitty	June 24, 2018
 GA204850-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TEO Kitty	June 24, 2018
 SKA8652E TP GIA RPT.PDF	Reports & Statement	GIA Report	TEO Kitty	June 24, 2018