



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 6230L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR-VIEW MIRROR (SN) (CONSISTENT)	CUT	144.70	142.60
1	FRAME SLIDERS (SN) (CONSISTENT)	CUT	252.00	414.00
1	CIVIC RACK (SN) (CONSISTENT)	NOT NECESSARY	162.00	-
1	SCREW TCEIR M5X (SN) (CONSISTENT)	NECESSARY	0.60	0.50
1	CLAMP (SN) (CONSISTENT)	NECESSARY	9.50	9.40
1	RIGHT BRACKET (SN) (CONSISTENT)	NECESSARY	23.20	22.90
1	SCREW, SPECIAL	NECESSARY	4.40	4.40
1	GUARD, KNUCKLE (SN) (CONSISTENT)	CRACKED	124.80	122.90
1	SCREW (SN) (CONSISTENT)	NECESSARY	0.90	0.90
1	SPACER (SN) (CONSISTENT)	NECESSARY	4.40	4.40
1	BUSH (SN) (CONSISTENT)	NECESSARY	21.00	20.70
1	BUSH (SN) (CONSISTENT)	NECESSARY	16.80	16.30
1	THROTTLE CONTROL (SN) (CONSISTENT)	NOT NECESSARY	143.80	-
1	SCREW TCEIF M8X (SN) (CONSISTENT)	NECESSARY	2.70	2.60
3	SCREW TCEIF M8X (SN) (CONSISTENT)	NECESSARY	8.10	7.80
1	HANDLEBAR BRACK (SN) (CONSISTENT)	BENT	79.90	78.70
1	HANDLE BAR (SN) (CONSISTENT)	BENT	249.50	245.80
2	SCREW (SN) (CONSISTENT)	NECESSARY	7.40	7.20
2	HOLDER, HANDLE (SN) (CONSISTENT)	BENT	109.80	108.20
2	SPACER (SN) (CONSISTENT)	NECESSARY	38.60	38.00
2	WASHER 10.5X18X (SN) (CONSISTENT)	NECESSARY	0.60	0.60
2	VIBRATION DAMPE (SN) (CONSISTENT)	BENT	42.00	41.40
1	STEERING HEAD (SN) (CONSISTENT)	BENT	364.30	358.90
1	SCREW (SN) (CONSISTENT)	NECESSARY	17.30	16.80
2	WASHER 10.5X28X (SN) (CONSISTENT)	NECESSARY	20.40	19.80
2	NUT (SN) (CONSISTENT)	NECESSARY	1.20	1.20
4	SCREW (SN) (CONSISTENT)	NECESSARY	8.00	8.00
1	THREAD, STEERIN (SN) (CONSISTENT)	NOT NECESSARY	74.90	-
2	SEAL RING (SN) (CONSISTENT)	NOT NECESSARY	21.20	-
2	BEARING, STEERI (SN) (CONSISTENT)	NOT NECESSARY	168.40	-
4	SCREW (SN) (CONSISTENT)	NOT NECESSARY	11.60	-

Report Ref No. CC4/ASM19004446/T1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	NUT (SN) (CONSISTENT)	NOT NECESSARY	0.40	-
2	THREAD DOWEL (SN) (CONSISTENT)	NOT NECESSARY	3.60	-
1	STEERING HEAD B (SN) (CONSISTENT)	NOT NECESSARY	364.30	-
1	WASHER (SN) (CONSISTENT)	NOT NECESSARY	3.90	-
1	LEVER, FRONT BR (SN) (CONSISTENT)	CUT	212.10	209.00
1	BOLT, PIVOT (SN) (CONSISTENT)	NECESSARY	12.70	12.30
1	HOSE CLAMP 8 MM (SN) (CONSISTENT)	NECESSARY	8.00	7.80
1	COVER PEDAL (SN) (CONSISTENT)	CUT	11.80	11.50
1	BRAKE CONTROL L (SN) (CONSISTENT)	BENT	174.70	172.10
1	PIN PEDAL (SN) (CONSISTENT)	NECESSARY	7.90	7.70
2	O-RING (SN) (CONSISTENT)	NECESSARY	0.60	0.60
1	BUSH (SN) (CONSISTENT)	NECESSARY	5.30	5.20
1	NUT (SN) (CONSISTENT)	NECESSARY	0.30	0.30
1	SCREW (SN) (CONSISTENT)	NECESSARY	4.30	4.20
1	WASHER 8.2X20X1 (SN) (CONSISTENT)	NOT NECESSARY	1.60	-
1	SPRING (SN) (CONSISTENT)	NOT NECESSARY	15.00	-
1	SPACER (SN) (CONSISTENT)	NOT NECESSARY	11.80	-
1	SCREW (SN) (CONSISTENT)	NOT NECESSARY	0.80	-
1	BRAKE CONTROL R (SN) (CONSISTENT)	NOT NECESSARY	37.50	-
1	REAR BRAKE PUMP (SN) (CONSISTENT)	NOT NECESSARY	100.20	-
1	PLATE (SN) (CONSISTENT)	NOT NECESSARY	25.00	-
1	SCREW (SN) (CONSISTENT)	NOT NECESSARY	1.80	-
1	SCREW TCEIR M6X (SN) (CONSISTENT)	NOT NECESSARY	1.00	-
1	RIGHT FORK LEG (SN) (CONSISTENT)	NOT NECESSARY	1,362.30	-
1	LEFT FORK LEG A (SN) (CONSISTENT)	NOT NECESSARY	1,362.30	-
1	FRONT WHEEL SPI (SN) (CONSISTENT)	NOT NECESSARY	220.30	-
1	RIGHT SPACER (SN) (CONSISTENT)	NOT NECESSARY	9.80	-
2	SEAL RING 35X47 (SN) (CONSISTENT)	NOT NECESSARY	17.00	-
2	BEARING (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	INNER SPACER (SN) (CONSISTENT)	NOT NECESSARY	45.90	-
1	LEFT SPACER (SN) (CONSISTENT)	NOT NECESSARY	14.20	-
1	WASHER 30X40X1 (SN) (CONSISTENT)	NOT NECESSARY	1.90	-
1	NUT (SN) (CONSISTENT)	NOT NECESSARY	19.70	-

Report Ref No. CC4/ASM19004446/T1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL RIM (SN) (CONSISTENT)	NOT NECESSARY	1,796.40	-
2	FRONT BRAKE DIS (SN) (CONSISTENT)	NOT NECESSARY	971.40	-
10	SCREW (SN) (CONSISTENT)	NOT NECESSARY	23.00	-
2	FOOTREST PIN (SN) (CONSISTENT)	NOT NECESSARY	15.40	-
2	CIRCLIP E-TYPE (SN) (CONSISTENT)	NOT NECESSARY	1.80	-
2	RIGHT FOOTREST (SN) (CONSISTENT)	CUT	70.00	69.00
2	FOOT PEG RUBBER (SN) (CONSISTENT)	NOT NECESSARY	20.80	-
1	SPRING RETAINER (SN) (CONSISTENT)	NOT NECESSARY	5.50	-
1	SPRING (SN) (CONSISTENT)	NOT NECESSARY	1.70	-
1	BALL (SN) (CONSISTENT)	NOT NECESSARY	0.50	-
1	SPRING. FOOTREST (SN) (CONSISTENT)	NOT NECESSARY	3.10	-
1	R.H. HALF-FAIRY (SN) (CONSISTENT)	CUT	748.50	737.40
1	STICKER DUCATI (SN) (CONSISTENT)	NECESSARY	15.30	15.10
5	SCREW (SN) (CONSISTENT)	NECESSARY	41.50	41.00
5	PAD (SN) (CONSISTENT)	NECESSARY	13.00	12.50
1	COVER, FRAME R (SN) (CONSISTENT)	NOT NECESSARY	38.70	-
1	CLUTCH COVER (SN) (CONSISTENT)	NOT NECESSARY	985.60	-
1	SCREW TCEIF M6X (SN) (CONSISTENT)	NOT NECESSARY	6.20	-
3	SCREW TCEIF M6X (SN) (CONSISTENT)	NOT NECESSARY	22.50	-
5	SCREW TCEIF M6X (SN) (CONSISTENT)	NOT NECESSARY	14.50	-
1	SCREW, SPECIAL (SN) (CONSISTENT)	NOT NECESSARY	9.50	-
1	SCREW (SN) (CONSISTENT)	NECESSARY	1.80	1.70
1	PLATE (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	PIN DOWEL (SN) (CONSISTENT)	NOT NECESSARY	2.10	-
1	WASHER 10X14X1 (SN) (CONSISTENT)	NOT NECESSARY	0.40	-
1	PLUG, THREADED (SN) (CONSISTENT)	NOT NECESSARY	2.60	-
1	O-RING 11.11X1 (SN) (CONSISTENT)	NOT NECESSARY	1.10	-
1	HANDLE (SN) (CONSISTENT)	NOT NECESSARY	164.70	-
1	HANDLE (SN) (CONSISTENT)	NOT NECESSARY	164.70	-
1	SWITCH, REAR BR (SN) (CONSISTENT) (ADDITIONAL)	DISTORTED	43.60	43.60
			11,448.90	3,045.00
	LABOUR			
	TO REPLACE DAMAGED PARTS CAUSE.		2,880.00	2,880.00

Report Ref No. CC4/ASM19004446/T1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			2,880.00	2,880.00
GRAND TOTAL			14,328.90	5,925.00
RECOMMENDED COST OF REPAIRS				5,925.00

Report Ref No. CC4/ASM19004446/T1ga3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.