

10-00000

ASS. REC. BY

Wei Yea

Three file

REF

es/SPF19004458/Jtd302

ed Instruction

From (Person)

Wei Yea Kim

of

SPF

Date/Time: 11/3/19 @ 3:45pm

Estimated Cost

Bill to:

①

TP / AWS / TP RES / OD RES / EVA / INV / MY7CS

To Inspect Vehicle Ho

Q X 11611

Insured

at Workshop n/a

SMRT

Tel.

9857 6861

of

Go woodlands Ind. park E4

Policy No

Claim No

HOMSPFETQ16000399

Sum Insured

Excess

Make of Vch

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 11/3/19 @ 4:41pm

Person Contacted

Mr. Koney

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
11/3 -	Q X 11611 - X
	revert to wei yea.
	Part by part \$12.383
	man hour: 27.

ASS. REC. BY: Hlee JiaREF: SPF

ASSIGNMENT

From: _____

Date: 12/3/19

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo Inspect Vehicle No: QX 1161 Jat Workshop m/s K8Sof Sungai Kadut Drive 2-D

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: QX 1161 J

Yr Regn: _____ /

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Chevrolet

C.C. _____

Colour: Dark BlueA/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 107502T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: _____

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or _____Tyre Size: F: 235/60R17

R: _____

BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or _____

Crosswind

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 2 mm

D.O.A. _____

D.O.I. 13/3/19Survey held at K8SDes. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee: 180

Transportation: _____

S+RS: \$ _____

Photos _____

Others _____

TOTAL

180

Report Format: _____

Lump Sum / L.E.R. (\$) _____

Nivitha (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Monday, 11 March 2019 3:45 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX1161J)
Attachments: QX1161J.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- **QX1161J**

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 14 March 2019 4:26 PM
To: Wei Yea LIM (SPF)
Cc: Kim Pang CHAY (SPF; Kwee Huat TAN (SPF; Perry HE (SPF; Bernard SEAH (SPF; Peng Seng NG (SPF; Rashid ABU HASAN (SPF; SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX1161J)
Attachments: QX1161J photo.pdf; QX 1161J.xls

Dear Wei Yea,

Please refer to the attachment of QX 1161J.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Monday, 11 March 2019 3:45 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAUTO)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX1161J)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- **QX1161J**

In attached, please find the recommended Parts and Labour required for the repair of this vehicle.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	SUV	UNIT:	PCG LOYANG BASE
VEH NO:	QX1161J	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL:	CHEVROLET CAPTIVA	ODOMETER:	107501		

Reference No. 1161/SPF/4W/19/03/04

iLMS No. 1100019965

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Rear Bumper / BUC	\$550.00	1			
1.2	Rear Bumper Retainer / CRA	\$35.00	1			
1.3	Rear LH Upper Bumper / XAH	\$220.00	1			
1.4	Rear RH Upper Bumper / DEF	\$220.00	1			
1.5	Rear Lower Bumper / DEF	\$380.00	1			
1.6	Rear End Panel / BUC	\$350.00	1			
1.7	Rear RH Tow-Eye Cover / DEF	\$38.00	1			
1.8	RHS Exhaust Muffler / BUC	\$3,000.00	1			
1.9	Rear Door / BUC	\$4,300.00	1			
1.10	Rear Door Trim / CRA	\$950.00	1			
1.11	Model Emblem / nrc	\$65.00	1			
1.12	Rear Windscreen / CRA	\$850.00	1			
1.13	Rear Windscreen Moulding / nrc	\$215.00	1			
1.14	Rear Windscreen Solar Film / nrc	\$180.00	1			
1.15	RHS Tail Lamp / CRA	\$1,250.00	1			
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:		Items 1.7, 1.8, 1.9, 1.10 & 1.13 requires Overseas Indentment. ETA: 8-10 weeks			Parts Total:	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Rear Bumper:		16	
	Remove & Replace Rear LH & RH Upper Bumper			
	Remove & Re-Install Reverse Camera & Reverse Sensor to facilitate repair works			
	Remove & Replace Rear Bumper			
	Remove & Replace Rear Lower Bumper			
	Remove & Replace Rear RH Tow-Eye Cover			
	Putty & Spray Paint for Rear LH & RH Upper Bumper (2 colours)			
	Putty & Spray Paint for Rear Bumper			
1.2	Rear End Panel & RHS Exhaust Muffler Tip:		8	
	Remove & Replace Rear End Panel			
	Remove & Replace RHS Exhaust Muffler Tip			
1.3	Rear Door:		6	
	Remove & Replace Rear Door			
	Remove & Replace Rear Door Trim			
	Remove & Replace Model Emblem			
	Putty & Spray Paint for Rear Door			
1.4	Rear Windscreen:		6	
	Remove Rear Windscreen Shattered Glass			
	Replace Rear Windscreen			
	Remove & Replace Rear Windscreen Moulding			
	Replace Rear Windscreen Solar Film			
	Water Seepage Test for Rear Windscreen			
1.5	RHS Tail Lamp:		1	
	Remove & Replace RHS Tail Lamp			
	Wiring for RHS Tail Lamp			
	SUB-TOTAL		30	
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
	SUB-TOTAL		2	238.00
	Labour Total:			
	GRAND TOTAL :			
	<i>Total sum billed under SOR only :</i>			
	<i>Total sum billed under CVR only :</i>			
Contractor shall complete the entire repair within <u>65</u> working days upon approval date . (Include parts awaiting time)				

Registration No. QX1161J

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Rear Bumper	1	Buckled	\$550.00	\$550.00	
1.2	Rear Bumper Retainer	1	Cracked	\$35.00	\$35.00	
1.3	Rear LH Upper Bumper	1	Not Necessary	\$220.00		
1.4	Rear RH Upper Bumper	1	Deformed	\$220.00	\$220.00	
1.5	Rear lower Bumper	1	Deformed	\$380.00	\$380.00	
1.6	Rear End Panel	1	Buckled	\$350.00	\$350.00	
1.7	Rear RH Tow- Eye Cover	1	Deformed	\$38.00	\$38.00	
1.8	RHS Exhaust Muffler	1	Buckled	\$3,000.00	\$3,000.00	
1.9	Rear Door	1	Buckled	\$4,300.00	\$4,300.00	
1.10	Rear Door Trim	1	Cracked	\$950.00	\$950.00	
1.11	Model Emblem	1	Necessary	\$65.00	\$65.00	
1.12	Rear Windscreen	1	Cracked	\$850.00	\$850.00	
1.13	Rear Windscreen Moulding	1	Necessary	\$215.00	\$215.00	
1.14	Rear Windscreen Solar Film	1	Necessary	\$180.00	\$180.00	
1.15	RHS Tail Lamp	1	Cracked	\$1,250.00	\$1,250.00	
1	LABOUR					

[illegible]

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19004458/Jtd3e2		
ACCIDENT CLAIM SECTION(SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 24-04-2019		
ATTN : WEI YEA LIM		Code : SPF		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 1161J	
Policy No.	Coverage (\$)		0.00	
Claim No. HOMSPFETQ16000399	Excess (\$)		0.00	
Assign From WEI YEA LIM	Assign Date		11/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET CAPTIVA	c.c	2384	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KL1CD26UJGB515911	Colour	DARK BLUE	
Odometer	107502	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R17	CROSSWIND	6 mm	
L/H Front Tyre	235/60 R17	CROSSWIND	6 mm	
R/H Rear Tyre	235/60 R17	CROSSWIND	6 mm	
L/H Rear Tyre	235/60 R17	CROSSWIND	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	Inspection Date		13/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				



Registration No. QX1161J

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Rear Bumper	1	Buckled	\$550.00	\$550.00	
1.2	Rear Bumper Retainer	1	Cracked	\$35.00	\$35.00	
1.3	Rear LH Upper Bumper	1	Not Necessary	\$220.00		
1.4	Rear RH Upper Bumper	1	Deformed	\$220.00	\$220.00	
1.5	Rear lower Bumper	1	Deformed	\$380.00	\$380.00	
1.6	Rear End Panel	1	Buckled	\$350.00	\$350.00	
1.7	Rear RH Tow- Eye Cover	1	Deformed	\$38.00	\$38.00	
1.8	RHS Exhaust Muffler	1	Buckled	\$3,000.00	\$3,000.00	
1.9	Rear Door	1	Buckled	\$4,300.00	\$4,300.00	
1.10	Rear Door Trim	1	Cracked	\$950.00	\$950.00	
1.11	Model Emblem	1	Necessary	\$65.00	\$65.00	
1.12	Rear Windscreen	1	Cracked	\$850.00	\$850.00	
1.13	Rear Windscreen Moulding	1	Necessary	\$215.00	\$215.00	
1.14	Rear Windscreen Solar Film	1	Necessary	\$180.00	\$180.00	
1.15	RHS Tail Lamp	1	Cracked	\$1,250.00	\$1,250.00	
1	LABOUR					
1.1	Rear Bumper:					6
	Remove & Replace Rear LH & RH Upper Bumper					
	Remove & Re-install Reverse Camera & Reverse Sensor to facilitate to repair works					
	Remove & Replace Rear Rear Bumper					
	Remove & Replace Rear lower Bumper					
	Remove & Replace Rear RH Tow-Eye Cover					

	Putty & Spray Paint for Rear LH & RH Upper Bumper(2colours)					
	Putty & Spray Paint for Rear Bumper					
1.2	Rear End Panel & RHS Exhaust Muffler Tip:					8
	Remove & Replace Rear End Panel					
	Remove & Replace RHS Exhaust Muffler Tip					
1.3	Rear Door:					6
	Remove & Replace Rear Door					
	Remove & Replace Rear Door Trim					
	Remove & Replace Model Emblem					
	Putty & wspray Paint for Rear Door					
1.4	Rear Windscreen:					6
	Remove rear Windscreen Shattered Glass					
	Replace Rear Windscreen					
	Remove & Replace Rear Windscreen Moulding					
	Replace Rear Windscreen Solar Flim					
	Water Seepage Test for Rear Windscreen					
1.5	RHS Tail Lamp:					1
	Remove & Replace RHS Tail Lamp					
	Wiring for rhs Tail Lamp					
COSTING		TOTAL PARTS COST			\$12,383.00	
		TOTAL MAN-HOUR				27

Registration No. QX1161J

Vehicle Inspected By

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.