

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

Not Authorised
1/1/19 & 2/1/19
Recovery After Paint

ESTIMATE

Date: 11/3/2019
DOA: 9/3/2019

Vehicle No: SJG2082U

Make & Model: Honda Fit 1.3 A

7 days

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Right Tail Lamp	\$ 455.70	X
2	1	Rear Right Tail Lamp Retainer	\$ 41.20	X
3	1	Rear Bumper	\$ 614.70	X
4	1	Rear R/H Bumper Retainer	\$ 50.00	X
5	1	Rear R/H Bumper Bracket	\$ 51.40	X
6	1	Rear Right Fender	\$ 812.80	X
7	1	Rear Right Fender Wheel House	\$ 306.60	X
8	1	Rear Right Fender Inner Garnish	\$ 354.40	X
9	1	Rear Right Fender Quarter Glass	\$ 126.10	X
10	1	Rear Right Fender MudFlap	\$ 130.20	X
11	1	Rear Right Door	\$ 937.70	X
12	1	Rear Right Door Lock Mechanism	\$ 163.30	X
13	1	Rear Right Door Lock Catch	\$ 67.50	X
14	1	Rear Right Door Hinges	\$ 41.90	X
15	1	Rear Right Door Weatherstrip	\$ 144.30	X
16	1	Rear Right Door Inner Trim Board	\$ 467.50	X
17	1	Rear Right Door Window Glass Moulding	\$ 164.50	X
18	1	Rear R/H Air Duct Ventilator	\$ 71.10	X
19	1	Rear Axle Beam	\$ 1,284.00	X
20	1	Rear R/H Wheel Hub	\$ 214.00	X
21	1	Rear R/H Bearing	\$ 158.10	X
22	1	Rear R/H Shock Absorber	\$ 211.90	X
			\$ 6,868.90	
		Less 20%	\$ 1,373.78	
			\$ 5,495.12	
		<u>Special Nett Items</u>		
1		Sundries	\$ 50.00	X
2	1	Rear Right Tail Lamp Sealant	\$ 35.00	X
3	1 set	Rear Tail Lamp Clips	\$ 30.00	X
4	1 set	Rear Bumper Clips	\$ 50.00	X
5	1	Rear Right Fender Sealant	\$ 80.00	X
6	1 set	Rear Right Fender Inner Garnish Clips	\$ 30.00	X
7	1	Rear End Panel Sealant	\$ 80.00	X
8	2	Rear Bumper Reverse Sensor	\$ 250.00	X
9	1	Rear R/H Tyre	\$ 400.00	X
10	1	Rear R/H Rim	\$ 300.00	X

			\$ 1,305.00	
		Total parts	\$ 6,800.12	
S/N	Labour Description	Amount	Amount	
1	Labour for panel beating, cut, weld, straighten rear fender and replace rear damaged parts.	\$ 1,800.00	9001	
2	To putty and spray painting rear portion.	\$ 1,400.00	7201	
3	To check rear lighting and wiring.	\$ 60.00	201	
4	To remove and install, inner garnish and trim to facilitate the repair.	\$ 350.00	1001	
5	To apply anti rust proofing to rear affected area.	\$ 250.00	601	
6	To remove and install rear reverse sensor.	\$ 150.00	501	
7	To perform 4 wheel alignment and balancing.	\$ 150.00	602	
8	To remove and install quarter glass.	\$ 180.00	501	
9	To remove front & rear undercarriage to facilitate repairs	\$ 380.00	?	
10	To remove & refit rear fender component to replace rear fender, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	201	
	Total labour :	\$ 4,840.00		
	Total parts :	\$ 6,800.12		
	Total labour :	\$ 4,840.00		
	Total repair cost : (Before GST)	\$ 11,640.12		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: