



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003251
INV Date 17/04/2020
Reference CC3/CTI19004469/Kea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5934G
Insured Veh. YL 6807R
Claim No. SNM19D201754C02
Policy No. DMCVSN3049301800
Accident Date 07/03/2019
Inspection Date 11/03/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19004469/Kea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 6807R	Veh. Inspected	SHD 5934G
Policy No.	DMCVSN3049301800	Coverage (\$)	0.00
Claim No.	SNM19D201754C02	Excess (\$)	0.00
Assign From		Assign Date	11/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU503079209	Colour	M.P. WHITE / RED
Odometer	12565	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	9 mm
L/H Front Tyre	195/65 R15	GOODYEAR	9 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	9 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/03/2019	Inspection Date	11/03/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5934G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	499.90	499.90
1	BRACKET,FRONT BUMPER EXTENSION MOUNTING	SERVICEABLE	101.20	-
1	REINFORCEMENT,FRONT BUMPER	TO REPAIR SEE LABOUR	696.40	-
1	ABSORBER,FRONT BUMPER,LOWER	SERVICEABLE	130.20	-
1	ABSORBER,FRONT BUMPER ENERGY	SERVICEABLE	78.10	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	78.00	78.00
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	78.00	-
1	FRONT BUMPER SUPPORT	SERVICEABLE	81.70	-
1	EXTENSION,FRONT BUMPER,RH	SERVICEABLE	117.80	-
1	EXTENSION,FRONT BUMPER,LH	SERVICEABLE	117.80	-
1	FRONT LED LAMP (LOWER) RH	CRACKED	907.75	907.75
1	FRONT LED LAMP (LOWER) LH	SERVICEABLE	907.75	-
1	FRONT HEADLAMP RH	CUT	2,909.04	2,909.04
1	COMPUTER SUB-ASSY,HEADLAMP,RH NO 1	SERVICEABLE	492.30	-
1	MOTOR,HEADLAMP LEVELING,RH	SERVICEABLE	413.10	-
1	FRONT HEADLAMP LH	SERVICEABLE	2,909.04	-
1	COMPUTER SUB-ASSY,HEADLAMP,RH NO 1	SERVICEABLE	492.30	-
1	MOTOR,HEADLAMP LEVELING,RH	SERVICEABLE	413.10	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	945.30	-
1	EXTENSION,FRONT FENDER,RH	SERVICEABLE	48.80	-
1	COVER SUB-ASSY,FRONT PILLAR,UPR RH	SERVICEABLE	98.30	-
1	LINER,FRONT FENDER,RH	SERVICEABLE	200.70	-
1	FRONT FENDER EMBLEM RH	NOT NECESSARY	86.50	-
1	SEAL,FENDER APRON MUDGUARD,RH	SERVICEABLE	50.90	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	950.50	-
1	FRONT LOWER ARM	SERVICEABLE	631.90	-
1	FRONT SHOCK ABSORBER	SERVICEABLE	398.20	-
1	SHAFT ASSY,FRONT DRIVE,RH	TO REPAIR SEE LABOUR	1,186.20	-

Report Ref No. CC3/CTI19004469/Kea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ARM SUB-ASSY,FRONT SUSPENSION LOWER NO,1 RH	SERVICEABLE	637.50	-
1	KNUCKLE,STEERING,RH	SERVICEABLE	562.30	-
1	LINK ASSY,FRONT STABILIZER,RH	SERVICEABLE	199.00	-
1	BAR,STABILIZER,FRONT	SERVICEABLE	360.30	-
1	SUPPORT SUB-ASSY,FRONT SUSPENSION,RH	SERVICEABLE	200.60	-
1	ABSORBER ASSY,SHOCK,FRONT RH	SERVICEABLE	401.80	-
1	COCK ASSY,RESERVE TANK	SERVICEABLE	117.80	-
	LESS 25% DISCOUNT		-4,625.02	-1,098.67
			13,875.06	3,296.02
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL RIM (SN)	SERVICEABLE	1,570.55	-
1	FRONT WHEEL RIM COVER (SN)	SERVICEABLE	175.80	-
1	CLIP,FRONT FENDER LINER (SN)	NOT NECESSARY	22.00	-
			1,768.35	-
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	440.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT,FRONT BUMPER,FRONT FENDER RH,FRONT BONNET AND SHAFT ASSY,FRONT DRIVE,RH.		4,200.00	300.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-

Report Ref No. CC3/CTI19004469/Kea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS.	NOT NECESSARY	380.00	-
			10,400.00	740.00
GRAND TOTAL			26,043.41	4,036.02

RECOMMENDED COST OF REPAIRS				4,036.02
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/CT119004469/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.