

03/20/2019

ASSIGNMENT

REF: CS/FCI 19004474/bgd3 ⁿ² Speed of Instruction

Assigned By:

Bryan

ASSIGNMENT (Office)

CWS

Karen Tan

FCI

Date/Time

3:33pm @ 26/3/19

Estimated Cost

Bill to

OD (TP) / WS / TP / RES / OD / RES / EVA / INV / MY / CS

To Inspect Vehicle No

SHC 7136K

Insured

SHC 2136T

at Workshop info

Chunni Motor

Tel

6542 5119

of

Blk 10 mmk Ind - Park 2A #03-19

Policy No

Claim No

D19002007MPF14

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A. 21/3/2019

CA / REV / REP. / REV 24 HRS

1up

26/3/19

H.O.D. Endorsement

Date/Time

3:56pm @ 28/3/19

Person Contacted

Lynn

Vehicle

IN / OUT

Date/Time

Action/Instruction (C) Estimate

SHC 7136K - CS3/FCI 18022 687/Gcbg2

D.O.A. 14/12/18

SHC 2136T - CS3/LCP 17016643/Kwbb3q2

D.O.A. 23/8/17

214@3:09pm - Revised preli advise via email

REF

SALARY

COB NOV 2023

From

To

Estimated Cost

OD / TP / WS / TP / RS / DO / RES / EVA / HV / MV

Country / Vehicle No

at Workshop

of

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐	☐
N/S	O/S	

Est. or Market Value

IDAC Accident Report Consistent? Yes or No

GIA / PR Score Consistent? Yes or No

Est. Repairs: 9 X days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Vehicle

SHC 7136 K

2015 Nov

Type: M Car / B Cycle / Bus / Van / Lorry / ☒ (Truck / Prime Mover)

Truck / Trailer or

Make: Hyundai I40

or 1685

Colour

Yellow

A/C Insured / Std / NI / NA

Sp. Roading

569154

T/Rollo Insured / Std / NI / NA

Eng/No

D4FDFU565012

Ch/No

KMHLB41UMGU080730

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inter / Jammed / Leaked / Burnt orBrake: ☒ Inter / Jammed / Leaked / Burnt orMod: ☒ S/Rim / STD A/Rim or

Tyre Size

F:

205/60 R16

R:

— " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Davanti

Front

Rear

R/Bal

S'

mm

R/Bal

S'

mm

L/Bal

S'

mm

L/Bal

S'

mm

D.O.A.

21/03/2019

D.O.I.

26/03/2019

Survey held at

Chunni AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHC 21361

18/14/19 provided 2/3 11,000/- with 9 days of work
(Red to 10078.24, 48%)

RECEIVED 23 APR 2019

Date/Time, File Path to?

☐

Prel. Report

1) 23/4 11,000/-

☐

Final Report

Date/Time, File Path to?

2)

Report Format

Lump Sum / 11,000/-

7P
11,000

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Weekend \$

Survey Fee:

Transportation

S + PS \$

Phone

Other

Total

24/4/19

11x15 = 165

170 + 165
50
50 + 50
168

653



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002007MFSH

Date: 2/4/2019

Our Ref: CS/FCI19004474/Dqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 7136K

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/3/2019 at the premises of M/s Chun Ni Motor have the following to report: -

Workshop Estimate Amount	: S\$ 21,078.24
Revised Estimate Amount	: S\$ 14,357.84
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-03-2019	Our Ref No. D19002007MFSH
Accident Date	21-03-2019	Claim Type. Third Party
Insured Vehicle	SHC2136T	Third Party Vehicle. SHC7136K
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 2 April 2019 3:09 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002007MFSH/1
Attachments: PRELI ADVISED SHC 7136K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 7136K**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 26 March 2019 8:01 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002007MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 25 March 2019 3:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002007MFSH/1

Dear Sir/Mdm,

10 Surveys by LKK

REPAIR ESTIMATE*

VEHICLE NO : SHC 7136K

DATE : 22.03.2019

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

[illegible]

SHC 7136K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 600/-
	Spray Painting Charge			\$ 1,000.00 500/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 30/-
	Towing Charge			\$ 50.00 20/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Dashboard			\$ 450.00 180/-
	Remove/Refix Fuse Box		1860.00	\$ 180.00 750/-
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 } 180/-
	TOTAL LABOUR			\$ 4,630.00
	ESTIMATE TOTAL			\$ 21,078.24
	26/03/2019 @ 1200hrs		14357.84	
	NA Antenna		1/511,000/-	
	2/Sum			
	2/ryan 9 days.			
	2KK Auto			
				
				
	<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHC 7136 K
Technician:
Mileage: 569154
Time Printed 26.3.19 12:39 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°33'		-3°00' 3°00'
4°13'		-0°19' 5°41'
2°41'		-1°30' 1°30'
15°54'		
15°21'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°49'		-3°00' 3°00'
4°04'		-0°19' 5°41'
-0°03'		-1°30' 1°30'
15°06'		
14°16'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°17'		-3°00' 3°00'
0°09'		-3°00' 3°00'
0°48'		-3°00' 3°00'
2°39'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°03'		-3°30' 2°30'
-0°01'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-2°12'		-3°30' 2°30'
-0°02'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°09'		-3°00' 3°00'
-0°03'		-3°00' 3°00'
0°01'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19004474/Dqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-04-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2136T	Veh. Inspected	SHC 7136K
Policy No.		Coverage (\$)	0.00
Claim No.	D19002007MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	26/03/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU080730	Colour	YELLOW
Odometer	569154	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	DAVANTI	5 mm
L/H Front Tyre	205/60 R16	DAVANTI	5 mm
R/H Rear Tyre	205/60 R16	DAVANTI	5 mm
L/H Rear Tyre	205/60 R16	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/03/2019	Inspection Date	26/03/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7136K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	DISTORTED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET (LH)	SERVICEABLE	24.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	MOUNTING BROKEN	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	DEFORMED	174.90	174.90
1	AIR CLEANER BOTTOM ASSY	NOT NECESSARY	325.00	-
1	FRONT DOOR MIRROR ASSY (LH)	CRACKED	670.00	670.00
1	FRONT WHEEL RIM (LH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	CUT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	540.50	540.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DAMAGED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	1,191.30	1,191.30
1	STG TIE END	DISTORTED	62.60	62.60
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
1	ABS SENSOR (LH)	NOT NECESSARY	234.00	-
1	WIRING-ENGINE	HOUSING BROKEN	3,326.00	3,326.00
1	ELECTRIC POWER STEERING	NOT NECESSARY	3,641.00	-
	LESS 20% DISCOUNT		-4,033.06	-3,099.46
			16,132.24	12,397.84
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE (LH)(SN)	SERVICEABLE	216.00	-
			316.00	100.00
	LABOUR			
	PANEL BEATING.		1,500.00	600.00
	SPRAY PAINTING CHARGE.		1,000.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE/REFIX DASHBOARD.		450.00	180.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET FRT ABS SYSTEM. }		200.00	-
	RE-SET FRT POWER WINDOW SYSTEM. }		200.00	-
			4,630.00	1,860.00
GRAND TOTAL			21,078.24	14,357.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/FCI19004474/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.