

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 26 Mar 2019)
Parts: 144 **MERCEDES-BENZ A200 1.6 W176 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: (Unsubmitted, no print-code for SKK7988R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F HEADLAMP CONTROL UNIT <i>Burn</i>	0.00	0.00	400.00 F <i>42</i>
Total Parts (S\$)						400.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Emile af
26/3/19

SUPP 870.00
 PARTS 1725.00
 SN 35.00
 LAB. 520.00

 3150

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK ALL FAULT CODE, REPROGRAM, INITIALISATION HEADLAMP MODULE LH - ATTACHED INVOICE	New	450 ✓
Gross Labour Cost (S\$)			0.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Two Qrf
03/4/19.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2019)
 Parts: 144 MERCEDES-BENZ A200 1.6 W176 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Car Care Pte Ltd/SKK7988R/12/03/2019 13:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

80 6916

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER X	0.00	0.00	390.00F
2	1	NA	*FRONT BUMPER SIDE HOLDER - LH / RH X	0.00	0.00	510.00F
3	10	NA	*FRONT BUMPER CLIPS X	0.00	0.00	25.00F
4	6	NA	*FRONT BUMPER SENSOR X	0.00	0.00	370.00F
5	1	NA	*FRONT BUMPER FOAM X	0.00	0.00	63.00F
6	1	NA	*FRONT BUMPER GRILLE - LOWER X NAI	0.00	0.00	63.00F
7	1	NA	*FRONT BUMPER NUMBER PLATE GARNISH X BR	0.00	0.00	1.00F
8	1	NA	*FRONT BUMPER LOGO X BR	0.00	0.00	32.00F
9	1	NA	*FRONT GRILLE OUTER CHROME - TOP / LOWER / INNER BASE X CAT	0.00	0.00	355.00F
10	1	NA	*FRONT GRILLE LOGO WITH LOGO BASE X BR	0.00	0.00	270.00F
11	1	NA	*FRONT HEADLAMP - LH X	0.00	0.00	1,100.00F
12	1	NA	*FRONT HEADLAMP - RH X	0.00	0.00	1,100.00F
13	1	NA	*CONDENSER X NN	0.00	0.00	100.00F

F=Franchise part

Total Parts (S\$)

5,274.00

1725

Progressive Car Care Pte Ltd/SKK7988R/12/03/2019 13:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

SE
 5/10K (CLKK) ~~W~~ ~~for~~
 8322 8813 00 - Rent Extra - \$600

RL before print
 20/3/19 12.30pm

Guo Qiang
 26/7/19

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	35.00 ✓
2	1	RADIATOR COOLANT	20.00 ✓
Sub Total (S\$)			55.00 35

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	200 ✓ 450.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS	New	200 ✓ 600.00
3	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00 ✓
4	TO CHECK WIRING	New	20.00 ✓
5	TO RESET ECU WITH DIAGNOSTIC FAULT	New	100 ✓ 150.00
Gross Labour Cost (S\$)			1,320.00 520

Progressive Car Care Pte Ltd/SKK7988R/12/03/2019 13:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-OLIER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs