

ASS. REC. BY: GQ REF: CC/FCI 19004500 / Etcd302 Special Instruction:

From (Person): Eileen Lee of FCI Date/Time: 2:36pm 12/3/19

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  WS / TP RES / OD RES / EYA / INV / MV / CS

To Inspect Vehicle No: SJS 1914M Insured: SHC 8108K

at Workshop m/s: progressive car Tel: 67415336

of Blk 3022A ubi rd 1 # 01-45

Policy No: \_\_\_\_\_ Claim No: D19000840MFS#

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh. (Client's Record): \_\_\_\_\_ D.O.A. 27/01/2019

CA / REV / REP. / REV 24 HRS 109 14/3/19 01:30am

Date/Time: 3:33pm 12/3/19 Person Contacted: SOO Vehicle IN /  OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 1914 M - X
12/3/19	SHC 8108K - NS/ENC 17024546 / K1 vbn 2 DOA - 23/12/2017 Pensed via email. press advise.
3/6-	Not yet sent in for repair.

reopen.  
 Submit final figure \$4401- (Red: 1301.13; 74%), 2 days.  
~~Close~~ 12/19.

file pass to Elaine

12/11/19 1st DOZ 11/6/19, reopen ref only ↓ 12/11/19

SINZYUIC

602

REF: FCI

ASSIGNMENT

(-2019)

From: \_\_\_\_\_ Date: 14/3/19

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJS1914M

at Workshop m/s: Progressive

of: Blk 3022A Ubi Rd 1 #01-15/46

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_


(Client's Record)

Make of Veh: 11:30am

see 4 GO

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$15K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJS1914M Yr Regn: 31 Jul 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota wish c.c 1797

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 185548 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 26E200005619

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/65 R15

R: N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. _____	D.O.I. 14-03-19
Survey held at: w/s	11:30
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or	

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Submit preli report.

RECEIVED 4 JUN 2019

Date/Time, File Pass to?  : Preli. Report

1) 21/6 Typist,  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

Survey Fee: 100

Transportation: 90

S + RS, SI \_\_\_\_\_

Photos: 42

Others \_\_\_\_\_

TOTAL: 192

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road | #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg  
 GST:201006949C RCB NO:201006949C

M/S : DAVID LAI  
 70 TREVOSE CRESCENT #04-06  
 SINGAPORE 298071

Estimate No: EST1504654  
 Date: 09 Mar 2019  
 Policy No: MT/00399776  
 Veh Reg No: SJS1914M  
 Make/Model: TOYOTA WISH 1.8X A  
 Chassis No: ZGE200005619  
 Engine No: 2ZR0422440  
 Reg. Date: 31/07/2009

ATTN: FIRST CAPITAL  
 Your Ref No: TP 0319-5435  
 Claim Type: Third Party  
 Accident Date: 27/04/2019  
 TP Veh Reg No: SHC 8108 K

### Estimate Repair Cost to Vehicle No :SJS1914M

Description	U/Price	Quantity	Price SS	Amount SS
<b>List Price</b>				
1 REAR BUMPER <i>X</i>	426.10	1 PC	<del>426.10</del>	
2 REAR BUMPER SIDE HOLDER - L/L, R/R <i>X</i>	66.10	2 PCS	<del>132.20</del>	
3 REAR BUMPER BRACKET - L/L, R/R <i>X</i>	67.30	2 PC	<del>134.60</del>	
4 REAR BUMPER CLIPS <i>X</i>	5.89	10 PC	<del>58.90</del>	
5 REAR BUMPER REFLECTOR - RH <i>X</i>	49.70	1 PC	<del>49.70</del>	
		Less 25%	200.38	601.13
<b>Special Net</b>				
6 REAR BUMPER SENSOR <i>X</i>	220.00	1 SET	<del>220.00</del>	220.00
<b>Labour</b>				
7 TO REMOVE, REALIGN, REPAIR, CUT/WELD, KNOCK OUT DENTS & REPLACE ACCIDENT PARTS	400.00	1 JOB	400.00	200 ✓
8 TO RESPRAY PAINT ON ACCIDENT PORTIONS	400.00	1 JOB	400.00	200 ✓
9 TO REMOVE, REPLACE REAR BUMPER SENSOR	120.00	1 JOB	120.00	40 ✓
			920.00	920.00
		Total		SS 1,741.13
		Add GST @ 7%		121.88
		Total Amount Payable		SS 1,863.01

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED SIXTY THREE AND CENTS ONE ONLY

*PART*  
 1 up to 5mm repair.  
 2 Days.  
 After repair photos.  
 Gino Qiang - 8288 0282  
 14/3/19.

For Progressive Car Care Pte Ltd

*[Signature]*  
 AUTHORIZED SIGNATURE  
 Total = 440.  
 Totalized \$440 with Ray.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19004500/Gtd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-06-2019	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SHC 8108K	<b>Veh. Inspected</b>	SJS 1914M
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D19000846MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	EILEEN LEE	<b>Assign Date</b>	12/03/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	TOYOTA WISH	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	ZGE200005619	<b>Colour</b>	SILVER
<b>Odometer</b>	185548	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	27/01/2019	<b>Inspection Date</b>	14/03/2019
<b>Survey held at</b>	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>		<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 1914M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	NOT NECESSARY	426.10	-
2	REAR BUMPER SIDE HOLDER-LH & RH @\$66.10	NOT NECESSARY	132.20	-
2	REAR BUMPER BRACKET-LH & RH @\$67.30	NOT NECESSARY	134.60	-
10	REAR BUMPER CLIPS @\$5.89	NOT NECESSARY	58.90	-
1	REAR BUMPER REFLECTOR-RH	NOT NECESSARY	49.70	-
	LESS 25% DISCOUNT		-200.38	-
			601.12	-
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER SENSOR (SN)	NOT NECESSARY	220.00	-
			220.00	-
<b>LABOUR</b>				
	TO REMOVE, REALIGN, REPAIR, CUT / WELD, KNOCK OUT DENTS & REPLACE ACCIDENT PARTS.		400.00	200.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		400.00	200.00
	TO REMOVE,REPLACE REAR BUMPER SENSOR.		120.00	40.00
			920.00	440.00
<b>GRAND TOTAL</b>			<b>1,741.12</b>	<b>440.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>440.00</b>

Report Ref No. CS/FC19004500/Gtd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.