Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19004555/KPS3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: M496321

Claimant SHD9857U Insured Vehicle No: SLJ5375R

Vehicle No: Shidasa Vehicle No: Stidasa Vehicl

Date of Loss: 11/03/2019 Nature of Claim: TP Claim No: MC20192087

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9857U

 Make & Model:
 RENAULT LATITUDE, 2.0 D dCi (A)
 Engine No:
 M9R8839C000986

 Reg. Date:
 09/05/2014 (Man. Year: 2013)
 Chassis No:
 VF1ABL15AUC277315

Colour: Metallic White/Red Odometer: 519955 km

Engine Capacity:
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

1995 сс

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Giti 6 mm Rear Left Side: Giti 8 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

12,091.98 0.00	5,707.21 0.00	6,384.77	52.80
	0.00		
	0.00	0.00	
7,410.00	1,050.00	6,360.00	85.83
0.00	0.00	0.00	
0.00	0.00	0.00	
19,501.98	6,757.21	12,744.77	65.35
	5,400.00		
19,501.98	5,400.00	14,101.98	72.31
1,365.14	378.00	987.14	72.31
20,867.12	5,778.00	15,089.12	72.31
+ Car Rental (4.0 x S\$96.99/day) (S\$) + Doc/Search Fee (S\$)			
ett Liability (S\$)	6,173.41		
	0.00 19,501.98 19,501.98 1,365.14 20,867.12 96.99/day) (S\$)	0.00 0.00 0.00 0.00 19,501.98 6,757.21 5,400.00 19,501.98 5,400.00 1,365.14 378.00 20,867.12 5,778.00 696.99/day) (S\$) 387.96 6earch Fee (S\$) 7.45	0.00 0.00 0.00 0.00 0.00 0.00 19,501.98 6,757.21 12,744.77 5,400.00 14,101.98 1,365.14 378.00 987.14 20,867.12 5,778.00 15,089.12 396.99/day) (\$\$) 387.96 Gearch Fee (\$\$) 7.45

INSPECTION

Date of Assignment: 13/03/2019

Date Inspected: 13/03/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jun 2019)

Parts: 143 RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD9857U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*-FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Cracked	404.56 FL	*404.56 FL
15	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
16	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL
17	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*-FL
18	1		*TAILLAMP LH	Serviceable	552.55 FL	*-FL
19	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
20	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
21	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
22	1		*SET REAR BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
23	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
24	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
25	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	
26	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
27	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
28	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
29	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*-FS
30	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
31	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
32	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
33	1		*REAR BOOT ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*-FS
34	1		*REAR BUMPER ADVERTISEMENT STICKER	Not Necessary	200.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (S\$)
 13,241.66
 6,323.01

 - List Item Discount on L Items 10.00/10.00% (S\$)
 1,149.68
 615.80

Total Parts (S\$) 12,091.98 5,707.21

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	500.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
	Gross Labou	r Cost (S\$)	7,410.00	1,050.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.