

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park S4, Singapore 757722
FAX Number : 63655552
Estimator Telephone Number : 68652523
Accident Reporting Number : 68652572

Date Generated : 26/04/2019

User ID : PehSuan

53630470 90	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Check	X
75536470 20	MOULDING LH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
75535470 20	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
55708472 30	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$666.90	0.00	\$0.00	Replace	Check	X
90467092 42	WIPER GARNISH LOUVER SUB-ASSY, CLIP	0.00	\$3.20	0.00	\$0.00	Replace	Check	X
55754470 70	WIPER GARNISH SHIELD, COWL WATER, LH	0.00	\$18.90	0.00	\$0.00	Replace	Check	X
55753470 90	WIPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Check	X
60118470 20	COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Check	X
88790281 00	THERMISTOR ASSY	0.00	\$68.00	0.00	\$0.00	Replace	Check	X
53289470 72	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check	X
53205479 00	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Check	X
53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X
53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
53202479 01	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
53217470 30	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	X
81145476 91	UNIT, HEADLAMP, RH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
81056476 90	COMPUTER SUBASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
86510470 50	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
86520470 30	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
88460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check	X
88710471 60	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
88703470 80	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
16592370 20	GUIDE, RADIATOR AIR,	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
16594370 10	GUIDE, RADIATOR AIR, UPPER	0.00	\$44.70	0.00	\$0.00	Replace	Check	X
16595370 50	GUIDE, RADIATOR AIR, LH	0.00	\$58.80	0.00	\$0.00	Replace	Check	X
16593370 40	GUIDE, RADIATOR AIR, RH	0.00	\$54.80	0.00	\$0.00	Replace	Check	X
16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X
90480400 21	GROMMET (FOR RADIATOR LOWER	0.00	\$12.70	0.00	\$0.00	Replace	Check	X
16523370 10	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$9.80	0.00	\$0.00	Replace	Check	X
16361370 60	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X
16361370 70	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X
16711371 60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X
16363370 60	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check	X
16363361 60	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check	X
16571372 10	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check	X
16572372 10	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check	X
16261371 50	HOSE, WATER BYPASS, NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 69602623
Accident Reporting Number : 88662672

Date Generated : 26/04/2019

User ID : PohSuan

67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair	R
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	
68610470 40	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check	X
68720121 51	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Check	X
68740121 20	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Check	X
53801470 80	FENDER SUB-ASSY, FR, RH	0.00	\$933.10	0.00	\$0.00	Replace	Check	X
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Check	X
57102470 90	MEMBER SUB-ASSY, FR LH	1.00	\$1,959.50	100.00	\$0.00	Replace	Repair	R
Total			\$41,073.50		\$6,775.41			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		28800371 30	BATTERY	1.00	\$1,584.90	10.00	\$1,426.41	Replace	Replace
		52811471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
		53214470 50	SUPPORT, RADIATOR UPPER LH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
		53028470 10	SUPPORT SUB-ASSY LOWER	1.00	\$397.40	25.00	\$298.05	Replace	Replace
		53203479 01	SUPPORT S/A LH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		88460103 20	AIR CON CONDENSER ASSY	1.00	\$1,317.70	25.00	\$988.28	Replace	Replace
		53213470 50	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
		51420470 30	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	Replace
		53205479 00	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.68	Replace	Replace
		53202479 01	SUPPORT S/A RH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		17752371 21	INLET, AIR CLEANER, NO 2	1.00	\$93.90	25.00	\$70.43	Replace	Replace
			COOLANT	1.00	\$12.30	0.00	\$12.30	Replace	Replace
		52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace
		53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace
		16592370 20	GUIDE, RADIATOR AIR,	1.00	\$93.90	25.00	\$70.43	Replace	Replace
		55708472 30	WIPER GARNISH LOUVER SUB-ASSY	1.00	\$666.90	25.00	\$500.18	Replace	Replace
		74404470 30	CLAMP SUB-ASSY, BATTERY	1.00	\$41.40	25.00	\$31.05	Replace	Replace
		53341470 40	INSULATOR, HOOD	1.00	\$393.90	25.00	\$295.43	Replace	Replace
		16400373 10	RADIATOR ASSY	1.00	\$1,841.10	25.00	\$1,380.83	Replace	Replace
		53289470 72	COVER, RADIATOR	1.00	\$227.80	25.00	\$170.85	Replace	Replace
		17700373 30	AIR CLEANER ASSY	1.00	\$956.20	25.00	\$717.15	Replace	Replace
		16711371 60	FAN SHROUD RADIATOR	1.00	\$219.30	25.00	\$164.48	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$166.95	Replace	Replace
Total					10,377.40		8,068.93		

14,844.34
+ 1,100.00
+ 1,510.00
17,454.34

13 days

57,482.70

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 8 August 2019 5:08 PM
To: Md Noor, Norsiah
Subject: [MANDATE REQUEST] Your ref : 5666809460SG, ACCIDENT ON 08/03/2019 INVOLVING SJY 1661K (OI) & SHC 4973E (TP)

Your ref : **5666809460SG**

Our ref : CC3/AIG19004557/R1eb3

Dear Sirs,

ACCIDENT ON 08/03/2019 INVOLVING SJY 1661K (OI) & SHC 4973E (TP)

We refer to the above matter.

The said chain collision involved 4 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) maybe affected.

We seek your approval to offer repairer " **SMRT AUTOMOTIVE SERVICES PTE LTD**" at **\$ 20,637.57 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 57,782.70	\$ 17,454.34
2. Loss of Rental (19days x \$117.17)	\$ 2,226.23	\$ 2,226.23 (19days x \$117.17)
3. Loss of Income (19days x \$60)	\$ 1,140.00	\$ 950.00 (19days x \$50)
4. LTA Search Fee	\$ 7.00	\$ 7.00
Total	\$ 61,155.93	\$ 20,637.57

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

8/21/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SHC4973E (5666809460SG)**

[SJY1661K]

TP

SMRT TAXIS PTE LTD

Mar 8 2019 8:00AM

[CHENG JIANKAI, EUGENE]

SMRT Automotive Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/08/2019 11:20 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20637.57) - SHC4973E - Claim Handler: MdNoor, Norsiah

Approved:20637.57.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019 Edit Reg		08 Mar 2019 00:00 Edit Adj Rpt	S\$17,454.34 Edit Estimates	S\$17,454.34 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	CHENG JIANKAI, EUGENE , ID: 58708002A		
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC4973E	Date of Loss:	08/03/2019 08:00 - :59 [16 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5666809460SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SJY1661K	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (16/08/2019): Alert - Adj Mandate Approved (S\$20637.57) - SHC4973E - Claim Handler: MdNoor, No...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC4973E (5666809460SG)**
[SJY1661K]
TP
SMRT TAXIS PTE LTD
Mar 8 2019 8:00AM
[CHENG JIANKAI, EUGENE]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼					
Video															1 per page ▼			☒					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)																Thumbnail			Print		
1	31/05/19 10:50	Video - Other From:OD - Reg. No: SJY1661K, Claimant: CHENG JIANKAI, EUGENE																Load MP4					
Letters/Correspondences																		1 per page ▼			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)																Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown																Edit					
Photos/Images																		3 per page ▼			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)																Thumbnail			Print		
1	11/04/19 11:58	General View																Load JPG			☒		
2	11/04/19 11:58	General View																Load JPG			☒		
3	11/04/19 11:58	General View																Load JPG			☒		
4	11/04/19 11:58	General View																Load JPG			☒		
5	11/04/19 11:58	General View																Load JPG			☒		
6	11/04/19 11:58	General View																Load JPG			☒		
7	11/04/19 11:58	General View																Load JPG			☒		
8	11/04/19 11:58	General View																Load JPG			☒		
9	11/04/19 11:58	General View																Load JPG			☒		
10	11/04/19 11:58	General View																Load JPG			☒		
11	11/04/19 11:58	General View																Load JPG			☒		
12	11/04/19 11:58	General View																Load JPG			☒		
13	11/04/19 11:58	General View																Load JPG			☒		
14	11/04/19 11:58	General View																Load JPG			☒		
15	11/04/19 11:58	General View																Load JPG			☒		
16	11/04/19 11:58	General View																Load JPG			☒		
17	11/04/19 11:58	General View																Load JPG			☒		
18	11/04/19 11:58	General View																Load JPG			☒		
19	11/04/19 11:58	General View																Load JPG			☒		
20	11/04/19 11:58	General View																Load JPG			☒		
21	11/04/19 11:58	General View																Load JPG			☒		
22	11/04/19 11:58	General View																Load JPG			☒		
23	11/04/19 11:58	General View																Load JPG			☒		
24	11/04/19 11:58	General View																Load JPG			☒		
25	11/04/19 11:58	General View																Load JPG			☒		
26	11/04/19 11:58	General View																Load JPG			☒		
27	11/04/19 11:58	General View																Load JPG			☒		
28	11/04/19 11:58	Odometer Reading																Load JPG			☒		

Video				1 per page ▾	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
29	11/04/19 11:58	General View		Load JPG	✓
30	11/04/19 11:58	General View		Load JPG	✓
31	11/04/19 11:58	General View		Load JPG	✓
32	11/04/19 11:58	General View		Load JPG	✓
33	11/04/19 11:58	General View		Load JPG	✓
34	11/04/19 11:58	General View		Load JPG	✓
35	11/04/19 11:58	General View		Load JPG	✓
36	11/04/19 11:58	General View		Load JPG	✓
37	11/04/19 11:58	General View		Load JPG	✓
38	11/04/19 11:58	General View		Load JPG	✓
39	11/04/19 11:58	General View		Load JPG	✓
40	11/04/19 11:58	General View		Load JPG	✓
41	11/04/19 11:58	General View		Load JPG	✓
42	11/04/19 11:58	General View		Load JPG	✓
43	11/04/19 11:58	General View		Load JPG	✓
44	11/04/19 11:58	General View		Load JPG	✓
45	11/04/19 11:58	General View		Load JPG	✓
46	11/04/19 11:58	General View		Load JPG	✓
47	11/04/19 11:58	General View		Load JPG	✓
48	11/04/19 11:58	General View		Load JPG	✓
49	11/04/19 11:58	General View		Load JPG	✓
50	11/04/19 11:58	General View		Load JPG	✓
51	11/04/19 11:58	General View		Load JPG	✓
52	11/04/19 11:58	General View		Load JPG	✓
53	11/04/19 11:58	General View		Load JPG	✓
54	11/04/19 11:58	General View		Load JPG	✓
55	11/04/19 11:58	General View		Load JPG	✓
56	11/04/19 11:58	General View		Load JPG	✓
57	11/04/19 11:58	General View		Load JPG	✓
58	11/04/19 11:59	General View		Load JPG	✓
59	11/04/19 11:59	General View		Load JPG	✓
60	11/04/19 11:59	General View		Load JPG	✓
61	11/04/19 11:59	General View		Load JPG	✓
62	11/04/19 11:59	General View		Load JPG	✓
63	11/04/19 11:59	General View		Load JPG	✓
64	11/04/19 11:59	General View		Load JPG	✓
65	11/04/19 11:59	General View		Load JPG	✓
66	11/04/19 11:59	General View		Load JPG	✓
67	11/04/19 11:59	General View		Load JPG	✓
68	11/04/19 11:59	General View		Load JPG	✓
69	11/04/19 11:59	General View		Load JPG	✓
70	11/04/19 11:59	General View		Load JPG	✓
71	11/04/19 11:59	General View		Load JPG	✓
72	11/04/19 11:59	General View		Load JPG	✓
73	11/04/19 11:59	General View		Load JPG	✓
74	11/04/19 11:59	General View		Load JPG	✓
75	11/04/19 11:59	General View		Load JPG	✓
76	11/04/19 11:59	General View		Load JPG	✓

Video			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
77	11/04/19 11:59	General View	Load JPG	☒
78	11/04/19 11:59	General View	Load JPG	☒
79	11/04/19 11:59	General View	Load JPG	☒
80	11/04/19 11:59	General View	Load JPG	☒
81	11/04/19 11:59	General View	Load JPG	☒
82	11/04/19 11:59	General View	Load JPG	☒
83	11/04/19 11:59	General View	Load JPG	☒
84	11/04/19 11:59	General View	Load JPG	☒
85	11/04/19 11:59	General View	Load JPG	☒
86	11/04/19 11:59	General View	Load JPG	☒
87	11/04/19 11:59	General View	Load JPG	☒
88	11/04/19 11:59	General View	Load JPG	☒
89	11/04/19 11:59	General View	Load JPG	☒
90	11/04/19 11:59	General View	Load JPG	☒
91	11/04/19 11:59	General View	Load JPG	☒
92	11/04/19 11:59	General View	Load JPG	☒
93	11/04/19 11:59	General View	Load JPG	☒
94	11/04/19 11:59	General View	Load JPG	☒
95	11/04/19 11:59	General View	Load JPG	☒
96	11/04/19 11:59	General View	Load JPG	☒
97	11/04/19 11:59	General View	Load JPG	☒
98	11/04/19 11:59	General View	Load JPG	☒
99	11/04/19 11:59	General View	Load JPG	☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/19 16:04	TP ESTIMATE- MARKED	Load PDF	
2	13/03/19 16:04	TP GIA REPORT	Load PDF	
3	10/07/19 09:00	LETTER TO OI	Load PDF	
4	10/07/19 09:00	LTA SEARCH	Load PDF	
5	10/07/19 09:00	RENTAL MILEAGE	Load PDF	
6	10/07/19 09:00	RENTAL RECEIPT	Load PDF	
7	04/09/19 14:11	LOD	Load PDF	
8	04/09/19 14:11	AUTHORISATION TO ACT	Load PDF	
9	04/09/19 14:11	RELEASE VOUCHER	Load PDF	
10	04/09/19 14:11	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/03/19 16:35	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY1661K (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4973E (TP veh)		
Date of Accident:	08/03/2019		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		57,782.70
Final Repair Cost	:	\$		17,454.34
Loss of Use	:	\$		950.00
Rental (if any)	:	\$		2,226.23
LTA / GIA Search Fee	:	\$		7.00
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		20,637.57

19.00 days at \$50.00 per day
19 days

Is Third Party Workshop GIA Registered?	[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 20,637.57
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

04 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill
(if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19004557/R1EB3S2
Date: 04/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SHC4973E **Insured Vehicle No :** SJY1661K
Date of Loss: 08/03/2019 **Nature of Claim:** TP **Claim No:** 5666809460SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC4973E**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZRS100121
 Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403573321
 Colour: Maroon Odometer: 133025 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	51,564.70	14,844.34	36,720.36	71.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,218.00	2,610.00	3,608.00	58.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	57,782.70	17,454.34	40,328.36	69.79
+ Loss of Use (19.0 x S\$50.00/day) (S\$)		950.00		
+ Car Rental (19.0 x S\$117.17/day) (S\$)		2,226.23		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		20,637.57		

INSPECTION

Date of Assignment: 08/03/2019
 Date Inspected: 08/03/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 13.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
2	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
4	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
5	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
6	2		*SEAL, RR BUMPER ARM, RH & LH	Necessary	22.00 F	*16.50 F
7	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
8	3		*PAD, RR BUMPER, CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
9	1		*COVER, FR BUMPER LH (DISC 25%)	Deformed	28.10 F	*21.08 F
10	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
11	1		*GRILLE SUB-ASSY (DISC 25%)	Cracked	335.60 F	*251.70 F
12	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	87.10 F	*65.33 F
13	1		*GRILLE, RADIATOR (DISC 25%)	Cracked	165.00 F	*123.75 F
14	1		*BRACKET, FR BUMPER (DISC 25%)	Necessary	99.80 F	*74.85 F
15	1		*SEAL, HOOD TO FR END (DISC 25%)	Necessary	24.40 F	*18.30 F
16	1		*SUPPORT, FR BUMPER LH (DISC 25%)	Necessary	82.30 F	*61.73 F
17	1		*HOD SUB-ASSY (DISC 25%)	Buckled	938.40 F	*703.80 F
18	1		*HINGE ASSY, HOOD, LH (DISC 25%)	Bent	57.00 F	*42.75 F
19	1		*HINGE ASSY, HOOD, RH (DISC 25%)	Bent	57.00 F	*42.75 F
20	1		*LOCK ASSY, HOOD (DISC 25%)	Bent	131.10 F	*98.33 F
21	1		*FENDER SUB-ASSY, FR, LH (DISC 25%)	Buckled	933.10 F	*699.83 F
22	1		*EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
23	1		*ABSORBER, FR BUMPER (DISC 25%)	Cracked	70.30 F	*52.73 F
24	1		*SUPPORT, RADIATOR UPPER LH (DISC 25%)	Bent	76.70 F	*57.53 F
25	1		*SUPPORT SUB-ASSY LOWER (DISC 25%)	Bent	397.40 F	*298.05 F
26	1		*SUPPORT S/A LH (DISC 25%)	Bent	237.00 F	*177.75 F
27	1		*AIR CON CONDENSER ASSY (DISC 25%)	Bent	1,317.70 F	*988.28 F
28	1		*SUPPORT, RADIATOR UPPER RH (DISC 25%)	Bent	76.70 F	*57.53 F
29	1		*COVER ASSY, ENGINE (DISC 25%)	Cracked	180.10 F	*135.08 F
30	1		*SUPPORT S/A UPPER (DISC 25%)	Bent	364.90 F	*273.68 F
31	1		*SUPPORT S/A RH (DISC 25%)	Bent	237.00 F	*177.75 F
32	1		*INLET, AIR CLEANER, NO 2 (DISC 25%)	Cracked	93.90 F	*70.43 F
33	1		*REINFORCEMENT FRONT UPPER (DISC 25%)	Bent	691.10 F	*518.33 F
34	1		*LINER, FR FENDER, LH (DISC 25%)	Cut	194.30 F	*145.73 F
35	1		*GUIDE, RADIATOR AIR, (DISC 25%)	Cracked	93.90 F	*70.43 F
36	1		*WIPER GARNISH LOUVER SUB-ASSY (DISC 25%)	Cracked	666.90 F	*500.18 F
37	1		*CLAMP SUB-ASSY, BATTERY (DISC 25%)	Cracked	41.40 F	*31.05 F
38	1		*INSULATOR, HOOD (DISC 25%)	Cut	393.90 F	*295.43 F
39	1		*RADIATOR ASSY (DISC 25%)	Bent	1,841.10 F	*1,380.83 F
40	1		*COVER, RADIATOR (DISC 25%)	Cracked	227.80 F	*170.85 F
41	1		*AIR CLEANER ASSY (DISC 25%)	Cracked	956.20 F	*717.15 F
42	1		*FAN SHROUD RADIATOR (DISC 25%)	Cracked	219.30 F	*164.48 F
43	1		*COVER, REAR FLOOR UNDER CENTER (DISC 25%)	Cracked	222.60 F	*166.95 F
44	1		*LAMP ASSY, FOG, LH (DISC 10%)	Cracked	910.20 F	*819.18 F
45	1		*UNIT, HEADLAMP, LH (DISC 10%)	Broken	2,558.90 F	*2,303.01 F
46	1		*BATTERY (DISC 10%)	Cracked	1,584.90 F	*1,426.41 F
47	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
48	1		*NUMBER PLATE (SN)	Broken	35.00 F	*35.00 F
49	1		*NUMBER PLATE FRAME (SN)	Deformed	25.00 F	*25.00 F
50	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*COOLANT (SN)	Necessary	12.30 F	*12.30 F
52	1		*SENSOR REVERSE (SN)	Cut	180.00 F	*180.00 F
53	1		*SENSOR REVERSE	Serviceable	180.00 F	*-F
54	1		*RETAINER, RR BUMPER, LH	Serviceable	111.50 F	*-F
55	1		*RETAINER, RR BUMPER, RH	Serviceable	112.70 F	*-F
56	1		*REAR BUMPER REINFORCEMENT	Serviceable	318.80 F	*-F
57	1		*COVER, GUARD RR BUMPER LOWER	Serviceable	14.80 F	*-F
58	1		*ANTENNA, ELECTRICAL KEY	Serviceable	60.30 F	*-F
59	1		*WIRE, LUGGAGE ROOM	Serviceable	143.50 F	*-F
60	1		*COVER, FR BUMPER RH	Serviceable	28.10 F	*-F
61	1		*SUPPORT, FR BUMPER RH	Serviceable	76.90 F	*-F
62	1		*ABSORBER, FR BUMPER	Serviceable	70.30 F	*-F
63	1		*REINFORCEMENT FRONT UPPER	Serviceable	691.10 F	*-F
64	1		*ABSORBER, FR BUMPER LOWER	Serviceable	117.00 F	*-F
65	1		*REINFORCEMENT FRONT LOWER	Serviceable	238.50 F	*-F
66	1		*EXTENSION SUBASSY, LH	Serviceable	116.30 F	*-F
67	1		*EXTENSION SUBASSY, RH	Serviceable	116.30 F	*-F
68	1		*INSULATOR, HOOD	Serviceable	393.90 F	*-F
69	1		*LAMP ASSY, FOG, RH	Not Necessary	910.20 F	*-F
70	1		*COVER ASSY, ENGINE	Not Necessary	180.10 F	*-F
71	1		*CABLE ASSY, HOOD	Not Necessary	53.20 F	*-F
72	1		*MOULDING LH	Not Necessary	83.30 F	*-F
73	1		*MOULDING RH	Not Necessary	83.30 F	*-F
74	1		*WIPER GARNISH LOUVER SUB-ASSY	Not Necessary	666.90 F	*-F
75	1		*WIPER GARNISH LOUVER SUB-ASSY, CLIP	Not Necessary	3.20 F	*-F
76	1		*WIPER GARNISH SHIELD, COWL WATER, LH	Not Necessary	18.90 F	*-F
77	1		*WIPER GARNISH SHIELD, COWL WATER, RH	Not Necessary	18.90 F	*-F
78	1		*COVER SUB-ASSY, FRONT PILLAR, UPR LH	Not Necessary	96.90 F	*-F
79	1		*THERMISTOR ASSY	Not Necessary	68.00 F	*-F
80	1		*COVER, RADIATOR	Not Necessary	227.80 F	*-F
81	1		*SUPPORT S/A UPPER	Not Necessary	364.90 F	*-F
82	1		*SUPPORT SUB-ASSY LOWER	Not Necessary	397.40 F	*-F
83	1		*SUPPORT S/A LH	Not Necessary	237.00 F	*-F
84	1		*SUPPORT S/A RH	Not Necessary	237.00 F	*-F
85	1		*BRACE, HOOD LOCK SUPPORT	Not Necessary	76.20 F	*-F
86	1		*SUPPORT, RADIATOR UPPER LH	Not Necessary	76.70 F	*-F
87	1		*SUPPORT, RADIATOR UPPER RH	Not Necessary	76.70 F	*-F
88	1		*UNIT, HEADLAMP, RH	Not Necessary	2,558.90 F	*-F
89	1		*COMPUTER SUBASSY, HEADLAMP, LH NO.1	Not Necessary	486.40 F	*-F
90	1		*HORN ASSY, HIGH	Not Necessary	112.80 F	*-F
91	1		*HORN ASSY, LOW	Not Necessary	112.80 F	*-F
92	1		*AIR CON CONDENSER ASSY	Not Necessary	1,317.70 F	*-F
93	1		*TUBE & ACCESSORY	Not Necessary	574.40 F	*-F
94	1		*HOSE SUB-ASSY, DISCHARGE	Not Necessary	337.10 F	*-F
95	1		*COOLANT	Not Necessary	12.30 F	*-F
96	1		*GUIDE, RADIATOR AIR,	Not Necessary	93.90 F	*-F
97	1		*GUIDE, RADIATOR AIR, UPPER	Not Necessary	44.70 F	*-F
98	1		*GUIDE, RADIATOR AIR, LH	Not Necessary	58.80 F	*-F
99	1		*GUIDE, RADIATOR AIR, RH	Not Necessary	54.60 F	*-F
100	1		*RADIATOR ASSY	Not Necessary	1,841.10 F	*-F
101	1		*GROMMET (FOR RADIATOR LOWER)	Not Necessary	12.70 F	*-F
102	1		*CUSHION, (FOR RADIATOR UPPER SUPPORT)	Not Necessary	9.80 F	*-F
103	1		*FAN RADIATOR, LH	Not Necessary	181.80 F	*-F
104	1		*FAN RADIATOR, RH	Not Necessary	233.00 F	*-F
105	1		*FAN SHROUD RADIATOR	Not Necessary	219.30 F	*-F
106	1		*MOTOR, COOLING FAN, LH	Not Necessary	543.50 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*MOTOR, COOLING FAN, RH	Not Necessary	443.40 F	*-F
108	1		*HOSE, RADIATOR, NO. 1	Not Necessary	42.60 F	*-F
109	1		*HOSE, RADIATOR, NO. 2	Not Necessary	40.20 F	*-F
110	1		*HOSE, WATER BYPASS, NO. 1	Not Necessary	37.40 F	*-F
111	1		*HOSE, WATER BYPASS, NO. 2	Not Necessary	37.40 F	*-F
112	1		*HOSE, WATER BYPASS, NO. 3	Not Necessary	20.10 F	*-F
113	1		*HOSE, WATER BYPASS, NO. 4	Not Necessary	13.20 F	*-F
114	1		*HOSE, WATER BYPASS, NO. 8	Not Necessary	37.90 F	*-F
115	1		*PIPE, WATER BYPASS, NO. 1	Not Necessary	11.00 F	*-F
116	1		*PIPE, WATER BYPASS, NO. 2	Not Necessary	11.00 F	*-F
117	1		*PIPE, WATER BYPASS, NO. 3	Not Necessary	56.40 F	*-F
118	1		*INVERTER WATER PUMP ASSY	Not Necessary	432.00 F	*-F
119	1		*HOSE, HV WATER PUMP INLET	Not Necessary	37.90 F	*-F
120	1		*HOSE, HV WATER PUMP OUTLET	Not Necessary	29.60 F	*-F
121	1		*TANK ASSY, INVERTER RESERVE	Not Necessary	371.30 F	*-F
122	1		*HOSE, INVERTER COOLING INLET	Not Necessary	43.10 F	*-F
123	1		*HOSE, INVERTER COOLING OUTLET	Not Necessary	29.60 F	*-F
124	1		*HOSE, INVERTER RADIATOR INLET	Not Necessary	40.70 F	*-F
125	1		*COOLER, MOTOR COOLING	Not Necessary	249.10 F	*-F
126	1		*WIRE, ENGINE ROOM MAN	Not Necessary	6,138.00 F	*-F
127	1		*BATTERY	Not Necessary	1,584.90 F	*-F
128	1		*CLAMP SUB-ASSY, BATTERY	Not Necessary	41.40 F	*-F
129	1		*CLAMP, BATTERY, NO.2	Not Necessary	43.30 F	*-F
130	1		*COVER, FUSIBLE LINK	Not Necessary	28.30 F	*-F
131	1		*BLOCK ASSY, FUSIBLE LINK	Not Necessary	99.80 F	*-F
132	1		*TERMINAL ASSY, BATTERY POSITIVE (+)	Not Necessary	48.00 F	*-F
133	1		*BLOCK, JUNCTION	Not Necessary	15.80 F	*-F
134	1		*SENSOR ASSY, BATTERY STATE	Not Necessary	256.80 F	*-F
135	1		*INLET, AIR CLEANER, NO1	Not Necessary	130.50 F	*-F
136	1		*INLET, AIR CLEANER, NO 2	Not Necessary	93.90 F	*-F
137	1		*INLET, AIR CLEANER, NO 3	Not Necessary	35.30 F	*-F
138	1		*CLAMP (FOR AIR CLEANER HOSE, NO.2)	Not Necessary	9.00 F	*-F
139	1		*CLAMP (FOR AIR CLEANER HOSE, NO.1)	Not Necessary	7.10 F	*-F
140	1		*HOSE, AIR CLEANER, NO.1	Not Necessary	62.10 F	*-F
141	1		*RESONATOR, INTAKE AIR	Not Necessary	14.90 F	*-F
142	1		*BRACKET, AIR CLEANER	Not Necessary	26.90 F	*-F
143	1		*AIR CLEANER ASSY	Not Necessary	956.20 F	*-F
144	1		*TUBE, UNION (FOR AIR CLEANER HOSE)	Not Necessary	19.40 F	*-F
145	1		*PROTECTOR, FR FENDER LH	Not Necessary	90.40 F	*-F
146	1		*SEAL SUB-ASSY, LH	Not Necessary	50.20 F	*-F
147	1		*LINER, FR FENDER, LH	Not Necessary	194.30 F	*-F
148	1		*PAD, FR WHEEL LH	Not Necessary	57.70 F	*-F
149	1		*APRON SUB-ASSY, FRONT FENDER, LH	Not Necessary	944.20 F	*-F
150	1		*CHECK ASSY, FRONT DOOR	Not Necessary	153.50 F	*-F
151	1		*HINGE ASSY, FRONT DOOR, UPPER LH	Not Necessary	82.10 F	*-F
152	1		*HINGE ASSY, FRONT DOOR, LOWER LH	Not Necessary	92.10 F	*-F
153	1		*FENDER SUB-ASSY, FR, RH	Not Necessary	933.10 F	*-F
154	1		*EMBLEM, SIDE PANEL (HYBRID)	Not Necessary	52.90 F	*-F
155	1		*PANEL SUB-ASSY, FRONT DOOR LH	Repair	1,249.60 F	*-F
156	1		*MEMBER SUB-ASSY, FR LH	Repair	1,959.50 F	*-F
157	1		*COVER, FR BUMPER (DISC 25%)	Deformed	495.50 F	*371.63 F

F=Franchise part.

Total Parts (\$\$)	51,564.70	14,844.34
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,028.00	1,100.00
2	SPRAY PAINT.	New	2,790.00	1,000.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	200.00	100.00
5	TO TOP UP A/C GAS.	New	120.00	80.00
6	TO ALIGN CHASSIS.	New	350.00	100.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	60.00
8	TO REMOVE AND REFIT WIRE HARDESS.	New	250.00	60.00
9	TO REMOVE & REFIX ENGINE & RADIATOR ASSY & NNER COOLER & AIR CON CONDENSER.	New	120.00	80.00
10	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
11	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			6,218.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685552
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/04/2019

User ID : PohSuan

16264371 20	HOSE, WATER BYPASS , NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check
16267370 90	HOSE, WATER BYPASS , NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check
16281371 00	HOSE, WATER BYPASS , NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check
16296370 10	HOSE, WATER BYPASS , NO.8	0.00	\$37.90	0.00	\$0.00	Replace	Check
16268371 00	PIPE, WATER BYPASS , NO.1	0.00	\$11.00	0.00	\$0.00	Replace	Check
16268371 20	PIPE, WATER BYPASS , NO.2	0.00	\$11.00	0.00	\$0.00	Replace	Check
16279370 20	PIPE, WATER BYPASS , NO.3	0.00	\$56.40	0.00	\$0.00	Replace	Check
G904047 040	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check
G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check
G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check
G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check
G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check
G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check
G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check
G125A47 010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check
28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Check
74404470 30	CLAMP SUB-ASSY, BATTERY	0.00	\$41.40	0.00	\$0.00	Replace	Check
74482470 10	CLAMP, BATTERY, NO.2	0.00	\$43.30	0.00	\$0.00	Replace	Check
82621470 20	COVER, FUSIBLE LINK	0.00	\$28.30	0.00	\$0.00	Replace	Check
82620470 90	BLOCK ASSY, FUSIBLE LINK	0.00	\$99.80	0.00	\$0.00	Replace	Check
90982050 61	TERMINAL ASSY, BATTERY POSITIVE (+)	0.00	\$48.00	0.00	\$0.00	Replace	Check
82671470 40	BLOCK, JUNCTION	0.00	\$15.80	0.00	\$0.00	Replace	Check
28850370 70	SENSOR ASSY, BATTERY STATE	0.00	\$256.80	0.00	\$0.00	Replace	Check
17751371 10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check
17752371 21	INLET, AIR CLEANER, NO 2	0.00	\$93.90	0.00	\$0.00	Replace	Check
17753370 10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check
96111107 50	CLAMP (FOR AIR CLEANER HOSE , NO.2)	0.00	\$9.00	0.00	\$0.00	Replace	Check
96111106 50	CLAMP (FOR AIR CLEANER INLET , NO.1)	0.00	\$7.10	0.00	\$0.00	Replace	Check
17881373 30	HOSE, AIR CLEANER , NO.1	0.00	\$62.10	0.00	\$0.00	Replace	Check
17893371 30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check
17771370 20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check
17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check
90904060 08	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check
53802471 00	FENDER SUB-ASSY, FR , LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
53828470 70	PROTECTOR, FR FENDER LH	0.00	\$90.40	0.00	\$0.00	Replace	Check
53808470 20	SEAL SUB-ASSY, LH	0.00	\$50.20	0.00	\$0.00	Replace	Check
53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check
53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Check
53702471 01	APRON SUB-ASSY, FRONT FENDER , LH	0.00	\$944.20	0.00	\$0.00	Replace	Check