

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19004606/KBA3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMG1812B

Insured Vehicle No : SGQ3368Y

Date of Loss: 09/03/2019

Nature of Claim: TP

Claim No: 6110821602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG1812B**

Make & Model: LEXUS GS450H, 3.5 Super Luxury (A)

Engine No: 2GR8664378

Reg. Date: 02/01/2009 (Man. Year: 2008)

Chassis No: JTHBC96SX05018892

Colour: Metallic Black

Odometer: 184867 km

Engine Capacity: 3456 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size:

245/40Z R18

Front Left Side: Michelin 4 mm

Rear Left Side:

Michelin 3 mm

Front Right Side: Michelin 4 mm

Rear Right Side:

Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/03/2019

Date Inspected: 15/03/2019 Inspected At:

Seng Kin Motor Works (HQ)
BLOCK 1, SIN MING INDUSTRIAL
ESTATE #01-131 SINGAPORE
575636
Singapore 575636

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Bent	0.00 F	*- F
2	1		*FRT LH FENDER INNER SHIELD	Serviceable	0.00 F	*- F
3	1		*FRT LH FENDER INNER SHIELD CLIPS	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >