



Case Details

Case Reference Number :
BUS/03/19/5003
Type of Repair : Accident Repair
Vehicle Registration Number :
SMB3584Y

Company Type : SMRT Buses Ltd
Estimation ID : EST-6077-ID
Assigned By : Audrey Woo Yee
Shin

Insurance Company Name : AXA Insurance Singapore Pte
Ltd
Accident Date and Time : 01/03/2019 08:20 AM
Vehicle Age(In Months) : 47

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Sur Fin Pri
Standard	Main	BODY LH	6011228	PANEL,EXTERIOR:L/H,FOR ADL DD BUS	1	436.30	436.30	10.00	392.67	Replace	1	3
Standard	Main	BODY LH	6011234	PANEL,EXTERIOR:L/H,FOR ADL DD BUS	1	537.40	537.40	10.00	483.66	Replace	1	4
Standard	Main	Body	6011241	MOULDING,WHEELARCH:LH & RH,FOR ADL DD	2	88.03	176.06	10.00	158.45	Replace	2	1
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	12	37.00	444.00	0.00	444.00	Replace	12	4
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	1	8
Standard	Main	CONSUMABLE	4006315	ACTIVATOR	1	80.00	80.00	0.00	80.00	Replace	1	8
Standard	Supplementary	BODY LH	6011229	PANEL,EXTERIOR:L/H,FOR ADL DD BUS	1	140.56	140.56	10.00	126.50	Replace	1	1
Total Spare Part Cost									1,765.28			Surveyor
Lump Sum Discount (%)									20.00			Lump Sum I
Final Spare Part Cost									1,412.22			Final Su

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	1,590.00	
Total:			2,120.00	1,590.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	1,218.00	1,048.00	
Total:			1,218.00	1,048.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,412.22	1,412.22
Total Labour Cost	2,120.00	1,590.00
Total Spray Painting	1,218.00	1,048.00
Other	0.00	0.00
Overall Total	4,750.22	4,050.22
Lump Sum Repair Option	☐	☒
Lump Sum Total	0.00	4,050.00
Surveyor Approved Amount		4,050.00
No of Repair Days*	6	5
Remarks	-	L/S Repair. PHOTO after paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	18/03/2019	