

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 6302C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	250.00	-
1	VISOR (CONSISTENT)	SCRATCHED	350.00	350.00
1	FRONT LH SIDE PANEL (CONSISTENT)	CRACKED	160.00	160.00
1	FRONT RH SIDE PANEL (CONSISTENT)	NOT NECESSARY	170.00	-
1	SET FORK TUBE (CONSISTENT)	DISTORTED	980.00	980.00
1	DASH COVER PANEL FRONT (CONSISTENT)	CUT	165.00	165.00
1	METER COVER (CONSISTENT)	NOT NECESSARY	198.00	-
1	FRONT PANEL (CONSISTENT)	CUT	200.00	200.00
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	250.00	-
1	REAR SIDE FAIRING (CONSISTENT)	MTG CRACKED	180.00	180.00
1	LH LOWER BELLY PAN (CONSISTENT)	CUT	150.00	150.00
1	FRONT HEADLAMP (CONSISTENT)	MTG CRACKED	265.00	265.00
	LESS 10% DISCOUNT		-331.80	-245.00
			2,986.20	2,205.00
	<u>LABOUR</u>			
	TOWING FEE.		40.00	30.00
	REMOVE & REPLACE PARTS ,ALIGN & ETC.		380.00	120.00
	REMOVE & REPLACE FORK TUBE ,TOP UP FORK OIL.		150.00	80.00
	RECONNECT ELECTRICAL WIRING.		80.00	20.00
	PUTTY & TOUCH UP PAINT WORK.		250.00	180.00
	FORK OIL SEAL.		150.00	50.00
			1,050.00	480.00
	GRAND TOTAL		4,036.20	2,685.00

RECOMMENDED COST OF LUMP SUM REPAIRS	2,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM19004612/Dga3q2



ANG BRYAN TANI

Automotive Assessor / Investigator