

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG17020334/R1TD3S2-1**Date:** 08/04/2019REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28671362MKF
Claimant Vehicle No :	YM7571H	Insured Vehicle No :	YN306Z
Date of Loss:	19/10/2017	Nature of Claim:	TP
		Claim No:	533900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YM7571H	Engine No:	J08EUB10667
Make & Model:	NISSAN PKC37BHHNP, 7.7 D (M)	Chassis No:	PKC37BN00245
Reg. Date:	24/11/2007 (Man. Year: 2007)	Odometer:	284708 km
Colour:	White		
Engine Capacity:	7684 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	11 R22.5	Rear Tyre Size:	11 R22.5 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,268.81	4,090.23	11,178.58	73.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,460.00	2,080.00	58.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,808.81	5,550.23	13,258.58	70.49
Approved Total (Overridden) (\$\$)		4,450.00		
(\$\$)	18,808.81	4,450.00	14,358.81	76.34
+ GST 7.00/7.00% (\$\$)	1,316.62	311.50	1,005.12	76.34
Nett Amount (\$\$)	20,125.43	4,761.50	15,363.93	76.34

INSPECTION

Date of Assignment:	24/10/2017	
Date Inspected:	28/12/2017 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Apr 2019)	
Parts:	N/A	NISSAN PKC37BHHNP 7.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM7571H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Warped / Grazed	3,210.00 FL	*3,210.00 FL
2	2		*FRONT BONNET HINGES L/R	Serviceable	580.00 FL	*- FL
3	1		*FRONT BONNET LOCK CATCH	Serviceable	48.00 FL	*- FL
4	2		*FRONT BONNET LOCK STRIKER L/R	Serviceable	84.40 FL	*- FL
5	2		*FRONT BONNET MECHANISM LOCK L/R	Serviceable	564.40 FL	*- FL
6	1		*FRONT BUMPER	Dented / Bent	1,360.80 FL	*1,360.80 FL
7	2		*FRONT BUMPER BRACKET L/R	Serviceable	1,160.80 FL	*- FL
8	2		*FRONT BUMPER FOGLAMP BRACKET (LOWER) L/R	Serviceable	136.40 FL	*- FL
9	2		*FRONT BUMPER FOGLAMP BRACKET (TOP) L/R	Serviceable	136.40 FL	*- FL
10	2		*FRONT BUMPER STAY BAR L/R	Serviceable	280.80 FL	*- FL
11	2		*FRONT BUMPER STAY BRACKET L/R	Serviceable	480.00 FL	*- FL
12	2		*FRONT CORNER SIDE PANEL L/R	Serviceable	1,530.40 FL	*- FL
13	12		*FRONT CORNER SIDE PANEL SCREW CLIPS L/R	Necessary	78.00 FL	*78.00 FL
14	1		*FRONT GRILLE	Bent / Cracked	480.10 FL	*480.10 FL
15	1		*FRONT GRILLE LOGO EMBLEM	Necessary	61.00 FL	*61.00 FL
16	6		*FRONT GRILLE CLIPS	Necessary	39.00 FL	*39.00 FL
17	2		*FRONT HEADLAMP BRACKET (NO:1) L/R	Serviceable	440.40 FL	*- FL
18	2		*FRONT HEADLAMP BRACKET (NO:2) L/R	Serviceable	440.40 FL	*- FL
19	8		*FRONT HEADLAMP CLIPS L/R	Serviceable	52.00 FL	*- FL
20	6		*FRONT HEADLAMP SIDE GARNISH CLIPS L/R	Serviceable	39.00 FL	*- FL
21	8		*FRONT SIDE LAMP CLIPS L/R	Serviceable	52.00 FL	*- FL
22	2		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Serviceable	48.00 FN	*- FN
23	1		*FRONT BONNET WEATHER STRIP	Serviceable	98.80 FN	*- FN
24	2		*FRONT BUMPER FOG LAMP L/R	Serviceable	1,040.80 FN	*- FN
25	2		*FRONT BUMPER FOG LAMP RIM GARNISH L/R	Serviceable	724.80 FN	*- FN
26	2		*FRONT BUMPER SIDE GARNISH L/R	Serviceable	841.20 FN	*- FN
27	2		*FRONT BUMPER GARNISH LAMP L/R	Serviceable	794.40 FN	*- FN
28	2		*FRONT HEADLAMP L/R	Not Necessary	2,720.80 FN	*- FN
29	2		*FRONT HEADLAMP SIDE GARNISH L/R	Not Necessary	196.80 FN	*- FN
30	2		*FRONT SIDE LAMP L/R	Not Necessary	796.40 FN	*- FN
31	1		*FRONT BONNET ADVERTISEMENT & ART WORK	Necessary	800.00 FS	*400.00 FS
32	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	19,371.30	5,658.90
- List Item Discount on L Items 30.00/30.00% (\$\$)	3,376.29	1,568.67
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	726.20	0.00
Total Parts (\$\$)	15,268.81	4,090.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)	New	120.00	0.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,800.00	800.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,500.00	600.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	60.00
Gross Labour Cost (\$)			3,540.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >