



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18016532/Gsd3e2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 03-04-2019



ATTN : LOH CHEE HENG

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SKM 8108Y	Veh. Inspected	SJR 1033K
Policy No.	2100354924	Coverage (\$)	0.00
Claim No.	1013070181SG-003	Excess (\$)	0.00
Assign From	LOH CHEE HENG	Assign Date	12/03/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KMH DU41BR9U771678	Colour	BLACK
Odometer	229292	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	NEUTON	8 mm
L/H Front Tyre	195/60 R15	NEUTON	8 mm
R/H Rear Tyre	195/60 R15	NEUTON	8 mm
L/H Rear Tyre	195/60 R15	NEUTON	8 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	09/09/2018	Inspection Date	29/03/2019
Survey held at	8 KAKI BUKIT AVE 4 #04-20		
Repairer	A-TEC AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**