

REF:

Signature: Rame

REF: NS/INC19004690/Rsd302

Tax 103/19/203

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

at _____

Insured: SMH 5077A

Policy No. 5107617573 (19/2/19-18/2/2020)

Claims No. MT/1035111-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IUAC Accident Report: _____ Consistent? Yes or No

GI/PR Score: _____ Consistent? Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: SUB 833H Yr Regn: 19 DEC 2017

Type: M.Car/M.Cycle/BUS/Van/Lorry/Taxi/Prime Mover/

Truck/Trailer or

Make: TOYOTA PRINS c.o. 1.798

Colour: MAROON A/C: Insured/Std/N/A

Sp. Reading: 186 584 T/Radio: Insured/Std/N/A

Eng/No: _____

Plat: JTDKB3FU703576990

Gen. Cond: Good/Fair/Poor/Burnt

Steering: Inorder/Jammed/Leaked/Burnt or

Brake: Inorder/Jammed/Leaked/Burnt or

Modi: Nil/S/Rim/STD A/Rim or

Tyre Size: F: 195/65 R15

R: 7

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/CHTSU/PIR/SUMI/

TOYO/YOKO or WELTACE (F), FALKEN (R)

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 8/3/19 U.O.I. 8.15.19

Survey held at IMRT WOODLANDS

Des. of Damages: Frt/Rear/OIS/NIS/UIC/Rooftop or

The UIC/Chassis frame/Body Structure affected due to collision

ENC P/P

Date / Time

Action / Instruction

photo taken by naz on 08/03/19

Survey done on 11/03/19

SUB 833H - NS/INC18606263 / Sub 2

SMH 5077A - X

Rasul, RECEIVED 10 OCT 2019

Plg 500 MP

16/10/19 Subm P/P \$ 4696.87 @ 5 days

with Recal (\$ 13,143.64 Red - 74)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 160

Transportation: 160

Site Insp (\$)

Interview (\$)

Tech. Invo (\$)

Weekend (\$)

Report Format: _____

Lump Sum I.B. (\$ 4696.87 P/P)

TOTAL

160

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	S107617573		LAW CHONG MENG DENNIS	S1758610F	GPC	drivo CLASSIC	SMH5077A	SMH5077A	19/02/2019	18/02/2020

TP Claims against NTUC Income: Follow-Through Survey

Date : 18/10/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1063635-002	SMRT TAXIS PTE LTD	SHF 412T	SLW 6652R	22/09/2019	13:10	\$ 10,032.90
2	MT/1066688-002	COMFORTDELGRO ENGINEERING PTE LTD	SHC 138SY	SLS 745S	14/10/2019	8:40	\$ 1,821.95
3	MT/1035111-002	SMRT TAXIS PTE LTD	SHB 833H	SMH 5077A	08/03/2019	8:30	\$ 17,840.51

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB833H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8263645
Chassis No.:	JTDKB3FU703576990
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,353.00
Total Rebate Amount:	\$30,103.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Oct 2019

OK

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 18 October 2019 11:50 am
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHB833H

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Friday, 18 October 2019 11:27 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHB833H

Hi Poh Suan,

Finalised amount is \$ 4,696.87. Is it correct?

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Friday, 18 October, 2019 9:18 AM
To: Rasul (LKKAuto)
Subject: RE: SHB833H

Hi Rasul,

Noted. Please confirm as soon as possible.

-----Original Message-----

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Friday, 18 October 2019 8:47 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHB833H

RE: SHB833H

Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>

Wed 16/10/2019 10:09 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Hi,

Amount confirmed as per your recommendation, thanks.

Regards

Poh Suan

-----Original Message-----

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]

Sent: Wednesday, 16 October 2019 9:26 AM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Cc: Shirley Hiew (LKK Auto)

Subject: RE: SHB833H

Hi Poh Suan,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]

Sent: Tuesday, 15 October, 2019 5:25 PM

To: Rasul (LKKAuto)

Cc: SUR; CS A Team

Subject: SHB833H

Hi Rasul,

Attached herewith the repair estimate of SHB 833H having Case No: TAX/03/19/2031.

There is no change to the approved amount of \$5,579.87 @ 5 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2019 10:00
Date Of Accident	08/03/2019 08:30
Exact Location Of Accident	MOUNT SINAI DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB833H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	NG AIK WEE
NRIC No	S1372744I
Date Of Birth	21/05/1959
Occupation	OUTDOOR
Date Of Driving Pass	25/06/1979
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG MOUNT SINAI ROAD WITH ONE PASSENGER (MALE CAUCASIAN) ON BOARD AS I WAS CHECKING IF I WAS TRAVELLING IN THE RIGHT DIRECTION. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SMH5077A HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH5077A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAW CHONG MENG DENNIS
NRIC/Passport Number	S1758610F
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

8-3-19.

[Signature]
8/3/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :
TAX/03/19/2031

Type of Repair : Accident
Repair

Vehicle Registration Number :
SHB833H

Company Type : SMRT Taxis
Pte Ltd

Estimation ID : EST-6027-ID

Assigned By : Taxi Claims
Manager Team

Insurance Company Name : NTUC Income Insurance
Co-operative Ltd

Accident Date and Time : 08/03/2019 12:33 AM

Vehicle Age(In Months) : 15

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation												Surveyor
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0
One Time Key In	Main			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	47.00	25.00	35.25	Replace	0	0
One Time Key In	Main			END PANEL , COVER, DECK TRIM, REAR	1	122.80	122.80	25.00	92.10	Replace	0	0
One Time Key In	Main			REINFORCEMENT ASSY, REAR FLOOR END PANEL , RH & LH	2	56.70	113.40	25.00	85.05	Replace	0	0
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0

Yes

Total Spare Part Cost 11,065.99

Surveyor Total

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 11,065.99

Final Sur Total

SMRT Recommendation

Survey

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0
One Time Key In	Main			BOARD, REAR FLOOR, NO.1	1	502.20	502.20	25.00	376.65	Replace	0	0
One Time Key In	Main			BOX, DECK FLOOR, REAR	1	102.20	102.20	25.00	76.65	Replace	0	0
One Time Key In	Main			BOX, DECK FLOOR, LH	1	303.40	303.40	25.00	227.55	Replace	0	0
One Time Key In	Main			BOX, DECK FLOOR, RH	1	304.00	304.00	25.00	228.00	Replace	0	0
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	1	394.2
One Time Key In	Main			TROUGH, BACK DOOR , LH	1	99.80	99.80	25.00	74.85	Replace	0	0
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	1	394.2
One Time Key In	Main			TROUGH, BACK DOOR , RH	1	99.80	99.80	25.00	74.85	Replace	0	0
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	0	0
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.9

Total Spare Part Cost 11,065.99

Surveyor Total

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 11,065.99

Final Sur Total

SMRT Recommendation

Surveyor

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0

Total Spare Part Cost 11,065.99

Surveyor Total

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 11,065.99

Final Sur Total

SMRT Recommendation

Survey

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	2	6.45 <i>new</i>
One Time Key In	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	2	3.30 <i>new</i>
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.73 <i>de</i>
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0 <i>yes</i>
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95 <i>new</i>
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0 <i>yes</i>
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12 <i>can</i>
One Time Key In	Main			WIRE, LUGGAGE ROOM	1	143.50	143.50	10.00	129.15	Replace	0	0
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0

Total Spare Part Cost 11,065.99

Surveyor Total

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 11,065.99

Final Sur Total

SMRT Recommendation

Survey

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0 <i>yes</i>
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	26.00	25.00	19.50	Replace	10	19.50 <i>no</i>
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.2	10	3.20	32.00	25.00	24.00	Replace	10	24.00 <i>no</i>
One Time Key In	Main			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	137.00	25.00	102.75	Replace	0	0 <i>X yes</i>
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	1,173.90	25.00	880.43	Replace	1	880.4 <i>X repair</i>
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	0 <i>X repair</i>
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0 <i>X repair</i>
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	0	0 <i>X yes</i>
One Time Key In	Main			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	0	0 <i>X yes</i>
One Time Key In	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0 <i>X yes</i>
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	0	0 <i>X yes</i>

Total Spare Part Cost 11,065.99

Surveyor Total

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 11,065.99

Final Sur Total

SMRT Recommendation

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surve
												Surveyor Final Price(\$)
One Time Key In	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	29.70	25.00	22.27	Replace	0	0 <i>Xsu</i>
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	1	14.77 <i>B</i>
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	29.90	25.00	22.42	Replace	0	0
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	29.90	25.00	22.42	Replace	0	0
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0 <i>Xsu</i>
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	0	0
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22 <i>3</i>
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22 <i>3</i>
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72 <i>3</i>
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80

Total Spare Part Cost 11,065.99

Surveyor Total

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 11,065.99

Final Sur Total

SMRT Recommendation

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60
Total Spare Part Cost												11,065.99
Lump Sum Discount (%)												0.00
Final Spare Part Cost												11,065.99

Surveyor Total

Lump Sum Dis (%)

Final Sur Total

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,183.00	1,183.00	
Total:			1,183.00	1,183.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
5	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
6	Main	TO RESPRAY REAR PANEL	180.00	100	
7	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
8	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
Total:			2,952.00	600.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY REAR FENDER LH	378.00	0 <i>Yes</i>	
10	Main	TO RESPRAY REAR FENDER RH	378.00	0 <i>Yes</i>	
11	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0 <i>X</i>	
12	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0 <i>100</i>	
Total:			2,952.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 <i>/</i>	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40.00 <i>/</i>	
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0 <i>Yes</i>	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60 <i>/</i>	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60 <i>/</i>	
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30 <i>/</i>	
7	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0 <i>Yes</i>	
8	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00 <i>Yes</i>	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Yes</i>	
10	Main	TO WASH AND VACUUM	60.00	0 <i>Yes</i>	
Total:			1,360.00	220.00	

Summary



	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	11,065.99	3,487.78
Total Labour Cost	1,183.00	1,183.00
Total Spray Painting	2,952.00	600.00
Other	1,360.00	220.00
Overall Total	16,560.99	5,490.78
Lump Sum Repair Option		
Lump Sum Total	0.00	5,490.78
Surveyor Approved Amount		5,490.78
No of Repair Days*	8	5
Remarks	-	RESURVEY BEFORE PAINT / PART BY PART
Surveyor Name		Rasul
Signature		
Survey Date	11/03/2019	

Save

Clear

Section A - Accident Details

Registration Number	SHB833H
Case Reference Number	TAX/03/19/2031
Registration Date	18/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG AIK WEE
Type of Accident	Head to Rear
Accident Date and Time	8/3/2019 8:33 AM
Accident Reported Date and Time	8/3/2019 10:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100496
Special Instruction to ARC, if any	TP/NTUC - LKK
Prepared Date and Time	11/3/2019 7:13 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Right

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,433.00	\$1,288.00 / 400
Total Spray Cost	\$3,312.00	\$500.00 /
Total Spare Part Cost	\$11,735.45	\$11,735.51 /
Total Other Cost	\$1,360.00	\$220.00 /
TOTAL COST	\$17,840.45	\$5,579.87 (PIP) / 4696.87
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	11/03/2019 1:32 PM	11/03/2019 5:46 PM
Signature		
Remarks	Supplementary = 2 days	RESURVEY BEFORE PAINT / PART BY PART

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0076	Invoice Number	
Quotation Date	06.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RR END PANEL	\$250.00	\$100.00 (5) -
TO REPAIR REAR PORTION	\$1,183.00	\$1,183.00 / 300
Total Labour	\$1,433.00	\$1,283.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00 /
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$100.00 /
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00 x n repeated
TO RESPRAY TAIL GATE	\$378.00	\$200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00 x n
TO RESPRAY REAR PANEL	\$180.00	\$100.00 /
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00 x n
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00 x n
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00 x n
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00 x n
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00 x n
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00 x n
Total Spray Painting & Panel Beating	\$3,312.00	\$800.00 /

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00 x n
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$80.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$60.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00 x n
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00 x n
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 x n
TO WASH AND VACUUM	\$60.00	\$0.00 x n
Total Other Costs	\$1,360.00	\$220.00 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		56307470 90	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check X
		64718470 80C0	END PANEL, COVER, DECK TRIM SERVICE	0.00	\$47.00	0.00	\$0.00	Replace	Check X
		64716471 30C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$122.80	0.00	\$0.00	Replace	Check X
		56350470 10	REINFORCEMENT ASSY, REAR FLOOR END PANEL	0.00	\$55.70	0.00	\$0.00	Replace	Check X
4006314			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given Y
		58311471 30	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Not Given X
		58415471 10C2	BOARD, REAR FLOOR, NO.1	0.00	\$502.20	0.00	\$0.00	Replace	Check X
		64993471 10	BOX, DECK FLOOR, REAR	0.00	\$102.20	0.00	\$0.00	Replace	Check X
		64997470 60	BOX, DECK FLOOR, LH	0.00	\$303.40	0.00	\$0.00	Replace	Check X
		64995470 50	BOX, DECK FLOOR, RH	0.00	\$304.00	0.00	\$0.00	Replace	Check X
		81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$438.10	10.00	\$394.29	Replace	Replace
		61622470 60	TROUGH, BACK DOOR, LH	0.00	\$99.80	0.00	\$0.00	Replace	Not Given X
		61602471 60	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given X
		81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	10.00	\$394.29	Replace	Replace
		61621470 50	TROUGH, BACK DOOR, RH	0.00	\$99.80	0.00	\$0.00	Replace	Not Given X
		61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given X
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$316.80	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52576470 40	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
		52599680 30	STOPPER, RR BUMPER, RH & LH	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		90189060 29	REAR BUMPER GROMMET SCREW	2.00	\$2.20	25.00	\$3.30	Replace	Replace
		52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Check X
		52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Check X
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		52189470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Check X
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Check X
		81591470 10	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 51 Woodlands Industrial Park S4, Singapore 757705
 FAX Number: 63655523
 Estimator Telephone Number: 68602025
 Accident Reporting Number: 68602072

Date Generated: 05/10/2019

User ID: P010000

82183470 20	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given	X
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Check	X
58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check	X
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Check	X
90467170 26A0	CLIP, FLOOR UNDER COVER, NO.1	10.00	\$2.60	25.00	\$19.50	Replace	Replace	new
90467170 27C0	CLIP, FLOOR UNDER COVER, NO.2	10.00	\$3.20	25.00	\$24.00	Replace	Replace	new
58327470 40	EXHAUST HEAT SHIELD INSULATOR, MAIN	0.00	\$137.00	0.00	\$0.00	Replace	Check	X
17430377 30	PIPE ASSY, EXHAUST, TAIL	1.00	\$1,173.90	100.00	\$0.00	Replace	Repair	R
67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	1.00	\$929.60	100.00	\$0.00	Replace	Repair	R
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	R
69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given	X
69321470 10	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Not Given	X
69430520 50	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X
75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	X
75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$19.70	25.00	\$14.75	Replace	Replace	new
75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
67881470 50	TAIL GATE WEATHERSTRIP, BACK	0.00	\$360.70	0.00	\$0.00	Replace	Not Given	X
89997301 00	ANTENNA ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X
75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	new
75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	new
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	new
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	new
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	new
Total			\$13,776.80		\$2,607.41			

11066.35

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$166.95	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$316.80	25.00	\$239.10	Replace	Replace
		64718470 80C0	END PANEL, COVER, DECK TRIM SERVICE HOLE	1.00	\$47.00	25.00	\$35.25	Replace	Replace
		52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace
		58398470 50	COVER, REAR FLOOR UNDER, RH	1.00	\$169.50	25.00	\$127.13	Replace	Replace
Total					892.60		669.46		

Suppl

3276.87
 + 1283.00
 + 1020.00
 5579.87

5 days

20933.40

4696.87

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19004690/R1sd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 01-11-2019	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 5077A	Veh. Inspected	SHB 833H	
Policy No.	5107617573	Coverage (\$)	0.00	
Claim No.	MT/1035111-002	Excess (\$)	0.00	
Assign From		Assign Date	08/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU703576990	Colour	MAROON	
Odometer	186584	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2019	Inspection Date	08/03/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 833H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.93
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00 (DISC 25%)	NECESSARY	22.00	16.50
1	RETAINER, RR BUMPER, LH (DISC 25%)	NECESSARY	111.50	83.63
2	STOPPER, RR BUMPER, RH & LH @\$4.30 (DISC 25%)	NECESSARY	8.60	6.45
2	REAR BUMPER GROMMET SCREW @\$2.20 (DISC 25%)	NECESSARY	4.40	3.30
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.73
3	PAD, RR BUMPER, CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
10	CLIP, FLOOR UNDER COVER, NO.1 @\$2.60 (DISC 25%)	NECESSARY	26.00	19.50
10	CLIP, FLOOR UNDER COVER, NO.2 @\$3.20 (DISC 25%)	NECESSARY	32.00	24.00
1	TAIL GATE MOULDING LOWER GLASS, BACK (DISC 25%)	NECESSARY	19.70	14.78
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	COVER, REAR FLOOR UNDER CENTER (DISC 25%)	MISSING	222.60	166.95
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	END PANEL, COVER, DECK TRIM SERVICE HOLE (DISC 25%)	DEFORMED	47.00	35.25
1	FILLER, RR BUMPER, RH (DISC 25%)	DEFORMED	119.90	89.93
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	CRACKED	14.80	11.10
1	COVER, REAR FLOOR UNDER, LH (DISC 25%)	CRACKED	169.50	127.13
1	LENS & BODY, REAR COMBINATION LAMP, LH (DISC 10%)	CRACKED	438.10	394.29
1	LENS & BODY, REAR COMBINATION LAMP, RH (DISC 10%)	CRACKED	438.10	394.29
1	LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	CRACKED	486.80	438.12
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00

Report Ref No. NS/INC19004690/R1sd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	END PANEL SUBASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	END PANEL, COVER, DECK TRIM SERVICE	SERVICEABLE	47.00	-
1	END PANEL, COVER, DECK TRIM, REAR	SERVICEABLE	122.80	-
1	REINFORCEMENT ASSY, REAR FLOOR END PANEL,	SERVICEABLE	56.70	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	SPARE TYRE PANEL, PAN, REAR FLOOR	SERVICEABLE	564.80	-
1	BOARD, REAR FLOOR, NO.1	SERVICEABLE	502.20	-
1	BOX, DECK FLOOR, REAR	SERVICEABLE	102.20	-
1	BOX, DECK FLOOR, LH	SERVICEABLE	303.40	-
1	BOX, DECK FLOOR, RH	SERVICEABLE	304.00	-
1	TROUGH, BACK DOOR, LH	SERVICEABLE	99.80	-
1	PANEL SUB-ASSY, FENDER REAR LH	SERVICEABLE	824.80	-
1	TROUGH, BACK DOOR, RH	SERVICEABLE	99.80	-
1	PANEL SUB-ASSY, FENDER REAR RH	SERVICEABLE	824.80	-
1	FILLER, RR BUMPER, LH	SERVICEABLE	119.90	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	14.80	-
1	LENS & BODY ASSY, RR BUMPER, RH	SERVICEABLE	486.80	-
1	WIRE, LUGGAGE ROOM	SERVICEABLE	143.50	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	EXHAUST HEAT SHIELD INSULATOR, MAIN	SERVICEABLE	137.00	-
1	TAIL GATE LOCK ASSY, BACK DOOR	SERVICEABLE	452.10	-
1	TAIL GATE LOCK COVER, BACK DOOR	SERVICEABLE	25.30	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	SERVICEABLE	24.90	-

Report Ref No. NS/INC19004690/R1sd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL GATE DAM, BACK DOOR GLASS UPPER	SERVICEABLE	27.90	-
1	TAIL GATE MOULDING GLASS, BACK DOOR	SERVICEABLE	29.70	-
1	TAIL GATE MOULDING LOWER GLASS, BACK	SERVICEABLE	29.90	-
1	TAIL GATE MOULDING LOWER GLASS, BACK	SERVICEABLE	29.90	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	TAIL GATE WEATHERSTRIP, BACK	SERVICEABLE	360.70	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	PIPE ASSY, EXHAUST, TAIL	TO REPAIR SEE LABOUR	1,173.90	-
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR	TO REPAIR SEE LABOUR	929.60	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR SEE LABOUR	891.20	-
			14,828.40	3,276.87
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PIPE ASSY, EXHAUST, TAIL, TAIL GATE PANEL SUB-ASSY, BACK DOOR AND TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY.		1,433.00	400.00
	SPRAY PAINT.		3,312.00	800.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	40.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	60.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			6,105.00	1,420.00
	GRAND TOTAL		20,933.40	4,696.87

Report Ref No. NS/INC19004690/R1sd3e2

RECOMMENDED COST OF REPAIRS (CONFIRMED)			4,696.87
---	--	--	----------

Report Ref No. NS/INC19004690/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.