


ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: FBF 3751R Yr Regn: June 2011
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha T135 c.c. 135
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 63024 T/Radio: Insured / Std / NI / NA
 Eng/No: 5YP302887
 C/No: 5YP302887
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 80/90 R17
 R: 90/80 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO/YOKO or Bridgestone
 Front _____ Rear _____
 R/Bal. 2 mm R/Bal. 2 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 10/03/2019 D.O.I. 19/03/2019
 Survey held at SG 98 Motw AMK
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Road
 The UIC / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>First Capital BHB 20833</u>
<u>30/07/19</u>	<u>Journal 2/5 1400/- with 3 days of rep</u> <u>(Red: 1302, 43%)</u>

RECEIVED 01 AUG 2019

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) 30/7 Typist
 Date/Time, File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 2

2) _____
 Report Format: TP
 Lump Sum / I.B.I: (\$) 1400/-

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee:	<u>130</u>
Transportation:	<u>50</u>
3 + RS, SI	<u>50</u>
Photos	<u>58</u>
Others	
TOTAL	<u>288</u>

MOTOR SURVEY ASSIGNMENT

Date	12-03-2019	Our Ref No. D19001755MFSH
Accident Date	10-03-2019	Claim Type. Third Party
Insured Vehicle	SHB2083S	Third Party Vehicle. FBF3751R
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 0	Fax No. 64524868
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA

Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 18 March 2019

To : LKK

By Fax: 6256-4315

Attn: Bryan Ang

Tel: 97237799

VEHICLE NO : FBF 3751R
ACCIDENT DATE: 10 March 2019

Yamaha LC 135 Spark

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1 Fork Tube <i>distorted</i> / set	1 set	480.00	✓
2 Fork Oil Seal <i>new</i>	1 set	125.00	✓
3 Front Mudguard <i>broken</i>	1	195.00	✓
4 Handle Bar <i>set</i>	1	135.00	✓
5 Balancer <i>new</i>	1 set	85.00	X
6 Front Signal RH <i>new</i>	1	75.00	X
7 Front LH Side Panel <i>new</i>	1	135.00	X
8 Front Rim <i>distorted</i>	1	325.00	✓
9 Front Brake Disc <i>distorted</i>	1	195.00	✓
10 Footrest Rubber <i>new</i>	1	65.00	X
11 Footrest Bracket <i>new</i>	1	95.00	X
12 Gear Pedal - <i>new</i>	1	75.00	X
13 Front Brake Caliper - <i>new</i>	1	95.00	✓

@ 205.00 *Headlamp cover - monkey work* Sub-Total ✓ 2,080.00
 @ 195.00 *Handle Bar bracket repair* Less 10% 208.00
 Sub-Total X 1,872.00

1660.00

1494.00

VEHICLE NO : FBF 3751R

Yamaha LC 135 Spark

Nett Items

1	Rear box <i>NY</i>	280.00	X
2	Towing fee	40.00	30/-
3	Remove & replace necessary parts, align & etc	250.00	120/-
4	Remove & replace fork tube, fork oil seal, brake disc, front rim & re-align	200.00	80/-
5	Check electrical wiring & connection	60.00	30/-

260.00

Sub-Total	830.00
Nett Total	2,702.00 <i>3062</i>

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

1754.00
4/3 1400/-

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

19/03/2019 @ 1100hr

LIA Andrew

2/3 sum

you 3 days

2 kt And

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC19004713/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2083S	Veh. Inspected	FBF 3751R
Policy No.		Coverage (\$)	0.00
Claim No.	D19001755MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	14/03/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA T135	c.c	135
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	5YP302887	Colour	BLACK
Odometer	63024	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90 R17	BRIDGESTONE	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80 R17	BRIDGESTONE	2 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/03/2019	Inspection Date	19/03/2019
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 3751R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET FORK TUBE	DISTORTED / BENT	480.00	480.00
1	SET FORK OIL SEAL	NECESSARY	125.00	125.00
1	FRONT MUDGUARD	BROKEN	195.00	195.00
1	HANDLE BAR	BENT	135.00	135.00
1	SET BALANCER	NOT NECESSARY	85.00	-
1	FRONT SIGNAL RH	NOT NECESSARY	75.00	-
1	FRONT LH SIDE PANEL	NOT NECESSARY	135.00	-
1	FRONT RIM	DISTORTED	325.00	325.00
1	FRONT BRAKE DISC	DISTORTED	195.00	195.00
1	FOOTREST RUBBER	NOT NECESSARY	65.00	-
1	FOOTREST BRACKET	NOT NECESSARY	95.00	-
1	GEAR PEDAL	NOT NECESSARY	75.00	-
1	FRONT BRAKE CALIPER	NOT NECESSARY	95.00	-
1	HEADLAMP COVER	MOUNTING CRACKED	205.00	205.00
1	HANDLE BAR BRACKET	TO REPAIR SEE LABOUR	195.00	-
	LESS 10% DISCOUNT		-248.00	-166.00
			2,232.00	1,494.00
SPECIAL NETT ITEMS				
1	REAR BOX (SN)	NOT NECESSARY	280.00	-
			280.00	-
LABOUR				
	TOWING FEE.		40.00	30.00
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF HANDLE BAR BRACKET.		250.00	120.00
	REMOVE & REPLACE FORK TUBE,FORK OIL SEAL,BRAKE DISC,FRONT RIM & RE-ALIGN.		200.00	80.00
	CHECK ELECTRICAL WIRING & CONNECTION.		60.00	30.00
			550.00	260.00



GRAND TOTAL		3,062.00	1,754.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/FC119004713/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.