



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2015 NISSAN QASHQAI 2.0 (SJY9556D)
Date of Loss	4 March 2019
Time of Loss	4.25
Loss Description	SJY9556D (INSD) C/W SJF2284J (TP)
Comment	

Workshop Details

Total Rebate Amount	55336
Nett Loss Amount	\$12,664.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	SJY9556D	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="27/11/2015"/>
Mileage	<input type="text" value="50410"/>	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2015	<input type="text" value="2015"/>
Make	NISSAN	<input type="text" value="NISSAN"/>
		<input type="text"/>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	KATHRYN LYN UITERMARKT	<input type="text"/>
Date of Birth	5 August 1979	<input type="text" value="dd/mm/yyyy"/>

Model CATEGORY	QASHQAI 2.0 POLICY INFORMATION	QASHQAI 2.0 C INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	SJNFBAJ11U1517841	<input type="text" value="SJNFBAJ11U15"/>
Engine No	MR20380356W	<input type="text" value="MR20380356W"/>
Engine Capacity		<input type="text" value="1997"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="68000"/>

CATEGORY Age	FNOL INFORMATION 40	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date	1 January 2019	<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	34 ALMOND ST, 677689, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Female	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	G3408796U	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

19/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

20

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary















Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		MOULDING DOOR PAD (DISC 5%)	Damaged	0	251.56	No		20			201.25	Reviewing
		0	1		MOULDING DOOR PAD (DISC 5%)	Damaged	0	307.42	No		20			245.94	Reviewing
		0	1		FENDER ARC (DISC 5%)	Damaged	0	458.85	No		20			367.08	Reviewing
		0	1		MOULDING SASH FR (DISC 5%)	Necessary	0	95.66	No		20			76.53	Reviewing
		0	1		TAPE-FR DOOR, LH	Serviceable	0	0	No		20			0	Deny
		0	1		DOOR-FRONT LH	Repair	0	0	No		20			0	Deny
		0	1		REGULATOR-DOOR	Serviceable	0	0	No		20			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		MOULDING SASH	Serviceable	0	0	No		20			0	Deny
		0	1		TAPE-RR DOOR, LH (DISC 5%)	Necessary	0	28.4	No		20			22.72	Reviewing
		0	1		TAPE, RR DOOR, LH (DISC 5%)	Necessary	0	28.4	No		20			22.72	Reviewing
		0	1		DOOR-REAR LH (DISC 5%)	Bent	0	1049.56	No		20			839.65	Reviewing

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL (DISC 5%)	0	114	0	0	Reviewing	
		0		APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL (DISC 5%)	0	95	0	0	Reviewing	
		0		ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - PASSENGER (DISC 5%)	0	88.35	0	0	Reviewing	
		0		TRANSFER MECHANISM PART FOR FRONT & REAR DOOR LHS \$80X2 (DISC 5%)	0	76	0	0	Reviewing	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
				CONDUCT WHEEL BALANCING & RENEW S/RIM REAR LH SIDE (DISC 5%)	0	14.25	0	0	Reviewing	
				REPAIR REAR FENDER LH & ROCKER PANEL LH SIDE RENEW FRONT & REAR DOOR LH SIDE (DISC 5%)	0	831.25	0	0	Reviewing	
				S/PAINT FRONT & REAR DOOR LH, RR FENDER LH, ROCKER PANEL LH SIDE (DISC 5%)	0	665	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 6 DAYS	Reviewing	0		
		0	WHEEL ROAD ALU	Reviewing	1681.5	SCRATCHED	
		0	SUNDRIES	Reviewing	20	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$4,761.24		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$1,775.89					
Labour	\$0.00	\$1,883.85					
Miscellaneous	\$0.00	\$1,701.50					
Excess		-\$600.00					

Submit for Review