

ASS. REC. BY:

REF:

CS/FCE/19004730/Es ds

n2

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From Person: WS May chuan

of

FCE

Date/Time: 3:49pm @ 15/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 9575H

Insured:

SHC 8070J

at Workshop m/s

TEAMWORK

Tel:

G8442475

of

53 Ubi Ave 1 #01-24

Policy No:

Claim No:

DI90U1815MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/3/2019

18/3/2019

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

DS

Date/Time:

4:34pm @ 15/3/19

Person Contacted:

Damen

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBH 9575H - NA / INC 19004507 / 24

DOA: 12/3/19

SHC 8070J - NA / INC 19004507 / 24

DUA: 12/3/19

03/04/19

@ 17:26 p.m. revised PA to May via email.

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 9575H Yt Regn: 14/11/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 2982
 Truck / Trailer or
 Make: Toyota Dyna cc: 3.0
 Colour: Silver A/C Insured / Std / NI / NA
 Sp. Reading: 14507 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: K0Y2318035552
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 175/75R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 12/3/19 D.O.I. 1/4/19
 Survey held at Teamwork
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

26/04/19 CR reviewed - PLS proceed.

RECEIVED 26 APR 2019

26/04/19 confirmed L/S \$ 2,600/- @ 4 days with Steve
 (\$ 3,685.64 Red - 59%)

Date/Time, File Pass to:

26/04/19

4)

Typ: S

Date/Time, File Return to:

2)

Report Format:

Lump Sum / I.B.L: \$ 2,600/- L/S

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) S + R: \$

) Photos

) Other:

)

Total

144
50
35
230



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001815MFSH

Date: 03 April 2019

Our Ref: CS/FCI19004730/Esd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBH 9575H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/04/2019 at the premises of M/s Teamwork Garage Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,905.64</u>
Revised Estimate Amount	: S\$ <u>3,704.00</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Chen Tsue Yee
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	14-03-2019	Our Ref No. D19001815MFSH
Accident Date	12-03-2019	Claim Type. Third Party
Insured Vehicle	SHC8070J	Third Party Vehicle. GBH9575H
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	DARREN	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Steve Chen (LKK Auto)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Friday, April 26, 2019 9:12 AM
To: Steve Chen (LKK Auto)
Cc: TEAMWORK
Subject: FINALISED GBH9575H

Dear Sir,

We confirm COR @\$2600 and DOR @4 days.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 April 2019 5:26 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'; assignments
Cc: SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001815MFSH/1
Attachments: GBH 9575H - Preli Advise -.pdf

Dear May,

Enclosed preliminary revised of vehicle GBH 9575H.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 15 March 2019 4:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001815MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 18/03/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 15 March 2019 3:47 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001815MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1372C
Vehicle Details	
Vehicle No.:	GBH9575H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2821580
Chassis No.:	KDY2318035552
Maximum Power Output:	-
Open Market Value:	\$34,050.00
Original Registration Date:	14 Nov 2018
First Registration Date:	14 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$1,703.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,354.00
COE Rebate Amount:	\$29,181.00
Total Rebate Amount:	\$29,181.00

The information contained herein is correct as at 02 Apr 2019

OK





Steve (LKK) will provide Pte Ltd
1/4/19 5.40pm
L/S
Ry Afy Ry
34 days

First Capital Insurance Ltd
6 Raffles Quay.
Singapore 048580

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
3RD PARTY CLAIM ESTIMATION

Vehicle number	GBH9575H
Make / Model	TOYOTA/DYNA
Chassis number	KDY2318035552
Accident date	12 March 2019
Reference	1903-23

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	TAILGATE X R / DD	1910.80 / 1588	
2	TAILGATE LOWER BRACKET	304.70 X	
2	TAILGATE STOPPER X NA	55.00 X	
1	FLOOR PANEL STEP BRACKET X NA	298.10 X	
2	REAR TAILLAMP RH - BR	315.90 157.95	
2	TAILLAMP PANEL RH - DD	294.40 119.30	
2	TAILGATE HINGE RH - DD	105.00 80	
1	TAILGATE LOWER MEMBER - DD	485.90 /	
1	SPARE TYRE CARRIER X NA	385.22 X	
1	REAR EXHAUST X NA	850.00 X	
1	REAR EXHAUST MOUNTING X NA	42.50 X	
		5047.52	
		Less 25%	1261.88
		Subtotal	3785.64
		Balance C/F	3785.64
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
		Balance B/F	3785.64
1	70KM/H STICKER AEC	30.00 /	
1	6 PAX STICKER NEC	30.00 /	
1 SET	REVERSE SENSOR AEC NA	400.00 X	
		Subtotal	460.00 60
		Balance C/F	4245.64
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	Balance B/F	4245.64
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30	
2	REMOVE AND RENEW REVERSE SENSOR	150.00 X	
3	TRANSFER PARTS, ATACHMENT FROM OLD TAILGATE TO NEW	200.00 X	
4	PANEL BEATING ON AFFECTED AREAS	600.00	
5	SPRAY PAINTING ON AFFECTED AREAS	500.00 400	
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00	
		Subtotal	1660.00
		Grand total	5905.64
			6285.64

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify

The Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6285.64



Pte Ltd

First Capital Insurance Ltd
6 Raffles Quay.
Singapore 048580

(Supp.)

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
REPAIR PERFORMA INVOICE

Vehicle number	GBH9575H
Make / Model	TOYOTA/DYNA
Chassis number	KDY2318035552
Accident date	12 March 2019
Reference	1903-23

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	#REF!
1	TEL: 63583219 STICKER / NEC	80.00 /
2	EMAIL STICKER / NEC	200.00 160 /
1	DYNA STICKER / NEC	50.00 30 /
1	1500KG STICKER / NEC	50.00 30 /
	Subtotal	380.00
	Balance C/F	380.00

300 /



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004730/Esd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8070J	Veh. Inspected	GBH 9575H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001815MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	15/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KDY2318035552	Colour	SILVER	
Odometer	14507	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/75 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	175/75 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	175/75 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	175/75 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2019	Inspection Date	01/04/2019	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9575H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	DENTED	1,910.80	1,588.00
2	TAILGATE LOWER BRACKET	TO REPAIR SEE LABOUR	304.70	-
2	TAILGATE STOPPER	NOT NECESSARY	55.00	-
1	FLOOR PANEL STEP BRACKET	NOT NECESSARY	298.10	-
2	REAR TAILLAMP	O/S BROKEN	315.90	157.95
2	TAILLAMP PANEL	O/S DENTED	294.40	119.30
2	TAILGATE HINGE	O/S DENTED	105.00	80.00
1	TAILGATE LOWER MEMBER	DENTED	485.90	485.90
1	SPARE TYRE CARRIER	NOT NECESSARY	385.22	-
1	REAR EXHAUST	NOT NECESSARY	850.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	42.50	-
	LESS 25% DISCOUNT		-1,261.88	-607.79
			3,785.64	1,823.36
SPECIAL NETT ITEMS				
1	70KM/H STICKER (SN)	NECESSARY	30.00	30.00
1	6 PAX STICKER (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	400.00	-
1	TEL: 63583219 STICKER (SN)(ADDITIONAL)	NECESSARY	80.00	80.00
2	EMAIL STICKER (SN)(ADDITIONAL)	NECESSARY	200.00	160.00
1	DYNA STICKER (SN)(ADDITIONAL)	NECESSARY	50.00	30.00
1	1500KG STICKER (SN)(ADDITIONAL)	NECESSARY	50.00	30.00
			840.00	360.00
LABOUR				
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND RENEW REVERSE SENSOR.	NOT NECESSARY	150.00	-
	TRANSFER PARTS, ATACHMENT FROM OLD TAILGATE TO NEW.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF TAILGATE LOWER BRACKET.		600.00	550.00
	SPRAY PAINTING ON AFFECTED AREAS.		500.00	400.00

Report Ref No. CS/FCI19004730/Esd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	60.00
			1,660.00	1,040.00
	GRAND TOTAL		6,285.64	3,223.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/FC119004730/Esd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.