

10/1/2019

ASS. REC. BY

SAM Velay

Buo Qiang

REP CS3/ASM1900489/Gcd3er

d Instruction

ASSIGNMENT (Office)

From (Person)

of

ASM(CAXA)

Date/Time

16/3/2019

Estimated Cost

Bill to

OD/TP/AWS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No

CB7528C

Insured

SGH 6998C

at Workshop m/s

Inno Auto

Tel.

9838 8224

of

Blk 5 Defu lane 10 # 01-574

Policy No

Claim No

39M01H3Z

Sum Insured

Excess

Make of Veh.
(Client's Record)

D.O.A

15/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

Person Contacted

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

CB7528C-X.

SGH 6998C-X.

After repair: 20/3/2019

Insurance

GA

REF:

AXA

ASSIGNMENT

From:

Date: 18/3/2019

Veh No:

CB 7528C

Yr Regn:

1

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB7528C
at Workshop m/s INNO AUTO Pte Ltd
of BIK 5 Duta Inn 107 01-574

Make:

Toyota Hiace 3.0 c.c 2882

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

66590

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 195 R15

R: 11

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

6 days

Res.: Yes or No

D.O.A.

D.O.I.

18-03-19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

w/s

3pm

CA / REV / REP. / 24 HRS

651

Des. of Damages : Frt / Rear / O/S / NIS / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/3

No estimate & No. GIA

~~\$800 - \$1000~~ \$3000 - \$4000

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 6

1)

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

100

Date/Time, File Return to?

Transportation:

2)

Add Fee:

: Site Insp (\$

) \$ + RS. SI

: Interview (\$

) Photos

: Tech. Invs (\$

) Others

: Weekend (\$

)

Report Format : PRS

Lump Sum / I.B.I: (\$

TOTAL

100

◀ Service Request Details

Claim
S9M01H3Z

Reference
None ✎

Loss Date
March 15, 2019

SMART CLAIM

Report Date
Mar 15, 2019 1:57:58 PM

Have not call the workshop yet.

Request Date
March 15, 2019

XGO

Due Date
March 22, 2019

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

in

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
CB7528C

Model

UNKNONW

Service Address

...

Primary Contact/Insured

LEE WEI PING LOUIS ALOYSIUS
BLK 614B EDGEFIELD PLAINS, #15-301, 822614, Singapore

LOUIS_ALOYSIUS@YAHOO.COM.SG

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

INNO AUTO PTE LTD

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171 FAX: 6385 1141

Co. Regn. No. 201118053M

Date: 15.03.2019

To AXA Singapore Insurance Pte Ltd
Motor Claims Department
8 Shenton Way #24-01
AXA Tower
Singapore 068811

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no. **CB7528C** and vehicle(s) no. **SGH6998G** had taken place at / along **Bekok North Road** on date **15.03.2019** at time **09.28** hrs.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call Ms Tan at 98388224 to arrange.

Yours sincerely,

PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM19004809/Gcd3e2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 05-04-2019	
ATTN : WINNIE HO		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SGH 6998G	Veh. Inspected	CB 7528C
Policy No.		Coverage (\$)	0.00
Claim No.	S9M01H3Z	Excess (\$)	0.00
Assign From	WINNIE HO	Assign Date	16/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE 3.0	c.c	2982
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	SILVER
Odometer	66590 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	MICHELIN	6 mm
L/H Front Tyre	195 R15	MICHELIN	6 mm
R/H Rear Tyre	195 R15	MICHELIN	6 mm
L/H Rear Tyre	195 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information			
Accident Date	15/03/2019	Inspect Date / Time	18/03/2019 (03:00 PM)
Survey held at	INNO AUTO PTE LTD BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/ASM19004809/Gcd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.