

ASS. REC. BY:

REF:

CS/FC/19004832/RIS03/72

Special Instruction:

Surveyor

Regul

ASSIGNMENT (Office)

From (Person):

Henry Rao

of

FCI

Date/Time:

18/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 5073A

Insured:

SHC 7987A

at Workshop m/s

Shu Eatt

Tel:

6273 0119 Course

of

BLK 1099 # 01-90 Bukit Merah Lane 3

Policy No:

Claim No:

D190V1686/MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

19/3/19 - 9am - 11am

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

✓ Estimate

SLP 5073A x

SHC 7987A x

21/03/19

@ 10:30 a.m. received PA to Henry Rao via email.

ASSIGNMENT

From: _____ Date: 19/3/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 5023A

at Workshop m/s: Shu Fatt

of Blk 1009 # 01-90 Bkt Meriah lane

Insured: 3

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 9am-11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 36k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24HRS 'DS'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 5023A Yr Regn: 2008 APR

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CROSSROAD 1-8A c.c. 1799

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RT 1000141

Gen. Cond: Good Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65 R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PRUCEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 07/03/19 D.O.I. 19/03/19

Survey held at SHU FATT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/05/19	Confirmed LS \$ 4,300/- @ 7 days with Resul. (\$ 5,260.04 Red - 55%)
	MV - \$ 36k
	LTA - \$ 16,507.00
	Nett - \$ 19,493.00

RECEIVED 13 MAY 2019

Date/Time, File Pass to?

13/05/19

1) Typk

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 4,300/- HS)

170

50

50

47

,

317



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001686MFSH

Date: 21 March 2019

Our Ref: CS/FCI19004832/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 5023A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2019 at the premises of M/s Shu Fatt Auto Works and have the following to report:-

Workshop Estimate Amount	: S\$ 9,560.04 .
Revised Estimate Amount	: S\$ 1,880.00 .
"Check" Items Amount	: S\$ 532.80 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 7 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 06-03-2019 Our Ref No. D19001686MFSH

Accident Date 07-03-2019 Claim Type. Third Party

Insured Vehicle SHC7989R Third Party Vehicle. SLP5023A

Survey Location BLK 1009 #01-90 BUKIT MERAH LANE 3

Contact Person. CONNIE WONG

Contact No. 62730119/ 0 Fax No. 62707065

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop SHU FATT AUTO WORKS Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge HENRY KAO

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Friday, 10 May 2019 10:11 AM
To: Shirley Hiew (LKK Auto)
Subject: FW: SLP 5023 A - finalised


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Pat-Shu Fatt Auto Works [<mailto:shufatt@singnet.com.sg>]
Sent: Friday, 10 May, 2019 9:59 AM
To: Rasul (LKKAuto)
Subject: RE: SLP 5023 A - finalised

Hi Rasul,

Confirm COR lump sum \$4300.00 before GST.
7 days.

Thanks & regards,
Pat
Shu Fatt Auto Works

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Wednesday, 8 May, 2019 5:06 PM
To: Pat-Shu Fatt Auto Works
Subject: RE: SLP 5023 A - finalised

Hi Pat,

Can we close at 4300?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Pat-Shu Fatt Auto Works [<mailto:shufatt@singnet.com.sg>]
Sent: Monday, 15 April, 2019 2:01 PM
To: Rasul (LKKAuto)
Subject: SLP 5023 A - finalised

Dear Rasul,

Please see attached after paint photos and finalized calculations.
Cost of repair: lump sum \$4350.00 before GST.
7 days.

Thanks & regards,
Pat
Shu Fatt Auto Works

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 March 2019 10:30 AM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001686MFSH/1
Attachments: SLP 5023A - Preli Advise -.pdf

Dear Henry,

Enclosed preliminary revised of vehicle SLP 5023A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 18 March 2019 11:40 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001686MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that the vehicle currently not in the workshop and repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 18 March 2019 11:33 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001686MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	9031D
Vehicle Details	
Vehicle No.:	SLP5023A
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CROSSROAD 1.8 A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R18A3000210
Chassis No.:	RT11000141
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,080.00
Original Registration Date:	04 Apr 2008
First Registration Date:	04 Apr 2008
Transfer Count:	1
Actual ARF Paid:	\$20,080.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Apr 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$20,441.00
COE Rebate Amount:	\$16,507.00
Total Rebate Amount:	\$16,507.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Mar 2019

OK

36,000
16,507

19,493



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo

7th March 2019

TP11

SEP 5023 A HONDA CROSSROAD

Spare Parts

1	Rear boot.	7A /	1347.90	
1	Rear boot logo.	acc /	38.50	
1	Rear boot "CrossRoad" emblem.	acc /	68.70	
1	Rear boot lock.	new bt /	129.20	
1	Rear boot rubber.	acc /	185.40	
1	Rear boot inner garnish.	acc /	380.10	
1	Rear boot lower garnish.	acc /	535.20	
1	Set rear boot lower garnish clips.	acc /	35.00	
1	Rear boot inner garnish handle.	MIS /	38.50	
1	Rear windscreen moulding.	acc /	112.50	
2	Rear tail lights.	@ \$453.20 X 2	906.40	
2	Rear tail light holders.	@ \$190.80 X 2	381.60	
1	Rear support panel.	repair /	540.70	
1	Rear panel inner garnish.	? X acc	X 255.70	
1	Set rear panel inner garnish clips.	acc /	35.00	
1	Rear bumper.	acc /	1150.70	
1	Rear bumper reinforcement.	? X acc	X 270.60	
2	Rear bumper brackets.	@ \$38.70 X 2	77.40	
1	Set rear bumper clips.	acc /	42.00	
2	Rear bumper side retainers.	@ \$35.80 X 2	X 71.60	
1	Rear bumper tow cover.	MIS /	35.90	
1	Rear bumper reflector.	MIS /	59.50	
1	Rear number plate lights.	? X acc	X 68.10	
1	Rear exhaust.	X acc	920.20	
2	Rear exhaust holders.	@ \$28.70 X 2	57.40	
1	Rear windscreen inner seal.	acc /	45.00	Snet
1	Rear windscreen sealant.	acc /	55.00	Snet
1	Rear number plate.	acc /	55.00	Snet

Less 20% : 1548.76

Labour

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, rear lower member, left rear fender, rt rear fender, left rear fender inner panel, rt rear fender inner panel, renew rear boot, rear support panel, rear lights, rear bumper, rear exhaust and assembly.
To respray damaged parts.
To remove, replace rear windscreen.
To remove rear garnishes, carpets, upholstery, seats to facilitate repairs and assembly.
To reseal joint, reinsulate, anti rust panels and assembly.

6350.04
1350.00 800
1350.00 800
180.00 200
180.00 80
150.00 80
9560.04

Yokohama
RT1- 1000141
129832

215/65R16

LKK Auto Consultancy
the Repairer of the following:
• To resurvey before repair
• To display damaged parts
• Parts prices are not to be exceeded
• Third party survey
• No alteration made to the original
• See attached photo of the car
Is subject to inspection by the relevant authority

Acknowledged by Repairer
Signature:
Date:



樹發汽車修理廠

SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
7th March 2010
TP11

SLP 5023 A HONDA CROSSROAD

Spare Parts

- | | | |
|---|-------------------------------------|--------------|
| 1 | Rear boot. | PA |
| 1 | Rear boot logo. | acc |
| 1 | Rear boot 'CrossRoad' emblem. | acc |
| 1 | Rear boot lock. | acc |
| 1 | Rear boot rubber. | acc |
| 1 | Rear boot inner garnish. | acc |
| 1 | Rear boot lower garnish. | acc |
| 1 | Set rear boot lower garnish clips. | acc |
| 1 | Rear boot inner garnish handle. | acc |
| 1 | Rear windscreen moulding. | acc |
| 2 | Rear tail lights. | @\$453.20 X |
| 2 | Rear tail light holders. | @\$190.80 X |
| 1 | Rear support panel. | repar |
| 1 | Rear panel inner garnish. | acc |
| 1 | Set rear panel inner garnish clips. | acc |
| 1 | Rear bumper. | acc |
| 1 | Rear bumper reinforcement. | ? |
| 2 | Rear bumper brackets. | @\$38.70 acc |
| 1 | Set rear bumper clips. | acc |
| 2 | Rear bumper side retainers. | @\$35.80 |
| 1 | Rear bumper tow cover. | acc |
| 1 | Rear bumper reflector. | acc |
| 1 | Rear number plate lights. | ? |
| 1 | Rear exhaust. | X |
| 2 | Rear exhaust holders. | @\$28.70 X |
| 1 | Rear windscreen inner seal. | acc |
| 1 | Rear windscreen sealant. | acc |
| 1 | Rear number plate. | 860 |

S\$
1347.90
38.50
68.70
129.20
185.40
380.10
535.20
35.00
38.50
112.50
906.40 X
381.60 X
540.70 X
255.70 X
35.00
1150.70
270.60 X
77.40
42.00
71.60 X
35.90
50.50
68.10 X
920.20 X
57.40 X
45.00 Sner
55.00 Sner
55.00 Sner

4271.50
202
3417.20

4575

Less 20%

7898.80
1548.76

6350.04
1358.00

800

1350.00 800
180.00 20
180.00 80

150.00 80

9560.04

1880

Passive
Hp 90010088
7 days
H/S
19/03/19 @ 1100hrs
Respray after repair

Parts: 4271.50
-20%: (854.30)

3417.20
Sner: 145.00

3562.20

Labour: 1880.00

Labour

5442.20

-20%: (1088.44)

4353.76

H/S: 4350

4300

2 days

Yokohama
RT1- 1000141
129832

21565R10

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, rear lower member, left rear fender, rt rear fender, left rear fender inner panel, rt rear fender inner panel, renew rear boot, rear support panel, rear lights, rear bumper, rear exhaust and assembly.
To respray damaged parts.
To remove, replace rear windscreen.
To remove rear garnishes, carpets, upholstery, seats to facilitate repairs and assembly.
To reseal joint, remulstate, anti rust panels and assembly.

LKK Auto Consu
the Repairer

- To resurvey before
- To display
- Parts
- Third party
- To
- To
- To
- To

Acknowledged by Repairer
Signature:
Date:

19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19004832/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7989R	Veh. Inspected	SLP 5023A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001686MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	18/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CROSSROAD 1.8 A	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RT11000141	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R16	FALKEN	6 mm	
L/H Front Tyre	215/65 R16	FALKEN	6 mm	
R/H Rear Tyre	215/65 R16	FALKEN	6 mm	
L/H Rear Tyre	215/65 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/03/2019	Inspection Date	19/03/2019	
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5023A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT	BENT	1,347.90	1,347.90
1	REAR BOOT LOGO	NECESSARY	38.50	38.50
1	REAR BOOT "CROSS ROAD" EMBLEM	NECESSARY	68.70	68.70
1	REAR BOOT LOCK	BENT	129.20	129.20
1	REAR BOOT RUBBER	NECESSARY	185.40	185.40
1	REAR BOOT INNER GARNISH	SCRATCHED	380.10	380.10
1	REAR BOOT LOWER GARNISH	DEFORMED	535.20	535.20
1	SET REAR BOOT LOWER GARNISH CLIPS	NECESSARY	35.00	35.00
1	REAR BOOT INNER GARNISH HANDLE	MISSING	38.50	38.50
1	REAR WINDSCREEN MOULDING	NECESSARY	112.50	112.50
2	REAR TAIL LIGHTS @\$453.20	NOT NECESSARY	906.40	-
2	REAR TAIL LIGHT HOLDERS @\$190.80	NOT NECESSARY	381.60	-
1	REAR SUPPORT PANEL	TO REPAIR SEE LABOUR	540.70	-
1	REAR PANEL INNER GARNISH	SERVICEABLE	255.70	-
1	SET REAR PANEL INNER GARNISH CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER	DEFORMED	1,150.70	1,150.70
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	270.60	-
2	REAR BUMPER BRACKETS @\$38.70	NECESSARY	77.40	77.40
1	SET REAR BUMPER CLIPS	NECESSARY	42.00	42.00
2	REAR BUMPER SIDE RETAINERS @\$35.80	NOT NECESSARY	71.60	-
1	REAR BUMPER TOW COVER	MISSING	35.90	35.90
1	REAR BUMPER REFLECTOR	MISSING	59.50	59.50
1	REAR NUMBER PLATE LIGHTS	SERVICEABLE	68.10	-
1	REAR EXHAUST	NOT NECESSARY	920.20	-
2	REAR EXHAUST HOLDERS @\$28.70	NOT NECESSARY	57.40	-
	LESS 20% DISCOUNT		-1,548.76	-854.30
			6,195.04	3,417.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	45.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	55.00	55.00

Report Ref No. CS/FCI19004832/R1sd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	BROKEN	55.00	45.00
			155.00	145.00
	LABOUR			
	TO KNOCK,STRAIGHTEN REAR INNER PANEL,REAR LOWER PANEL,REAR SIDE PANEL,REAR FLOOR BOARD,REAR SPARE WHEEL BASE,REAR LOWER MEMBER,LEFT REAR FENDER,RT REAR FENDER,LEFT REAR FENDER INNER PANEL,RT REAR FENDER INNER PANEL,RENEW REAR BOOT,REAR SUPPORT PANEL,REAR LIGHTS,REAR BUMPER,REAR EXHAUST AND ASSEMBLY.INCLUSIVE OF THE REPAIR OF REAR SUPPORT PANEL.		1,350.00	800.00
	TO RESPRAY DAMAGED PARTS.		1,350.00	800.00
	TO REMOVE,REPLACE REAR WINDSCREEN.		180.00	120.00
	TO REMOVE REAR GARNISHES,CARPETS,UPHOLSTERY, SEATS TO FACILITATE REPAIRS AND ASSEMBLY.		180.00	80.00
	TO RESEAL JOINT,REINSULATE,ANTI RUST PANELS AND ASSEMBLY.		150.00	80.00
			3,210.00	1,880.00
GRAND TOTAL			9,560.04	5,442.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/FCI19004832/R1sd3n2

MARKET VALUE: \$36,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$16,507.00=NETT VALUE: \$19,493.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.