Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19004837/AGA3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994310

Claimant SI V9173S Insured Vehicle No: SKO194D

Vehicle No: SLV9173S Insured Vehicle No: SKQ194D

Date of Loss: 13/03/2019 Nature of Claim: TP Claim No: 1709935232SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV9173S

 Make & Model:
 BMW M3, 3.0 (A)
 Engine No:
 20444544S65B40A

 Reg. Date:
 26/10/2009 (Man. Year: 2009)
 Chassis No:
 WBSWD92000PY38626

Colour: White Odometer: 84721 km

Engine Capacity: 3999 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35 R19 Rear Tyre Size: 265/35 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,268.30	8,532.65	9,735.65	53.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,590.00	1,380.00	34.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,238.30	11,122.65	11,115.65	49.98
Approved Total (Overridden) (S\$)		8,900.00		
(S\$)	22,238.30	8,900.00	13,338.30	59.98
+ GST 7.00/7.00% (S\$)	1,556.68	623.00	933.68	59.98
Nett Amount (S\$)	23,794.98	9,523.00	14,271.98	59.98
+ Car Rental (7.0 x S	60.50/day) (S\$)	1,123.50		
	(S\$)	10,646.50		
Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$) Global Sum Settlement (S\$)		5,323.25		
		7.45		
		5,330.70		
		5,400.00		

INSPECTION

Date of Assignment: 15/03/2019

Date Inspected: 15/03/2019 Inspected At: MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B,

Adjuster Report Page 2 of 4

VICOM Inspection Centre Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT DOOR RH	Repair	2,550.80 F	*-FL
1		*REAR FENDER RH	Dented	3,688.50 F	*1,980.00 FL
1		*REAR FENDER QUARTER GLASS MOULDING RH	Necessary	214.00 F	*214.00 FL
1		*REAR LOWER ARM RH	Bent	769.50 F	*605.00 FL
1		*REAR UPPER ARM RH	Bent	550.00 F	*450.00 FL
1		*REAR STAY BAR RH	Bent	102.10 F	*102.10 FL
1		*REAR STEERING CONTROL ARM RH	Not Necessary	486.05 F	*- FL
1		*REAR SHOCK ABSORBER	Not Necessary	980.00 F	*-FL
1		*REAR KNUCKLE ARM RH	Bent	1,101.70 F	*1,101.70 FL
1		*REAR KNUCKLE BEARING WITH HUB RH	Damaged	300.15 F	*300.15 FL
1		*SIDE SKIRT RH	Deformed	1,050.00 F	*785.00 FL
1		*REAR BUMPER	Torn	1,988.50 F	*1,728.00 FL
1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	187.00 F	*-FL
1		*SET SIDE SKIRT CLIPS	Necessary	30.00 FS	*30.00 FS
1		*SET REAR BUMPER CLIPS	Not Necessary	20.00 FS	*-FS
1		*REAR WHEEL TYRE RH	Not Necessary	850.00 FS	*-FS
1		*REAR WHEEL RIM RH	Cut	1,600.00 FS	*1,000.00 FS
1		*COATING	Necessary	1,800.00 FS	*600.00 FS
ınchise	part. S=Spc	Nett. L=ListItemDisc.			
			, ,	•	8,895.95
		- List Item Discount on L Items	0.00/5.00% (S\$)	0.00	363.30
			Total Parts (S\$)	18,268.30	8,532.65
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*FRONT DOOR RH *REAR FENDER RH *REAR FENDER QUARTER GLASS MOULDING RH *REAR LOWER ARM RH *REAR UPPER ARM RH *REAR STAY BAR RH *REAR STEERING CONTROL ARM RH *REAR SHOCK ABSORBER *REAR KNUCKLE ARM RH *REAR KNUCKLE BEARING WITH HUB RH *SIDE SKIRT RH *SIDE SKIRT RH *REAR BUMPER *REAR BUMPER SIDE RETAINER RH *SET SIDE SKIRT CLIPS *SET REAR BUMPER CLIPS *REAR WHEEL TYRE RH *REAR WHEEL TYRE RH *REAR WHEEL RIM RH *COATING **COATING **COATING	1 *FRONT DOOR RH 1 *REAR FENDER RH Dented 1 *REAR FENDER QUARTER GLASS MOULDING RH 1 *REAR LOWER ARM RH Bent 1 *REAR UPPER ARM RH Bent 1 *REAR STAY BAR RH Bent 1 *REAR STEERING CONTROL ARM RH Not Necessary 1 *REAR SHOCK ABSORBER Not Necessary 1 *REAR KNUCKLE ARM RH Bent 1 *REAR KNUCKLE BEARING WITH HUB RH Damaged 1 *SIDE SKIRT RH Deformed 1 *REAR BUMPER Torn 1 *REAR BUMPER SIDE RETAINER RH Not Necessary 1 *SET SIDE SKIRT CLIPS Necessary 1 *SET REAR BUMPER CLIPS Not Necessary 1 *REAR WHEEL TYRE RH Not Necessary 1 *REAR WHEEL TYRE RH Not Necessary 1 *REAR WHEEL TYRE RH Not Necessary 1 *REAR WHEEL RIM RH Cut 1 *COATING Necessary nuchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$)	1 *FRONT DOOR RH Repair 2,550.80 F 1 *REAR FENDER RH Dented 3,688.50 F 1 *REAR FENDER QUARTER GLASS MOULDING RH Necessary 214.00 F 1 *REAR LOWER ARM RH Bent 769.50 F 1 *REAR UPPER ARM RH Bent 550.00 F 1 *REAR STAY BAR RH Bent 102.10 F 1 *REAR STEERING CONTROL ARM RH Not Necessary 486.05 F 1 *REAR SHOCK ABSORBER Not Necessary 980.00 F 1 *REAR KNUCKLE ARM RH Bent 1,101.70 F 1 *REAR KNUCKLE BEARING WITH HUB RH Damaged 300.15 F 1 *SIDE SKIRT RH Deformed 1,050.00 F 1 *REAR BUMPER Torn 1,988.50 F 1 *REAR BUMPER SIDE RETAINER RH Not Necessary 30.00 FS 1 *SET REAR BUMPER CLIPS Not Necessary 20.00 FS 1 *REAR WHEEL TYRE RH Not Necessary 850.00 FS 1 *REAR WHEEL RIM RH Cut <

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	1,000.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	100.00	50.00
4	REMOVE AND REFIX REAR UNDERCARRIAGE	New	450.00	280.00
5	FOUR WHEEL ALIGNMENT	New	100.00	80.00
6	TUFF COAT	New	150.00	80.00
7	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	130.00	100.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	240.00	0.00
	Gross Labour	3,970.00	2,590.00	
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >