Shiau Chan (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Thursday, 24 January 2019 4:30 PM

To:

Shiau Chan (LKKAuto)

Cc:

FW: <Request for the Survey Report> TCS REF: AAD1308-218--Accident involving

Subject:

SHC1233C & SHD5772G on 21.08.13

Attachments:

image002.wmz; image006.wmz; SHD5772G 21.08.13 - GIA.pdf; AAD1308-218 -ESTIMATE MARKING.pdf; IMG_1188.JPG; IMG_1199.JPG; IMG_1206.JPG; IMG_

1214.JPG; IMG_1211.JPG

WITHOUT PREJUDICE

Dear Shiau Chan

Any updates for the survey report.

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Ng Wai Yin [mailto:waiyin.ng@transcab.com.sg]

Sent: Friday, 11 January, 2019 10:39 AM

To: 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>

Subject: < Request for the Survey Report > TCS REF: AAD1308-218--Accident involving SHC1233C & SHD5772G on Cc: 'calvin.er' <calvin.er@transcab.com.sg>

21.08.13

WITHOUT PREJUDICE

Dear Shiau Chan

Refer to our tele-conversation moment ago, we request for a copy of the survey report for out taxi SHD 5772G.

Enclosed is our GIA report and estimate marking for your attention.

Thank You very much Best Regards, Ng Wai Yin Finance Department

Shiau Chan (LKKAuto)

From:

calvin.er <calvin.er@transcab.com.sg>

Sent:

Tuesday, 26 March 2019 1:20 PM

To:

Shiau Chan (LKKAuto); Kenneth Kong (LKKAuto)

Cc:

'Ng Wai Yin'; jasminetan@transcab.com.sg; claims@transcab.com.sg

Subject:

RE: <Request for the Survey Report> TCS REF: AAD1308-218--Accident involving

SHC1233C & SHD5772G on 21.08.13

Attachments:

image002.emz; image013.emz; image017.emz; image018.emz; image019.wmz;

image022.wmz

Dear Shiau Chan

Date of registration 29.10.10

Thank You Best Regards, Calvin Er Finance Department TEL: 6603 1265 Ext.307

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Tuesday, 26 March, 2019 1:11 PM

To: calvin.er <calvin.er@transcab.com.sg>; Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

Cc: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; jasminetan@transcab.com.sg; claims@transcab.com.sg

Subject: RE: <Request for the Survey Report> TCS REF: AAD1308-218--Accident involving SHC1233C & SHD5772G on 21.08.13

Dear Calvin,

Kindly advise the date of registration of SHD 5772G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: calvin.er < calvin.er@transcab.com.sg>

Sent: Friday, 15 March 2019 8:46 AM

To: Kenneth Kong (LKKAuto) < KennethKong@lkkauto.com >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- nsurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	ACCIDENT STATEMENT	
Date Of Report	22/08/2013 11:22	
Date Of Accident	21/08/2013 13:30	
Exact Location Of Accident	Tampines Ave 8 X Tamines St 84	
Exact Education of Figure 1	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD5772G	
Insured/Policyholder		
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD	
Co Peg No	200303878K	

Vehicle Particulars

Co Reg No

TOYOTA Manufacturer WISH-2.0 (A) Model Exact Purpose for which vehicle was being used Hire and Reward

at time of accident Are you claiming under your own insurance policy No

for repair to your vehicle?

Third Party If No, Please state action to be taken Taxi Vehicle Category

Insurance Company

First Capital Insurance Ltd Name of Insurance Company

Third Party Type Of Coverage Yes

Fleet Policy D-12047359MFSH Policy Number

Cover Note Number

Driver

MUHAMMAD NOOR BIN ABDULLAH Name of Driver

S1519082E NRIC No 13/01/1962 Date Of Birth Outdoor Occupation 15/06/1990 Date Of Driving Pass

23 Years And 2 Months **Driving Experience**

Male Gender

(Local) +65-82765589 Mobile Number

Fax Number Contact Number

NOEMAIL **EMail Address**

BLK 351 CLEMENTI AVE 2

Address #03-49 120351 Postcode

Was driver an employee of the Insured's Company No.

Other - Hirer If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

7.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident Collision- Cross Junction

Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident?

Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

No

Details of Police Action

Was the accident reported to the police?

Yes

If Yes, Please state which Police Station

Police Station Name Clementi Neighbourhood Police Centre

ROAD: No. 20 Clementi Avenue 5 , POSTCODE: 129858 , COUNTRY:

Singapore

Police Station Contact TEL NO: 1800-8729999 - FAX NO: 67748639

Was notice of intended Prosecution given?

No

If Yes, against whom?

Police Station Address

Circumstances of Accident

Please refer to Police Report - T/20130821/4122

Are accident photos available for attachment?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC1233C
Vehicle Make/Model/Colour COMFORT TAXI

Details Of Properties

Name of Driver YUSOF

NRIC/Passport Number

Contact Number 90071237

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address


SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.

- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report here made available aforecast. TAMPINES ST 85 report being made available aforesaid.



Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

POEL Witnessed by Reporting Centre Personnel

Police Report Pg.1

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999

No. of Pedestrians Injured: NIL





1 of 3 Report No. T/20130821/4122

ate/Time R 1/08/2013 1	eport M	ade:	- 01	Vide Rep		IC ACCID		St 59	ation Dia	ry No.:
nformant's	-market at the	lors			A SCHOOL ST	1	Service Profession		Haman	Spirit I
Name of Info MUHAMMA ABDULLA	ormant: AD NOO H			120351	351 CLEMI	BNTI AVE	NUE 2 #03-	-49 S	SINGAPO	RE
D Type / ID NRIC NO / I	No.: \$151908	32E		Contact N Home/Of			Mobile/Pa	iger:	8276558	9
Nationality: SINGAPOR	E CITIZ	EN		Email:						
Sex: Male	Age:	Date of I 13/01/19		Type of I Driver	nformant:	2415-2-12	upar M			
Race:		***		Language English			Institution	1 / Sc	hool Nan	ne:
Occupation: Taxi Driver				Driving I Class:	icence Infor	mation:	Date of E	xpir	y:	
eneral Info	rmatio	n of the Acci	dent	Aleks years as		12 A 17 B	新发展的		EN AREA	
Type of Ac		n of the Acci Injury Others	dent	13	Drink Drive: No	Date/Tim 21/08/20	e of Accide 13 13:30	nt:	Type of	Location
Type of Acc Location: Junction of TAMPINE: TAMPINE:	Road 1	Others and Road 2	dent	1	No		13 13:30			
Type of Acc Location: Junction of TAMPINE:	Road 1	Others and Road 2	dent	13	No		13 13:30	Road	1 Speed L	imit:
Type of Acc Location: Junction of TAMPINE: TAMPINE:	Road 1 S AVEN S STRE	Others and Road 2	dent	1	No rface:		13 13:30	Road	l Speed L	imit: ne:
Type of Acc Location: Junction of TAMPINE: TAMPINE: Weather: Traffic Flor	Road 1 S AVEN S STRE	Others and Road 2		Road Su	No rface:		13 13:30	Road Traf	1 Speed L	imit: ne:
Type of Acc Location: Junction of TAMPINE: TAMPINE: Weather: Traffic Flor Type of Co Between M	Road 1 S AVEN S STRE	Injury Others and Road 2 IUE 8 ET 84		Road Su	No rface:	21/08/20	13 13:30	Road Traf Any amb Yes	I Speed L fic Volum one convo- ulance:	imit: ne: eyed by
Type of Acc Location: Junction of TAMPINE: TAMPINE: Weather: Traffic Flor Type of Co Between M	Road 1 S AVEN S STRE w: Ullision: (oving V	Injury Others and Road 2 (UE 8 ET 84	d To Sid	Road Su Traffic (rface: Control:	21/08/20	13 13:30	Road Traf Any amb Yes	I Speed L fic Volum one convo ulance:	imit: ne: eyed by
Type of Acc Location: Junction of TAMPINE: TAMPINE: Weather: Traffic Flor Type of Co Between M	Road 1 S AVEN S STRE	Injury Others and Road 2 (UE 8 ET 84	d To Sid	Road Su Traffic (rface: Control:	21/08/20	13 13:30	Road Traf Any amb Yes	I Speed L fic Volum one convo ulance:	imit: ne: eyed by

Use of Pedestrian Crossing: NA

Police Report Pg.1

Police Station Of Origin: Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999





T/20130821/4122

2 of 3

Report No. T/20130821/4122

CONTINUATION OF REPORT

Driver Name	YUSOF		ID No.		NIL
Related Vehicle	SHC1233C (Taxi)		Contac	t No.	90071237
Hospital/Clinic	NIL	William Willia	Class of Drivin Licence Expiry	g e &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc		NIL	
No. of Days grant	ed Medical Leave (MC) NIL	Degree o	f Injury	NIL	THE RESERVE OF THE PARTY OF THE
Driver	MILE SECTION OF THE PERSON	SCOTTO PAREL	STATE OF THE PARTY.		S1519082E
Name	MUHAMMAD NOOR BIN ABD	ULLAH	ID No		S1319062E
Related Vehicle	SHD5772G (Taxi)		Conta	ct No.	NIL
Hospital/Clinic	NIL .		Class Drivin Licen Expir	ıg	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Dis		NIL	
	ted Medical Leave (MC) NIL	Degrees	f Injury	Sligh	of .

Brief Details.

On 21/08/13 at about 1330hrs, I was driving along Tampines Ave 8 towards Tampines St 81. I was driving along lane 1 approaching the juntion of Tampines St 84. I saw that the traffic light was green so I proceeded straight, When I was at the junction, I saw a taxi coming from my left side, from Tampines St 84. I tried to swerve to the right but the taxi still knocked onto the front left side of my taxi. My passenger was injured and conveyed to hospital by ambulance. I felt pain on few parts of my body but yet to see a doctor. The front of my taxi was badly damaged and was towed away.

Police Report Pg.1

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999





Report No. T/20130821/4122

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Singapore Police Force

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: D / YEO SEE YONG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date: 21/08/2013 16:46
Officer In Charge Of Case: TP / Contact No.:	Classification Of Case:
Authentication Stamp NP168 SN 037	



Traffic Police Department Charge Office 10 Ubi Avenue 3 Singapore 408865

: Muhd Noor Bin Abdullah : 7 20130821 4122 Name NP 168 No. : BK 357 Churchi ALZ \$05-49 Address : 21 3 15 @ 132040 Accident Date/Time s (120351) : SHC 1233 C Vehicle(s) Involved : SI519082E NRIC No SHD 57726 : 82765589 Tel No : 22/8/13 Date Dear Sir / Madam (To yoka taxo) Accident involving success (Tari) at 1550 on 2/8/15 along Tempines Are 3 + Fampiness remaines at \$4 (date) 1646 hours (time) make a With reference to the above, I have on 21/8/11 (Police Station/NPP/NPC) police report at Clementi In NP 168- T/ 3 20130821 4132 On 22 8 13 (date), 100 hours (time) at Chon Chu Kang (Police Station/NPP/NPC), I make the following amendments to the above report; I tried to sharve to the right but the taxi still bucked outs the front left side of my taxi, anxing my tari to sherve. After colliding on to my tari, the gent but sear of the tari hit the rear of my taxi , causing my taxi to move forward & hit and the traffic lights. I mished to state that at the point of accordent, the traffic lights were grown, in my know, And after the accident, the text reversal & moved forced tampines he & t stepped in the right Yours Faithfully, (Signature) FOR OFFICIAL USE

If a police officer recorded these amendments, please complete the following.

Name / Rank No Date and Time Station Dairy No

Signature

Page 7 of 13

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHD 5772G - III

Vehicle No.: Chassis No.: Vehicle Make: Vehicle Model: Date of Accident: Third Party Insurer: NOT Authorisal

LISmp 8

SHD 5772G · ROEL JTDGJ20W405002929* TOYOTA WISH 2.0 BI-FUEL 21,08,2013 III

		PART		LIST
			But	BALLAS 50505
1	1	Rear bumper	\$	383.30
2	1	Rear bumper stay LH	\$	02.00
3	1	Rear bumper side retainer LH	\$ \$	CM 68.76
4	1	Rear bumper side support LH	\$	She # 104.76 40 X
5	1	Rear bumper bracket LH	\$	R # 108,00 *
6	1	Rear bumper reflectors LH	***	In 66.00 X
7	1	Rear fender LH	\$	BT 1,216.32
8	1	Rear fender panel deck trim side LH	\$	5~ 738.00 X
9	1	Rear fender inner wheel house panel LH	\$	A 745.32 X
10	1	Rear fender side panel LH	\$	OD. 11 X
11	1	Rear fender air vent lourve LH	\$	Sm 104.04 x
12	1	Rear fender inner top gamish LH	\$	Sm 101.52 (
13	1	Rear fender inner cowling LH	\$	278.52 X
14	1	Rear fender rubber cover-big LH	\$	Su 14.52 K
15	1	Petrol tank filler pipe	\$	Sm 242.40 x
16	1	Petrol tank filler pipe - extension hose	\$	Sh 200.40 X
17	1	Tyre mechanical jack	\$	R 260.28 X
18	1	Tyre mechanical jack holder bracket	****	M 199.56 X
19	1	Front Bumper	\$	Allem 585.36
20	1	Front Bumper Lower Absorber	\$	mis 130.00 -
21	1	Front Bumper Reinforcement	\$	Ay 318.11 —
22	1	Front Bumper side support LH	\$	mil 76.20 -
23	1	Front Bumper side support RH	\$	m1 76.20
24	1	Front Bumper retainer RH	\$	CM 102.00 -
25	1	Front Bumper retainer LH	\$	CM 102.00 -
26	1	Front bumper centre grille	\$	cm 139.92 -
27	1	Front bumper lower grille	\$ \$ \$	M 129.36 -
28	1	Front bumper bracket LH	\$	By 108.00 —
29	1	Front bumper bracket RH	\$	A 108.00 —
30	1	Front bumper fog lamp outer chrome RH	\$	AN 190.00
31	1	Front bumper fog lamp outer chrome LH	*	190.00
32	1		\$ \$ \$	Mil 208.00
33	1	이 얼마나 가다니까? 그 아들이 아이가 있으면 이 가는 그렇게 아이를 가면 보세요?	\$	M13 208.00

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019826G SHD 5772G - III

U., P. U.	177			
34	1	Front bumper fog lamp grille RH	\$	150.00
35	1	Front bumper fog lamp grille LH	\$	Mis 150.00
+			\$	miy 100.00 -
36	1	Front bumper fog lamp protector grille Front tow hook bracket	*	R 47.28 X
37	1		***	Ar 1,222.32
38	1	Front support panel assy	\$	Br 95.49 -
39	1	Front brace panel	\$	Bn 672.00 -
40	1	Headlamp RH	\$	n 732.00 X
41	1	Headlamp RH inner panel	4	DIVA 67.56
42	1	Front headlamp bracket RH		Pro 672.00
. 43	1	Headlamp LH	\$ \$	R 732.00 X
44	1	Headlamp LH inner panel	Φ	Di7 67.56 -
45	1	Front headlamp bracket LH	\$	
46	1	Indicator light switch	\$	374.28 X Sh 86.57 7/
47	1	Front fuse box - top cover	\$	
48	1	Front fuse box lower cover	4	cm 150.28 X
49	1	Front fuse box centre junction	*	€ 48.00 X
50	1	Front fuse box centre cover	***	
51	1	Radiator assembly	\$	2,200.24
52	1	Radiator fan blade	\$	In 223.95 7
53	1	Radiator Fan Motor	\$	Sh 372.76 ₹
54	1	Radiator cowling	\$	CM 221.73 -
55	1	Radiator expansion tank	\$	pd 180.76 -
56	1	Radiator Grille	***	mi) 462.48
57	1	Aircon Fan Blade	\$	NJP 155.16 X
58	1	Aircon Fan Motor	\$	5/2./03
59	1	Fan Cowling	\$	
60	1	Shroud Fan	\$	0 271.00 /
61	1	Water pump	\$	434.04 /
62	1	Aircon condenser	\$	By 1,375.50
63	1	Aircon hose - condenser to evaporator	\$	216.00 7
64	1	Air-con blade	\$	NIP 169.22 X
65	1	Air cleaner assembly	\$	1,036.44 7
66	1	Air-cleaner intake duct	\$	Del 101.57 -
67	1	Air-cleaner intake hose	\$	199.42
68	1	Battery	\$	DU 240.00 50/sn
69	1	Fuse box top (cover)	\$	88.44 7
70	1	Fuse box lower	\$	84.24 7
71	1	Fuse box centre	\$	254.04 7
72	1	Fuse box centre cover	\$	238.32 7 Jux
73	1	Steering rack & pinion assy	\$	3,167.33 7
		T. 그리면 전에 가장이 되었다면 열면 보다 이번 없는 사람들이 있다면 있다면 사람들이 가장 없었다.	*****	246.50 ?
			\$	30.00 ₺
74 75	1 1	Steering rack end Steering rack & pinion bushing	\$ \$	

ROEL

6

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019626G SHD 5772G - III

			\$	A 55.14 X
76	1	Bracket-strg rack no 1 (\$10/12)	\$	n 37.42X
77	1	Bracket-strg rack no 2 (\$10/12)	э \$	Ju 127.44 %
78	1	Steering tie-rod end	\$	Su 1,679.76 X
. 79	1	Steering Wheel	\$	sh 1,921.32 x
80	1	Steering wheel assy	\$	BURY 2,480.52
81	1	Steering wheel air bag	\$	Nu 522.72
82	1	Steering Wheel air bag sensor	. \$	Nu 522.60 -
83	1	Steering Wheel air bag control unit	\$	Max 654.96 -
84	1	Dash Board air bag control unit	\$	1. 854.28 X
85	.1	Dash Board re-inforcement bar	\$	n 263.76 x
86	1	Dash Board re-inforcement pracket	\$	5~ 613.92 X
87	1	Dash Board lower fuse box assy	\$	558.00x
88	1	Front shock absorber assy RH	\$	Di' 620.57 3
89	1	Front lower arm LH		By 490.74 -
90	1	Front knuckle arm LH	\$ \$	Su 120.95x
91	1	Front strut bar	φ.	1 277.90 X
92.	1	Front strut bar bracket	**	5 441.12 Z
93	1	Front stabilizer bar	4	20.72 %
94	1	Front stabilizer bar bush	4	Th 862.20
95	1	Front Seat Belt RH	\$	CM 253.68
96	1	Front safety belt cover garnish LH	4	n 862.20
97	1	Front Seat Belt LH	\$	CM 253.68
98	1	Front safety belt cover garnish RH	\$	Bt 837.60
99	1	Front Fender LH	\$	Dr1 369.14
100	1	Front Fender Liner LH	\$	€~ 95.80 X
101	1	Front Fender indicator lamp LH	\$	By 714.86 -
102	1	Front fender inner wheel house panel LH	\$	Bu 837.60
103		Front Fender RH	\$	CA4 369.14 -
104	100	Front Fender Liner RH	\$	Sn 95.80 X
105		Front Fender indicator lamp RH	\$	K 714 86 V
106	20.0	Front fender inner wheel house panel RH	\$	Bu 1,019.16
107		Bonnet	\$	Cut 71.99 -
108			475334	Br 81.60 -
109)	Bonnet hinge RH	.00	BT 81.60 -
110) .	1 Bonnet hinge LH	4	NJP 194.36 X
111		1 Bonnet moulding	4	Bt 90.02 -
112		1 Bonnet lock	ф	Jm 53.32 -
113		1 Bonnet cable	ф	A17115.44
114		1 Bonnet centre 'TOYOTA' logo badge	i.P	In 854.28 X
11.		1 Rocker panel outer LH	D D	R = 150.00 × X
11	753	1 V-belt	***	CPA 1,406.64
11		1 Front Windscreen	P	~ · · · · · · · · · · · · · · · · · · ·

ROEL

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6586 FAX NO.6386 8862 CO/GST REG NO.201019826G SHD 5772G - III

S	HD 577	2G - I		2	New 150.00
	118	1	Front ERP unit MANIFOLD, INTAKE	\$ \$ t	n 16,629.60 7
	119	1	Gear box assy	P	1,454.28
	120 121	1	Gear hox cross member	\$	L 239.76 7
	122	1	Gear box cross member bracket	\$	349.68 3
	123	1	Gear box mounting	\$	R 9,512.81 ×
	124	1	Engine block	\$	厂 209.58 入
	125	1	Engine mounting side	\$	CRA 254.28
	126	1	Engine lower splashield cover	\$	Sn 350.04X
	127	1	Engine oil sump	\$	S~ 115.68 ℃
	128	1	Engine oil sump strainer	\$	CRA 178.20 -
	129	1	Engine splash cover RH	\$	CM 178.20
	130	1	Engine splash cover LH	\$	5~ 4,584.24 X
	131	1	ECU assy	\$	Ser 5,679.60 &
	132	1	ABS pump	\$	sn 82.08 X
	1.3.3	1	ABS pump pipe	· p	•

TOTAL \$	89,164.42
25% \$	22,291.11
\$	66,873.32

Specical Nett

1 set 6 10 1 4 6 1 2 2 8 3	Coporate logo - 6555-3333	*******	IN 300.00 X No. 21.60 X No. 36.00 No. 15.00 No. 14.40 X No. 21.60 X 190.00 7 No. 380.00 7 No. 450.00 / pass No. 18.00 X No. 18.00 X
1 брз	Coporate logo - 6555-3333	\$ \$	
4	Front Bumper fastener clip Radiator Grille clip	\$	Ma 18.00 —
6 10 1	Bonnet under weatherstrip seat clips	\$ \$	Ma 42.00 - By 50.00 mar 25500-

		OFFICES PTE LTD			ROEL
T	O.42 SUNGE	NO.201019626G			
	1115 017-	4		Φ.	NG 48.00305M
	1	Rear fender 1/4 glass inner spong	e seal	***	Na 72.00 40sn-
	1	Rear fender 1/4 glass sealant		\$	Ma 86.40 -
	1	Front Windscreen Moulding		\$	Mc 80.00 40sh
	1	Front windscreen sealant	120	A	ma 60.00 3asn
	1	Front windscreen inner sponge sec	al	ው ታ	Ma 40.00 2652
	1	Front ERP bracket		<i>\$</i>	AN FE 61.44 X
	1	Engine overhaul gasket			Am 20.00 X
	1	Engine oil sump sealant		D.	Na 12.00
	4	Engine splash cover clip RH	343	*	na 12.00 -
	4	Engine splash cover clip LH		\$	12.00
			TOTAL	*	2,340.04
			IOIAL	4	
		TO	AL PARTS	\$	69,213.36
		Panel Beating, Knocking And Stro The Necessary Portion, Remove A	na	20	04
		Renewal Of Parts, Adjust And Re	align The	\$	2400.00 8,400.00
	*	Same			5.
		Towing Fees.		\$	120.00 506
		To Check Electrical Lighting Coru	erned.	\$	170.00 60/
		To Remove And Refit Rear W/Sc To Facilitate Bodywork Repair.	reen Glass	\$	N~ 170.00 X.
	n	To dismantle and refit rear unde parts, final checking and testing	rcarriage	\$	380.00 7 18d
		Labour charge to mount and dis vehicle on jig bench, to facilitate	mount repair.	\$	380.00 250/
		To transfer of tailgate fittings ar water seepage test,	nd conduct	\$	NN 170.00 X
		Proof 1 of the Control of the Contro			104

TRANS-CAB AUTO SERVICES PTE LTD NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6866 FAX NO.6366 8862 CO/GST REG NO.201019626G SHD 5772G - III

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	NN 170.00 X
To dismantle and refit rear seat, backrest, trimings, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$	380.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00)
To reinstall rear bumper parking sensor.	\$	170.00 50/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	Rejected 380.00 X
To drop diesel/petrol tank, pipes, hoses and renew the necessary parts and final checking and testing for leak.	\$	440.00 601
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 2601
To remove and renew engine and gear box mounting.	\$	380.00 2801
To dismantle and refit engine cross-member and engine mounting.	\$	380.00
To lift-up engine with gear box and refit.	\$	440.00)
To remove and renew power steering pump, oil cooler pipe and final checking and testing	. \$	~~ 440.00 X
To remove and refit air bag system and reset.	\$	480.00 2 bol

TRANS-CAB AUTO SERVICES PTE LTD NO.42 SUNGEL KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862 CO/GST REG NO.201019626G SHD 5772G - III

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	Agreal 380.00 X
To conduct and perform a comprehensive engine diagnostic check.	\$	NN 380.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	. \$	270.00
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 /26/
Putty and spray painting of the affected portion.	\$	8,100.00 16001
To check ABS brake efficiency, final checking and testing.	\$	380.00 601
To remove and refit ABS pump relay to enable repair.	\$	N € 380.00 X
To rust-proofing of the affected areas.	\$	170.00 1501
To check steering geometry and computer wheel alignment	\$	220.00 601
To transfer of tire, rim and on wheel balancing.	\$	170.00 40L
To vacuum, replace, refix and recharge air condenser	\$	380.00 100[
To replace, refix and top up coolant for radiator	\$	170.00 501
To reseal sealant on gap	\$	120.00 801
. TOTA	L \$	25,500.00

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6368 8862 CO/GST REG NO.201019626G SHD 5772G - III

ROEL

Over All Total \$

94,713.36

Repair Days

20 DAYS

94443.36



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale	Des Experts En Automobile
Affiliated to redefation internation	TO STATE OF THE ST

TRANS-CAB AUTO SERVICES PTE LTD

Ref: CS/TP19004865/Kqd3e2

NO.2 ANG MO KIO STREET 63SINGAPORE 569111 Date: 02-04-2019



J.2 ANO INC 113 011	REET 635INGAPORE 509	Code: TP378	
	Delley Portious	ars :- THIRD PARTY CLA	MIM
	Policy Particula	Veh. Inspected	SHD 5772G
Insured Veh.		Coverage (\$)	0.00
Policy No.		Excess (\$)	0.00
Claim No.		Assign Date	22/08/2013
Assign From	W 11 1- D	articulars & Condition	CONTRACTOR OF THE PARTY OF THE
		The second secon	1987
Make & Model	TOYOTA WISH (A)	c.c Year of Reg.	2010
Engine No.	HIDDEN		RED
Chassis No.	JTDGJ20W405002929	Colour	IN ORDER
Odometer	236488		NIL
Brakes	IN ORDER	Modification	,,,,,
General	GOOD		
3.	Co	nditions of Tyres	Balance
	Size	Make	6 mm
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	O IIIII
4.	Desc	cription of Damages	AD DODTION
THE VEHICLE S	USTAINED DAMAGES AT TH	IE N/S FRONT AND N/S RE	AR PORTION.
DAMAGES SEE	DETAILS.		
5.	Ge	eneral Information	
Accident Date	21/08/2013	Inspection Date	22/08/2013
Survey held at	THE PERSON NAMED IN	/ICES PTE LTD	
	NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.		Remarks	DACIC
	TION WAS CONDUCTED ON NCE TO YOUR INSTRUCTION	NO, WE THE TO THE	DRISED REPAIRS.
5b.	Est	imate Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR	R: 15 Workin	g Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5772G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
20120	REPLACEMENT OF PARTS			585.36
- 1	REAR BUMPER	BUCKLED	585.36	505.30
	REAR BUMPER STAY LH	SERVICEABLE	82.08	
	REAR BUMPER SIDE RETAINER LH	CRACKED	68.76	100000000000000000000000000000000000000
	REAR BUMPER SIDE SUPPORT LH	SERVICEABLE	104.76	1
	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	108.00	
-	REAR BUMPER REFLECTORS LH	SERVICEABLE	66.00	10000
	REAR FENDER LH	BENT	1,216.32	S I I I I I I I I I I I I I I I I I I I
1	REAR FENDER PANEL DECK TRIM SIDE LH	SERVICEABLE	738.00	
1	REAR FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	745.32	
1	REAR FENDER SIDE PANEL LH	TO REPAIR SEE LABOUR	82.4	
	REAR FENDER AIR VENT LOURVE LH	SERVICEABLE	104.0	**
	REAR FENDER INNER TOP GARNISH LH	SERVICEABLE	101.5	2
	1 REAR FENDER INNER COWLING LH	SERVICEABLE	278.5	
	1 REAR FENDER RUBBER COVER-BIG LH	SERVICEABLE	14.5	(表)
	1 PETROL TANK FILLER PIPE	SERVICEABLE	242.4	
	1 PETROL TANK FILLER PIPE - EXTENSION HOSE	SERVICEABLE	200.4	
	1 TYRE MECHANICAL JACK	TO REPAIR SEE LABOUR	260.2	
	1 TYRE MECHANICAL JACK HOLDER BRACKET	TO REPAIR SEE LABOUR	199.5	197,000 53
	TO OUT DUMPER	BENT / CRACKED	585.3	200
	1 FRONT BUMPER	MISSING	130.0	00 130.0
	1 FRONT BUMPER LOWER ABSORBER 1 FRONT BUMPER REINFORCEMENT	BENT	318.	11 318.
	1 FRONT BUMPER SIDE SUPPORT LH	MISSING	76.	
	1 FRONT BUMPER SIDE SUPPORT RH	MISSING	76.	723
	1 FRONT BUMPER RETAINER RH	CRACKED	102.	3113
	1 FRONT BUMPER RETAINER LH	CRACKED	102.	500
	1 FRONT BUMPER CENTRE GRILLE	CRACKED	139	
		CRACKED	129	5.55
	1 FRONT BUMPER LOWER GRILLE	BENT	108	
	1 FRONT BUMPER BRACKET LH	BENT	108	.00 108
	1 FRONT BUMPER BRACKET RH 1 FRONT BUMPER FOG LAMP OUTER CHROME RH	MISSING	190	.00 190



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	FRONT BUMPER FOG LAMP OUTER CHROME LH	MISSING	190.00	190.00
	FRONT BUMPER FOG LAMP RH	MISSING	208.00	208.00
	FRONT BUMPER FOG LAMP LH	MISSING	208.00	208.00
	FRONT BUMPER FOG LAMP GRILLE RH	MISSING	150.00	150.00
	FRONT BUMPER FOG LAMP GRILLE LH	MISSING	150.00	150.00
	FRONT BUMPER FOG LAMP PROTECTOR GRILLE	MISSING	100.00	100.00
	FRONT TOW HOOK BRACKET	TO REPAIR SEE LABOUR	47.28	200440000
1	FRONT SUPPORT PANEL ASSY	BENT	1,222.32	1,222.32
	FRONT BRACE PANEL	BENT	95.49	95.49
	HEADLAMP RH	BROKEN	672.00	672.0
- 85	HEADLAMP RH INNER PANEL	TO REPAIR SEE LABOUR	732.00	januari v
- 1	FRONT HEADLAMP BRACKET RH	DISTORTED	67.56	67.5
	HEADLAMP LH	BROKEN	672.00	672.0
	HEADLAMP LH INNER PANEL	TO REPAIR SEE LABOUR	732.00	
8	FRONT HEADLAMP BRACKET LH	DISTORTED	67.56	67.5
	INDICATOR LIGHT SWITCH	SERVICEABLE	374.28	3
	FRONT FUSE BOX - TOP COVER	SERVICEABLE	86.5	7
	FRONT FUSE BOX LOWER COVER	SERVICEABLE	150.28	3
	FRONT FUSE BOX CENTRE JUNCTION	CRACKED	196.13	196.1
	1 FRONT FUSE BOX CENTRE COVER	SERVICEABLE	48.0	The statement of the st
	1 RADIATOR ASSEMBLY	BENT	2,268.2	4 2,268.2
	1 RADIATOR FAN BLADE	SERVICEABLE	223.9	5
	1 RADIATOR FAN MOTOR	SERVICEABLE	372.7	91
	1 RADIATOR COWLING	CRACKED	221.7	
	1 RADIATOR EXPANSION TANK	DENTED	180.7	S. Comment
	1 RADIATOR GRILLE	MISSING	462.4	
	1 AIRCON FAN BLADE	NO SUCH PARTS	155.1	6
	1 AIRCON FAN MOTOR	NO SUCH PARTS	372.7	6
	1 FAN COWLING	NO SUCH PARTS	228.4	8
	1 SHROUD FAN	NO SUCH PARTS	241.0	
	1 WATER PUMP	SERVICEABLE	434.0	300000000
	1 AIRCON CONDENSER	BENT	1,375.5	
	1 AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	216.0	
	1 AIR-CON BLADE	NO SUCH PARTS	169.2	22



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

ty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	THE ACCEMBLY	SERVICEABLE	1,036.44	10 <u>2</u> 10000 (0.00
	AIR CLEANER ASSEMBLY	DENTED	101.57	101.57
	AIR-CLEANER INTAKE DUCT	CRACKED	199.42	199,42
- 10	AIR-CLEANER INTAKE HOSE	SERVICEABLE	88.44	372
	FUSE BOX TOP (COVER)	SERVICEABLE	84.24	
	FUSE BOX LOWER	SERVICEABLE	254.04	
	FUSE BOX CENTRE	SERVICEABLE	238.32	2
1	FUSE BOX CENTRE COVER	SERVICEABLE	3,167.33	3
1	STEERING RACK & PINION ASSY	SERVICEABLE	246.50	o l
	STEERING RACK END	SERVICEABLE	30.00	D
	STEERING RACK & PINION BUSHING BRACKET-STRG RACK NO 1 (S10/12)	TO REPAIR SEE	55.1	4
4	BRACKET-STRG RACK NO2 (S10/12)	TO REPAIR SEE	37.4	
10	STEERING TIE-ROD END	SERVICEABLE	127.4	
	STEERING WHEEL	SERVICEABLE	1,679.7	6
	STEERING WHEEL ASSY	SERVICEABLE	1,921.3	T1111111111111111111111111111111111111
	1 STEERING WHEEL AIR BAG	BURST	2,480.5	25
	1 STEERING WHEEL AIR BAG SENSOR	NECESSARY	522.7	
	1 STEERING WHEEL AIR BAG CONTROL UNIT	NECESSARY	522.6	160
	1 DASH BOARD AIR BAG CONTROL UNIT	NECESSARY	654.9	654.9
	1 DASH BOARD RE-INFORCEMENT BAR	TO REPAIR SEE LABOUR	854.2	
	1 DASH BOARD RE-INFORCEMENT BRACKET	TO REPAIR SEE LABOUR	263.7	
	1 DASH BOARD LOWER FUSE BOX ASSY	SERVICEABLE	613.9	
	1 FRONT SHOCK ABSORBER ASSY RH	SERVICEABLE	558.	55
	1 FRONT LOWER ARM LH	DISTORTED	620.	200000
	1 FRONT KNUCKLE ARM LH	BENT	490.	
	1 FRONT STRUT BAR	SERVICEABLE	120.	
	1 FRONT STRUT BAR BRACKET	TO REPAIR SEE LABOUR	277.	
	1 FRONT STABILIZER BAR	SERVICEABLE	441	3.5
	1 FRONT STABILIZER BAR BUSH	SERVICEABLE	20	7022
	1 FRONT SEAT BELT RH	JAMMED	862	
	1 FRONT SAFETY BELT COVER GARNISH LH	CRACKED	253	100
	1 FRONT SEAT BELT LH	JAMMED	862	
	1 FRONT SAFETY BELT COVER GARNISH RH	CRACKED	253	.68 253



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
0.5	THE SENDED LIE	BENT	837.60	837.60
201	FRONT FENDER LH	DISTORTED	369.14	369.14
	FRONT FENDER LINER LH	SERVICEABLE	95.80	Ť
	FRONT FENDER INDICATOR LAMP LH	BENT	714.86	714.86
(702)	FRONT FENDER INNER WHEEL HOUSE PANEL LH	BUCKLED	837.60	837.60
	FRONT FENDER RH	CRACKED	369.14	369.14
	FRONT FENDER LINER RH	SERVICEABLE	95.80	
	FRONT FENDER INDICATOR LAMP RH FRONT FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE	714.86	
- 24	BONNET	BUCKLED	1,019.16	
1	BONNET UNDER WEATHERSTRIP SEAL	CUT	71.99	1
1	BONNET HINGE RH	BENT	81.60	16446666
	BONNET HINGE LH	BENT	81.60	81.60
- 1	BONNET MOULDING	NO SUCH PARTS	194.30	8
	BONNET LOCK	BENT	90.0	2 90.02
88	BONNET CABLE	JAMMED	53.3	2 53.33
	BONNET CABLE BONNET CENTRE 'TOYOTA' LOGO BADGE	MISSING	115.4	4 115.4
	ROCKER PANEL OUTER LH	SERVICEABLE	854.2	8
	V-BELT	SERVICEABLE	150.0	58
	1 FRONT WINDSCREEN	CRACKED	1,406.6	
	1 FRONT ERP UNIT	NECESSARY	150.0	
	1 MANIFOLD, INTAKE	DENTED	506.2	506.2
	1 GEAR BOX ASSY	TO REPAIR SEE LABOUR	16,629.6	50
	1 GEAR BOX CROSS MEMBER	SERVICEABLE	1,454.2	28
	1 GEAR BOX CROSS MEMBER BRACKET	SERVICEABLE	239.7	76
	1 GEAR BOX MOUNTING	SERVICEABLE	349.6	38
	1 ENGINE BLOCK	TO REPAIR SEE LABOUR	9,512.8	
	1 ENGINE MOUNTING SIDE	SERVICEABLE	209.5	(2)
	1 ENGINE LOWER SPLASHSHIELD COVER	CRACKED	254.	28 254.2
	1 ENGINE OIL SUMP	SERVICEABLE	350.	04
	1 ENGINE OIL SUMP STRAINER	SERVICEABLE	115.	68
	1 ENGINE SPLASH COVER RH	CRACKED	178.	
	1 ENGINE SPLASH COVER LH	CRACKED	178.	11
	1 ECU ASSY	SERVICEABLE	4,584.	24
	1 ABS PUMP	SERVICEABLE	5,679	60



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
-	- PORTUNE PIPE	SERVICEABLE	82.08	-
1	ABS PUMP PIPE		-22,231.11	-6,895.82
	LESS 25% DISCOUNT		66,693.31	20,687.44
	BATTERY (SN) (50%)	DENTED	240.00	120.00
-1	LESS 25% DISCOUNT		-60.00	
	LESS 23 / BIOCOUT		180.00	120.00
	SPECIAL NETT ITEMS	3.5050445578		
	SET REVERSE SENSOR (SN)	SERVICEABLE	300.00	
	REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	21.60	A CONTRACTOR
	REAR BUMPER FASTENER CLIP (SN)	NECESSARY	36.00	
	CNG STICKER (SN)	NECESSARY	15.00	
	REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	14.40	
	REAR FENDER INNER COWLING CLIP LH (SN)	NOT NECESSARY	21.60	
3	1 REAR TYRE (SN)	SERVICEABLE	190.0	
	2 FRONT TYRE LH AND RH (SN)	SERVICEABLE	380.0	
	3 WHEEL RIM (SN) (LOCAL REPAIR)	DENTED-2PCS ONLY	450.0	0 100.00
	3 REAR WHEEL RIM HUB - CAP - ACCESSORY (SN)	NOT FITTED	150.0	33
	1 COPORATE LOGO - 6555-3333 (SN)	NECESSARY	80.0	- AD-1-38-10
	6 PETROL TANK INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	18.0	3
	4 FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	40.0	
	6 RADIATOR GRILLE CLIP (SN)	NECESSARY	18.0	West and the
	6 BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NECESSARY	21.6	100
	0 BONNET INSULATOR CLIP (SN)	NECESSARY	42.0	258
1	1 FRONT LICENCE PLATE (SN)	BENT	50.0	
	1 REAR FENDER 1/4 GLASS INNER SPONGE SEAL (SN)	NECESSARY	48.0	3 m
1	1 REAR FENDER 1/4 GLASS SEALANT (SN)	NECESSARY	72.0	
	1 FRONT WINDSCREEN MOULDING (SN)	NECESSARY	86.4	40 86.4
	1 FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.0	
1	1 FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	60.0	명과 [
	1 FRONT ERP BRACKET (SN)	NECESSARY	40.0	26.0
	1 ENGINE OVERHAUL GASKET (SN)	NOT NECESSARY	61.	44
	1 ENGINE OIL SUMP SEALANT (SN)	NOT NECESSARY	20.	12.55
	4 ENGINE SPLASH COVER CLIP RH (SN)	NECESSARY	12.	00 12.0



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	ENGINE SPLASH COVER CLIP LH (SN)	NECESSARY	12.00	12.00
			2,340.04	604.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH, REAR FENDER INNER WHEEL HOUSE PANEL LH, REAR FENDER SIDE PANEL LH, TYRE MECHANICAL JACK, TYRE MECHANICAL JACK HOLDER BRACKET, FRONT TOW HOOK BRACKET, HEADLAMP RH INNER PANEL, HEADLAMP LH INNER PANEL,		8,400.00	2,400.00
	BRACKET-STRG RACK NO 1 (S10/12), BRACKET-STRG RACK NO2 (S10/12), DASH BOARD RE-INFORCEMENT BAR, DASH BOARD RE-INFORCEMENT BRACKET, FRONT STRUT BAR BRACKET, FRONT FENDER INNER WHEEL HOUSE PANEL RH, GEAR BOX ASSY AND ENGINE BLOCK.}			
	TOWING FEES.		120.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	60.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	180.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	250.00
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	
	TO DISMANTLE AND REFIT REAR SEAT, BACKREST, TRIMINGS, GARNISH, ROOF-LINING, SPEAKER SHELFBOARD, CARPETING AND OTHER TO ENABLE BODY WORK REPAIR. }		380.00	100.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. }		380.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	REPEATED	380.00	
	TO DROP DIESEL / PETROL TANK, PIPES, HOSES AND RENEW THE NECESSARY PARTS AND FINAL CHECKING AND TESTING FOR LEAK.		440.00	60.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
,	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND	-	380.00	260.00
	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING. }		380.00	280.00
	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING. }		380.00	0.5
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT. }	Day News Co.	440.00	/ = 1
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.		480.00	280.00
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	REPEATED	380.00	
	TO CONDUCT AND PERFORM A COMPREHENSIVE ENGINE DIAGNOSTIC CHECK.	NOT NECESSARY	380.00	
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		8,100.00	S00000000
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.		380.00	
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.	NOT NECESSARY	380.0	1
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.0	
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.0	
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.0 380.0	
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		170.0	
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		110000	
	TO RESEAL SEALANT ON GAP.		120.0 25,230.0	
			A 3054896397	
	GRAND TOTAL		94,443.3	27,641.44
	DECOMMENDED COST OF LUMP SUM REPAIRS			22,100.0

RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

22,100.00

Report Ref No. CS/TP19004865/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.