



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 5001S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT SIDE MIRROR ARM ASSY	SCRATCHED	1,630.00	1,630.00
1	FRONT SIDE MIRROR OUTER COVER LH	TO REPAIR SEE LABOUR	141.10	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,033.90	-
1	FRONT DOOR RUBBER (AT DOOR) LH	NOT NECESSARY	115.00	-
1	FRONT DOOR OUTER LOWER PROTECTOR BLACK LH	SCRATCHED	183.90	183.90
1	REAR DOOR LH	DENTED	1,032.90	1,032.90
1	REAR DOOR RUBBER (AT DOOR) LH	NOT NECESSARY	115.00	-
1	REAR DOOR OUTER LOWER PROTECTOR BLACK LH	SCRATCHED	115.00	115.00
1	ROCKER PANEL OUTER SIDE SKIRT LH	CUT	600.00	600.00
10	ROCKER PANEL OUTER SIDE SKIRT CLIPS	NECESSARY	50.00	50.00
1	REAR FENDER WHEEL ARCH BLACK LH	CUT	150.00	150.00
10	REAR FENDER WHEEL ARCH BLACK CLIPS	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-521.68	-381.18
			4,695.12	3,430.62
<u>SPECIAL NETT ITEMS</u>				
1	SPORT RIM LH REAR 18 INCH (SN)	CUT	1,681.50	1,434.50
1	TYRE LH REAR (SN) (\$180.00) (80%)	SCRATCHED	180.00	144.00
1	REAR WHEEL BEARING LH (SN)	NOT NECESSARY	330.50	-
			2,192.00	1,578.50
<u>LABOUR</u>				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.	NOT NECESSARY	40.00	-
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR FACILITATE REPAIR.FRONT DOOR LH,REAR DOOR LH.		160.00	60.00
	TO REPLACE FRONT SIDE MIRROR LH.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REINSTALL/REPLACE REAR WHEEL BEARING LH.	NOT NECESSARY	150.00	-
	TO RESET FRONT SIDE MIRROR LH,ABS LIGHT.	NOT NECESSARY	280.00	-
	TO REMOVE AND REINSTALL BUMPER SENSORS.	NOT NECESSARY	60.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER LH,REAR BUMPER INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF FRONT SIDE MIRROR OUTER COVER LH AND FRONT DOOR LH.		700.00	400.00
	TO SPRAY FRONT DOOR LH,REAR DOOR LH,REAR FENDER LH,REAR BUMPER,FRONT SIDE MIRROR LH.		900.00	700.00
			2,530.00	1,250.00
GRAND TOTAL			9,417.12	6,259.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/FCI19004883/Gtd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.