



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

QBE INSURANCE (S) PTE LTD

INV No. AC2303830

1 RAFFLES QUAY #29-10 SOUTH TOWER  
SINGAPORE 048583

INV Date 16/06/2023

Reference CC6/QBE19004919/Apa3q2

Code QBE

#### PROFESSIONAL SERVICE FEE

Vehicle No. GBC 1342S

Insured Veh. GBC 709A

Claim No. VC012338

Policy No. 8-V0014616-MVA-R001

Accident Date 23/02/2019

Inspection Date 14/03/2019

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                 |  |  |                       |
|---|--|--|-----------------------|
| QBE INSURANCE (S) PTE LTD<br>1 RAFFLES QUAY #29-10 SOUTH<br>TOWERSINGAPORE 048583 |  | Ref: CC6/QBE19004919/Apa3q2<br>Date: 16/06/2023<br>Code: QBE |                       |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                 |  |  |                       |
| <b>Insured Veh.</b>   | GBC 709A   | <b>Veh. Inspected</b>  | GBC 1342S             |
| <b>Policy No.</b>   | 8-V0014616-MVA-R001  | <b>Coverage (\$)</b>   | 0.00                  |
| <b>Claim No.</b>  | VC012338   | <b>Excess (\$)</b>   | 0.00                  |
| <b>Assign From</b>  |  | <b>Assign Date</b>   | 14/03/2019            |
| <b>2. Vehicle Particulars &amp; Condition</b>                                     |  |  |                       |
| <b>Make &amp; Model</b>   | MITSUBISHI CANTER  | <b>c.c</b>   | 0                     |
| <b>Engine No.</b>   | HIDDEN   | <b>Year of Reg.</b>  |                       |
| <b>Chassis No.</b>  | FB70BBA20324   | <b>Colour</b>  | WHITE                 |
| <b>Odometer</b>   | 358406 KM  | <b>Steering</b>  | IN ORDER              |
| <b>Brakes</b>   | IN ORDER   | <b>Modification</b>  | NIL                   |
| <b>General</b>  | GOOD   |  |                       |
| <b>3. Conditions of Tyres</b>   |  |  |                       |
|   | <b>Size</b>  | <b>Make</b>  | <b>Balance</b>        |
| <b>R/H Front Tyre</b>   | 195/70 R15C  | MICHELIN   | 6 mm                  |
| <b>L/H Front Tyre</b>   | 195/70 R15C  | MICHELIN   | 6 mm                  |
| <b>R/H Rear Tyre</b>  | 195/70 R15C  | MICHELIN   | 6 mm                  |
| <b>L/H Rear Tyre</b>  | 195/70 R15C  | MICHELIN   | 6 mm                  |
| <b>4. Description of Damages</b>  |  |  |                       |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.  |  |                       |
| <b>5. General Information</b>   |  |  |                       |
| <b>Accident Date</b>  | 23/02/2019   | <b>Inspection Date</b>                                       | 14/03/2019            |
| <b>Survey held at</b>   | TEK SOON MOTOR REPAIR & SPRAY PAINTING<br>AUTOBAY @ KAKI BUKIT<br>1 KAKI BUKIT AVE 6 BLK D #01-93<br>SINGAPORE 417883                  |  |                       |
| <b>5a. Remarks</b>  |  |  |                       |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                       |
| <b>5b. Estimate Days of Repair</b>  |  |  |                       |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | <b>3 Working Days</b> |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 1342S

| Qty   | Description of Parts            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---------------------------------|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b>  |                                 |               |                           |                   |
| 1   | FRONT WINDSCREEN                | CRACKED       | 1,413.40                  | 1,413.40          |
| 1   | FRONT WINDSCREEN MOULDING       | NECESSARY     | 285.30                    | 285.30            |
| 1   | FRONT WIPER GARNISH             | DEFORMED      | 562.00                    | 562.00            |
| 1   | CENTER STICKER                  | NECESSARY     | 96.00                     | 96.00             |
| 1   | FRONT WIPER ARM LH              | BENT          | 89.90                     | 89.90             |
| 1   | FRONT WIPER BLADE LH            | CUT           | 33.90                     | 33.90             |
| 1   | FRONT WING MIRROR (ROUND)       | MISSING       | 112.50                    | 112.50            |
| 1   | FRONT WING MIRROR (RECTANGULER) | NOT NECESSARY | 126.20                    | -                 |
| 1   | FRONT WING MIRROR STAY          | NOT NECESSARY | 378.00                    | -                 |
|   | LESS 25% DISCOUNT               |               | -                         | -648.25           |
|   |                                 |               | 3,097.20                  | 1,944.75          |
| <b><u>SPECIAL NETT ITEMS</u></b>  |                                 |               |                           |                   |
| 1   | FRONT WINDSCREEN SEALANT (SN)   | NECESSARY     | 60.00                     | 60.00             |
| 1   | ERP BRACKET (SN)                | NECESSARY     | 26.00                     | 26.00             |
|   |                                 |               | 86.00                     | 86.00             |
| <b><u>LABOUR</u></b>  |                                 |               |                           |                   |
|   | PANEL BEATING.                  |               | 200.00                    | 100.00            |
|   | SPRAY PAINTING .                | NOT NECESSARY | 250.00                    | -                 |
|   | TO REPLACE FRONT WINDSCREEN.    |               | 180.00                    | 120.00            |
|   |                                 |               | 630.00                    | 220.00            |
| <b>GRAND TOTAL</b>  |                                 |               | <b>3,813.20</b>           | <b>2,250.75</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                 |               |                           | <b>1,800.00</b>   |

Report Ref No. CC6/QBE19004919/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBC 1342S

## INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBC 1342S

## RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBC 1342S

## RE-INSPECTION

