

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19004923/DGA3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994697

Claimant
Vehicle No : FBN3796U **Insured Vehicle No :** SLK3956Y

Date of Loss: 10/03/2019 Nature of Claim: TP Claim No: 9279555524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN3796U	Engine No:	G3E6E0424188
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740J0120575
Reg. Date:	24/09/2018 (Man. Year: 2018)	Odometer:	18824 km
Colour:	Silver		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80 R17	Rear Tyre Size:	70/80 R17
Front Left Side:	VOLANS 4 mm	Rear Left Side:	VOLANS 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,078.80	2,995.20	1,083.60	26.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	670.00	590.00	46.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,338.80	3,665.20	1,673.60	31.35
Approved Total (Overridden) (\$\$)		2,900.00		
Nett Amount (\$\$)	5,338.80	2,900.00	2,438.80	45.68
+ Loss of Use (4.0 x S\$30.00/day) (\$\$)		120.00		
(S\$)		3,020.00		
Liabe Amount (50.00%) (\$\$)		1,510.00		

INSPECTION

Date of Assignment: 14/03/2019

Date Inspected: 19/03/2019 Inspected At:

Sg 98 Motor Pte Ltd (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL
PARK 1 #01-21
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	195.00 FL	*195.00 FL
2	1		*SET BALANCER	Cut	135.00 FL	*135.00 FL
3	1		*HEAD LAMP	Cut	235.00 FL	*235.00 FL
4	1		*FRONT TOP COVER	Cut	125.00 FL	*125.00 FL
5	1		*FRONT PANEL	Cut	185.00 FL	*185.00 FL
6	1		*FRONT LEFT SIGNAL	Cut	95.00 FL	*95.00 FL
7	1		*FRONT INNER GARNISH PANEL	Cut	135.00 FL	*135.00 FL
8	1		*FRONT LH SIDE FAIRING	Cut	135.00 FL	*135.00 FL
9	1		*HEAD LIGHT SWITCH COVER	Not Necessary	165.00 FL	*- FL
10	1		*GEAR PEDAL	Bent / Cut	65.00 FL	*65.00 FL
11	1		*FOOTREST BRACKET LH	Bent	75.00 FL	*75.00 FL
12	1		*FOOT PEG LH	Cut	75.00 FL	*75.00 FL
13	1		*ENGINE CASING LH	Not Necessary	145.00 FL	*- FL
14	1		*REAR LH FAIRING	Cut	195.00 FL	*195.00 FL
15	1		*SET FRONT FORK	Not Necessary	480.00 FL	*- FL
16	1		*SWING ARM	Bent	380.00 FL	*380.00 FL
17	1		*REAR RIM	Distorted	350.00 FL	*350.00 FL
18	1		*REAR WHEEL HUB	Not Necessary	165.00 FL	*- FL
19	1		*REAR WHEEL SHAFT	Bent	125.00 FL	*125.00 FL
20	1		*REAR WHEEL BEARING	Not Necessary	75.00 FL	*- FL
21	1		*CHAIN SPROCKET ASSY	Not Necessary	79.00 FL	*- FL
22	1		*REAR LH SIGNAL	Broken	65.00 FL	*65.00 FL
23	1		*REAR MUDGUARD	Cut	178.00 FL	*178.00 FL
24	1		*BRAKE PEDAL	Not Necessary	95.00 FL	*- FL
25	1		*EXHAUST PIPE	Cut / Dented	580.00 FL	*580.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,532.00	3,328.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	453.20	332.80
Total Parts (\$\$)	4,078.80	2,995.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	50.00	30.00
2	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC	New	280.00	150.00
3	REMOVE & REPLACE FORK ASSY ,SWING ARM ,RIM ,SHAFT ,SPROCKET CHAIN ASSY & ETC	New	280.00	120.00
4	SUPPLY BODY DECAL STICKER	New	200.00	100.00
5	TOUCH UP ,RESPRAY PAINT WORK	New	250.00	150.00
6	RE-ALIGN REAR BODY FRAME	New	200.00	120.00
Gross Labour Cost (\$\$)			1,260.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >