


Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE

Licence Number: **S043785F**

Name: **TAN SEE LENG
(CHEN SHILING)**

Birth Date: **23 Oct 1964**

Issue Date: **03 Mar 2006**

#01325604C



Driving License



120800013412



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

INVOICE

Ms Tan See Leng
C/o. 53 Ubi Avenue 1 #01-33
Paya Ubi Industrial Park
Singapore 408934

Invoice No. : HA/1811-29

Date : 10/11/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 585.00
SGD Dollar : Five Hundred Eighty Five Dollars Only.	
Our Reference : PAS/TP/0421018	
Vehicle No. : SKW2727Y	
Make & Model : Honda HR-V	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD

My Car Consultant Pte Ltd

53, Ubi Avenue 1, Paya Ubi Industrial Park,
#01-33, Singapore 408934
HP: 9888 8885 (Jeremy) Email: Jeremy_dav_86@live.com

INVOICE

Claimant: Ms Tan See Leng

Date of Invoice : 10/11/2018

C/o. M/s. My Car Consultant Pte Ltd
53, Ubi Avenue 1 #01-33
Paya Ubi Industrial Park
Singapore 408934

Claim Type : Third Party
Vehicle Reg. No : SKW2727Y
Vehicle Make/Model : Honda HR-V

Date of Accident : 17/10/2018

Description	Amount (S\$)
Lump Sum Repairs As Per Recommendation.	\$ 7,110.00
Total	\$ 7,110.00

Singapore Dollar : Seven Thousand One Hundred Ten Dollars Only.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

INVOICE

Ms Tan See Leng
C/o. 53 Ubi Avenue 1 #01-33
Paya Ubi Industrial Park
Singapore 408934

Invoice No. : HA/1811-29

Date : 10/11/2018


Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 585.00
SGD Dollar : Five Hundred Eighty Five Dollars Only.	
Our Reference : PAS/TP/0421018	
Vehicle No. : SKW2727Y	
Make & Model : Honda HR-V	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".
Please indicate our "INVOICE NO." on the reverse side of the cheque.
Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD





PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0421018

Date of Report : 10/11/2018

To : Ms Tan See Leng
C/o. 53 Ubi Avenue 1 #01-33
Paya Ubi Industrial Park
Singapore 408934

Date of Assignment : 18/10/2018
Report requested by : Ms Tan See Leng
Date of Accident : 17/10/2018
Date of Inspection : 18/10/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SKW2727Y
Make & Model : Honda HR-V
Date of Registration : 04/05/2018
Colour : Met. Red

Engine Capacity (cc) : 1496cc
Mileage (km) : 7880km
Chassis / Frame No. : JHMRU1810GX204092
Engine No. : L15B4534093

TYRE CONDITION

Front LH : 8 mm
Make : Dunlop

Front RH : 8 mm
Make : Dunlop

Rear LH : 8 mm
Make : Dunlop

Rear RH : 8 mm
Make : Dunlop

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. My Car Consultant Pte Ltd
53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate : \$ 12,626.48
Revised Amount : \$ 8,894.00
Less Excess : \$ -
Recommended Reserve : \$ 7,110.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SKW2727Y

Report No. : PAS/TP/0421018

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. My Car Consultant Pte Ltd, 53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front and rear portions.

DAMAGES

The bonnet, front bumper, front support panel, front chassis members, front fenders, RH headlamp, RH fog lamp, front grilles, tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$8,894.00.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$7,110.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(528890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKW2727Y

Report No. : PAS/TP/0421018

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	2 pcs	Headlamp (LED) R/L	RH Cracked	\$ 1,589.80	\$ 3,179.60	\$ 1,589.80 CRAW
2	1 pc	Frt grille garnish assy	Dented/Cracked		\$ 223.80	\$ 223.80 CRAW
3	1 pc	Frt grille base	Dented/Cracked		\$ 207.30	\$ 207.30 DDV
4	1 pc	Frt grille emblem	Necessary		\$ 28.20	\$ 28.20 NECV
5	1 pc	Frt bumper	Dented		\$ 485.70	\$ 485.70 DDV
6	1 pc	Frt bumper tow cover	Refit		\$ 22.70	\$ -
7	1 pc	Frt bumper grille	Refit		\$ 77.80	\$ 190.00
8	2 pcs	Frt bumper fog lamp R/L	RH Cracked	\$ -237.90	\$ -475.80	\$ -237.90 CRAW
9	2 pcs	Frt bumper fog lamp garnish R/L	RH Dented/Cracked	\$ 54.50	\$ 109.00	\$ 44.00 54.50 CRAW
10	8 pcs	Frt bumper clip	Necessary	\$ 3.00	\$ 24.00	\$ 24.00 NECV
11	2 pcs	Frt bumper retainer R/L	Cracked/Necessary	\$ 25.20	\$ 50.40	\$ 50.40 NECV
12	2 pcs	Frt bumper bracket R/L	RH Dented/Cracked	\$ 63.80	\$ 127.60	\$ 35.00 63.80 DDV
13	1 pc	Frt bumper reinforcement	Dented		\$ 272.30	\$ 272.30 DDV
14	1 pc	Frt support panel	Dented/Repair		\$ 682.00	\$ 195.00
15	1 pc	Tailgate	Dented		\$ 812.80	\$ 812.80 DDV
16	1 pc	Tailgate windscreen moulding	Necessary		\$ 26.20	\$ 26.20
17	4 pcs	Tailgate windscreen dam	Necessary	\$ 9.20	\$ 36.80	\$ 36.80
18	4 pcs	Tailgate windscreen fastener	Necessary	\$ 6.40	\$ 25.60	\$ 25.60
19	1 pc	Tailgate emblem (Logo)	Not necessary		\$ 22.50	\$ -
20	1 pc	Tailgate emblem (HR-V)	Necessary		\$ 32.70	\$ 32.70
21	1 pc	Tailgate emblem (i-VTEC)	Necessary		\$ 28.60	\$ 28.60
22	1 pc	Tailgate no.plate garnish	Refit		\$ 120.30	\$ 10.87
23	1 pc	Tailgate inner trim	Cracked/Deformed		\$ 130.80	\$ 130.80 CRAW
24	10 pcs	Tailgate inner trim clip	Necessary	\$ 3.00	\$ 30.00	\$ 30.00 NECV
25	1 pc	Tailgate lock	Dented/Damaged		\$ 118.20	\$ 118.20
26	1 pc	Tailgate lock striker	Bent		\$ 22.30	\$ 22.30
27	1 pc	Tailgate weatherstrip	Torn/Necessary		\$ 128.60	\$ 128.60 TNV
28	1 pc	Rr bumper	Dented		\$ 517.10	\$ 517.10 DDV
29	2 pcs	Rr bumper side cover R/L	LH Dented/Cracked	\$ 114.90	\$ 229.80	\$ 114.90 NNX
30	2 pcs	Rr bumper reverse sensor R/L	LH Dented/Damaged	\$ 128.00	\$ 512.00	2pcs \$ 256.00 DDV
31	2 pcs	Rr bumper reflector R/L	LH Cracked	\$ 148.40	\$ 296.80	\$ 148.40 CRAW
32	8 pcs	Rr bumper clip	Necessary	\$ 3.00	\$ 24.00	\$ 24.00 NECV
33	2 pcs	Rr bumper retainer R/L	Cracked/Necessary	\$ 20.70	\$ 41.40	\$ 41.40 NECV
34	1 pc	Rr end panel	Dented/Distorted		\$ 425.90	\$ 425.90 KX
35	1 pc	Rr end panel trim	Dented/Cracked		\$ 72.00	\$ 72.00 CRAW
36	1 pc	Frt fender R/L	Dented/Repair			(Refer labour no. 1 & 2)
37	1 pc	Frt support panel	Dented/Repair			(Refer labour no. 1 & 2)
38	1 pc	Rr fender R/L	Dented/Repair			(Refer labour no. 5, 6 & 10)
39	1 pc	Rr floor panel	Dented/Repair			(Refer labour no. 5, 6 & 10)
					\$ 9,620.60	\$ 6,230.00
				Less Discount : 20%	\$ 1,924.12	20% \$ 1,246.00
				List Parts Sub-Total :	\$ 7,696.48	\$ 4,984.00
1	1 set	Frt no.plate (w/bracket)	Dented/Cracked	S/N	\$ 50.00	\$ 30.00 50.00 CRAW
2	1 pc	Tailgate windscreen sealant	Necessary	S/N	\$ 50.00	\$ 40.00
3	1 pc	Rr end panel sealant	Necessary	S/N	\$ 50.00	\$ 40.00
				Special Nett Sub-Total :	\$ 150.00	\$ 130.00
				Parts Total :	\$ 7,846.48	\$ 5,114.00



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKW2727Y

Report No. : PAS/TP/0421018

S/No. Labour Descriptions

Repairer's
Estimate (S\$)

Our
Assessment (S\$)

1 To straighten, repair, realign on front affected area and replace damaged parts.

\$ 800.00

\$ 550.00

2 To spray painting, blending on front affected and adjacent area.

\$ 800.00

\$ 600.00

3 To check electrical system and focus headlamp.

\$ 60.00

\$ 50.00

4 To remove, reinstall radiator, a/c condenser and pipings for necessary repairs.
(Include pressure test cooling system and vacuum, recharge a/c gas)

\$ 200.00

\$ 180.00

5 To straighten, repair, realign on rear affected area and replace damaged parts.

\$ 1,000.00

\$ 770.00

6 To spray painting, blending on rear affected and adjacent area.

\$ 1,200.00

\$ 1,000.00

7 To transfer tailgate component parts to new tailgate.
(Include transfer rear spoiler and supply sealant)

\$ 150.00

\$ 140.00

8 To transfer rear windscreen to new tailgate.

\$ 120.00

\$ 120.00

9 To check rear electrical wiring system.

\$ 60.00

\$ 50.00

10 To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.

\$ 100.00

\$ 80.00

11 To remove, replace and/or transfer rear reverse sensors & reset control unit.

\$ 200.00

\$ 180.00

12 To spray anti-rust coating on new and affected panels.

\$ 90.00

\$ 60.00

Labour Total :

\$ 4,780.00

\$ 3,780.00

Total (Parts & Labour) :

\$ 12,626.48

\$ 8,894.00

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 7,110.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 10 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

95 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD18019250/Bqd3s2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 27-03-2019



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLE 2743H	Veh. Inspected	SKW 2727Y
Policy No.	PNPV2017-00005247-01	Coverage (\$)	0.00
Claim No.	1201800013412	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	15/03/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV 1.5 DX CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMRU1810GX204092	Colour	RED
Odometer	78805	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	7 mm
L/H Front Tyre	215/60R16	DUNLOP	7 mm
R/H Rear Tyre	215/60R16	DUNLOP	7 mm
L/H Rear Tyre	215/60R16	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/10/2018	Inspection Date	23/10/2018
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 2727Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	HEADLAMP (LED) R/L @ \$1589.80	O/S CRACKED	3,179.60	1,589.80
1	FRT GRILLE GARNISH ASSY	CRACKED	223.80	223.80
1	FRT GRILLE BASE	DENTED	207.30	207.30
1	FRT GRILLE EMBLEM	NECESSARY	28.20	28.20
1	FRT BUMPER	DENTED	485.70	485.70
1	FRT BUMPER TOW COVER	REFIT	22.70	-
1	FRT BUMPER GRILLE	REFIT	77.80	-
2	FRT BUMPER FOG LAMP R/L @ \$237.90	O/S CRACKED	475.80	190.00
2	FRT BUMPER FOG LAMP GARNISH R/L @ \$54.50	O/S CRACKED	109.00	44.00
8	FRT BUMPER CLIP @ \$3.00	NECESSARY	24.00	24.00
2	FRT BUMPER RETAINER R/L @ \$25.20	NECESSARY	50.40	50.40
2	FRT BUMPER BRACKET R/L @ \$63.80	O/S DENTED	127.60	35.00
1	FRT BUMPER REINFORCEMENT	DENTED	272.30	195.00
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	682.00	-
1	TAILGATE	DENTED	812.80	812.80
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	26.20	26.20
4	TAILGATE WINDSCREEN DAM @ \$9.20	NECESSARY	36.80	36.80
4	TAILGATE WINDSCREEN FASTENER @ \$6.40	NECESSARY	25.60	25.60
1	TAILGATE EMBLEM (LOGO)	NOT NECESSARY	22.50	-
1	TAILGATE EMBLEM (HR-V)	NECESSARY	32.70	32.70
1	TAILGATE EMBLEM (I-VTEC)	NECESSARY	28.60	10.87
1	TAILGATE NO. PLATE GARNISH	REFIT	120.30	-
1	TAILGATE INNER TRIM	CRACKED	130.80	130.80
10	TAILGATE INNER TRIM CLIP @ \$3.00	NECESSARY	30.00	30.00
1	TAILGATE LOCK	NOT NECESSARY	118.20	-
1	TAILGATE LOCK STRIKER	NOT NECESSARY	22.30	-
1	TAILGATE WEATHERSTRIP	TORN	128.60	128.60
1	RR BUMPER	DENTED	517.10	517.10
2	RR BUMPER SIDE COVER R/L @ \$114.90	NOT NECESSARY	229.80	-
4	RR BUMPER REVERSE SENSOR R/L @ \$128.00	N/S CUT	512.00	200.00

Report Ref No. CS3/FWD18019250/Bqd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RR BUMPER REFLECTOR R/L @ \$148.40	N/S CRACKED	296.80	131.50
8	RR BUMPER CLIP @ \$3.00	NECESSARY	24.00	24.00
2	RR BUMPER RETAINER R/L @ \$20.70	NECESSARY	41.40	41.40
1	RR END PANEL	TO REPAIR SEE LABOUR	425.90	-
1	RR END PANEL TRIM	CRACKED	72.00	72.00
1	FRT FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,924.12	-1,058.71
			7,696.48	4,234.86
	SPECIAL NETT ITEMS			
1	SET FRT NO. PLATE (W/BACKET) (SN)	CRACKED	50.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	RR END PANEL SEALANT (SN)	NECESSARY	50.00	40.00
			150.00	110.00
	LABOUR			
	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL, FRT FENDER R/L AND FRT SUPPORT PANEL.		800.00	300.00
	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA.		800.00	250.00
	TO CHECK ELECTRICAL SYSTEM AND FOCUS HEADLAMP.		60.00	30.00
	TO REMOVE, REINSTALL RADIATOR, A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM AND VACUUM, RECHARGE A/C GAS)	NOT NECESSARY	200.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR END PANEL, RR FENDER R/L AND RR FLOOR PANEL.		1,000.00	500.00

Report Ref No. CS3/FWD18019250/Bqd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA.		1,200.00	600.00
	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE. (INCLUDE TRANSFER REAR SPOILER AND SUPPLY SEALANT)		150.00	80.00
	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE.		120.00	80.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		60.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.		100.00	50.00
	TO REMOVE, REPLACE AND/OR TRANSFER REAR REVERSE SENSOR & RESET CONTROL UNIT.		200.00	100.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		90.00	40.00
			4,780.00	2,060.00
GRAND TOTAL			12,626.48	6,404.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CS3/FWD18019250/Bqd3s2-1

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.