

Poh KIN

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49589
Date Estimated : 02/01/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
WOO WEN SIANG
86 PUNGGOL CENTRAL
#11-14

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

SINGAPORE 828720

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE		
SMC710P	7B51478	26/06/2018	218i AT	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace RH open side grille include making good the front bumper and knocking out dents caused by the accident	850.00		850.00			
To respray front bumper	934.00		934.00			
To check electrical wiring systems at the front section for proper function	150.00		150.00			
Sundries	40.00		40.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
GRILLE SIDE OPEN RH (PDC)	109.75	1.00		109.75

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	109.75
Total Labour & Parts :	2,083.75
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,083.75
GST @7%:	145.86
Grand Total :	2,229.61

Mon 15/04 @ 10am SMC710P
S&R

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

19 MAR 2019

ESTIMATE

Estimate No. : b1 49589	Page No. : 1 of 4
Date Estimated : 02/01/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - WOO WEN SIANG 86 PUNGGOL CENTRAL #11-14 SINGAPORE 828720	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC710P	7B51478	26/06/2018	218i AT	0

DESCRIPTION	VALUE
To replace front bumper includ ing to knock out dented area caused by the accident	850 1,275.00
To respray front bumper	934 1,038.00
To replace right headlight.	408? 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	40 ? 80.00

Total Labour 1: 3,051.00

DESCRIPTION

BODY NUT ? xnn
FRT BUMPER PANEL PRIMED (PMA repair)
GRILLE SIDE OPEN RH (PDC) xnn
C CLIP NUT ? xnn
RH HEADLIGHT LED TECHNOLOGY ? xnn

QTY	PRIC	VALUE
10	0.90	9.00
1	880.15	880.15
1	95.65	109.7595.65
12	1.30	15.60
1	2,348.00	2,348.00

Total Parts : 3,348.40

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No _____ Claim No. _____

Date of Time 15/04/19 1350 Excess \$ _____

Surveyor's Name RPNL Sign _____

Surveyor's Tel 92060688 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

Labour 1	:	3,051.00
Parts	:	3,348.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	447.96
Grand Total	:	6,847.36

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **