



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5539P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	550.00	-
1	FRONT LH SPLASH SHIELD (CONSISTENT)	NOT NECESSARY	144.00	-
15	FRONT LH SPLASH SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	75.00	-
1	FRONT LH WHEEL ARCH (CONSISTENT)	SCRATCHED	125.00	125.00
10	FRONT LH WHEEL ARCH CLIPS (CONSISTENT)	NECESSARY	50.00	20.00
1	FRONT LH DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	963.00	-
1	FRONT LH DOOR LOWER PROTECTOR (CONSISTENT)	NOT NECESSARY	488.00	-
10	FRONT LH BUMPER CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT LH BUMPER (CONSISTENT)	NOT NECESSARY	786.00	-
1	LHS HEADLAMP (CONSISTENT)	NOT NECESSARY	789.00	-
1	FRONT LH RIM (CONSISTENT)	CUT	1,152.00	800.00
1	FRONT LH TYRE (CONSISTENT)	CUT	450.00	300.00
1	FRONT LH SHOCK ABSORBER (CONSISTENT)	* CHECK	436.00	-
1	FRONT LH STABILIZER LINK (CONSISTENT)	* CHECK	123.00	-
1	FRONT LH KNUCKLE BEARING (CONSISTENT)	* CHECK	139.00	-
1	FRONT LH KNUCKLE ARM (CONSISTENT)	* CHECK	322.00	-
1	FRONT LH LOWER ARM (CONSISTENT)	* CHECK	304.00	-
1	FRONT LH SHOCK ABSORBER MOUNTING (CONSISTENT)	* CHECK	120.00	-
	LESS 10% DISCOUNT		-706.60	-124.50
			6,359.40	1,120.50
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE & INSTALL LHS BODY ATTACHMENTS & FITTINGS TO ENABLE REPAIRS ,LHS FRONT FENDER ,TO REPLACE DAMAGED PARTS AS LISTED ABOVE .INCLUSIVE OF THE REPAIR OF FRONT LH FENDER AND FRONT LH DOOR .		1,800.00	450.00
	TO SPRAY PAINT ON LHS FRONT DOOR (INNER,OUTER),LHS SILL GARNISH ,LHS FRONT FENDER ,FRONT LH BUMPER .		1,800.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & TRANSFER RHS FRONT LH DOORS TRIM BOARDS ,DOOR SCREENS ,POWER WINDOW & ELECTRICAL WIRINGS & SERVICEABLE FITTINGS TO NEW DOORS & TEST FUNCTIONS.	NOT NECESSARY	150.00	-
	TO CHECK ,DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	NOT NECESSARY	280.00	-
	WHEEL ALIGNMENT .		120.00	60.00
	LABOUR FOR REMOVE & INSTALL FRONT LH UNDERCARRIAGE.		350.00	200.00
	TOWING FEES.	* CHECK	180.00	-
			4,680.00	1,210.00
GRAND TOTAL			11,039.40	2,330.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,479.60 NETT)				1,850.00

Report Ref No. CC4/ASM19004949/Jba3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.