



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8662C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	R/R OUTER LAMP (CONSISTENT) (WCP)	CRACKED	207.91	80.00
1	R/R LAMP COVER (CONSISTENT) (WCP)	SCRATCHED	126.38	100.00
1	R/OUTER COVER (CONSISTENT) (WCP) (NPA)	NOT NECESSARY	-	-
	COST PLUS 15%		50.14	27.00
			384.43	207.00
	<b><u>LABOUR</u></b>			
	27.0 WU X 45.00 SGD/H.		121.50	31.50
	LABOUR COST 31.0 WU X 45.00 SGD/H.		139.50	58.50
	MATERIAL COST.		25.39	25.06
			286.39	115.06
	<b>GRAND TOTAL</b>		<b>670.82</b>	<b>322.06</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>322.06</b>

Report Ref No. CC4/ASM19004950/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.