

# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBB8662C / 08032019 / WW

Version: 1810

Date calculated: 03/19/2019 10:21 AM

Full Report

Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

## Summary Information

### Claim

Location: Singapore (SG)  
Printed by: Toh Wee Ngo  
Claim Reference:  
Estimated Repair Time:  
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd  
Currency: SGD  
Date of Incident: 2019-03-08  
Hire Car Start:  
Hire Car End:

## Vehicle Details

### Vehicle

Manufacturer: FIAT  
Model: DOBLO VAN  
Sub Model: CARGO  
Model Sheet Number: 08 47 01  
Registration: GBB8662C  
VIN number: ZFA22300005698111  
Odometer:

### Model Specs

FROM 05/2009	RR WING DOOR W/GLASS	AIR CONDITIONING	FRT ELECTRIC WINDOWS
REM CENTRAL LOCKING	ELECT DOOR MIRRORS	DRIVER SEAT ARMREST	ADJ P/SEAT ARMREST
FRT SEAT HEIGHT ADJ	DRIVER'S PROT GRILLE	TACHOMETER	REAR SEAT BELT
R/SLIDING DOOR	L/SLIDING DOOR	1.2 LTR 55KW	5 SPEED GEARBOX
POWER STEERING	ADJ STRG COLUMN	DRIVER AIRBAG	TYRES 175/70 TR 14
WHEELS 5.5J X 14	WHEELBASE 2583MM	TWO COAT METALLIC	PAINTED BUMPER

# ComfortDelGro Engineering Pte Ltd

Claim Reference:  
Assessment number: GBB8662C / 08032019 / WW  
Version: 1810  
Date calculated: 03/19/2019 10:21 AM

Full Report  
Registration: GBB8662C

Printed: 19/03/2019 10:21 AM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
7604A 02	VEHICLE PREPARATION TIME		2.0	9.00
7660C 04	R + R R/R SIDE BUMPER		2.0	9.00
5540A 44	R + R R/OUTER TAILLAMP		2.0	9.00
5540A 43	R + R R/TAILLAMP COVER		1.0	4.50
2592	R/R BUMPER CORNER REPAIR		20.0*	90.00
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>2.70</b>	<b>27.0</b>
<b>Total of Labour</b>				<b>121.50</b>

# ComfortDelGro Engineering Pte Ltd

Claim Reference:  
Assessment number: GBB8662C / 08032019 / WW  
Version: 1810  
Date calculated: 03/19/2019 10:21 AM

Full Report  
Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

## Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0

## Paint Material Per Part

Code	Description	Price SGD
2592	R/R BUMPER CORNER REPAIR PAINT PLASTIC	7.29

### Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		10.0	
Preparation Comp. Work Plastic	2.10	21.0	94.50
<b>Total</b>	10 WU/h	3.10	31.0

### Material Cost - Paint

	Price SGD
Repair Painting Plastic	7.29
Material-constant Plastic	18.10
<b>Total</b>	25.39

## Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01 Price SGD
3282	R/R OUTER LAMP	0000051755144	✓ CRA	207.91
3576	R/R LAMP COVER	0000735417808	✓ CRA	126.38
3578	R/OUTER COVER	0000735418900	✓ CRA	0.00
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			334.29
u: Used parts	<b>Addition(+15.00%)</b>			50.14
	<b>Total</b>			384.43

# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBB8662C / 08032019 / WW

Version: 1810

Date calculated: 03/19/2019 10:21 AM

Full Report

Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

## Final Calculation

	SGD	SGD
<b>Parts</b>	334.29	
Addition(+15.00%)	50.14	
<b>Total Parts</b>		<b>384.43</b>
<b>Labour Time Base 10 WU/h</b>		
Total 27.0 WU X 45.00 SGD/h	121.50	
<b>Total of Labour</b>		<b>121.50</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 31.0 WU X 45.00 SGD/h	139.50	
Material Cost	25.39	
<b>Total Paint Including Material</b>		<b>164.89</b>
<b>Repair Cost Excludes GST</b>		<b>670.82</b>
GST (+7.0%)		46.96
<b>Repair Cost Included GST</b>		<b>717.78</b>

## Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 Days.

part by part.

After repair photos.

Guo Qiang - 82880282

21/3/19.