

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBB8662C / 08032019 / WW

Version: 1810

Date calculated: 03/19/2019 10:21 AM

Full Report

Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Toh Wee Ngo	Currency:	SGD
Claim Reference:		Date of Incident:	2019-03-08
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	FIAT
Model:	DOBLO VAN
Sub Model:	CARGO
Model Sheet Number:	08 47 01
Registration:	GBB8662C
VIN number:	ZFA22300005698111
Odometer:	

Model Specs

FROM 05/2009	RR WING DOOR W/GLASS	AIR CONDITIONING	FRT ELECTRIC WINDOWS
REM CENTRAL LOCKING	ELECT DOOR MIRRORS	DRIVER SEAT ARMREST	ADJ P/SEAT ARMREST
FRT SEAT HEIGHT ADJ	DRIVER'S PROT GRILLE	TACHOMETER	REAR SEAT BELT
R/SLIDING DOOR	L/SLIDING DOOR	1.2 LTR 55KW	5 SPEED GEARBOX
POWER STEERING	ADJ STRG COLUMN	DRIVER AIRBAG	TYRES 175/70 TR 14
WHEELS 5.5J X 14	WHEELBASE 2583MM	TWO COAT METALLIC	PAINTED BUMPER

ComfortDelGro Engineering Pte Ltd

Claim Reference:
Assessment number: GBB8662C / 08032019 / WW

Version: 1810

Date calculated: 03/19/2019 10:21 AM

Full Report
Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

Vehicle Condition

Vehicle Status


Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐

Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
7604A 02	VEHICLE PREPARATION TIME		2.0	9.00
7660C 04	R + R R/R SIDE BUMPER		2.0	9.00
5540A 44	R + R R/OUTER TAILLAMP		2.0	9.00
5540A 43	R + R R/TAILLAMP COVER		1.0	4.50
2592	R/R BUMPER CORNER REPAIR		20.0*	90.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			2.70	27.0
Total of Labour				121.50

ComfortDelGro Engineering Pte Ltd

Claim Reference:
Assessment number: GBB8662C / 08032019 / WW
Version: 1810
Date calculated: 03/19/2019 10:21 AM

Full Report
Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0

Paint Material Per Part

Code	Description	Price SGD
2592	R/R BUMPER CORNER REPAIR PAINT PLASTIC	7.29

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		10.0	
Preparation Comp. Work Plastic	2.10	21.0	94.50
Total	10 WU/h	31.0	139.50

Material Cost - Paint

	Price SGD
Repair Painting Plastic	7.29
Material-constant Plastic	18.10
Total	25.39

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01 Price SGD
3282	R/R OUTER LAMP	0000051755144	✓ CRA	207.91
3576	R/R LAMP COVER	0000735417808		126.38
3578	R/OUTER COVER	0000735418900	✓ mm Ser.	0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			334.29
u: Used parts	Addition(+15.00%)			50.14
	Total			384.43

ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBB8662C / 08032019 / WW

Version: 1810

Date calculated: 03/19/2019 10:21 AM

Full Report

Registration: GBB8662C

Printed: 19/03/2019 10:21 AM

Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	334.29	
	50.14	
Total Parts		384.43
Labour Time Base 10 WU/h		
Total 27.0 WU X 45.00 SGD/h	121.50	
Total of Labour		121.50
Paint Work Time Base 10 WU/h		
Labour Cost 31.0 WU X 45.00 SGD/h	139.50	
Material Cost	25.39	
Total Paint Including Material		164.89
Repair Cost Excludes GST		670.82
GST (+7.0%)		46.96
Repair Cost Included GST		717.78

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 Days.

part by part.

After repair photos.

One Qian - 82880282

21/3/19.