

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

AXA - JM

VEHICLE NO : SHD 7197D

DATE 18/3/2019 11:53

MAKE :

PIP

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X repair			\$ 544.50
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp (LH) X			\$ 1,388.00
	Front Fender (LH) /			\$ 566.30
	Front Fender Shield (LH) X			\$ 174.90
	Front Fender Retainer X			\$ 24.60
	Front Wheel Hub Cap (LH) /			\$ 107.10
	Front door X repair			
	Rear door X repair			
	SUB TOTAL			\$ 2,852.40
	Rock Panel Grantiash (LH) X repair			\$ 570.48
	DISCOUNTED TOTAL			\$ 2,281.92
	Front Door Comfort Logo (LH) /			\$ 75.00
	Rear Door Comfortdelgro & Apps Sticker (LH) /			\$ 80.00
				\$ 155.00
	Labour Charge			
	Panel Beating			\$ 400
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 1,200.00
	Tuff Kote			\$ 30.00
	FRT Wheel Alignment			\$ 50.00
				\$ 80.00
	TOTAL LABOUR			\$ 2,160.00
	ESTIMATE TOTAL			\$ 4,596.92

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Any item(s) must be resurveyed and is subject to final approval from Insurance Company

Ka lah 100%

18/3/19 1505 hr.

3 hrs

PIP

Before Part photo.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.