

INS. CASE OWNER:

CC 6, 11 1900 4455, 15/3/19

LAC:

IDAC:

ASSIGNMENT

SYMBOL:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A: 13/3/2019

Nature of Accident:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SGJ 1340B



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 26/6/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

08-08-19

FILE PASS TO TYPIST TO PREPARE REPORT.

* DV - spelling wrong. Amended by correction date.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

SS\$4,500

(6 days)

Reduction:

46 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 12.12.19

Confirm with: MAND

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

SS\$4,815.00

Loss of Rental (LOR):

SS\$ 615.00

(6 days)

x 100

Loss of Use (LOU):

SS\$ -

(\$ x days)

Loss of Income (LOI):

SS\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS\$ 2.00

Medical:

SS\$ -

Disbursement:

SS\$ -

(e.g. Tow/ Independent)

Legal Cost

SS\$ -

Total:

SS\$3,459.00

Global Sum SS\$:

FINAL PAYMENT

Date/Time: 12.12.19

Confirm with: MAND

Email ☒ Call ☐

Payee 1:

SS\$3,459.00

Name 1:

HUI YANG MOTOR PTE. LTD.

Payee 2: (Strike if N.A.)

SS\$ -

Name 2:

Payee 3: (Strike if N.A.)

SS\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

400

COPY SENT 12/12/19

ASS. REC. BY:

REF:

AAA/
672

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGJ1340B

Yr Regn:

06, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

MPV

Make:

Toyota Wish

c.c.

1794

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

330475

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

82E10

0303148

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F: GY

195/85R15

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

13/3/19

D.O.I.

15/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

1/4 = 4,500 (RED: +3,822.18 46%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

13/03/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA WISH 1.8A - SGJ1340B

1pc	rear tailgate
2pcs	rear tailgate hinge @\$89.50
1pc	rear tailgate chome moulding
2pcs	rear tailgate number plate lamp @\$28.90
1pc	rear tailgate toyota logo
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
2pcs	rear taillamp @\$371.45
2pcs	rear taillamp lower bracker @\$122.10
1pc	rear taillamp LH panel
1pc	rear bumper
2pcs	rear bumper side retainer @\$121.35
2pcs	rear bumper reflector @\$83.10
1pc	rear end panel panel
1pc	rear end panel inner garnish
2pcs	rear end panel side bracket @\$121.10
1pc	rear LH fender inner trim
1pc	rear floor panel

Rt	\$	985.25	✓
SM	\$	179.00	X
Wap	\$	198.80	✓
Ln	\$	57.80	X
Ln	\$	61.10	✓
Ln	\$	281.90	✓
135.851N	Di 1/4	\$	271.70 50/1N
Ng 017	\$	374.45	2
MS Ln	\$	748.90	4
MS 017	\$	244.20	4
Rt	\$	385.75	2
Rt	\$	481.70	✓
MS 017	\$	242.70	4
Ln	\$	166.20	X
Rt	\$	781.90	✓
MS 017	\$	289.95	✓
Rt	\$	242.20	X
CMS	\$	588.95	2
Rt	\$	781.25	X

less 25%

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action shall be allowed
- Supplementary items must be surveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

remove & refix rear windscreen

\$ 7,363.70

\$ 1,840.93

\$ 5,522.78

\$ 120.00 ✓

sealant
wiring
tuffkote
spray painting
labour charges
Total

Ln \$ 80.00 401N
\$ 80.00 201
\$ 120.00 601
\$ 1,200.00 800L
\$ 1,200.00 701
\$ 8,322.78



Not Authorize
L1 Rm 824500f
Person After Paint
6 days

Tel: 64515752 (2 Lines) . Fax: 64514658

Not Notched
L 1 Long 87
Persony After Paint
6 days

Owner: HYMS CAR LEASING PTE LTD

1pc	rear tailgate	
2pcs	rear tailgate hinge @\$89.50	
1pc	rear tailgate chome moulding	
2pcs	rear tailgate number plate lamp @\$28.90	
1pc	rear tailgate toyota logo	
1pc	rear tailgate inner lock	
1pc	rear tailgate inner rubber	
1pc	rear tailgate inner garnish	
2pcs	rear taillamp @\$371.45	274.48
2pcs	rear taillamp lower bracker @\$122.10	
1pc	rear taillamp LH panel	
1pc	rear bumper	
2pcs	rear bumper side retainer @\$121.35	
2pcs	rear bumper reflector @\$83.10	
1pc	rear end panel panel	
1pc	rear end panel inner garnish	
2pcs	rear end panel side bracket @\$121.10	
1pc	rear LH fender inner trim	
1pc	rear floor panel	

LKK Auto Consultants hereby notify the Repairer of the following:

- To remove belt/under body coating
- To replace damaged panels using factory
- Paint brand and color of Manufacturer
- Trim and chrome like a "Factory Fresh" look
- Any mechanical repairs allowed
- All necessary work to be reviewed and approved by Customer when Insurance Company

Approved by Repairer

Signature

Date

sealant	
wiring	
tuffkote	
spray painting	
labour charges	
Total	

R ₁	\$	985.25	✓
	\$	179.00	X
ap	\$	198.80	✓
ln	\$	57.80	X
me	\$	61.10	—
me	\$	281.90	✓
161	\$	271.70	50/10
017	\$	374.45	2
11	\$	748.90	4
11	\$	244.20	4
R ₁	\$	385.75	2
R ₁	\$	481.70	✓
11	\$	242.70	4
11	\$	166.20	X
R ₁	\$	781.90	✓
011	\$	289.95	✓
11	\$	242.20	X
11	\$	588.95	2
11	\$	781.25	X

\$ 7,363.70
\$ 1,840.93
\$ 5,522.78

\$ 120.00	✓
\$ 80.00	405m
\$ 80.00	201
\$ 120.00	601
\$ 1,200.00	8001
\$ 1,200.00	701
<u>\$ 8,322.78</u>	





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI19004955/Kfa3

Date: 19/03/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGJ 1340B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/03/2019 at the premises of M/s Hui Yang Motor Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	8,322.78
Revised Estimate Amount	: S\$	5,525.74
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	5,525.74
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19004955/Kea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-12-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 6220R	Veh. Inspected	SGJ 1340B
Policy No.	DMHCSN1664151802	Coverage (\$)	0.00
Claim No.	SNM19D201181C02/0	Excess (\$)	0.00
Assign From		Assign Date	15/03/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100303148	Colour	METALLIC GREY
Odometer	330479	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	2 mm
L/H Front Tyre	195/65 R15	GOODYEAR	2 mm
R/H Rear Tyre	195/65 R15	BRIDGESTONE	2 mm
L/H Rear Tyre	195/65 R15	BRIDGESTONE	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/03/2019	Inspection Date	15/03/2019
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 1340B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	985.25	985.25
2	REAR TAILGATE HINGE @\$89.50	TO REPAIR SEE LABOUR	179.00	-
1	REAR TAILGATE CHROME MOULDING	WARPED	198.80	198.80
2	REAR TAILGATE NUMBER PLATE LAMP @\$28.90	SERVICEABLE	57.80	-
1	REAR TAILGATE TOYOTA LOGO	NECESSARY	61.10	61.10
1	REAR TAILGATE INNER LOCK	DENTED	281.90	281.90
1	REAR TAILGATE INNER GARNISH	MTG DISTORTED	374.45	374.45
2	REAR TAILLAMP @\$371.45	N/S CUT	748.90	371.45
2	REAR TAILLAMP LOWER BRACKET @\$122.10	N/S DISTORTED	244.20	122.10
1	REAR TAILLAMP LH PANEL	BENT	385.75	385.75
1	REAR BUMPER	BENT	481.70	481.70
2	REAR BUMPER SIDE RETAINER @\$121.35	N/S CRACKED	242.70	121.35
2	REAR BUMPER REFLECTOR @\$83.10	SERVICEABLE	166.20	-
1	REAR END PANEL	BENT	781.90	781.90
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	289.95	289.95
2	REAR END PANEL SIDE BRACKET @\$121.10	TO REPAIR SEE LABOUR	242.20	-
1	REAR LH FENDER INNER TRIM	CRACKED	588.95	588.95
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	781.25	-
	LESS 25% DISCOUNT		-1,773.00	-1,261.16
			5,319.00	3,783.49
1	REAR TAILGATE INNER RUBBER (50%) (SN)	DISTORTED / CUT	271.70	135.85
	LESS 25% DISCOUNT		-67.93	-
			203.77	135.85
SPECIAL NETT ITEMS				
1	SEALANT (SN)	NECESSARY	80.00	40.00
			80.00	40.00

Report Ref No. CC6/CTI19004955/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE & REFIX REAR WINDSCREEN.		120.00	120.00
	WIRING.		80.00	20.00
	TUFFKOTE.		120.00	60.00
	SPRAY PAINTING.		1,200.00	800.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE HINGE,REAR END PANEL SIDE BRACKET AND REAR FLOOR PANEL.		1,200.00	700.00
			2,720.00	1,700.00
	GRAND TOTAL		8,322.77	5,659.34
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00

Report Ref No. CC6/CTI19004955/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.