

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004982/AGSD3E2

Date: 21/05/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29096446QMY

Claimant Vehicle No : SJF8865T

Insured Vehicle No : SLH339P

Date of Loss: 08/03/2019

Nature of Claim: TP

Claim No: 587108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF8865T**

Make & Model: TOYOTA VIOS, 1.5 J (A)

Engine No: 1NZX745267

Reg. Date: 13/06/2008 (Man. Year: 2008)

Chassis No: MR053HY9305062249

Colour: Grey

Odometer: 238058 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R14

Rear Tyre Size: 185/60 R14

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,588.70	1,139.10	2,449.60	68.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,110.00	870.00	43.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,568.70	2,249.10	3,319.60	59.61
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	5,568.70	1,800.00	3,768.70	67.68

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 19/03/2019 Inspected At:

Tk Motor Workshop (HQ)

Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @

Kaki Bt

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2020)
Parts:	143	TOYOTA VIOS 1.5 J (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF8865T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR L/H FENDER	Repair	754.70 F	*- FL
2	1		*REAR BUMPER	Deformed	620.20 F	*545.00 FL
3	8		*REAR BUMPER CLIP	Necessary	30.40 F	*30.40 FL
4	1		*REAR BUMPER L/H SIDE RETAINER	Necessary	72.40 F	*36.00 FL
5	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
6	1		*REAR END PANEL	Not Necessary	479.40 F	*- FL
7	1		*REAR END PANEL GARNISH	Not Necessary	75.40 F	*- FL
8	1		*REAR L/H TOOLS BOX SPONGE	Not Necessary	145.80 F	*- FL
9	1		*REAR L/H FENDER INNER SHIELD	Torn	45.70 F	*45.70 FL
10	4		*REAR L/H FENDER INNER SHIELD CLIP	Necessary	15.20 F	*15.20 FL
11	1		*REAR L/H FENDER AIR GRILLE GARNISH	Cracked	36.40 F	*36.40 FL
12	1		*REAR L/H TAILLAMP	Cracked	420.20 F	*343.00 FL
13	2		*REAR L/H TAILLAMP CLIP	Necessary	15.80 F	*10.00 FL
14	1		*REAR L/H SPORT RIM	Cut	457.10 F	*457.10 FL
15	1		*REAR L/H TYRE	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,588.70	1,518.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	379.70
Total Parts (\$\$)	3,588.70	1,139.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY PAINTING	New	800.00	450.00
3	TO WHEEL ALIGNMENT	New	90.00	80.00
4	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	0.00
5	TO REMOVE & REFIX REAR INTERIOR UPHOUSLY & CUSHION	New	80.00	50.00
6	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	50.00
7	TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & REINSTALL REAR REVERSE SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING	New	80.00	50.00
8	TO LABOUR CHARGE FOR PANEL BEATING, WELDING REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	650.00	400.00
Gross Labour Cost (S\$)			1,980.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >