

ASS REC BY:

REF

CS3/2PC18013797/GSD3-1

Instruction

Surveyor

GWO Qiang

ASSIGNMENT (Office)

From (Person)

ong h i i

of

LPC

Date/Time

19/03/2019

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKX 2153Y

Insured:

SGQ 4284Z

at Workshop m/s

N-51 Automotive

Tel

68420051

of

2 Kaki Bkt Ave 2 #01-17/118

Policy No

Claim No:

18/18/18/VPOS/020794

Sum Insured

Excess:

Make of Veh

(Client's Record)

D.O.A

29/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement

Date/Time

12:40pm @ 30/7/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SKX 2153Y - CS3/CRI/7008804/Gb3m2


D.O.A 29/7/2018

SGQ 4284Z - CS/ASM/18000831/Arbs 2-1

D.O.A 10/3/2018

\$7500, 9 Days.

(\$10,600/- Red - 59%)



5/4/2019.

RECEIVED 05 APR 2019


PRS
Ked.

REF: Lpc

3-46C

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no: N-51
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKX253Y Yr Regn: 30 Nov 2015
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer of: _____
 Make: Toyota Altis cc 1598
 Colour: Blue A/O Insured / Std / NI / NA
 Sp. Reading: 258488 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MK053RTH 104538075
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / R/m or
 Tyre Size: F: 205/55 R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 30-07-18
 Survey held at: w/s 4:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

\$7000 - \$8000

RECEIVED 2 AUG 2018

Date/Time. File Pass to?

02/08/18

1) Typist

Date/Time. File Return to?

2)

Report Format :

PRS

Lump Sum / I.B.I. / S

☒ : Preli. Report
☐ : Final Report

Days Of Repair: /

Resurvey No. of Trip: /

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) S - RES. BI

) Photo

) Others

TOTAL

450

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 19 March 2019 10:27 AM
To: Nivitha (LKK Auto)
Cc: MT_Claim_SG; assignments@lkkauto.com
Subject: RE: Our Ref: 18/18/18/VP05/020794 SKX2153Y & SGQ4284Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS [External General]
Attachments: 20794 SURVEY REPORT 1.pdf

Lonpac External - General

Dear Nivitha


Attached is the TP survey report (part 1 of 3).

Please let us have your surveyor's review and report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 30 July, 2018 12:46 PM
To: ONG LI LI
Cc: MT_Claim_SG; assignments@lkkauto.com
Subject: RE: Our Ref: 18/18/18/VP05/020794 RE: SKX2153Y & SGQ4284Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Li Li,

Noted, with thanks.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Monday, 30 July 2018 12:43 PM
To: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com
Subject: RE: Our Ref: 18/18/18/VP05/020794 RE: SKX2153Y & SGQ4284Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Nivitha

Please see attached for your handling.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Monday, 30 July, 2018 12:32 PM

To: ONG LI LI

Cc: MT_Claim_SG; assignments@lkkauto.com; Nivitha (LKK Auto)

Subject: Re: Our Ref: 18/18/18/VP05/020794 RE: SKX2153Y & SGQ4284Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

Please see attached.

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Mon, Jul 30, 2018 at 12:29 PM, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Dear Melody

We are not agreeable to your proposed list of surveyors, we shall appoint LKK Auto Consultants Pte Ltd to conduct pre-repair survey.

Dear Nivitha/Catherine

Please arrange.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Monday, 30 July, 2018 12:25 PM

To: ONG LI LI

Cc: MT_Claim_SG; assignments@lkkauto.com; Nivitha (LKK Auto)

Subject: Re: Our Ref: 18/18/18/VP05/020794 RE: SKX2153Y & SGQ4284Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Mon, Jul 30, 2018 at 12:13 PM, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input type="checkbox"/>

4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Monday, 30 July, 2018 11:51 AM

To: MT_Claim_SG

Subject: SKX2153Y & SGQ4284Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



This email has been checked for viruses by AVG antivirus software.
www.avg.com

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0099-19-N51

25 February 2019

ACCIDENT VEHICLE SURVEY REPORT

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SKX2153Y	Odometer:	258488km
Make & Model:	Toyota Corolla Altis 1.6	Colour:	Grey
Chassis number:	MR053REH104538075	Date of accident:	29/07/2018
Year of Regn.:	30/11/2015	Date inspected:	30/07/2018
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	10/08/2018

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Michelin	5mm/Michelin	205/55R16
Rear:	5mm/Habilead	5mm/Habilead	205/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
FRONT AIRCON CONDENSER	1	bent	1,712.45	X 1,712.45	NN
FRONT BONNET	1	buckled	1,218.85	X 1,218.85	Repair
FRONT BONNET HINGES L/R	2	repaint	270.20	X 270.20	
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	2	deformed	87.40	X 87.40	NN
FRONT BONNET INNER RUBBER TOP MOULDING	1	deformed	135.10	X 135.10	
FRONT BONNET INSULATOR MAT	1	deformed	303.10	X 303.10	
FRONT BONNET MECHANISM LOCK	1	bent	182.10	/ 182.10	
FRONT BRACE PANEL	1	bent	100.40	/ 100.40	
FRONT BUMPER	1	squashed	561.60	/ 561.60	
FRONT BUMPER FOGLAMP GARNISH L/R	2	warped	364.50	X 364.50	NN
FRONT BUMPER FOGLAMP L/R	2	fractured	563.40	X 563.40	
FRONT BUMPER LOWER GRILLE	1	fractured	191.40	/ 191.40	155.4
FRONT BUMPER REINFORCEMENT	1	bent	374.40	X 374.40	
FRONT BUMPER REINFORCEMENT BRACKET L/R	2	bent	220.70	X 220.70	NN
FRONT BUMPER SIDE RETAINER L/R	2	necessary	264.20	X 264.20	
FRONT BUMPER SPONGE	1	deformed	87.00	/ 87.00	
FRONT GRILLE	1	fractured	372.80	/ 372.80	
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	61.10	/ 61.10	37.2
FRONT HEADLAMP L/R	2	fractured	1,890.40	/ 1,890.40	
FRONT HORN L/R	2	distortion	364.20	X 364.20	NN
REAR BOOTLID	1	buckled	755.00	/ 755.00	
REAR BOOTLID 'ALTIS' EMBLEM	1	necessary	48.00	/ 48.00	
REAR BOOTLID 'COROLLA' EMBLEM	1	necessary	48.00	/ 48.00	
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	60.00	/ 60.00	
REAR BOOTLID HINGES L/R	2	bent	133.80	X 133.80	NN
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	2	deformed	50.00	X 50.00	NN
REAR BOOTLID INNER TRIM BOARD	1	deformed	212.00	/ 212.00	
REAR BOOTLID MECHANISM LOCK	1	bent	382.50	/ 382.50	349.6
REAR BOOTLID NUMBER PLATE LAMP L/R	2	fractured	125.80	X 125.80	NN
REAR BOOTLID OUTER CHROME GARNISH	1	fractured	231.30	X 231.30	NN
REAR BOOTLID REFLECTOR INNER BLACK RUBBER GASKET L/R	2	necessary	50.00	X 50.00	NN
REAR BOOTLID REFLECTOR L/R	2	fractured	710.00	/ 710.00	
REAR BOOTLID WEATHER STRIP	1	deformed	185.00	/ 185.00	
REAR BUMPER	1	squashed	482.30	/ 482.30	
REAR BUMPER REFLECTOR L/R	2	fractured	354.80	X 354.80	NN
REAR BUMPER REINFORCEMENT	1	bent	395.00	/ 395.00	
REAR BUMPER REINFORCEMENT BRACKET L/R	2	bent	330.00	X 330.00	NN
REAR BUMPER REVERSE SENSOR HOLDER L/R	2	necessary	24.00	X 24.00	NN
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	reuse	715.30	0.00	
REAR BUMPER SIDE RETAINER L/R	2	necessary	207.00	/ 207.00	171.8
REAR END PANEL	1	buckled	590.00	/ 590.00	

REAR END PANEL TOP GARNISH	1	fractured	217.00	/ 217.00	
REAR EXHAUST GASKET	1	necessary	43.20	X 43.20	
REAR EXHAUST RUBBER MOUNTING	2	distorted	80.60	X 80.60	NN
REAR EXHAUST SILENCER BOX	1	bent	920.00	X 920.00	
REAR FENDER INNER TRIM L/R	2	deformed	622.00	X 622.00	
REAR LH FENDER	1	buckled	977.70	X 977.70	Repair.
REAR SPARE TYRE LOCK SCREW	1	bent	235.10	X 235.10	NN
REAR SPARE TYRE PANEL TOP BOARD	1	deformed	329.00	/ 329.00	298.1
REAR TAILLAMP INNER BLACK RUBBER GASKET L/R	2	necessary	86.20	X 86.20	NN
REAR TAILLAMP L/R	2	fractured	790.00	/ 790.00	
REAR TAILLAMP LOWER BRACKET L/R	2	bent	164.00	X 164.00	NN
REAR TAILLAMP PANEL L/R	2	L-buckled	210.00	X 105.00	Repair.
REAR WINDSCREEN MOULDING	1	necessary	78.60	X 78.60	NN
Subtotal before discount			S\$ 20,168.50	S\$ 19,348.20	8661.5
Percentage discount 25% and 25%			S\$ 5,042.13	S\$ 4,837.05	
Sub-total 1			S\$ 15,126.38	S\$ 14,511.15	6496.13
REAR BUMPER REVERSE SENSOR L/R	2	shorted	360.00	360.00	200
Subtotal before discount			S\$ 360.00	S\$ 360.00	
Percentage discount 10% and 10%			S\$ 36.00	S\$ 36.00	
Sub-total 2			S\$ 324.00	S\$ 324.00	
FRONT BONNET INSULATOR MAT CLIPS - SET	1	necessary	60.00	X 60.00	NN
FRONT BUMPER CLIPS - SET	1	necessary	100.00	/ 100.00	30
FRONT BUMPER NUMBER PLATE	1	bent	25.00	/ 25.00	10
FRONT BUMPER NUMBER PLATE HOLDER	1	bent	50.00	/ 50.00	30
FRONT GRILLE CLIPS - SET	1	necessary	60.00	/ 60.00	10
REAR BOOTLID CAMERA	1	shorted	800.00	X 800.00	NN
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	1	necessary	60.00	/ 60.00	30
REAR BOOTLID NUMBER PLATE	1	bent	25.00	X 0.00	NN
REAR BOOTLID NUMBER PLATE HOLDER	1	bent	50.00	X 50.00	NN
REAR BOOTLID OUTER CHROME GARNISH CLIPS - SET	1	necessary	50.00	X 50.00	NN
REAR BOOTLID REFLECTOR CLIPS L/R - SET	2	necessary	40.00	X 40.00	NN
REAR BUMPER CLIPS - SET	1	necessary	100.00	/ 100.00	30
REAR END PANEL TOP GARNISH CLIPS - SET	1	necessary	50.00	/ 50.00	20
REAR FENDER INNER TRIM CLIPS L/R - SET	2	necessary	160.00	X 160.00	NN
REAR LH FENDER PETROL LID RIVET	1	necessary	20.00	X 20.00	X NN
REAR SPARE TYRE PANEL INSULATOR MAT	1	necessary	300.00	X 300.00	X NN
REAR TAILLAMP CLIPS L/R - SET	2	necessary	60.00	/ 60.00	20
REAR WINDSCREEN SEALANT	1	necessary	100.00	X 100.00	X NN
Subtotal before discount			S\$ 2,110.00	S\$ 2,085.00	180
Sub-total 3			S\$ 2,110.00	S\$ 2,085.00	
Parts-total			S\$ 17,560.38	S\$ 16,920.15	


LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	150.00	20
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	120.00	100.00	20
To remove, reinstall windscreen (REAR)	150.00	X 120.00	NN
To remove, reinstall petrol tank. (to FR)	80.00	X 60.00	NN
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	180.00	120.00	60
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	2,000.00	1,320.00	1000
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	X 120.00	NN
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,600.00	2,250.00	1200
To apply anti-rust chemical on repaired and replaced panel.	120.00	120.00	60
Labour Total			
	SS 5,610.00	SS 4,360.00	
Parts & Labour Total			
	SS 23,170.38	SS 21,280.15	

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 18,100.00 and the recommended number of working days for the repairs is within 12 day(s).


B J Loi (I Eng., MIM, AIRTE)
Automotive Appraiser

9386.13
20% : 7500

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 13:16
Date Of Accident	29/07/2018 09:30
Exact Location Of Accident	BALESTIER RD->LAVENDAR ST JUNCTION INTO CTE(CITY)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX2153Y
Insured/Policyholder	
Name Of Registered Owner	TWINCAR LEASING PTE LTD
Co Reg No	201533046C
Email Address	SALES@N51.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96868628

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V11639/VPZ/R02
Cover Note Number	

Driver

Name of Driver	PUNG CHUN TIONG
NRIC No	S7110553I
Date Of Birth	22/03/1971
Occupation	OUTDOOR
Date Of Driving Pass	30/03/1994
Driving Experience	24 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93877599
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 307 CANBERRA ROAD #10-91
Postcode	750307
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ4284Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHA2824B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

4

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

Passenger 2

NAME: : UNKNOWN

GENDER: : MALE

Passenger 3

NAME: : UNKNOWN

GENDER: : FEMALE

DETAILS OF INJURED PERSON 1

Name

PUNG CHUN TIONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

BLK 307 CANBERRA ROAD #10-91

Postcode

750307

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 19 March 2019 1:54 PM
To: assignments
Cc: Admin A
Subject: FW: NOTICE TO INSPECT OUR CLIENT'S VEHICLE SKR2843X; ACCDT INVLG SKR2843X & SHC5453H(AXA) ON 18.03.2019
Attachments: EST & GIA.SKR2843X.pdf

smartclaim new case*

SPOKEN WITH SHARON -VEH IN ***KINDLY ARRANGE ADRIAN SURVEY TODAY

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kangcar@singnet.com.sg <kangcar@singnet.com.sg>
Sent: Tuesday, 19 March 2019 11:45 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>; NIKAM Santosh Pandurang <santosh.nikam@axa.com.sg>
Cc: Kang Car (yahoo) <kangcar176@yahoo.com.sg>; SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: NOTICE TO INSPECT OUR CLIENT'S VEHICLE SKR2843X; ACCDT INVLG SKR2843X & SHC5453H(AXA) ON 18.03.2019

WITHOUT PREJUDICE

Dear Sirs,

Our client's motor vehicle no: SKR2843X, which was damaged as a result of the above accident, is now lying at our premises/workshop, awaiting for repairs to be carried out.

As you are the insurers of motor vehicle SHC5453H, we hereby give you NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR VEHICLE at our premises/workshop. If your representative/surveyor does not inspect our client's damaged motor vehicle within the next two(2) days, we shall proceed to repair our client's damaged motor vehicle without any further notice and our client will thereafter look to you/your insured for the repair costs. This is without prejudice to our client's claim for damages, loss of use and incidental loss.

We enclosed herewith our estimate cost of repairs and our client's accident report for your reference.

Kindly forward us a list of your panel surveyors for our consideration.

Thank you & Regards,

Sharon

Kang Car Repairers Pte Ltd

Tel: 6747 7636

Fax: 6748 5071




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18013797/Gsd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 05-04-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SGQ 4284Z	Veh. Inspected	SKX 2153Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020794	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	19/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MR053REH104538075	Colour	BLUE	
Odometer	258488	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2018	Inspection Date	30/07/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 2153Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT AIRCON CONDENSER	NOT NECESSARY	1,712.45	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,218.85	-
2	FRONT BONNET HINGES L/R	NOT NECESSARY	270.20	-
2	FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	NOT NECESSARY	87.40	-
1	FRONT BONNET INNER RUBBER TOP MOULDING	NOT NECESSARY	135.10	-
1	FRONT BONNET INSULATOR MAT	NOT NECESSARY	303.10	-
1	FRONT BONNET MECHANISM LOCK	BENT	182.10	182.10
1	FRONT BRACE PANEL	BENT	100.40	100.40
1	FRONT BUMPER	SQUASHED	561.60	561.60
2	FRONT BUMPER FOGLAMP GARNISH L/R	NOT NECESSARY	364.50	-
2	FRONT BUMPER FOGLAMP L/R	NOT NECESSARY	563.40	-
1	FRONT BUMPER LOWER GRILLE	FRACTURED	191.40	155.40
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	374.40	-
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	NOT NECESSARY	220.70	-
2	FRONT BUMPER SIDE RETAINER L/R	NOT NECESSARY	264.20	-
1	FRONT BUMPER SPONGE	DEFORMED	87.00	87.00
1	FRONT GRILLE	FRACTURED	372.80	372.80
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	61.10	37.20
2	FRONT HEADLAMP L/R	FRACTURED	1,890.40	1,890.40
2	FRONT HORN L/R	NOT NECESSARY	364.20	-
1	REAR BOOTLID	BUCKLED	755.00	755.00
1	REAR BOOTLID 'ALTIS' EMBLEM	NECESSARY	48.00	48.00
1	REAR BOOTLID 'COROLLA' EMBLEM	NECESSARY	48.00	48.00
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	60.00	60.00
2	REAR BOOTLID HINGES L/R	NOT NECESSARY	133.80	-
2	REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	NOT NECESSARY	50.00	-
1	REAR BOOTLID INNER TRIM BOARD	DEFORMED	212.00	212.00
1	REAR BOOTLID MECHANISM LOCK	BENT	382.50	349.60
2	REAR BOOTLID NUMBER PLATE LAMP L/R	NOT NECESSARY	125.80	-
1	REAR BOOTLID OUTER CHROME GARNISH	NOT NECESSARY	231.30	-

Report Ref No. CS3/LPC18013797/Gsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BOOTLID REFLECTOR INNER BLACK RUBBER GASKET L/R	NOT NECESSARY	50.00	-
2	REAR BOOTLID REFLECTOR L/R	FRACTURED	710.00	710.00
1	REAR BOOTLID WEATHER STRIP	DEFORMED	185.00	185.00
1	REAR BUMPER	SQUASHED	482.30	482.30
2	REAR BUMPER REFLECTOR L/R	NOT NECESSARY	354.80	-
1	REAR BUMPER REINFORCEMENT	BENT	395.00	395.00
2	REAR BUMPER REINFORCEMENT BRACKET L/R	NOT NECESSARY	330.00	-
2	REAR BUMPER REVERSE SENSOR HOLDER L/R	NOT NECESSARY	24.00	-
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	REUSE	715.30	-
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	207.00	171.80
1	REAR END PANEL	BUCKLED	590.00	590.00
1	REAR END PANEL TOP GARNISH	FRACTURED	217.00	217.00
1	REAR EXHAUST GASKET	NOT NECESSARY	43.20	-
2	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	80.60	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	920.00	-
2	REAR FENDER INNER TRIM L/R	NOT NECESSARY	622.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	977.70	-
1	REAR SPARE TYRE LOCK SCREW	NOT NECESSARY	235.10	-
1	REAR SPARE TYRE PANEL TOP BOARD	DEFORMED	329.00	298.10
2	REAR TAILLAMP INNER BLACK RUBBER GASKET L/R	NOT NECESSARY	86.20	-
2	REAR TAILLAMP L/R	FRACTURED	790.00	790.00
2	REAR TAILLAMP LOWER BRACKET L/R	NOT NECESSARY	164.00	-
2	REAR TAILLAMP PANEL L/R	TO REPAIR SEE LABOUR	210.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	78.60	-
	LESS 25% DISCOUNT		-5,042.13	-2,174.68
			15,126.37	6,524.02
	NETT ITEMS			
2	REAR BUMPER REVERSE SENSOR L/R (N)	SHORTED	360.00	200.00
	LESS 10% DISCOUNT		-36.00	-20.00
			324.00	180.00

Report Ref No. CS3/LPC18013797/Gsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	25.00	10.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	BENT	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	60.00	10.00
1	REAR BOOTLID CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BOOTLID OUTER CHROME GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
2	SET REAR BOOTLID REFLECTOR CLIPS L/R (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	20.00
2	SET REAR FENDER INNER TRIM CLIPS L/R (SN)	NOT NECESSARY	160.00	-
1	REAR LH FENDER PETROL LID RIVET (SN)	NOT NECESSARY	20.00	-
1	REAR SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	60.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
			2,110.00	180.00
	<u>LABOUR</u>			
	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.		180.00	120.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		120.00	70.00
	TO REMOVE, REINSTALL WINDSCREEN (REAR).	NOT NECESSARY	150.00	-
	TO REMOVE, REINSTALL PETROL TANK (TO FR).	NOT NECESSARY	80.00	-
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		180.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		2,000.00	1,000.00

Report Ref No. CS3/LPC18013797/Gsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET, REAR LH FENDER AND REAR TAILLAMP PANEL L/R.		2,600.00	1,200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			5,610.00	2,510.00
GRAND TOTAL			23,170.37	9,394.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,500.00

Report Ref No. CS3/LPC18013797/Gsd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.