

LAW/MS/

ASSIGNMENT

REF: CS/MSG/1900500H/ED362

Approved Instruction

Surveyor

Hwei Jie

ASSIGNMENT (Office)

From (Person):

Clara Milah. Yeo

of

MSIG

Date/Time:

19-Mar-2019 16:34 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

XE 1080B

Insured:

at Workshop no:

Megastone Holdings Pte Ltd

Tel:

63655108 / 93719627

of

42A Sungai Kadut Street 1

Policy No:

28627607

Claim No:

586021

Sum Insured:

Excess:

\$2000.00

Make of Vehicle:

D.O.A.

22.2.2019

(Client's Record)

CA /

REV

/

REF:

/

REV 24 HRS

H.O.D. Endorsement:

Date/Time:

22.2.2019

9.30am

Person Contacted:

Fatt Chai

Vehicle:

(IN)

OUT

Date/Time:

Action/Instruction (✓) Estimate

XE 1080B - X

pending mv; Hwei Jie will let know.

revert via merimen.

22/3-

26/3@

15:31pm - authorise repair by too AI NGOH

26/3@

5:10pm - inform Fatt Chai authorise repair. excess \$2000

Three Die

MS19

VEHICLE INSURANCE

Date: 20.3.2019

Vehicle No: XE1080B

Policy No: 14 Oct 2015

Insured Party:

Type: M/Car / B/Cycle / Bus / Van / Lorry / Truck / Motor Vehicle

TP / WVS / TP RES / OD RES / LVA / HV / MV

Truck / Trailer or

Vehicle Make: XE 1080 B

Make: Hina FS1EK

Year: 12913

at Workshop: megastone Holdings

Colour: Blue

ACC: Insured / Std / HI / NA

at 42A Sungai Kadut Street 1

Chassis No: 231618

CR/CR: Insured / Std / HI / NA

Insured:

Engine:

Policy No:

Chassis No: FS1EK M10018

Claim No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess: \$2000+

Steering: Locked / Jammed / Loose / Burnt or

Policy Condition:

Brake: Locked / Jammed / Loose / Burnt or


Make of Vehicle:

Mod: NR / STD / Affirm or

Policy Condition:

Tyre Size: F: 295 / 80 R22.5

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firenza

Front

Rear

R/Rat: 7 mm R/Rat: 7 / 7 mm

L/Rat: 7 mm L/Rat: 7 / 7 mm

U.D.A: 22/2/19 D.O.J: 20/3/19

Survey held at megastone

Des. of Damages: Prt / Rmr / HS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

* 10/10/19 Mart Donald Eng... the electronic parts need technical report for

MU - \$105,000

PV - \$22,984

NV - \$82,016

RECEIVED 14 JAN 2020

Donald told need to wait his boss to look thru before can finalized.

Approval amount confirm with donald \$46,538.80. (Red: 22417-13: 32%)

File Name: File Path:

Prof. Report

Days Of Repair: 7

13/1 Typist

Final Report

Resurvey No. of Trip:

File Name: File Path:

Add Fee: [] Late byp: 15

[] Late byp: 15

[] Late byp: 15

[] Late byp: 15

Report Format:

OD

Comp Sum: 46,538.80

Category:

Subcategory:


Code:

Code:

Code:

Code:

Code:



...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2019		19 Mar 2019 16:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		SAMWOH CORPORATION PTE LTD, Co. Reg. No.: 198502202Z [Created by insurer]							
Vehicle Reg. No.:	XE1080B	Date of Loss:	22/02/2019 08:00 - :59 [49 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 586021	Policy/Cover Note No.:	28627607 (Comprehensive) Coverage: 14/10/2018 - 13/10/2019						
		Excess:	S\$2,000.00						
Repairer:	MEGASTONE HOLDINGS PTE LTD (HQ) 25E Sungei Kadut Street 1, 729333 Sungei Kadut - Tel: 63652066								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm. Advice due 20/03/2019]								
Driver/Custodian:	PANG WOO NEOW (67 / Male), NRIC: S2023527F, Tel: +6596758115 Email: NOEMAIL								
Adj Asg. Remarks:	Survey appt tmr at 1.30pm. Owner waiting at 42A Sungei Kadut Street 1, Singapore 729347. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert. Thanks.								
ASSOCIATED MAIL RECEIVED									
		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***XE1080B (586021)**

OD

Feb 22 2019 8:00AM

[SAMWOH CORPORATION PTE LTD]
MEGASTONE HOLDINGS PTE LTD

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 26/03/2019 15:31 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$57596.20) - XE1080B - Claim Handler: Clara Milah Yeo

Approved:57596.20.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2202Z
Vehicle Details	
Vehicle No.:	XE1080B
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	HINO
Vehicle Model:	HINO FS1EKMD-KAS
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	E13CWA11211
Chassis No.:	FS1EKM10018
Maximum Power Output:	-
Open Market Value:	\$82,942.00
Original Registration Date:	14 Oct 2015
First Registration Date:	14 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$4,148.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,038.00
COE Rebate Amount:	\$22,984.00
Total Rebate Amount:	\$22,984.00

The information contained herein is correct as at 21 Mar 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 22 Mar 2019

Preliminary Advice

Vehicle No	: XE1080B	Accident Date	: 22/02/2019
Make	: HINO FS1ELKD	Policy No.	: 28627607
Assignment Date	: 19/03/2019	Excess	: S\$2,000.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 7.00
Inspection At	: MEGASTONE HOLDINGS PTE LTD (HQ) 25E SUNGEI KADUT STREET 1 SINGAPORE 729333		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	63,071.04
Revised Amount	:S\$	7,526.40
Check Items (Estimated)	:S\$	50,069.80
Total	:S\$	57,596.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	22,984.00
Salvage Value	:S\$	
Margin for Repair	:S\$	82,016.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 21 Mar 2019

Preliminary Advice

Vehicle No	: XE1080B	Accident Date	: 22/02/2019
Make	: HINO FS1ELKD	Policy No.	: 28627607
Assignment Date	: 19/03/2019	Excess	: S\$2,000.00
Date of Inspection	: 20/03/2019	Est. Duration of Repair	: 7.00
Inspection At	: MEGASTONE HOLDINGS PTE LTD (HQ) 25E SUNGEI KADUT STREET 1 SINGAPORE 729333		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	63,071.04
Revised Amount	:S\$	7,526.40
Check Items (Estimated)	:S\$	50,069.80
Total	:S\$	57,596.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.
Pending market value, will re-mandate again once market value is confirm.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 12:40
Date Of Accident	22/02/2019 08:15
Exact Location Of Accident	TUAS SOUTH BOLEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE1080B
Insured/Policyholder	
Name Of Registered Owner	SAMWOH CORPORATION PTE LTD
Co Reg No	198502202Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96758115
Alternative Phone No	OFFICE-96758115
Vehicle Particulars	
Manufacturer	HINO
Model	FS1ELKD-12.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28627607 MKC
Cover Note Number	
Driver	
Name of Driver	PANG WOO NEOW
NRIC No	S2023527F
Date Of Birth	25/10/1951
Occupation	OUTDOOR
Date Of Driving Pass	10/01/1975
Driving Experience	44 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96758115
Fax Number	
Contact Number	OFFICE-96758115
E Mail Address	NOEMAIL

Address	924 JURONG WEST ST 92 #03-11
Postcode	S640924
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. SPOKEN TO JOWLYN OF MSIG TO PROCEED AS VEHICLE NOT PRESENT TO PHOTO TAKING

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	WEIGH BRIDGE
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- E. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

25 FEB 2019
VAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/19 8.15am I was at site (HueiDang) as I am duty to discard waste soil to the said site - Thus south Boulevard
As usual I report and proceed to the weigh Bridge for the soil tonnage. Upon completion, I prepare to leave the weigh Bridge with slow speed, suddenly my lorry lost control and crash into the right side weigh Bridge railing, one of the tank (for chemical) and my steering pump damaged. No body injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Date & Sign:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

25 FEB 2019

IDAG BUKIT BATOK (P) LTD
511 Bukit Batok Street 22
Singapore 650542
Tel: 6560 3312 Fax: 6560 0722
E-mail: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No. _____

**MSIG****MSIG Insurance (Singapore) Pte. Ltd.**

4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form: M.E.300

Goods Carrying Vehicle - Veh I

COMMERCIAL VEHICLE**Comprehensive**

Certificate No. B 28627607 MKC

Excess: SGD2,000

1. Index Mark and Registration Number of Vehicle

XB1080B

2. Name of Policyholder

Samwon Corporation Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

14/10/2018

4. Date of Expiry of Insurance

13/10/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.

Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover:

(1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

(WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

CF

10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref 1510150401N014028730

15 Oct 2015

SAMWOH CORPORATION PTE LTD
25E SUNGEI KADUT STREET 1
SINGAPORE 729333



Dear Sir/Madam

**NOTIFICATION OF SUCCESSFUL AMENDMENT OF VEHICLE SPECIFICATION FOR
VEHICLE NO. XE1080B**

We wish to inform you that we have updated the following specification(s) for your vehicle, XE1080B, with effect from 15 Oct 2015. The Business Transaction Reference No. is 20151015075424061834.

Vehicle Details:	Original Specifications	New Specifications
Primary Colour :	White	Blue

2. The following are the key owner and vehicle particulars for the vehicle. The full particulars are given at Annex A. Please check and ensure that the details are correct.

1.	Name	: SAMWOH CORPORATION PTE LTD
2.	Identification No. Type	: Company
3.	Identification No.	: 198502202Z
4.	Place Of Passport Issue	: -
5.	Vehicle No.	: XE1080B
6.	Vehicle Type	: B33 - Goods (Open) Tipper/Dumper Truck
7.	Vehicle Scheme	: Normal
8.	Vehicle Make	: HINO
9.	Vehicle Model	: HINO FS1EKMD-KAS
10.	Remarks	: -

3. Please contact our customer service officers at tel: 1800-CALL LTA (1800-2255 582) should you require further assistance.

4. Thank you.

Yours sincerely

NG LAY CHOO (MS)
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS
VEHICLE SERVICES GROUP
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)



SAMWOH GROUP OF COMPANIES

25E Sungai Kaih Street 1, Singapore 729133
Tel: 6269 7288 Fax: 6168 2885

INTERNAL ACCIDENT REPORT FORM

USER PARTICULAR / DRIVER / OPERATOR			
Vehicle / Machine No:	XE 1080B	Date / Time of Accident:	22.2.19 8.15am
Exact Location of Accident:	Tuas South Boulevard		
Name Of Driver / Operator:	Pang Woo Neow	Company / Department:	C#2
NRIC / FIN / Passport Number:	S2023527 F	Contact No:	96258115
Class of License:		License No:	
Event of Accident: On 22/2/19 8.15am I was visiting site office as I need to discard waste soil, before discard, I as usual report and proceed to weigh bridge, upon completion, while leaving the weigh bridge my lorry suddenly lost control and crash right side of the weigh bridge railing, one of the tank (contain chemical water) and steering pump damaged.			
Witness (if any):		Contact No:	
Detail of Damaged / Injuries:		Have you informed the police?	YES / NO
Photograph(s) taken?	YES / NO	Have you report to IDAC?	YES / NO
Have you informed to relevant authorities?	YES / NO		
Driver / Operator:		Person-in-charge:	
Signature / Date:		Signature / Date:	
THIRD PARTY PERSON DETAILS AND VEHICLE / PROPERTY DAMAGED ITEMS			
Vehicle No. / Property:		Name:	
NRIC / FIN / Passport Number:		License No:	
Contact No:		Company:	
Insurance Company:			
Damaged To Third Party Vehicle / Property:			
DETAIL OF CLAIM / REPAIR DAMAGE VEHICLE / MACHINERY			
Own Claim:	YES / NO	Samwoh Workshop	Other Workshop
Third Party Claim:	YES / NO	Samwoh Workshop	Other Workshop
Third Party Vehicle Repair By:		Samwoh Workshop	Other Workshop
Private Settlement:	YES / NO		
WORKSHOP / INSURANCE CLAIM DEPARTMENT COMMENTS			
Detail of Comments:			
Est. Repair Cost \$:			
Bill To: Driver / Operator ☐ Department ☐ Third Party ☐			
Recommendation By:			
Name / Signature / Date:			
APPROVED BY HEAD OF DEPARTMENT			
Comments and Recommendation by Head of Department:			
Name / Signature / Date:			
Approved Claim Amount \$:			
Bill To: Driver / Operator ☐ Department ☐ Third Party ☐			
ACKNOWLEDGE BY DRIVER / OPERATOR			
I, _____, authorise Company to deduct the repair cost of \$ _____ from my salary.			
The deduction shall be as follows:			
per month ☐ X No. of months ☐ total = _____			
Signature / Date:			
cc:			
HR - To deduct the repair cost upon endorse by Department Head.			
Finance - For info only			
Donald 25 May 2011			

Note: Return to Workshop for safe keeping and billing.

Return On: _____



18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

	Description	Qty	U/Price	Total Price	
	Gear Assy, Power Steering ? / Janned	1 pc	\$8,013.60	\$8,013.60	
	Link Assy, Steering ? / BT	1 pc	\$956.20	\$956.20	
	Column Assy, Steering ? / Janned	1 pc	\$1,240.10	\$1,240.10	
Q	Holder ? / X N/A	1 pc	\$972.40	\$972.40	X
	Bracket Assy UREA BT	1 pc	\$843.50	\$843.50	
	Bracket sub assy UREA BT	1 pc	\$673.30	\$673.30	
	Bolt n/c	2 pcs	\$6.50	\$13.00	
	Nut n/c	2 pcs	\$2.20	\$4.40	
Short	Sensor Assy, UREA ? / X N/A	1 pc	\$1,288.30	\$1,288.30	
	Tank Sub assy, UREA CUT	1 pc	\$1,576.20	\$1,576.20	
	Cap Assy, UREA Tank n/c X	1 pc	\$113.40	\$113.40	
	Arm Sub Assy, Rocket ? / X N/A	1 pc	\$75.20	\$75.20	
	Insulator sub assy ? / X DO	1 pc	\$518.30	\$518.30	
DO	Insulator, Main ? / X N/A	1 pc	\$85.00	\$85.00	
Short	Injector assy, UREA ? / X N/A	1 pc	\$1,455.20	\$1,455.20	
Short	Pump Assy, UREA ? / X N/A	1 pc	\$4,695.80	\$4,695.80	
	Pipe sub Assy, Exhaust DO	1 pc	\$1,897.40	\$1,897.40	
Short	Wire Engine ? / X N/A	1 pc	\$309.90	\$309.90	
Short	Wire assy Engine ? / X N/A	1 pc	\$210.20	\$210.20	
	Valve Assy, Engine ? / X CPA	1 pc	\$228.10	\$228.10	
n/c	Hose sub assy Water ? / X N/A	1 pc	\$28.00	\$28.00	
n/c	Hose sub assy ? / X N/A	1 pc	\$23.80	\$23.80	
n/c	Hose water ? / X N/A	1 pc	\$12.00	\$12.00	
n/c	Water Hose ? / X N/A	1 pc	\$8.30	\$8.30	
n/c	Pipe sub assy Water ? / X N/A	2 pcs	\$128.00	\$256.00	
n/c	Hose sub assy ? / X N/A	1 pc	\$167.00	\$167.00	
	Bracket ? / X BT	1 pc	\$125.40	\$125.40	
	Bracket sub assy ? / X BT	1 pc	\$232.80	\$232.80	
	Bracket Assy ? / X BT	1 pc	\$85.30	\$85.30	
	Bracket Sub Assy PL ? / X BT	1 pc	\$123.20	\$123.20	
n/c	Hose Assy ? / X N/A	1 pc	\$545.50	\$545.50	
n/c	Hose Sub Assy, Water ? / X N/A	1 pc	\$79.00	\$79.00	
Short	Sensor, Temperature ? / X N/A	1 pc	\$203.20	\$203.20	
Short	Sensor, Exhaust Gas ? / X N/A	1 pc	\$145.70	\$145.70	
Short	Sensor Lean Mixture ? / X N/A	2 pcs	\$1,333.80	\$2,667.60	
	Pipe sub Assy Exhaust DO	1 pc	\$909.70	\$909.70	

53285

Gasket, Exhaust Main	✓	1 pc	\$88.90	\$88.90	✓
Computer Assy Emission	✓	1 pc	\$2,877.70	\$2,877.70	✓
Flange Exhaust Pipe	✓	2 pcs	\$130.50	\$261.00	✓
Gasket Exhaust Pipe	✓	4 pcs	\$195.50	\$782.00	✓
Support Exhaust Pipe	✓	3 4 pcs	\$109.50	\$438.00	✓
Support Exhaust Pipe	✓	1 pc	\$89.00	\$89.00	✓
Converter Assy	✓	1 pc	\$9,342.30	\$9,342.30	
Converter Assy Mono	✓	1 pc	\$6,648.40	\$6,648.40	
Chamber sub Assy INL	✓	1 pc	\$909.40	\$909.40	
Chamber Sub Assy MIX	✓	1 pc	\$1,636.60	\$1,636.60	
Chamber sub Assy SCR	✓	1 pc	\$1,663.60	\$1,663.60	
Chamber Sub Assy OUT	✓	1 pc	\$671.00	\$671.00	
			Total Parts	\$56,189.90	
Labour Charge					
Labour to Remove & Replace Above Parts Assy		1 job	\$2,250.00	\$2,250.00	
Labour to Re-programming Engine ECU		1 job	\$225.00	\$225.00	120
All Wheel Alignment Provide Report		1 job	\$280.00	\$280.00	200
			Total Labour:	\$2,755.00	
			Sub-Total:	\$58,944.90	
			7% GST	\$4,126.14	
			Grand Total	\$ 63,071.04	

Thanks,

Jou Chung Fat
Workshop In-charge



[Signature]
26/3/19
Hwee Lin - LKK

20/3/19

c/s 2days.

and Authorise

Excess: \$2000+

Workshop In-charge

Signature: _____

Date: _____



Steve 24/6/19

06th Jun 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Supplementary quotation for supply parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Bracket Assy, CA / DD	1 pc	\$1,610.40	✓ \$1,610.40
Bracket Sub Assy, CA / DT	1 pc	\$1,129.10	✓ \$1,129.10
Support, Exhaust Pipe X DT 26.6.2019	1 pc	\$109.50	\$109.50 X NH
Member Sub Assy, FR / DT	1 pc	\$706.30	✓ \$706.30
Hose Sub Assy, Water / DT	1 pc	\$23.80	\$23.80
Bracket Sub Assy, URE / DT	1 pc	\$673.30	✓ \$673.30
Bracket Sub Assy, UREA / DT	1 pc	\$843.50	\$843.50
Bracket Sub Assy, HO X	1 pc	\$232.80	\$232.80 X NH
Splash Board, Side RH / BR	1 pc	\$171.20	\$171.20
		Total Parts	\$5,499.90
		Sub-Total:	\$5,499.90
		7% GST	\$384.99
		Grand Total	\$ 5'884.89

Thanks,

Jou Chung Fat
Workshop In-charge



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Hino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462

Tel no.: 6631-1108 / 6631-1818
Customer Detail

TAX INVOICE

Account Detail	Account No	Customer Detail
Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333	S1000950 / SAMWOH	M/s Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333 Attn: Sam Tan Work: 62697288
	Document No 41037359	
	Document Date 28/06/2019	

Year	Make	Model	Reg Date	Web Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKMD	14/10/2015	XE1080B	231620	30661	XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

FS1EKM10018 E13CWA11211 30 Henry Lau 22/03/2019 13.35 28/06/2019 11.05

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
20	3	H87209-E0090 HOSE SUB-ASSY, WATER	1.00	28.00	40.00	16.80
21	4	H87209-E0830 HOSE SUB-ASSY, WATER	1.00	23.80	40.00	14.28
22	5	H87209-E0113 HOSE SUB-ASSY, WATER	1.00	167.00	40.00	100.20
23	6	H87208-E0473 PIPE SUB-ASSY, WATER	2.00	128.00	40.00	153.60
24	7	H87245-E0800 HOSE, WATER	1.00	12.00	40.00	7.20
25	8	H87245-E0860 HOSE, WATER	1.00	8.30	40.00	4.98
26	9	HS4702-E0283 BRACKET SUB-ASSY, HO	1.00	85.30	40.00	51.18
27	0	HS4702-E0561 BRACKET SUB-ASSY, HO	1.00	125.40	40.00	75.24
28	1	HS4702-E0830 BRACKET SUB-ASSY, HO	1.00	232.80	40.00	139.68
29	2	HS5005-E0122 BRACKET SUB-ASSY, PI	1.00	123.20	40.00	73.92
30	3	H87209-E0621 HOSE SUB-ASSY, WATER	1.00	29.00	40.00	47.40
31	4	H87209-E0601 HOSE SUB-ASSY, WATER	1.00	545.50	40.00	327.30
32	5	H89425-E0050 SENSOR, EXHAUST GAS	1.00	145.70	40.00	87.42
33	6	H89429-E0050 SENSOR, TEMPERATURE	1.00	203.20	40.00	121.92
34	7	H89463-E0013 SENSOR, LEAN MIXTURE	2.00	133.80	40.00	160.56
35	8	H17405-E0780 PIPE SUB-ASSY, EXHAU	1.00	909.70	40.00	545.82
36	9	H17173-E0090 GASKET, EXHAUST MANI	1.00	88.80	40.00	53.28
37	0	H89550-E0046 COMPUTER ASSY, EMISS	1.00	2877.70	40.00	1726.62
38	1	H17441-E0250 FLANGE, EXHAUST PIPE	2.00	130.50	40.00	156.60
39	2	H17451-E0060 GASKET, EXHAUST PIPE	4.00	195.50	40.00	469.20

CERTIFIED TRUE COPY

27 SEP 2019

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of	Customer's Signature	Change Summary	Total
Borneo Motors HENRY LAU SERVICE ENGINEER DD: 6631-1108 HP: 6794-4148 FAX: 6365-5097		Parts Labour Materials Lubrication/Fluid Others	Less Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 11 INCHCAPE CENTRE, SINGAPORE 128462

4012705



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Rino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462

Tel No: 6631 1188 / 6631 1818
Customer Detail

Account Detail	Account No	
Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333	S1000950 / SAMWOH	
	Document No	M/s Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1
	41037359	
	Document Date	Singapore 729333
	28/06/2019	Attn: Sam Tan Work: 62697288

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKMD	14/10/2015	XE1080B	231620	30661	PR 115033 XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
FS1EKM10019	E13CWA11211	30	Henry Lau	22/03/2019 13.35	28/06/2019 11.05		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
40	3	H17564-E0230 SUPPORT, EXHAUST PIP	1.00	89.00	40.00	53.40
41	4	HS1806-E0020 CHAMBER SUB-ASSY, INL	1.00	909.40	40.00	545.64
42	5	HS1808-E0010 CHAMBER SUB-ASSY, MIX	1.00	1636.60	40.00	981.96
43	6	HS1809-E0010 CHAMBER SUB-ASSY, SCR	1.00	1663.60	40.00	998.16
44	7	HS180A-E0010 CHAMBER SUB-ASSY, OUT	1.00	671.00	40.00	402.60
45	8	H17564-E0210 SUPPORT, EXHAUST PIP	1.00	109.50	40.00	65.70
46	9	H87240-E0030 VALVE ASSY, WATER	1.00	228.10	40.00	136.86
47	0	HS17J0-E0011 INJECTOR ASSY UREA	1.00	1455.20	40.00	873.12
48	1	H45897-E0020 BOLT, STEERING LOCK	2.00	4.30	40.00	5.16
49	2	H17564-E0210 SUPPORT, EXHAUST PIP	2.00	109.50	40.00	131.40
50	3	H17564-E0210 SUPPORT, EXHAUST PIP	1.00	109.50	40.00	65.70
51	4	HS53A1-E0030 SPLASHBOARD, SIDE RH	1.00	171.20	40.00	102.72
52	T	RECORD FOR RECORD PURPOSE.		0.00		

REMARK : 115SD

Backchange to 30-536

Accident claim

**CERTIFIED
TRUE COPY**



Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
BORNEO MOTORS (S) PT. HENRY LAU SERVICE ENGINEER DID: 6631 1805 HP: 6734 5195 FAX: 6631 8097	Please acknowledge receipt of vehicle 	Parts 22,687.26 Labour 12,341.74 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	35,029.00 GST 7.00% 2,452.03 Less 0.00 Amount Due 37,481.03

PLEASE MAIL YOUR CHEQUE TO: 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

401270



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Rino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462

Tel no.: 6631 1188 / 6631 1818
Customer Detail

TAX INVOICE

Account Detail	Account No	
Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333	S1000950 / SAMWGH	
	Document No	M/s Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1
	41037359	
	Document Date	Singapore 729333
	28/06/2019	Attn: Sam Tan Work: 62697288

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKMD	14/10/2015	XE1080B	231620	30661	XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

FS1EKM1001B E13CWA11211 30 Henry Lau 22/03/2019 13.35 28/06/2019 11.05

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	A	11504ARE LABOUR TO REMOVE AND REPLACE ABOVE PARTS	33	2250.00	30.00	1575.00
		ASSY				
2	A	86306ARE LABOUR TO RE-PROGRAMMING ENGINE ECU	66	225.00	30.00	157.50
3	Z	ZZ CONVERTER ASSY SCR		5605.38		5605.38
4	Z	ZZ CONVERTER ASSY MONO		3989.04		3989.04
5	Z	ZZ HOLDER		583.44		583.44
6	Z	ZZ BRACKET, EXHAUST PIP		151.38		151.38
7	Z	ZZ ADJUST WHEEL ALIGNMENT		280.00		280.00
8	1	H44110-E0050 GEAR ASSY, POWER STE	1.00	8031.60	40.00	4818.96
9	2	H45440-E0S11 LINK ASSY, STEERINGD	1.00	956.20	40.00	573.72
10	3	H45250-E0051 COLUMN ASSY, STEERIN	1.00	1240.10	40.00	744.06
11	4	HSG400-E0012 SENSOR ASSY UREA	1.00	1288.30	40.00	772.98
12	5	HS17G1-E0030 TANK SUB-ASSY, UREA	1.00	1576.20	40.00	945.72
13	6	HS17GA-E0020 CAP, UREA TANK5	1.00	113.40	40.00	68.04
14	7	HS17H0-E0042 PUMP ASSY, UREA	1.00	14695.80	40.00	8817.48
15	8	H17401-E0L30 PIPE SUB-ASSY, EXHAU	1.00	1897.40	40.00	1138.44
16	9	HS170B-E0063 INSULATOR SUB-ASSY,	1.00	518.30	40.00	310.98
17	0	H58327-E0011 INSULATOR, MAIN MUFF	1.00	85.00	40.00	51.00
18	1	H82121-E1A72 WIRE, ENGINE	1.00	210.20	40.00	126.12
19	2	H82121-E1A50 WIRE, ENGINE	1.00	306.90	40.00	184.14

**CERTIFIED
TRUE COPY**

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
BORNEO MOTORS (S) PTE LTD HENRY LAU SERVICE ENGINEER MOB: 6631 1805 HP: 9794 6195 FAX: 8305 9007	Please acknowledge receipt of vehicle 	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462


4012706



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota PL account & more!

TAX INVOICE



Borneo Motors (Singapore) Pte Ltd

Online Service Booking: 1206/1
www.toyota.com.sg 120470/1206/1

Hino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462

Tel no.: 6631 1188 / 6631 1818
Customer Detail

Account Detail		Account No	Customer Detail	
Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333		S1000950 / SAMWOH	M/s Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333 Attn: Sam Tan Work: 62697288	
		Document No		
		41037360		
		Document Date		
		28/06/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKM0	14/10/2015	XF1080B	231620	30661	XF1080B
Chassis No		Engine No		Terms		Service Engineer	Vehicle In
FS1EKM10018		E13CWA11211		30		Henry Lau	22/03/2019 13.35 28/06/2019 11.05

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
---	----	-----------------------	-----	------------	--------	--------

1	1	HS170F-E0261	BRACKET SUB-ASSY, URE	1.00	673.30	40.00	403.98
2	2	HS170F-E0271	BRACKET SUB-ASSY, URE	1.00	843.50	40.00	506.10
3	3	H17503-E0090	BRACKET SUB-ASSY, CA	1.00	1610.40	40.00	966.24
4	4	H17503-E0101	BRACKET SUB-ASSY, CA	1.00	1129.10	40.00	677.46
5	5	HS3705-E0460	MEMBER SUB-ASSY, FR	1.00	706.30	40.00	423.78

Backcharge to 202-584/
Accident claim



CERTIFIED TRUE COPY

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors HENRY LAU SERVICE ENGINEER MO: 8631 1805 HP: 9794 5195 FAX: 8365 6097	Customer's Signature Please acknowledge receipt of vehicle	Charge Summary Parts Labour 2,977.56 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	Total 2,977.56 GST 7.00% 208.43 Less 0.00 Amount Due 3,185.99
---	---	---	---

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

4012699



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Hino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462

Tel no.: 6631 1188 / 6631 1818

Account Detail	Account No	Customer Detail
Service Retail Cash Sales Pandan Hino Service Service Retail Cash Sales Pandan Hino Service	c0100041/HNPREC Document No 41043812 Document Date 18/11/2019	M/s Samwoh Corporation Pte Ltd 25E Sungei Kadut Street 1 Singapore 729333 Attn: Sam Tan Work: 62697288

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKM	14/10/2015	XE1080B	231620	30661	XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
FS1EKM10018	E13CWA11211	00	Henry Lau	22/03/2019 13.35	28/06/2019 11.05		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	T	RECORD TECHNICAL REPORT ON VEHICLE XE1080B 1.P2032 : INLET EXHAUST GAS TEMPERATURE SENSOR STANDARD : 50 DEGREE AT 9.7 K? RESULT : 15.8K? ACTION : REPLACE SENSOR		0.00		
2	T	RECORD 2.P2033 OUTLET EXHAUST GAS TEMPERATURE S ENSOR STANDARD : 50 DEGREE AT 9.7 K? RESULT : 3.8 K? ACTION : REPLACE SENSOR		0.00		
3	T	RECORD 3.P204F DCU ASSY STANDARD : ENGINE CODE CAN BE CLEAR RESULT : CANNOT ERASE CODE ACTION : REPLACE DCU ASSY		0.00		
4	T	RECORD 4.P204B ADNORMALITY IN ASBLUE PRESSURE S ENSOR STANDARD : ENGINE CODE CAN BE CLEAR RESULT : CANNOT ERASE CODE ACTION : REPLACE PUMP ASSY		0.00		

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4111865

TO SECURITY GUARD

4111865

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/11/2019
TIME 13:46

VEHICLE NO XE1080B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg
Hino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462
Tel no.: 6631 1188 / 6631 1818

Account Detail	Account No	Customer Detail
Service Retail Cash Sales Pandan Hino Service	c0100041/HNPPREG	M/s Samwoh Corporation Pte Ltd
Service Retail Cash Sales Pandan Hino Service	Document No 41043812	25E Sungei Kadut Street 1
	Document Date 18/11/2019	Singapore 729333 Attn: Sam Tan Work: 62697288

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKMD	14/10/2015	XE1080B	231620	30661	XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
FS1EKM10018	E13CWA11211	00	Henry Lau	22/03/2019 13.35	28/06/2019 11.05		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
5	T	RECORD 5.P2201 ADNORMALITY IN UPSTREAM NOX SENS OR STANDARD : 24V WHEN SWITCH ON IGNITION RESULT : NO CURRENT WHEN SWITCH ON IGNITION ACTION : REPLACE NOX SENSOR		0.00		
6	T	RECORD 6.P2214 ADNORMALITY IN DOWN STREAM NOX S ENSOR STANDARD : 24v WHEN SWITCH ON IGNITION RESULT : NO CURRENT WHEN SWITCH ON IGNITION ACTION : REPLACE NOX SENSOR		0.00		
7	T	RECORD 7.P203C MALFUNCTION OF ADBLUE TANK LEVEL SENSOR STANDARD : 20 DEGREE AT 15 K? RESULT : 8K? ACTION : REPLACE SENSOR ASSU UREA		0.00		
8	T	RECORD 8. P2047 MALFUNCTION OD ADBLUE INJECTOR STANDARD : WHEN DISCONNECT THE INJECTOR WIRE CONNECTOR THE WIRE CONNECTOR ? SHOULD BE FROM 11K? - 12K? RESULT : 15K? ACTION : REPLACE INJECTOR UREA		0.00		
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	0.00
		Labour 0.00	GST 7.00%
		Materials 0.00	0.00
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 0.00

PLEASE TAKE YOUR PERFORMED CAR

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/11/2019
TIME 13:46

VEHICLE NO XE1080B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor

4111866

4111866



Reg No : 196700086Z
ST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyota.com.sg
Hino Service Centre
No. 2 PANDAN CRESCENT
SINGAPORE 128462
Tel no.: 6631 1188 / 6631 1818

Account Detail

Service Retail Cash Sales Pandan Hino Service
Service Retail Cash Sales
Pandan Hino Service

Account No
C0100041 / HNPCREG
Document No
41043812
Document Date
18/11/2019

Customer Detail

M/s Samwoh Corporation Pte Ltd
25B Sungai Kadut Street 1
Singapore 729333
Attn: Sam Tan
Work: 62697208

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKMD	14/10/2015	XE1080B	231620	30661	XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
FS1EKMD10018	E13CWA11211	00	Henry Lau	22/03/2019 13.35	28/06/2019 11.05		

L	Co	Job/Parts Description	Qty	Unit Price	Disc %	Amr
5	T	RECORD 5. P2201 ADNORMALITY IN UPSTREAM NOX SENS OR STANDARD : 24V WHEN SWITCH ON IGNITION RESULT : NO CURRENT WHEN SWITCH ON IGNITION No. 35 ACTION : REPLACE NOX SENSOR ✓	2 items	0.00		
6	T	RECORD 6. P2214 ADNORMALITY IN DOWN STREAM NOX S ENSOR STANDARD : 24V WHEN SWITCH ON IGNITION RESULT : NO CURRENT WHEN SWITCH ON IGNITION No. 35 ACTION : REPLACE NOX SENSOR ✓		0.00		
7	T	RECORD 7. P203C MALFUNCTION OF ADBLUE TANK LEVEL SENSOR STANDARD : 20 DEGREE AT 15 K? No. 9 RESULT : 8K? ACTION : REPLACE SENSOR ASSU UREA ✓		0.00		
8	T	RECORD 8. P2047 MALFUNCTION OF ADBLUE INJECTOR STANDARD : WHEN DISCONNECT THE INJECTOR WIRE CONNECTOR THE WIRE CONNECTOR ? SHOULD BE FROM 11K? - 12K? RESULT : 15K? No. 15 ACTION : REPLACE INJECTOR UREA ✓		0.00		
Borneo Motors is the only authorised workshop to maintain your Toyota, Borneo Motors Toyota only Guarantee 11000 km / 100000 km whichever comes first to enjoy your warranty benefits. Conditions apply						

For & on behalf of
Borneo Motors

Customer's Signature

Please acknowledge receipt of vehicle

Change Summary

Total	0.00
GST 7.00%	0.00
Less	0.00
Amount Due	0.00

411186

411186

O SECURITY GUARD

DATE 18/11/2019
TIME 13:46

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES

VEHICLE NO XE1080B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Moto



o Reg No : 196700086Z
ST Reg No : MR-8500000-9

ownload "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Rino Service Centre

No. 2 PANDAN CRESCENT

SINGAPORE 128462

Tel no. : 6631 1188 / 6631 1818

Account Detail	Account No	Customer Detail
Service Retail Cash Sales Pandan Rino Service Service Retail Cash Sales Pandan Rino Service	c0100041 / HNPCREG	M/s Samwoh Corporation Pte Ltd 25B Sungei Kadut Street 1 Singapore 729333 Attn: Sam Tan Work: 62697288
	Document No 41043812	
	Document Date 18/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	KAS	FS1EKM	14/10/2015	XE1080B	231620	30661	XE1080B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
FS1EKM10018	E13CWA11211	00	Henry Lau	22/03/2019 13.35	28/06/2019 11.05		

L	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1 T	RECORD TECHNICAL REPORT ON VEHICLE XE1080B 1.P2032 : INLET EXHAUST GAS TEMPERATURE SENSOR ✓ STANDARD : 50 DEGREE AT 9.7 K? No.33 RESULT : 15.8K? ACTION : REPLACE SENSOR		0.00		
2 T	RECORD 2.P2033 OUTLET EXHAUST GAS TEMPERATURE S ✓ ENSOR STANDARD : 50 DEGREE AT 9.7 K? RESULT : 3.8 K? No.34 ACTION : REPLACE SENSOR		0.00		
3 T	RECORD 3.P204F DCU ASSY STANDARD : ENGINE CODE CAN BE CLEAR No.38 RESULT : CANNOT ERASE CODE ACTION : REPLACE DCU ASSY ✓		0.00		
4 T	RECORD 4.P204B ADNORMALITY IN ASBLUE PRESSURE S ENSOR STANDARD : ENGINE CODE CAN BE CLEAR RESULT : CANNOT ERASE CODE ACTION : REPLACE PUMP ASSY ✓ No.16		0.00		

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 10,000km or 6 months (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

411186!

411186!

SECURITY GUARD

411186!

LEASE ALLOW THE UNDERMENTIONED
EHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/11/2019
TIME 13:46

VEHICLE NO XE1080B

USTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

inform surveyor 21/11/2019

Technical Report On Vehicle XE1080

quotation

Technical Report On Vehicle XE1080						Your list No.
S/N	Engine Code	Diagnosis Item	Standard	Result	Action	
1.	P2032	Inlet EXHAUST GAS TEMPERATURE SENSOR	50 degree (3.7kΩ)	15.8kΩ	Replace Sensor	23
2.	P2033	Outlet EXHAUST GAS TEMPERATURE SENSOR	50 degree (3.7kΩ)	3.8kΩ	Replace Sensor	24
3.	P204F	OCU Assy	engine code can be clear	Cannot erase code	Replace OCU assy	38
4.	P204B	Adnormality in adblue pressure sensor	engine code can be clear	Cannot erase code	Replace Pump Assy	18
5.	P2201	Adnormality in upstream NOX sensor	24V when switch on ignition	No current when switch on ignition	Replace NOX sensor	35
6.	P2214	Adnormality in downstream NOX sensor	24V when switch on ignition	No current when switch on ignition	Replace NOX sensor	35
7.	P203C	Malfunction of adblue tank level sensor	20 degree (15kΩ)	8kΩ	Replace Sensor Assy Urea	9
8.	P2047	Malfunction of adblue injector	when disconnect the injector wire connector the Ω should be from 11kΩ - 12kΩ	15kΩ	injector Assy, Urea	15

No	Description	Qty	Borneo Motors
4	Holder	1	Dented
9	Sensor Assy, Urea	1	not sending signal
14	Insulator, Main	1	Dented
15	Injector Assy, Urea	1	not working
16	Pump Assy, Urea	1	not pumping SCR
18	Wire Engine	1	harness poor connection
19	Wire Assy Engine	1	harness poor connection
21	Hose Sub Assy Water	1	leaking, chocking & deform
22	Hose Sub Assy Water	1	leaking, chocking & deform
23	Hose water	1	leaking, chocking & deform
24	Water Hose	1	leaking, chocking & deform
25	Pipe sub assy water	2	leaking, chocking & deform
26	Hose sub assy	1	leaking, chocking & deform
31	Hose assy	1	leaking, chocking & deform
32	Hose sub assy water	1	leaking, chocking & deform
33	Sensor temperature	1	engine faulty code
34	Sensor, exhaust gas	1	engine faulty code
35	Sensor lean mixture	2	engine faulty code
37	Gasket exhaust main	1	dented
38	Computer assy emission	1	ECU light on



✓ - Given

X - not Given

18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

	Description	Qty	U/Price	Total Price
1	Gear Assy, Power Steering	1 pc	\$8,013.60	\$8,013.60
2	Link Assy, Steering	1 pc	\$956.20	\$956.20
3	Column Assy, Steering	1 pc	\$1,240.10	\$1,240.10
4	Holder	1 pc	\$972.40	\$972.40
5	Bracket Assy UREA	1 pc	\$843.50	\$843.50
6	Bracket sub assy UREA	1 pc	\$673.30	\$673.30
7	Bolt	2 pcs	\$6.50	\$13.00
8	Nut	2 pcs	\$2.20	\$4.40
9	Sensor Assy, UREA	1 pc	\$1,288.30	\$1,288.30
10	Tank Sub assy, UREA	1 pc	\$1,576.20	\$1,576.20
11	Cap Assy, UREA Tank	1 pc	\$113.40	\$113.40
12	Arm Sub Assy, Rocket	1 pc	\$75.20	\$75.20
13	Insulator sub assy	1 pc	\$518.30	\$518.30
14	Insulator, Main	1 pc	\$85.00	\$85.00
15	Injector assy, UREA	1 pc	\$1,455.20	\$1,455.20
16	Pump Assy, UREA	1 pc	\$4,695.80	\$4,695.80
17	Pipe sub Assy, Exhaust	1 pc	\$1,897.40	\$1,897.40
18	Wire Engine	1 pc	\$309.90	\$309.90
19	Wire assy Engine	1 pc	\$210.20	\$210.20
20	Valve Assy, Engine	1 pc	\$228.10	\$228.10
21	Hose sub assy Water	1 pc	\$28.00	\$28.00
22	Hose sub assy	1 pc	\$23.80	\$23.80
23	Hose water	1 pc	\$12.00	\$12.00
24	Water Hose	1 pc	\$8.30	\$8.30
25	Pipe sub assy Water	2 pcs	\$128.00	\$256.00
26	Hose sub assy	1 pc	\$167.00	\$167.00
27	Bracket	1 pc	\$125.40	\$125.40
28	Bracket sub assy	1 pc	\$232.80	\$232.80
29	Bracket Assy	1 pc	\$85.30	\$85.30
30	Bracket Sub Assy PL	1 pc	\$123.20	\$123.20
31	Hose Assy	1 pc	\$545.50	\$545.50
32	Hose Sub Assy, Water	1 pc	\$79.00	\$79.00
33	Sensor, Temperature	1 pc	\$203.20	\$203.20
34	Sensor, Exhaust Gas	1 pc	\$145.70	\$145.70
35	Sensor Lean Mixture	2 pcs	\$1,333.80	\$2,667.60
36	Pipe sub Assy Exhaust	1 pc	\$909.70	\$909.70

Cost plus 10%



Steve 24/6/19

06th Jun 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Supplementary quotation for supply parts, necessary equipment and tools for the repair of XE1080B.

	Description	Qty	U/Price	Total Price
52	Bracket Assy, CA / 00	1 pc	\$1,610.40	\$1,610.40
53	Bracket Sub Assy, CA / 01	1 pc	\$1,129.10	\$1,129.10
54	Support, Exhaust Pipe X the 26.6.2019, 01	1 pc	\$109.50	\$109.50
55	Member Sub Assy, FR / 01	1 pc	\$706.30	\$706.30
56	Hose Sub Assy, Water / 01	1 pc	\$23.80	\$23.80
57	Bracket Sub Assy, URE / 01	1 pc	\$673.30	\$673.30
58	Bracket Sub Assy, UREA / 00	1 pc	\$843.50	\$843.50
59	Bracket Sub Assy, HO X	1 pc	\$232.80	\$232.80
60	Splash Board, Side RH / 08	1 pc	\$171.20	\$171.20
			Total Parts	\$5,499.90
			Sub-Total	\$5,499.90
			7% GST	\$384.99
			Grand Total	\$ 5'884.89

Thanks,

Jou Chung Fat
Workshop In-charge



06th Jun 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Supplementary quotation for supply parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Bracket Assy, CA	1 pc	\$1,610.40	\$1,610.40
Bracket Sub Assy, CA	1 pc	\$1,129.10	\$1,129.10
Support, Exhaust Pipe	1 pc	\$109.50	\$109.50
Member Sub Assy, FR	1 pc	\$706.30	\$706.30
Hose Sub Assy, Water	1 pc	\$23.80	\$23.80
Bracket Sub Assy, URE	1 pc	\$673.30	\$673.30
Bracket Sub Assy, UREA	1 pc	\$843.50	\$843.50
Bracket Sub Assy, HO	1 pc	\$232.80	\$232.80
Splash Board, Side RH	1 pc	\$171.20	\$171.20
		Total Parts	\$5,499.90
		Sub-Total:	\$5,499.90
		7% GST	\$384.99
		Grand Total	\$ 5'884.89

Thanks,

Jou Chung Fat
Workshop In-charge



25/5/2019

14:16

18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Gear Assy, Power Steering ? ✓	1 pc	\$8,013.60	\$8,013.60
Link Assy, Steering ? ✓	1 pc	\$956.20	\$956.20
Column Assy, Steering ? ✓	1 pc	\$1,240.10	\$1,240.10
Holder 1 ?	1 pc	\$972.40	\$972.40
Bracket Assy UREA 2 BT ✓	1 pc	\$843.50	\$843.50
Bracket sub assy UREA 7 BT ✓	1 pc	\$673.30	\$673.30
Bolt n/c ✓	2 pcs	\$6.50	\$13.00
Nut n/c ✓	2 pcs	\$2.20	\$4.40
Sensor Assy, UREA ? coming ✓	1 pc	\$1,288.30	\$1,288.30
Tank Sub assy, UREA CUT ✓	1 pc	\$1,576.20	\$1,576.20
Cap Assy, UREA Tank n/c X ✓	1 pc	\$113.40	\$113.40
Arm Sub Assy, Rocket ? coming	1 pc	\$75.20	\$75.20
Insulator sub assy ? ✓	1 pc	\$518.30	\$518.30
Insulator, Main ? ✓	1 pc	\$85.00	\$85.00
Injector assy, UREA ? ✓	1 pc	\$1,455.20	\$1,455.20
Pump Assy, UREA ? ✓	1 pc	\$4,695.80	\$4,695.80
Pipe sub Assy, Exhaust on coming	1 pc	\$1,897.40	\$1,897.40
Wire Engine ? ✓	1 pc	\$309.90	\$309.90
Wire assy Engine ? ✓	1 pc	\$210.20	\$210.20
Valve Assy, Engine ? ✓	1 pc	\$228.10	\$228.10
Hose sub assy Water ? ✓	1 pc	\$28.00	\$28.00
Hose sub assy ? ✓	1 pc	\$23.80	\$23.80
Hose water ? ✓	1 pc	\$12.00	\$12.00
Water Hose ? ✓	1 pc	\$8.30	\$8.30
Pipe sub assy Water ? ✓	2 pcs	\$128.00	\$256.00
Hose sub assy ? ✓	1 pc	\$167.00	\$167.00
Bracket ? ✓	1 pc	\$125.40	\$125.40
Bracket sub assy ? coming	1 pc	\$232.80	\$232.80
Bracket Assy ? ✓	1 pc	\$85.30	\$85.30
Bracket Sub Assy PL ? ✓	1 pc	\$123.20	\$123.20
Hose Assy ? ✓	1 pc	\$545.50	\$545.50
Hose Sub Assy, Water ? ✓	1 pc	\$79.00	\$79.00
Sensor, Temperature ? ✓	1 pc	\$203.20	\$203.20
Sensor, Exhaust Gas ? coming	1 pc	\$145.70	\$145.70
Sensor Lean Mixture ? ✓	2 pcs	\$1,333.80	\$2,667.60
Pipe sub Assy Exhaust on ✓	1 pc	\$909.70	\$909.70

Gasket, Exhaust Main	1 pc	\$88.90	\$88.90
Computer Assy Emission	1 pc	\$2,877.70	\$2,877.70
Flange Exhaust Pipe	2 pcs	\$130.50	\$261.00
Gasket Exhaust Pipe	4 pcs	\$195.50	\$782.00
Support Exhaust Pipe	4 pcs	\$109.50	\$438.00
Support Exhaust Pipe	1 pc	\$89.00	\$89.00
Converter Assy	1 pc	\$9,342.30	\$9,342.30
Converter Assy Mono	1 pc	\$6,648.40	\$6,648.40
Chamber sub Assy INL	1 pc	\$909.40	\$909.40
Chamber Sub Assy MIX	1 pc	\$1,636.60	\$1,636.60
Chamber sub Assy SCR	1 pc	\$1,663.60	\$1,663.60
Chamber Sub Assy OUT	1 pc	\$671.00	\$671.00
		Total Parts	\$56,189.90
Labour Charge			
Labour to Remove & Replace Above Parts Assy	1 job	\$2,250.00	\$2,250.00
Labour to Re-programming Engine ECU	1 job	\$225.00	\$225.00
All Wheel Alignment	1 job	\$280.00	\$280.00
		Total Labour:	\$2,755.00
		Sub-Total:	\$58,944.90
		7% GST	\$4,126.14
		Grand Total	\$ 63,071.04

Thanks,

Jou Chung Fat
Workshop In-charge

Hwee Lin - LKK

20/3/19

c/s 2 days.

and Authorise

Excess: \$2000



06th Jun 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Supplementary quotation for supply parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Bracket Assy, CA	1 pc	\$1,610.40	\$1,610.40
Bracket Sub Assy, CA	1 pc	\$1,129.10	\$1,129.10
Support, Exhaust Pipe	1 pc	\$109.50	\$109.50
Member Sub Assy, FR	1 pc	\$706.30	\$706.30
Hose Sub Assy, Water	1 pc	\$23.80	\$23.80
Bracket Sub Assy, URE	1 pc	\$673.30	\$673.30
Bracket Sub Assy, UREA	1 pc	\$843.50	\$843.50
Bracket Sub Assy, HO	1 pc	\$232.80	\$232.80
Splash Board, Side RH	1 pc	\$171.20	\$171.20
		Total Parts	\$5,499.90
		Sub-Total:	\$5,499.90
		7% GST	\$384.99
		Grand Total	\$ 5'884.89

Thanks,

Jou Chung Fat
Workshop In-charge



25/5/2019

19-16

18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Gear Assy, Power Steering ? ✓	1 pc	\$8,013.60	\$8,013.60
Link Assy, Steering ? ✓	1 pc	\$956.20	\$956.20
Column Assy, Steering ? ✓	1 pc	\$1,240.10	\$1,240.10
Holder ? ✓	1 pc	\$972.40	\$972.40
Bracket Assy UREA BT ✓ coming	1 pc	\$843.50	\$843.50
Bracket sub assy UREA BT ✓	1 pc	\$673.30	\$673.30
Bolt nec ✓	2 pcs	\$6.50	\$13.00
Nut nec ✓	2 pcs	\$2.20	\$4.40
Sensor Assy, UREA ? coming ✓	1 pc	\$1,288.30	\$1,288.30
Tank Sub assy, UREA CUT ✓	1 pc	\$1,576.20	\$1,576.20
Cap Assy, UREA Tank ✓	1 pc	\$113.40	\$113.40
Arm Sub Assy, Rocket ? coming ✓	1 pc	\$75.20	\$75.20
Insulator sub assy ✓	1 pc	\$518.30	\$518.30
Insulator, Main ✓	1 pc	\$85.00	\$85.00
Injector assy, UREA ✓	1 pc	\$1,455.20	\$1,455.20
Pump Assy, UREA ✓	1 pc	\$4,695.80	\$4,695.80
Pipe sub Assy, Exhaust on ✓ coming	1 pc	\$1,897.40	\$1,897.40
Wire Engine ? ✓	1 pc	\$309.90	\$309.90
Wire assy Engine ? ✓	1 pc	\$210.20	\$210.20
Valve Assy, Engine ? ✓	1 pc	\$228.10	\$228.10
Hose sub assy Water ? ✓	1 pc	\$28.00	\$28.00
Hose sub assy ? ✓	1 pc	\$23.80	\$23.80
Hose water ? ✓	1 pc	\$12.00	\$12.00
Water Hose ? ✓	1 pc	\$8.30	\$8.30
Pipe sub assy Water ? ✓	2 pcs	\$128.00	\$256.00
Hose sub assy ? ✓	1 pc	\$167.00	\$167.00
Bracket ? ✓	1 pc	\$125.40	\$125.40
Bracket sub assy ? ✓ coming	1 pc	\$232.80	\$232.80
Bracket Assy ? ✓	1 pc	\$85.30	\$85.30
Bracket Sub Assy PL ? ✓	1 pc	\$123.20	\$123.20
Hose Assy ? ✓ truck	1 pc	\$545.50	\$545.50
Hose Sub Assy, Water ? ✓	1 pc	\$79.00	\$79.00
Sensor, Temperature ? ✓	1 pc	\$203.20	\$203.20
Sensor, Exhaust Gas ? ✓ coming	1 pc	\$145.70	\$145.70
Sensor Lean Mixture ? ✓	2 pcs	\$1,333.80	\$2,667.60
Pipe sub Assy Exhaust on ✓	1 pc	\$909.70	\$909.70

Gasket, Exhaust Main	1 pc	\$88.90	\$88.90
Computer Assy Emission	1 pc	\$2,877.70	\$2,877.70
Flange Exhaust Pipe	2 pcs	\$130.50	\$261.00
Gasket Exhaust Pipe	4 pcs	\$195.50	\$782.00
Support Exhaust Pipe	4 pcs	\$109.50	\$438.00
Support Exhaust Pipe	1 pc	\$89.00	\$89.00
Converter Assy	1 pc	\$9,342.30	\$9,342.30
Converter Assy Mono	1 pc	\$6,648.40	\$6,648.40
Chamber sub Assy INL	1 pc	\$909.40	\$909.40
Chamber Sub Assy MIX	1 pc	\$1,636.60	\$1,636.60
Chamber sub Assy SCR	1 pc	\$1,663.60	\$1,663.60
Chamber Sub Assy OUT	1 pc	\$671.00	\$671.00
		Total Parts	\$56,189.90
Labour Charge			
Labour to Remove & Replace Above Parts Assy	1 job	\$2,250.00	\$2,250.00
Labour to Re-programming Engine ECU	1 job	\$225.00	\$225.00
All Wheel Alignment Provide Report	1 job	\$280.00	\$280.00
		Total Labour:	\$2,755.00
		Sub-Total:	\$58,944.90
		7% GST	\$4,126.14
		Grand Total	\$ 63,071.04

Thanks,

Jou Chung Fat
Workshop In-charge

Hwee Lin - LKK

20/3/19

c/s 2 days.

not Authorise

Excess: \$2000+



18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Gear Assy, Power Steering ?	1 pc	\$8,013.60	\$8,013.60
Link Assy, Steering ?	1 pc	\$956.20	\$956.20
Column Assy, Steering ?	1 pc	\$1,240.10	\$1,240.10
Holder ?	1 pc	\$972.40	\$972.40
Bracket Assy UREA BT ✓	1 pc	\$843.50	\$843.50
Bracket sub assy UREA BT ✓	1 pc	\$673.30	\$673.30
Bolt n/c ✓	2 pcs	\$6.50	\$13.00
Nut n/c ✓	2 pcs	\$2.20	\$4.40
Sensor Assy, UREA ?	1 pc	\$1,288.30	\$1,288.30
Tank Sub assy, UREA CUT ✓	1 pc	\$1,576.20	\$1,576.20
Cap Assy, UREA Tank un X ✓	1 pc	\$113.40	\$113.40
Arm Sub Assy, Rocket ?	1 pc	\$75.20	\$75.20
Insulator sub assy ?	1 pc	\$518.30	\$518.30
Insulator, Main de ✓	1 pc	\$85.00	\$85.00
Injector assy, UREA ?	1 pc	\$1,455.20	\$1,455.20
Pump Assy, UREA ?	1 pc	\$4,695.80	\$4,695.80
Pipe sub Assy, Exhaust 00 ✓	1 pc	\$1,897.40	\$1,897.40
Wire Engine ?	1 pc	\$309.90	\$309.90
Wire assy Engine ?	1 pc	\$210.20	\$210.20
Valve Assy, Engine ?	1 pc	\$228.10	\$228.10
Hose sub assy Water ?	1 pc	\$28.00	\$28.00
Hose sub assy ?	1 pc	\$23.80	\$23.80
Hose water ?	1 pc	\$12.00	\$12.00
Water Hose ?	1 pc	\$8.30	\$8.30
Pipe sub assy Water ?	2 pcs	\$128.00	\$256.00
Hose sub assy ?	1 pc	\$167.00	\$167.00
Bracket ?	1 pc	\$125.40	\$125.40
Bracket sub assy ?	1 pc	\$232.80	\$232.80
Bracket Assy ?	1 pc	\$85.30	\$85.30
Bracket Sub Assy PL ?	1 pc	\$123.20	\$123.20
Hose Assy ?	1 pc	\$545.50	\$545.50
Hose Sub Assy, Water ?	1 pc	\$79.00	\$79.00
Sensor, Temperature ?	1 pc	\$203.20	\$203.20
Sensor, Exhaust Gas ?	1 pc	\$145.70	\$145.70
Sensor Lean Mixture ?	2 pcs	\$1,333.80	\$2,667.60
Pipe sub Assy Exhaust 00 ✓	1 pc	\$909.70	\$909.70

Gasket, Exhaust Main	1 pc	\$88.90	\$88.90
Computer Assy Emission	1 pc	\$2,877.70	\$2,877.70
Flange Exhaust Pipe	2 pcs	\$130.50	\$261.00
Gasket Exhaust Pipe	4 pcs	\$195.50	\$782.00
Support Exhaust Pipe	4 pcs	\$109.50	\$438.00
Support Exhaust Pipe	1 pc	\$89.00	\$89.00
Converter Assy	1 pc	\$9,342.30	\$9,342.30
Converter Assy Mono	1 pc	\$6,648.40	\$6,648.40
Chamber sub Assy INL	1 pc	\$909.40	\$909.40
Chamber Sub Assy MIX	1 pc	\$1,636.60	\$1,636.60
Chamber sub Assy SCR	1 pc	\$1,663.60	\$1,663.60
Chamber Sub Assy OUT	1 pc	\$671.00	\$671.00
		Total Parts	\$56,189.90
Labour Charge			
Labour to Remove & Replace Above Parts Assy	1 job	\$2,250.00	\$2,250.00
Labour to Re-programming Engine ECU	1 job	\$225.00	\$225.00
All Wheel Alignment	1 job	\$280.00	\$280.00
		Total Labour:	\$2,755.00
		Sub-Total:	\$58,944.90
		7% GST	\$4,126.14
		Grand Total	\$ 63,071.04

Thanks,

Jou Chung Fat
Workshop In-charge

Hwee Lin - LKK

20/3/19

c/s 2 days.

not Authorise

Excess: \$2000+



25/5/2019

19-16

18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Gear Assy, Power Steering ✓	1 pc	\$8,013.60	\$8,013.60
Link Assy, Steering ✓	1 pc	\$956.20	\$956.20
Column Assy, Steering ✓	1 pc	\$1,240.10	\$1,240.10
Holder ✓	1 pc	\$972.40	\$972.40
Bracket Assy UREA BT ✓	1 pc	\$843.50	\$843.50
Bracket sub assy UREA BT ✓	1 pc	\$673.30	\$673.30
Bolt nec ✓	2 pcs	\$6.50	\$13.00
Nut nec ✓	2 pcs	\$2.20	\$4.40
Sensor Assy, UREA ? coming ✓	1 pc	\$1,288.30	\$1,288.30
Tank Sub assy, UREA CUT ✓	1 pc	\$1,576.20	\$1,576.20
Cap Assy, UREA Tank un X ✓	1 pc	\$113.40	\$113.40
Arm Sub Assy, Rocket ? coming X	1 pc	\$75.20	\$75.20
Insulator sub assy ✓	1 pc	\$518.30	\$518.30
Insulator, Main ✓	1 pc	\$85.00	\$85.00
Injector assy, UREA ✓	1 pc	\$1,455.20	\$1,455.20
Pump Assy, UREA ✓	1 pc	\$4,695.80	\$4,695.80
Pipe sub Assy, Exhaust on coming	1 pc	\$1,897.40	\$1,897.40
Wire Engine ✓	1 pc	\$309.90	\$309.90
Wire assy Engine ✓	1 pc	\$210.20	\$210.20
Valve Assy, Engine ✓	1 pc	\$228.10	\$228.10
Hose sub assy Water ✓	1 pc	\$28.00	\$28.00
Hose sub assy ✓	1 pc	\$23.80	\$23.80
Hose water ✓	1 pc	\$12.00	\$12.00
Water Hose ✓	1 pc	\$8.30	\$8.30
Pipe sub assy Water ✓	2 pcs	\$128.00	\$256.00
Hose sub assy ✓	1 pc	\$167.00	\$167.00
Bracket ✓	1 pc	\$125.40	\$125.40
Bracket sub assy ✓	1 pc	\$232.80	\$232.80
Bracket Assy ✓	1 pc	\$85.30	\$85.30
Bracket Sub Assy PL ✓	1 pc	\$123.20	\$123.20
Hose Assy ✓	1 pc	\$545.50	\$545.50
Hose Sub Assy, Water ✓	1 pc	\$79.00	\$79.00
Sensor, Temperature ✓	1 pc	\$203.20	\$203.20
Sensor, Exhaust Gas ✓	1 pc	\$145.70	\$145.70
Sensor Lean Mixture ✓	2 pcs	\$1,333.80	\$2,667.60
Pipe sub Assy Exhaust on ✓	1 pc	\$909.70	\$909.70

Gasket, Exhaust Main	1 pc	\$88.90	\$88.90
Computer Assy Emission	1 pc	\$2,877.70	\$2,877.70
Flange Exhaust Pipe	2 pcs	\$130.50	\$261.00
Gasket Exhaust Pipe	4 pcs	\$195.50	\$782.00
Support Exhaust Pipe	4 pcs	\$109.50	\$438.00
Support Exhaust Pipe	1 pc	\$89.00	\$89.00
Converter Assy	1 pc	\$9,342.30	\$9,342.30
Converter Assy Mono	1 pc	\$6,648.40	\$6,648.40
Chamber sub Assy INL	1 pc	\$909.40	\$909.40
Chamber Sub Assy MIX	1 pc	\$1,636.60	\$1,636.60
Chamber sub Assy SCR	1 pc	\$1,663.60	\$1,663.60
Chamber Sub Assy OUT	1 pc	\$671.00	\$671.00
		Total Parts	\$56,189.90
Labour Charge			
Labour to Remove & Replace Above Parts Assy	1 job	\$2,250.00	\$2,250.00
Labour to Re-programming Engine ECU	1 job	\$225.00	\$225.00
All Wheel Alignment	1 job	\$280.00	\$280.00
		Total Labour:	\$2,755.00
		Sub-Total:	\$58,944.90
		7% GST	\$4,126.14
		Grand Total	\$ 63,071.04

Thanks,

Jou Chung Fat
Workshop In-charge

Hwan Lin - LKK

20/3/19

c/s 2 days.

and Authorise

Excess: \$2000

MEGASTONE HOLDINGS PTE LTD

Megastone Holdings Pte Ltd

(A Member of Sarnett Group)
Company Registration No.: 199504010N GST Registration No.: 19-6004010-N



18th March 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Quotation to supply labour, parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Gear Assy, Power Steering	1 pc	\$8,013.60	\$8,013.60
Link Assy, Steering	2 pc	\$956.20	\$956.20
Column Assy, Steering	1 pc	\$1,240.10	\$1,240.10
Holder	4 pc	\$972.40	\$972.40
Bracket Assy UREA	5 pc	\$843.50	\$843.50
Bracket sub assy UREA	6 pc	\$673.30	\$673.30
Bolt	2 pcs	\$6.50	\$13.00
Nut	2 pcs	\$2.20	\$4.40
Sensor Assy, UREA	1 pc	\$1,288.30	\$1,288.30
Tank Sub assy, UREA	1 pc	\$1,576.20	\$1,576.20
Cap Assy, UREA Tank	1 pc	\$113.40	\$113.40
Arm Sub Assy, Rocket	1 pc	\$75.20	\$75.20
Insulator sub assy	1 pc	\$518.30	\$518.30
Insulator, Main	1 pc	\$85.00	\$85.00
Injector assy, UREA	1 pc	\$1,455.20	\$1,455.20
Pump Assy, UREA	1 pc	\$4,695.80	\$4,695.80
Pipe sub Assy, Exhaust	1 pc	\$1,897.40	\$1,897.40
Wire Engine	1 pc	\$309.90	\$309.90
Wire assy Engine	1 pc	\$210.20	\$210.20
Valve Assy, Engine	1 pc	\$228.10	\$228.10
Hose sub assy Water	1 pc	\$28.00	\$28.00
Hose sub assy	1 pc	\$23.80	\$23.80
Hose water	1 pc	\$12.00	\$12.00
Water Hose	1 pc	\$8.30	\$8.30
Pipe sub assy Water	2 pcs	\$128.00	\$256.00
Hose sub assy	1 pc	\$167.00	\$167.00
Bracket	1 pc	\$125.40	\$125.40
Bracket sub assy	1 pc	\$232.80	\$232.80
Bracket Assy	1 pc	\$85.30	\$85.30
Bracket Sub Assy PL	1 pc	\$123.20	\$123.20
Hose Assy	1 pc	\$545.50	\$545.50
Hose Sub Assy, Water	1 pc	\$79.00	\$79.00
Sensor, Temperature	1 pc	\$203.20	\$203.20
Sensor, Exhaust Gas	1 pc	\$145.70	\$145.70
Sensor Lean Mixture	2 pcs	\$1,333.80	\$2,667.60
Pipe sub Assy Exhaust	1 pc	\$909.70	\$909.70

Gasket, Exhaust Main	37	1 pc	\$88.90	\$88.90
Computer Assy Emission	38	1 pc	\$2,877.70	\$2,877.70
Flange Exhaust Pipe	39	2 pcs	\$130.50	\$261.00
Gasket Exhaust Pipe	40	4 pcs	\$195.50	\$782.00
Support Exhaust Pipe	41	4 pcs	\$109.50	\$438.00
Support Exhaust Pipe	42	1 pc	\$89.00	\$89.00
Converter Assy	43	1 pc	\$9,342.30	\$9,342.30
Converter Assy Mono	44	1 pc	\$8,648.40	\$8,648.40
Chamber sub Assy INL	45	1 pc	\$909.40	\$909.40
Chamber Sub Assy MIX	46	1 pc	\$1,636.60	\$1,636.60
Chamber sub Assy SCR	47	1 pc	\$1,663.60	\$1,663.60
Chamber Sub Assy OUT	48	1 pc	\$671.00	\$671.00
			Total Parts	\$56,189.90
Labour Charge				
Labour to Remove & Replace Above Parts Assy		1 job	\$2,250.00	\$2,250.00
Labour to Re-programming Engine ECU		1 job	\$225.00	\$225.00
All Wheel Alignment		1 job	\$280.00	\$280.00
			Total Labour:	\$2,755.00
			Sub-Total:	\$58,944.90
			7% GST	\$4,126.14
			Grand Total	\$ 63,071.04

Thanks,

Jou Chung Fat
Workshop In-charge



MEGASTONE HOLDINGS PTE LTD

Megastone Holdings Pte Ltd

(A Member of Samweh Group)

Company Registration No: 199504215R GST Registration No: 19-8854215-4



06th Jun 2019

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Attention: Motor Insurance Claims

Dear Sir/ Madam,

Supplementary quotation for supply parts, necessary equipment and tools for the repair of XE1080B.

Description	Qty	U/Price	Total Price
Bracket Assy, CA 49 ✓	1 pc	\$1,610.40	\$1,610.40
Bracket Sub Assy, CA 50 ✓	1 pc	\$1,129.10	\$1,129.10
Support, Exhaust Pipe 51	1 pc	\$109.50	\$109.50
Member Sub Assy, FR 52 -	1 pc	\$706.30	\$706.30
Hose Sub Assy, Water 53	1 pc	\$23.80	\$23.80
Bracket Sub Assy, URE 54 ✓	1 pc	\$673.30	\$673.30
Bracket Sub Assy, UREA 55 ✓	1 pc	\$843.50	\$843.50
Bracket Sub Assy, HO 56 ✓	1 pc	\$232.80	\$232.80
Splash Board, Side RH 57	1 pc	\$171.20	\$171.20
		Total Parts	\$5,499.90
		Sub-Total:	\$5,499.90
		7% GST	\$384.99
		Grand Total	\$ 5,884.89

Thanks,

Jou Chung Fat
Workshop In-charge

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2019		19 Mar 2019 16:34 Edit Adj Rpt	\$546,538.80 Edit Estimates	\$546,538.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAMWOH CORPORATION PTE LTD, Co. Reg. No.: 198502202Z								
Vehicle Reg. No.:	XE1080B	Date of Loss:	22/02/2019 08:00 - :59 [40 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 586021	Policy/Cover Note No.:	28627607 (Comprehensive) Coverage: 14/10/2018 - 13/10/2019						
		Excess:	\$52,000.00						
Repairer:	MEGASTONE HOLDINGS PTE LTD (HQ) 25E Sungei Kadut Street 1, 729333 Sungei Kadut - Tel: 63652066								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Richard Ang Wei Guang - 6594 2560]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 18/04/2019]								
Driver/Custodian:	PANG WOO NEOW (67 / Male), NRIC: S2023527F, Tel: +6596758115 Email: NOEMAIL								
Adj Asg. Remarks:	Survey appt tmr at 1.30pm. Owner waiting at 42A Sungei Kadut Street 1, Singapore 729347. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert. Thanks.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (27/12/2019): Alert - Adj Mandate Approved (\$546538.80) - XE1080B - Claim Handler: Richard Ang... - MSIG_SG (26/03/2019): Alert - Adj Mandate Approved (\$557596.20) - XE1080B - Claim Handler: Clara Milah...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE1080B (586021)
OD
Feb 22 2019 8:00AM
[SAMWOH CORPORATION PTE LTD]
MEGASTONE HOLDINGS PTE LTD

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/19 18:02	Adjuster Immediate Advice		Load HTM
2	22/03/19 09:53	Adjuster Immediate Advice		Load HTM
3	26/12/19 14:50	Adjuster Immediate Advice		Load HTM
4	26/12/19 15:09	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/19 15:40	Accident Photo		Load JPG
2	26/02/19 15:40	Accident Photo		Load JPG
3	26/02/19 15:40	Accident Photo		Load JPG
4	26/02/19 15:40	Accident Photo		Load JPG
5	26/02/19 15:40	Accident Photo		Load JPG
6	26/02/19 15:40	Accident Photo		Load JPG
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/19 09:34	General View		Load JPG
2	21/03/19 09:34	General View		Load JPG
3	21/03/19 09:34	General View		Load JPG
4	21/03/19 09:34	General View		Load JPG
5	21/03/19 09:34	General View		Load JPG
6	21/03/19 09:34	General View		Load JPG
7	21/03/19 09:34	General View		Load JPG
8	21/03/19 09:34	General View		Load JPG
9	21/03/19 09:34	General View		Load JPG
10	21/03/19 09:34	General View		Load JPG
11	21/03/19 09:34	General View		Load JPG
12	21/03/19 09:34	General View		Load JPG
13	21/03/19 09:34	General View		Load JPG
14	21/03/19 09:34	General View		Load JPG
15	21/03/19 09:34	General View		Load JPG
16	21/03/19 09:34	General View		Load JPG
17	21/03/19 09:34	General View		Load JPG
18	21/03/19 09:34	General View		Load JPG
19	21/03/19 09:34	General View		Load JPG
20	21/03/19 09:34	General View		Load JPG
21	21/03/19 09:34	General View		Load JPG
22	21/03/19 09:34	General View		Load JPG
23	21/03/19 09:34	General View		Load JPG
24	21/03/19 09:34	General View		Load JPG
25	21/03/19 09:34	General View		Load JPG
26	21/03/19 09:34	General View		Load JPG
27	21/03/19 09:34	General View		Load JPG
28	21/03/19 09:34	General View		Load JPG
29	21/03/19 09:34	General View		Load JPG
30	21/03/19 09:34	General View		Load JPG
31	21/03/19 09:34	General View		Load JPG
32	21/03/19 09:34	General View		Load JPG

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	21/03/19 09:34	General View	 Load JPG	☒
34	21/03/19 09:34	General View	 Load JPG	☒
35	21/03/19 09:34	General View	 Load JPG	☒
36	21/03/19 09:34	General View	 Load JPG	☒
37	21/03/19 09:34	General View	 Load JPG	☒
38	21/03/19 09:34	General View	 Load JPG	☒
39	21/03/19 09:34	General View	 Load JPG	☒
40	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
41	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
42	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
43	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
44	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
45	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
46	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
47	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
48	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
49	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
50	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
51	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
52	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
53	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
54	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
55	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
56	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
57	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
58	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
59	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
60	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
61	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
62	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
63	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
64	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
65	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
66	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
67	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
68	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
69	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
70	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
71	03/09/19 11:00	Photographs of Damaged Items	 Load JPG	☒
72	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
73	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
74	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
75	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
76	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
77	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
78	03/09/19 11:01	Photographs of Damaged Items	 Load JPG	☒
79	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
80	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
81	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
82	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
83	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
84	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
85	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
86	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
87	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒
88	03/09/19 11:01	Photographs of Damaged Items	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
89	03/09/19 11:01	Photographs of Damaged Items		☒
90	03/09/19 11:01	Photographs of Damaged Items		☒
91	03/09/19 11:01	Photographs of Damaged Items		☒
92	03/09/19 11:01	Photographs of Damaged Items		☒
93	03/09/19 11:01	Photographs of Damaged Items		☒
94	03/09/19 11:01	Photographs of Damaged Items		☒
95	03/09/19 11:01	Photographs of Damaged Items		☒
96	03/09/19 11:01	Photographs of Damaged Items		☒
97	03/09/19 11:01	Photographs of Damaged Items		☒
98	03/09/19 11:01	Photographs of Damaged Items		☒
99	03/09/19 11:01	Photographs of Damaged Items		☒
100	03/09/19 11:01	Photographs of Damaged Items		☒
101	03/09/19 11:01	Photographs of Damaged Items		☒
102	03/09/19 11:01	Photographs of Damaged Items		☒
103	03/09/19 11:01	Photographs of Damaged Items		☒
104	03/09/19 11:01	Photographs of Damaged Items		☒
105	03/09/19 11:01	Photographs of Damaged Items		☒
106	03/09/19 11:01	Photographs of Damaged Items		☒
107	03/09/19 11:01	Photographs of Damaged Items		☒
108	03/09/19 11:01	Photographs of Damaged Items		☒
109	03/09/19 11:01	Photographs of Damaged Items		☒
110	03/09/19 11:01	Photographs of Damaged Items		☒
111	03/09/19 11:01	Photographs of Damaged Items		☒
112	03/09/19 11:01	Photographs of Damaged Items		☒
113	03/09/19 11:01	Photographs of Damaged Items		☒
114	03/09/19 11:01	Photographs of Damaged Items		☒
115	03/09/19 11:01	Photographs of Damaged Items		☒
116	03/09/19 11:01	Photographs of Damaged Items		☒
117	03/09/19 11:01	Photographs of Damaged Items		☒
118	03/09/19 11:01	Photographs of Damaged Items		☒
119	03/09/19 11:01	Photographs of Damaged Items		☒
120	03/09/19 11:01	Photographs of Damaged Items		☒
121	03/09/19 11:01	Photographs of Damaged Items		☒
122	03/09/19 11:01	Photographs of Damaged Items		☒
123	03/09/19 11:01	Photographs of Damaged Items		☒
124	03/09/19 11:01	Photographs of Damaged Items		☒
125	03/09/19 11:01	Photographs of Damaged Items		☒
126	03/09/19 11:01	Photographs of Damaged Items		☒
127	03/09/19 11:01	Photographs of Damaged Items		☒
128	03/09/19 11:01	Photographs of Damaged Items		☒
129	03/09/19 11:01	Photographs of Damaged Items		☒
130	03/09/19 11:01	Photographs of Damaged Items		☒
131	03/09/19 11:01	Photographs of Damaged Items		☒
132	03/09/19 11:01	Photographs of Damaged Items		☒
133	03/09/19 11:01	Photographs of Damaged Items		☒
134	03/09/19 11:01	Photographs of Damaged Items		☒
135	03/09/19 11:01	Photographs of Damaged Items		☒
136	03/09/19 11:01	Photographs of Damaged Items		☒
137	03/09/19 11:01	Photographs of Damaged Items		☒
138	03/09/19 11:04	Photographs of Damaged Items		☒
139	03/09/19 11:04	Photographs of Damaged Items		☒
140	03/09/19 11:04	Photographs of Damaged Items		☒
141	03/09/19 11:04	Photographs of Damaged Items		☒
142	03/09/19 11:04	Photographs of Damaged Items		☒
143	03/09/19 11:04	Photographs of Damaged Items		☒
144	03/09/19 11:04	Photographs of Damaged Items		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
145	03/09/19 11:04	Photographs of Damaged Items		☒
146	03/09/19 11:04	Photographs of Damaged Items		☒
147	03/09/19 11:04	Photographs of Damaged Items		☒
148	03/09/19 11:04	Photographs of Damaged Items		☒
149	03/09/19 11:05	Photographs of Damaged Items		☒
150	03/09/19 11:05	Photographs of Damaged Items		☒
151	03/09/19 11:05	Photographs of Damaged Items		☒
152	03/09/19 11:05	Photographs of Damaged Items		☒
153	03/09/19 11:05	Photographs of Damaged Items		☒
154	03/09/19 11:05	Photographs of Damaged Items		☒
155	03/09/19 11:05	Photographs of Damaged Items		☒
156	03/09/19 11:05	Photographs of Damaged Items		☒
157	03/09/19 11:05	Photographs of Damaged Items		☒
158	03/09/19 11:05	Photographs of Damaged Items		☒
159	03/09/19 11:05	Photographs of Damaged Items		☒
160	03/09/19 11:05	Photographs of Damaged Items		☒
161	03/09/19 11:05	Photographs of Damaged Items		☒
162	03/09/19 11:05	Photographs of Damaged Items		☒
163	03/09/19 11:05	Photographs of Damaged Items		☒
164	03/09/19 11:05	Photographs of Damaged Items		☒
165	03/09/19 11:05	Photographs of Damaged Items		☒
166	03/09/19 11:05	Photographs of Damaged Items		☒
167	03/09/19 11:05	Photographs of Damaged Items		☒
168	03/09/19 11:05	Photographs of Damaged Items		☒
169	03/09/19 11:05	Photographs of Damaged Items		☒
170	03/09/19 11:05	Photographs of Damaged Items		☒
171	03/09/19 11:05	Photographs of Damaged Items		☒
172	03/09/19 11:05	Photographs of Damaged Items		☒
173	03/09/19 11:05	Photographs of Damaged Items		☒
174	03/09/19 11:05	Photographs of Damaged Items		☒
175	03/09/19 11:05	Photographs of Damaged Items		☒
176	03/09/19 11:05	Photographs of Damaged Items		☒
177	03/09/19 11:05	Photographs of Damaged Items		☒
178	03/09/19 11:05	Photographs of Damaged Items		☒
179	03/09/19 11:05	Photographs of Damaged Items		☒
180	03/09/19 11:05	Photographs of Damaged Items		☒
181	03/09/19 11:05	Photographs of Damaged Items		☒
182	03/09/19 11:05	Photographs of Damaged Items		☒
183	03/09/19 11:05	Photographs of Damaged Items		☒
184	03/09/19 11:05	Photographs of Damaged Items		☒
185	03/09/19 11:05	Photographs of Damaged Items		☒
186	03/09/19 11:05	Photographs of Damaged Items		☒
187	03/09/19 11:05	Photographs of Damaged Items		☒
188	03/09/19 11:05	Photographs of Damaged Items		☒
189	03/09/19 11:05	Photographs of Damaged Items		☒
190	03/09/19 11:05	Photographs of Damaged Items		☒
191	03/09/19 11:05	Photographs of Damaged Items		☒
192	03/09/19 11:05	Photographs of Damaged Items		☒
193	03/09/19 11:05	Photographs of Damaged Items		☒
194	03/09/19 11:05	Photographs of Damaged Items		☒
195	03/09/19 11:05	Photographs of Damaged Items		☒
196	03/09/19 11:05	Photographs of Damaged Items		☒
197	03/09/19 11:05	Photographs of Damaged Items		☒
198	03/09/19 11:05	Photographs of Damaged Items		☒
199	03/09/19 11:05	Photographs of Damaged Items		☒
200	03/09/19 11:05	Photographs of Damaged Items		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
201	03/09/19 11:05	Photographs of Damaged Items		☒
202	03/09/19 11:05	Photographs of Damaged Items		☒
203	03/09/19 11:05	Photographs of Damaged Items		☒
204	03/09/19 11:05	Photographs of Damaged Items		☒
205	03/09/19 11:05	Photographs of Damaged Items		☒
206	03/09/19 11:05	Photographs of Damaged Items		☒
207	03/09/19 11:05	Photographs of Damaged Items		☒
208	03/09/19 11:05	Photographs of Damaged Items		☒
209	03/09/19 11:05	Photographs of Damaged Items		☒
210	03/09/19 11:05	Photographs of Damaged Items		☒
211	03/09/19 11:05	Photographs of Damaged Items		☒
212	03/09/19 11:05	Photographs of Damaged Items		☒
213	03/09/19 11:05	Photographs of Damaged Items		☒
214	03/09/19 11:05	Photographs of Damaged Items		☒
215	03/09/19 11:05	Photographs of Damaged Items		☒
216	03/09/19 11:05	Photographs of Damaged Items		☒
217	03/09/19 11:05	Photographs of Damaged Items		☒
218	03/09/19 11:05	Photographs of Damaged Items		☒
219	03/09/19 11:05	Photographs of Damaged Items		☒
220	03/09/19 11:05	Photographs of Damaged Items		☒
221	03/09/19 11:05	Photographs of Damaged Items		☒
222	03/09/19 11:05	Photographs of Damaged Items		☒
223	03/09/19 11:05	Photographs of Damaged Items		☒
224	03/09/19 11:05	Photographs of Damaged Items		☒
225	03/09/19 11:05	Photographs of Damaged Items		☒
226	03/09/19 11:05	Photographs of Damaged Items		☒
227	03/09/19 11:05	Photographs of Damaged Items		☒
228	03/09/19 11:05	Photographs of Damaged Items		☒
229	03/09/19 11:05	Photographs of Damaged Items		☒
230	03/09/19 11:05	Photographs of Damaged Items		☒
231	03/09/19 11:05	Photographs of Damaged Items		☒
232	03/09/19 11:05	Photographs of Damaged Items		☒
233	03/09/19 11:05	Photographs of Damaged Items		☒
234	03/09/19 11:05	Photographs of Damaged Items		☒
235	03/09/19 11:05	Photographs of Damaged Items		☒
236	03/09/19 11:05	Photographs of Damaged Items		☒
237	03/09/19 11:07	Photographs of Damaged Items		☒
238	03/09/19 11:07	Photographs of Damaged Items		☒
239	03/09/19 11:07	Photographs of Damaged Items		☒
240	03/09/19 11:07	Photographs of Damaged Items		☒
241	03/09/19 11:07	Photographs of Damaged Items		☒
242	03/09/19 11:07	Photographs of Damaged Items		☒
243	03/09/19 11:07	Photographs of Damaged Items		☒
244	03/09/19 11:07	Photographs of Damaged Items		☒
245	03/09/19 11:07	Photographs of Damaged Items		☒
246	03/09/19 11:07	Photographs of Damaged Items		☒
247	03/09/19 11:07	Photographs of Damaged Items		☒
248	03/09/19 11:07	Photographs of Damaged Items		☒
249	03/09/19 11:07	Photographs of Damaged Items		☒
250	03/09/19 11:07	Photographs of Damaged Items		☒
251	03/09/19 11:07	Photographs of Damaged Items		☒
252	03/09/19 11:07	Photographs of Damaged Items		☒
253	03/09/19 11:07	Photographs of Damaged Items		☒
254	03/09/19 11:07	Photographs of Damaged Items		☒
255	03/09/19 11:07	Photographs of Damaged Items		☒
256	03/09/19 11:07	Photographs of Damaged Items		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
257	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
258	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
259	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
260	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
261	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
262	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
263	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
264	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
265	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
266	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
267	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
268	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
269	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
270	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
271	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
272	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
273	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
274	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
275	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
276	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
277	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
278	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
279	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
280	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
281	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
282	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
283	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
284	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
285	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
286	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
287	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
288	03/09/19 11:07	Photographs of Damaged Items	 Load JPG	☒
289	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
290	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
291	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
292	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
293	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
294	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
295	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
296	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
297	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
298	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
299	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
300	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
301	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
302	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
303	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
304	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
305	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
306	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
307	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
308	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
309	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
310	03/09/19 11:09	Photographs of Damaged Items	 Load JPG	☒
311	03/09/19 11:09	Photographs of Damaged Items	Load JPG	☒
312	03/09/19 11:09	Photographs of Damaged Items	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
313	03/09/19 11:09	Photographs of Damaged Items		☒
314	03/09/19 11:09	Photographs of Damaged Items		☒
315	03/09/19 11:09	Photographs of Damaged Items		☒
316	03/09/19 11:09	Photographs of Damaged Items		☒
317	03/09/19 11:09	Photographs of Damaged Items		☒
318	03/09/19 11:09	Photographs of Damaged Items		☒
319	03/09/19 11:09	Photographs of Damaged Items		☒
320	03/09/19 11:09	Photographs of Damaged Items		☒
321	03/09/19 11:09	Photographs of Damaged Items		☒
322	03/09/19 11:09	Photographs of Damaged Items		☒
323	03/09/19 11:09	Photographs of Damaged Items		☒
324	03/09/19 11:09	Photographs of Damaged Items		☒
325	03/09/19 11:09	Photographs of Damaged Items		☒
326	03/09/19 11:09	Photographs of Damaged Items		☒
327	03/09/19 11:09	Photographs of Damaged Items		☒
328	03/09/19 11:09	Photographs of Damaged Items		☒
329	03/09/19 11:11	After Repair Photo		☒
330	03/09/19 11:11	After Repair Photo		☒
331	03/09/19 11:11	After Repair Photo		☒
332	03/09/19 11:11	After Repair Photo		☒
333	03/09/19 11:11	After Repair Photo		☒
334	03/09/19 11:11	After Repair Photo		☒
335	03/09/19 11:11	After Repair Photo		☒
336	03/09/19 11:11	After Repair Photo		☒
337	03/09/19 11:11	After Repair Photo		☒
338	03/09/19 11:11	After Repair Photo		☒
339	03/09/19 11:11	After Repair Photo		☒
340	03/09/19 11:11	After Repair Photo		☒
341	03/09/19 11:11	After Repair Photo		☒
342	03/09/19 11:11	After Repair Photo		☒
Documentation			1 per page	☒
No	Finalized On	M5IG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/03/19 08:54	Workshop contact details		☒
2	19/03/19 10:42	Repair Estimate		☒
3	19/03/19 10:44	Request for survey		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/03/19 15:27	estimate		☒
2	26/12/19 15:11	ESTIMATE		☒
3	26/12/19 15:11	SUPPLEMENTARY		☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	04/09/19 00:09	Accident Statement		☒
Documentation			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	25/02/19 12:50	Sketch Plan		☒
2	25/02/19 12:50	Sketch Plan #2		☒

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19005004/ETD3E2

Date: 14/01/2020

REFERENCE

Insured/Claimant: SAMWOH CORPORATION PTE LTD
Date of Loss: 22/02/2019

Policy No: 28627607

Nature of Claim: OD Claim No: 586021

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE1080B**
Make & Model: HINO FS1ELKD, 12.9 D (M)
Reg. Date: 14/10/2015 (Man. Year: 2015)
Colour: Blue
Engine Capacity: 12913 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: E13CWA11211
Chassis No: FS1EKM10018
Odometer: 231618 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: Firenza 7 mm Rear Left Side: Firenza 7/7 mm
Front Right Side: Firenza 7 mm Rear Right Side: Firenza 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,689.80	45,018.80	16,671.00	27.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,755.00	1,520.00	1,235.00	44.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	64,444.80	46,538.80	17,906.00	27.79
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	62,444.80	44,538.80	17,906.00	28.67
+ GST 7.00/7.00% (S\$)	4,371.14	3,117.72	1,253.42	28.67
Nett Amount (S\$)	66,815.94	47,656.52	19,159.42	28.67

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 20/03/2019 Inspected At:

MEGASTONE HOLDINGS PTE LTD
(HQ)
42A SUNGEI KADUT STREET 1
SINGAPORE 729347

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jan 2020)	
Parts:	N/A	HINO FS1ELKD 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE1080B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GEAR ASSY, POWER STEERING	Jammed	8,013.60 FS	*8,013.60 FS
2	1		*LINK ASSY, STEERING	Bent	956.20 FS	*956.20 FS
3	1		*COLUMN ASSY, STEERING	Jammed	1,240.10 FS	*1,240.10 FS
4	1		*HOLDER	Not Necessary	972.40 FS	*- FS
5	1		*BRACKET ASSY UREA	Bent	843.50 FS	*843.50 FS
6	1		*BRACKET SUB ASSY UREA	Bent	673.30 FS	*673.30 FS
7	2		*BOLT	Necessary	13.00 FS	*13.00 FS
8	2		*NUT	Necessary	4.40 FS	*4.40 FS
9	1		*SENSOR ASSY, UREA	Not Necessary	1,288.30 FS	*- FS
10	1		*TANK SUB ASSY, UREA	Cut	1,576.20 FS	*1,576.20 FS
11	1		*CAP ASSY, UREA TANK	Not Necessary	113.40 FS	*- FS
12	1		*ARM SUB-ASSY, ROCKET	Not Necessary	75.20 FS	*- FS
13	1		*INSULATOR SUB ASSY	Dented	518.30 FS	*518.30 FS
14	1		*INSULATOR, MAIN	Not Necessary	85.00 FS	*- FS
15	1		*INJECTOR ASSY, UREA	Not Necessary	1,455.20 FS	*- FS
16	1		*PUMP ASSY, UREA	Not Necessary	4,695.80 FS	*- FS
17	1		*PIPE SUB ASSY, EXHAUST	Dented	1,897.40 FS	*1,897.40 FS
18	1		*WIRE ENGINE	Not Necessary	309.90 FS	*- FS
19	1		*WIRE ASSY ENGINE	Not Necessary	210.20 FS	*- FS
20	1		*VALVE ASSY, ENGINE	Cracked	228.10 FS	*228.10 FS
21	1		*HOSE SUB ASSY WATER	Not Necessary	28.00 FS	*- FS
22	1		*HOSE SUB ASSY	Not Necessary	23.80 FS	*- FS
23	1		*HOSE WATER	Not Necessary	12.00 FS	*- FS
24	1		*WATER HOSE	Not Necessary	8.30 FS	*- FS
25	2		*PIPE SUB ASSY WATER	Not Necessary	256.00 FS	*- FS
26	1		*HOSE SUB ASSY	Not Necessary	167.00 FS	*- FS
27	1		*BRACKET	Bent	125.40 FS	*125.40 FS
28	1		*BRACKET SUB ASSY	Bent	232.80 FS	*232.80 FS
29	1		*BRACKET ASSY	Bent	85.30 FS	*85.30 FS
30	1		*BRACKET SUB ASSY PL	Bent	123.20 FS	*123.20 FS
31	1		*HOSE ASSY	Not Necessary	545.50 FS	*- FS
32	1		*HOSE SUB ASSY, WATER	Not Necessary	79.00 FS	*- FS
33	1		*SENSOR, TEMPERATURE	Not Necessary	203.20 FS	*- FS
34	1		*SENSOR, EXHAUST GAS	Not Necessary	145.70 FS	*- FS
35	2		*SENSOR LEAN MIXTURE	Not Necessary	2,667.60 FS	*- FS
36	1		*PIPE SUB ASSY EXHAUST	Dented	909.70 FS	*909.70 FS
37	1		*GASKET, EXHAUST MAIN	Necessary	88.90 FS	*88.90 FS
38	1		*COMPUTER ASSY EMISSION	Not Necessary	2,877.70 FS	*- FS
39	2		*FLANGE EXHAUST PIPE	Necessary	261.00 FS	*261.00 FS
40	4		*GASKET EXHAUST PIPE	Necessary	782.00 FS	*782.00 FS
41	1		*SUPPORT EXHAUST PIPE (4PCS)	Bent (3Pcs Only)	438.00 FS	*328.50 FS
42	1		*SUPPORT EXHAUST PIPE	Bent	89.00 FS	*89.00 FS
43	1		*CONVERTER ASSY	Dented	9,342.30 FS	*9,342.30 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*CONVERTER ASSY MONO	Dented	6,648.40 FS	*6,648.40 FS
45	1		*CHAMBER SUB ASSY INL	Dented	909.40 FS	*909.40 FS
46	1		*CHAMBER SUB ASSY MIX	Dented	1,636.60 FS	*1,636.60 FS
47	1		*CHAMBER SUB ASSY SCR	Dented	1,663.60 FS	*1,663.60 FS
48	1		*CHAMBER SUB ASSY OUT	Dented	671.00 FS	*671.00 FS
49	1		*BRACKET ASSY, CA	Dented	1,610.40 FS	*1,610.40 FS
50	1		*BRACKET SUB ASSY, CA	Bent	1,129.10 FS	*1,129.10 FS
51	1		*SUPPORT, EXHAUST PIPE	Not Necessary	109.50 FS	*- FS
52	1		*MEMBER SUB ASSY, FR	Bent	706.30 FS	*706.30 FS
53	1		*HOSE SUB ASSY, WATER	Bent	23.80 FS	*23.80 FS
54	1		*BRACKET SUB ASSY, URE	Bent	673.30 FS	*673.30 FS
55	1		*BRACKET SUB ASSY, UREA	Dented	843.50 FS	*843.50 FS
56	1		*BRACKET SUB ASSY, HO	Not Necessary	232.80 FS	*- FS
57	1		*SPLASH BOARD, SIDE RH	Broken	171.20 FS	*171.20 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					61,689.80	45,018.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REPLACE ABOVE PARTS ASSY	New	2,250.00	1,200.00
2	LABOUR TO RE-PROGRAMMING ENGINE ECU	New	225.00	120.00
3	ALL WHEEL ALIGNMENT	New	280.00	200.00
Gross Labour Cost (S\$)			2,755.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >