

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbro@gmail.com

Invoice/Ref No: GBB872R190309

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Date: 18-03-19

Vehicle No: GBB872R

Model/Make: Toyota Hiace

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>cut/de</i>	\$ 599.30	
2	Bumper Clips 1 set <i>scr</i>	\$ 48.00	
3	Tail Lamp <i>ols scr</i>	\$ 303.10	
4	Tail Lamp Lower Garnish <i>cut</i>	\$ 165.10	
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Remove and refix rear bumper reverse sensor	\$ 80.00	- 50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 300
	To putty & spray painting & including touch up paint on accident affect	\$ 500.00	- 300
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	- X

Total Parts & Labour of estimate for damaged vehicle

\$ 2,295.50

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not authorized
new
4/5
1200
19/3/19
3 dy.

P-1115.5
257
836.62
1506.62

Liu's Brother Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: