

not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.





## RE: Pls upload delivery order and purchase order

Type

🔗 Question

Message

Hi, For parts ordered due to unavailability, please refer to PO. Listed items are critical parts that do not allow repair to progress unless available. Surveyor had checked with Komoco at that time and confirmed that they do not have parts for this make and model vehicle as it has stopped production, and replaced with electric model, different from third party vehicle. 57 days inclusive of Sunday and PH. All parts were air freight by stockists reducing unnecessary downtime if by sea freight. We are unable to comment whether 57 days is reasonable because we are not privy to stock availability and / or others facts at ordered country which may affect the delivery of parts. Thank you. Kindly let us have your mandate after review the case. Hsiao Tong- 29 July 2019

Reply



## Pls upload delivery order and purchase order

Type

Question

Message

TP requested for 57-day LOU for waiting of parts. Please advise what parts they were and if they would disrupt the repair of other parts. Please also comment if those parts are unavailable in SG, and if such a long waiting time is reasonable.

Reply

- for due to unavailability,
- Parts ordered pls refer to PO. Listed items are ~~critical~~ critical parts that do not allow repair to progress unless ~~arrived~~ available.
- Ben has checked with Komaco <sup>at that time</sup> and confirmed that they do not have parts for this make and model vehicle as it has stopped production, and replaced with ~~and an~~ electric model; different from TP vehicle.
- 57 days inclusive of PH and Sunday. All parts were airfreight by <sup>stockish</sup> ~~refused~~ reducing unnecessary downtime if by sea freight.



## ◀ Pls reconfirm the price on RH Centre Door Pillar

Type

🔔 Question

Message

We will also review on the down time.

Reply

Kamoco price is —



## ◀ RE: Pls reconfirm the price on RH Centre Door Pillar

Type

🔗 Question

Message

Hi, We have checked the price from Komoco and some local stockist and the price in the estimate was within the price range. Thank you. Kindly let us have your mandate asap. Hsiao Tong - 01 Aug 2019

Reply



## Hsiao Tong (LKKAUTO)

**From:** Shu Pei (LKKAUTO)  
**Sent:** Friday, 16 August 2019 9:27 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: New message for service request 105247, vehicle number SLZ9083Y

<input type="checkbox"/>	Message Hi, We have checked the price from Komoco and some local stockist and the price in the estimate was within the price range. Thank you. Kindly let us have your mandate asap. Hsiao Tong - 01 Aug 2019	CHT	1/8/2019 5:37:07 PM
<input type="checkbox"/>	8/15/19 1:18 PM WANG Peter----- Pls proceed DS with below revised quantum----- COR: \$30924.25 (\$45422.50 labour less 50% + \$1473.00 Special Net + \$6740.00 Labour) LOU: \$4100.00 (\$50/day for 82 days); TOWING FEE: \$120.00. Total: 35144.25. If TP rejects, you have mandate up to \$35200 for global-sum settlement.	LSP	16/8/2019 9:13:49 AM

Best Regards,  
Shu Pei | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
Sent: Thursday, 15 August 2019 1:47 PM  
To: Admin A <admin-a@lkkauto.com>  
Subject: FW: New message for service request 105247, vehicle number SLZ9083Y

Best Regards,  
Summer Lee | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: peter.wang@axa.com.sg <peter.wang@axa.com.sg>  
Sent: Thursday, 15 August, 2019 1:35 PM  
To: admin-d@lkkauto.com  
Subject: New message for service request 105247, vehicle number SLZ9083Y

AXA Insurance has sent you a message for claim number S9M01HIF.  
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.  
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.





## RE: Pls proceed DS with below revised quantum

Type

🔔 Question

Message

Hi, third party rejected our offer and counter proposed g/s \$38,800.00(all-in). Kindly let us have your further mandate/ instruction. Thank you. Hsiao Tong - 19 Aug 2019

Reply





## Service Request Details

Claim

S9M01HIF

Reference

CC4/ASM19005049/Dpb3 

Loss Date

19 March 2019

Report Date

20 Mar 2019 9:12:00 AM

Request Date

25 July 2019

Due Date

20 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Finish the work

Complete Work

More ▼

### Vehicle Information



Make

TPVD

Model

HYUNDAI

Service Address

---

...

Primary Contact/Insured

---

LEONG MUN LUI @ FOO AH HOE  
68 BELMONT ROAD, 269900, Singapore  
81116888  
johan.lim05@gmail.com

Claim Handler

---

WANG Peter  
  
peter.wang@axa.com.sg  
Additional Instructions

12

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE	<div>?</div>
SENT	22/8/19 2:01 PM
FROM	WANG Peter
SUBJECT	You may offer up to \$37k
BODY	Pls start offer up to \$36.5k.





LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

SENT 20/8/19 2:07 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Pls offer up to \$36000 (global-sum) for amicable settlement

BODY Hi, Peter, we have offered up to global sum \$36K(a...



TYPE



SENT 19/8/19 5:35 PM

FROM WANG Peter

SUBJECT Pls offer up to \$36000 (global-sum) for amicable settlement

BODY .



TYPE



SENT 19/8/19 4:16 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Pls proceed DS with below revised quantum

BODY Hi, third party rejected our offer and counter pro...



TYPE





LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

FROM WANG Peter

SUBJECT Pls proceed DS with below revised quantum

BODY COR: \$30924.25 (\$45422.50 labour less 50% + \$1473...



TYPE



SENT 1/8/19 5:48 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Pls reconfirm the price on RH Centre Door Pillar

BODY Hi, We have checked the price from Komoco and some...



TYPE



SENT 30/7/19 5:22 PM

FROM WANG Peter

SUBJECT Pls reconfirm the price on RH Centre Door Pillar

BODY We will also review on the down time.



TYPE



SENT 29/7/19 5:13 PM



SUBJECT RE: Pls upload delivery order and purchase order

BODY Hi, For parts ordered due to unavailability, pleas...



TYPE



SENT 26/7/19 4:09 PM

FROM WANG Peter

SUBJECT Pls upload delivery order and purchase order

BODY TP requested for 57-day LOU for waiting of parts. ...



TYPE



SENT 25/7/19 2:39 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: <TP - Mandate IA> - S9M01HIF [ACCIDENT INVOLVING SS 333P(OI) & SLZ 9083Y(TP) ON 19/03/2019]

BODY [4th REMINDER] Liability: 100%. Insured driver bea...



TYPE



SENT 8/7/19 12:24 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

BODY

Hi, we will inform third party liability is in the...



TYPE



SENT

8/7/19 11:08 AM

FROM

YONG Johnny

SUBJECT

mandate

BODY

Insd had admitted that he moved his car when the t...



TYPE



SENT

8/7/19 9:06 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

RE: <TP - Mandate IA> - S9M01HIF [ACCIDENT INVOLVING SS  
333P(OI) & SLZ 9083Y(TP) ON 19/03/2019]

BODY

[3rd REMINDER] Liability: 100%. Insured driver bea...



TYPE



SENT

26/6/19 10:06 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

RE: <TP - Mandate IA> - S9M01HIF [ACCIDENT INVOLVING SS  
333P(OI) & SLZ 9083Y(TP) ON 19/03/2019]



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu



TYPE



SENT

19/6/19 5:17 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

RE: Pending confirmation if lawyer discharged themselves from TPPD claim

BODY

Hi Peter, we were informed by third party repairer...



TYPE



SENT

19/6/19 10:52 AM

FROM

WANG Peter

SUBJECT

Pending confirmation if lawyer discharged themselves from TPPD claim

BODY

Hi Hsiao Tong, we received LOD from Kuru &amp; Co earl...



TYPE



SENT

10/6/19 4:49 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT


RE: &lt;TP - Mandate IA&gt; - S9M01HIF [ACCIDENT INVOLVING SS 333P(OI) &amp; SLZ 9083Y(TP) ON 19/03/2019]



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu



TYPE 


SENT 1/6/19 10:02 AM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT <TP - Mandate IA> - S9M01HIF [ACCIDENT INVOLVING SS 333P(OI) & SLZ 9083Y(TP) ON 19/03/2019]

BODY Liability: 100%. Insured driver beat red light and...



TYPE 


SENT 4/4/19 5:58 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT IA - SLZ 9083Y

BODY Hi Peter, kindly inform need to indent parts from ...



TYPE 

SENT 2/4/19 2:18 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Pls update status on DS

BODY Hi All, Pls ignore our msg dated 02/04/2019@2.02PM...



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

TYPE



SENT

2/4/19 2:02 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

RE: Pls update status on DS

BODY

Dear Peter, Please be informed that vehicle has b...



TYPE



SENT

25/3/19 2:25 PM

FROM

WANG Peter

SUBJECT

Pls update status on DS

BODY

We received TPPD LOD from lawyer. Please update st...



TYPE



SENT

20/3/19 6:14 PM

FROM

WANG Peter

SUBJECT

Liability clear - pls get OI LOA and driver DL

BODY





LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

SENT 20/3/19 3:31 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT VEH IN

BODY





## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Thursday, 22 August 2019 2:44 PM  
**To:** Alfred Quah  
**Cc:** Bryan Ang (LKKAUTO)  
**Subject:** RE: Your Ref: SLZ9083Y// LKK REF: CC4/ASM19005049/Dpb3(SS333P) DOA: 19/03/2019  
**Attachments:** EXPRESS SETTLEMENT FORM\_SLZ9083Y.pdf

### Without Prejudice

Dear Mr Alfred,

As spoken earlier, we confirm settlement at a global sum of \$37,000.00(all-in).

Please duly sign the document attached and return to us for our necessary action.

Thanks.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Alfred Quah <[alfredauto@hotmail.com](mailto:alfredauto@hotmail.com)>  
**Sent:** Saturday, 17 August 2019 2:18 PM  
**To:** Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Bryan Ang (LKKAUTO) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>  
**Subject:** Re: Your Ref: SLZ9083Y// LKK REF: CC4/ASM19005049/Dpb3(SS333P) DOA: 19/03/2019

Dear Hsiao Tong,

With reference to our Letter of Demand Dated 17 May 2019, with Ref: SS 333 P, our cost of repair outlay (without waiver) amounts to S\$43,773.47. As a good will, we waived the Freight Charges of S\$2,890 and the cost of disbursement of S\$343.47, thus the total of S\$40,540.

For an amicable settlement within a week (by 23 September 2019) our client is prepared to settle for a amount of S\$38,800 (final).

After the 23 September 2019, our client has instructed us to hand the said claim to our legal council to seek recourse.

Alfred Quah



**From:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Sent:** Friday, August 16, 2019 1:02 PM  
**To:** [alfredauto@hotmail.com](mailto:alfredauto@hotmail.com) <[alfredauto@hotmail.com](mailto:alfredauto@hotmail.com)>  
**Cc:** Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>  
**Subject:** Your Ref: SLZ9083Y// LKK REF: CC4/ASM19005049/Dpb3(SS333P) DOA: 19/03/2019

**Without Prejudice**

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair	\$ 30,924.25
2. Loss of Use (82days x \$50.00)	\$ 4,100.00
3. Towing Fee	\$ 120.00
<b>Total</b>	<b>\$ 35,144.25</b>

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# KURU & CO

## PRE REPAIR INSPECTION (PRI) MEMO 1

Our ref no : L.19.0388  
 Date : 27.03.19  
 Attn. : ALFRED / GOH LEE HWA  
 Vehicle no/DOA/Model : SLZ 9083Y / 19.03.2018 / HYUNDAI

Dear Sir,

The PRI notification letter to the Third Party insurer was sent on 22 / 03 / 19 @ 0923 AM / ~~PM~~. Time frame - 2 working days (not including Saturday, Sunday and Public Holiday)

- ☐ **NO REPLY** from Third Party insurer. Please proceed to appoint your surveyor and repair the vehicle.
- ☐ We have received the Third Party insurer's **REPLY** with their list of surveyors on \_\_\_\_ / \_\_\_\_ / \_\_\_\_ @ \_\_\_\_ AM / PM. Copy enclosed.
- ☐ If you **AGREE**, please indicate your choice of surveyor(s)

- 1) LKK AUTO CONSULTANTS  
 2) \_\_\_\_\_  
 3) \_\_\_\_\_

Their surveyor has to **NOTIFY YOU IN WRITING** to state that the PRI is completed and that you may proceed to repair the vehicle. (This letter also support your claim for loss of use/rental)

Please forward us the repair bill and supporting documents when it's ready for us to proceed with your claim.

Meanwhile, please let us the following information that is required for the claim:

1	PRI (Before dismantle)	Date: <u>28/03/2019</u>	Time: <u>1100hrs</u>
2	PRI (Dismantle) <u>5/4/19</u>	Date: <u>28/3/19</u>	<u>Sign 2kk And 4.30pm</u>
3	Post repair inspection (if any)	Date: <u>17/5/2019</u>	<u>mtk</u>
4	Surveyor	Co: <u>LKK.</u>	Name: _____
5	Agreed COR / Days for repair	\$ _____	Days: _____
6	Vehicle	Date in: _____	Date out: _____

If their surveyor is asking for Direct Settlement, our legal fees at this stage is \$321.00 plus disbursements incurred.

- ☐ If you **OBJECT**, please let us have your list of 10 surveyor company, surveyor name and contact number.

Please let us have your **reply ASAP before the 2 working days**. Otherwise, it will be deemed that you have **AGREED** to ANY of the surveyors listed by the Third Party insurer.

Please fax back to 65322 007.

Warmest Rgds,  
 Anne / Lena / Irena



# KOMOCO MOTORS PTE. LTD.

253 Alexandra Road #01-01 Singapore 159936  
Parts Department Tel: (65) 6479 3335 Fax: (65) 6479 4626

To Account: D/S002  
MIN GHEE AUTO PTE LTD  
8 #01-01 JALAN LEMBAH KALLANG  
MIN GHEE BUILDING  
SINGAPORE 339564  
Tel :62983888 Fax :62970863

TAX INVOICE (CREDIT SALE)  
GST Ref No MR-8500364-4  
Company Reg 199609283R

Invoice No : CGI-APC-2019000753  
Date : 18/04/2019  
Payment Terms : 30 Days Credit  
Type :  
Remarks : PO 40217  
POH

S/N	Part Number	Description	Qty	Unit Price	Discount %	Total SGD
1	87722J9000	GARNISH ASSY-FR DR SIDE RH	1			
2	82308J9100RFT	PANEL ASSY-FRONT DOOR TRIM,RH	1			
3	71120J9A00	PANEL ASSY-PILLAR OUTER,RH	1			
4	87742J9000CA	GARNISH ASSY-QTR SIDE,RH	1			
5	85845J9000TRY	TRIM ASSY-CTR PILLAR LWR RH	1			
6	87732J9000	GARNISH ASSY-RR DR SIDE,RH	1			
7	AIR FREIGHT	AIR FREIGHT	1			

ORIGINAL

All Payment to be made payable to **Komoco Motors Pte Ltd**  
Goods sold are not returnable

E. & O. E.

CGI-APC-2019000753

Page : 1 / 2

Created By : PD020 18/04/2019 5:08:25 PM

Printed By : PD020 18/04/2019 5:08:33 PM





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19005049/Dpb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-08-2019		
ATTN: JOHNNY YONG		Code : ASM		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SS 333P	Veh. Inspected	SLZ 9083Y	
Policy No.	GA310756/1	Coverage (\$)	0.00	
Claim No.	S9M01HIF	Excess (\$)	0.00	
Assign From	JOHNNY YONG	Assign Date	20/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI KONA	c.c	998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHK3811LJU094455	Colour	GREY	
Odometer	12635	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S FRONT PORTION, O/S BODY, O/S REAR PORTION AND REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/03/2019	Inspection Date	28/03/2019	
Survey held at	GOH LEE HWA AUTOMOBILE BLK 5033, #01-255 AVENUE 3 ANG MO KIO IND. PARK 2 SINGAPORE 569536			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>25 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 9083Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	CUT	481.00	481.00
1	FRONT BUMPER CENTRE GRILLE TOP (CONSISTENT)	NOT NECESSARY	485.00	-
1	FRONT BUMPER LOWER SPOILER (CONSISTENT)	CUT	265.00	265.00
2	FRONT BUMPER H/LAMP GARNISH RH/LH @ \$239.20 (CONSISTENT)	N/S CUT / O/S NOT NECESSARY	478.40	239.20
2	FRONT BUMPER H/LAMP COVER @ \$39.60 (CONSISTENT)	NOT NECESSARY	79.20	-
2	FRONT BUMPER FOG LAMP GRILLE @ \$51.40 (CONSISTENT)	N/S CUT / O/S NOT NECESSARY	102.80	51.40
2	FRONT BUMPER SIDE RETAINER @ \$20.50 (CONSISTENT)	NOT NECESSARY	41.00	-
1	FRONT BUMPER BEAM (CONSISTENT)	BENT	645.40	645.40
1	FRONT BUMPER REFLECTOR LH (CONSISTENT)	NOT NECESSARY	69.00	-
1	FRONT BUMPER LOWER LIP (CONSISTENT)	CUT / DEFORMED	289.00	289.00
1	FRONT BUMPER LOWER GARNISH (CONSISTENT)	NOT NECESSARY	265.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	TORN	96.20	96.20
4	SETS FRONT BUMPER PARKING SENSOR @ \$179.80 (CONSISTENT)	DAMAGED 2PCS ONLY	719.20	359.60
1	FRONT GRILLE & LOGO (CONSISTENT)	CRACKED	486.85	486.85
2	FRONT HEADLAMP RH/LH ASSY @ \$1844.00 (CONSISTENT)	MTG CRACKED / BROKEN	3,688.00	3,688.00
2	FRONT SIGNAL LAMP RH/LH ASSY @ \$773.50 (CONSISTENT)	N/S CUT / O/S NOT NECESSARY	1,547.00	773.50
1	FRONT SUPPORT LOWER GARNISH (CONSISTENT)	NOT NECESSARY	355.00	-
10	FRONT SUPPORT GARNISH CLIPS @ \$5.50 (CONSISTENT)	NOT NECESSARY	55.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	BENT / CRACKED	949.00	949.00
1	FRONT AIR BAGS SENSOR (BUMPER LH) (CONSISTENT)	ACTIVATED	385.00	385.00
1	FRONT HORN (CONSISTENT)	NOT NECESSARY	98.00	-
1	RH FRONT FENDER (CONSISTENT)	DENTED	551.50	551.50
1	RH FRONT FENDER GARNISH (CONSISTENT)	NOT NECESSARY	144.45	-
1	RH FRONT FENDER PROTECTOR (CONSISTENT)	CUT	105.00	-
12	RH FRONT FENDER GARNISH CLIPS @ \$5.50 (CONSISTENT)	NOT NECESSARY	66.00	-

Report Ref No. CC4/ASM19005049/Dpb3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH FRONT FENDER DUST GARNISH (CONSISTENT)	NOT NECESSARY	175.48	-
10	FRONT FENDER DUST GARNISH CLIPS @ \$5.50 (CONSISTENT)	NOT NECESSARY	55.00	-
1	RH DOOR (FRONT) (CONSISTENT)	BUCKLED	1,594.30	1,594.30
1	RH DOOR HINGE UPPER (CONSISTENT)	BENT	63.20	63.20
1	RH DOOR HINGE LOWER (CONSISTENT)	BENT	63.20	63.20
1	RH DOOR CENTRE STOPPER (CONSISTENT)	BENT	65.30	65.30
1	RH DOOR PROTECTOR (CONSISTENT)	DISLODGE	173.20	173.20
1	RH DOOR LOCK ASSY (CONSISTENT)	DAMAGED	245.30	245.30
1	RH DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY	147.50	-
1	RH DOOR SIDE MIRROR ASSY (CONSISTENT)	NOT NECESSARY	692.00	-
1	RH DOOR FRAME STICKER (CONSISTENT)	NECESSARY	77.10	77.10
1	RH DOOR GLASS MOULDING (CONSISTENT)	BENT	72.60	72.60
1	RH DOOR INNER RUBBER (CONSISTENT)	DEFORMED	135.00	135.00
1	RH DOOR POWER WINDOW REGULATOR ASSY (CONSISTENT)	BENT	195.00	195.00
1	RH DOOR BOARD (CONSISTENT)	DEFORMED	512.00	512.00
1	RH DOOR CONTROL SWITCH (CONSISTENT)	NOT NECESSARY	573.00	-
1	RH DOOR INNER SEAL (FRONT) (CONSISTENT)	NECESSARY	146.60	146.60
1	RH DOOR INNER MOULDING (CONSISTENT)	NOT NECESSARY	72.60	-
1	RH DOOR CHANNEL RUBBER (CONSISTENT)	NOT NECESSARY	95.30	-
1	RH FRONT DOOR FRAME RUBBER (CONSISTENT)	DEFORMED	89.10	89.10
1	RH REAR DOOR (CONSISTENT)	BUCKLED	1,832.95	1,832.95
1	RH REAR DOOR HINGE UPPER (CONSISTENT)	BENT	63.20	63.20
1	RH REAR DOOR HINGE LOWER (CONSISTENT)	BENT	63.20	63.20
1	RH REAR DOOR STOPPER (CONSISTENT)	BENT	65.30	65.30
1	RH REAR DOOR PROTECTOR (CONSISTENT)	BENT	142.00	142.00
1	RH REAR DOOR LOCK ASSY (CONSISTENT)	DAMAGED	238.20	238.20
1	RH REAR DOOR OUTER HANDLE (CONSISTENT)	DAMAGED	147.20	147.20
1	RH REAR DOOR FRAME STICKER (CONSISTENT)	NECESSARY	63.00	63.00
1	RH REAR DOOR GLASS MOULDING (CONSISTENT)	BENT	89.00	89.00
1	RH REAR DOOR INNER RUBBER (CONSISTENT)	DEFORMED	168.00	168.00
1	RH REAR DOOR POWER WINDOW REGULATOR ASSY (CONSISTENT)	BENT	190.00	190.00

Report Ref No. CC4/ASM19005049/Dpb3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH REAR DOOR BOARD (CONSISTENT)	MTG CRACKED	533.00	533.00
1	RH REAR DOOR INNER SEAL (CONSISTENT)	NOT NECESSARY	147.00	-
1	RH REAR DOOR INNER SEALANT (CONSISTENT)	NOT NECESSARY	80.00	-
1	RH CENTRE DOOR PILLAR (CONSISTENT)	BUCKLED	3,539.00	3,539.00
1	RH CENTRE PILLAR HOUSING (CONSISTENT)	DENTED	946.50	946.50
1	RH CENTRE LOCAL PANEL (CONSISTENT)	BUCKLED	1,480.00	1,480.00
1	RH CENTRE LOCAL PANEL GARNISH (CONSISTENT)	DEFORMED	338.00	338.00
1	RH REAR DOOR PILLAR RUBBER (CONSISTENT)	NOT NECESSARY	65.30	-
1	RH REAR FENDER (CONSISTENT)	DENTED	1,768.00	1,768.00
1	RH REAR FENDER PROTECTOR (CONSISTENT)	DISLODGE	181.00	181.00
1	REAR BUMPER (CONSISTENT)	CUT	475.00	475.00
2	REAR BUMPER SIDE RETAINER @ \$37.00 (CONSISTENT)	NOT NECESSARY	74.00	-
1	SET REAR BUMPER PARKING SENSOR @ \$217.50 (CONSISTENT)	DAMAGED	870.00	870.00
1	REAR BUMPER BEAM (CONSISTENT)	NOT NECESSARY	218.00	-
2	REAR BUMPER CATCH @ \$28.00 (CONSISTENT)	NOT NECESSARY	56.00	-
1	REAR BUMPER SPONGE (CONSISTENT)	DISLODGE	110.00	110.00
1	REAR FENDER DUST GARNISH (CONSISTENT)	DISLODGE	159.50	159.50
1	REAR FENDER HOUSING (CONSISTENT)	BUCKLED	1,085.00	1,085.00
1	REAR BUMPER CENTRE PAD (CONSISTENT)	CUT	168.00	168.00
2	REAR BUMPER LAMP ASSY @ \$162.00 (CONSISTENT)	BROKEN	324.00	324.00
1	REAR BUMPER DUST GARNISH RH (CONSISTENT)	NOT NECESSARY	96.00	-
1	REAR BUMPER PANEL GARNISH RH (CONSISTENT)	NOT NECESSARY	109.00	-
1	ROOF AIRBAGS (CONSISTENT)	ACTIVATED	1,440.00	1,440.00
1	CUSHION SEAT AIRBAGS (CONSISTENT)	ACTIVATED	1,166.30	1,166.30
1	ROOF AIRBAGS SENSOR (CONSISTENT)	DAMAGED	526.00	526.00
1	CUSHION AIRBAGS CONTRL UNIT (CONSISTENT)	ACTIVATED	1,061.00	1,061.00
1	FRONT RH WINDSCREEN PILLAR GARNISH (CONSISTENT)	NOT NECESSARY	158.00	-
1	SET ROOF LINING ASSY (CONSISTENT)	BENT	1,535.30	1,535.30
1	FRONT RH SAFETY BELT (CONSISTENT)	ACTIVATED	909.50	909.50
1	REAR RH SAFETY BELT CONTROL UNIT (CONSISTENT)	NOT NECESSARY	645.00	-
1	RH CUSHION ASSY (DRIVER) (CONSISTENT)	DAMAGED	1,690.00	1,690.00

Report Ref No. CC4/ASM19005049/Dpb3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FCA CONTROL UNIT (AGENT CONTROL ITEM) (FORWARD COLLISION AVOIDANCE ASST.) (CONSISTENT)	DAMAGED	1,990.00	1,990.00
1	CENTRE PILLAR UPPER GARNISH (CONSISTENT)	MTG CRACKED	64.50	64.50
1	CENTRE PILLAR LOWER GARNISH (CONSISTENT)	BROKEN	65.30	65.30
1	FRONT WINDSCREEN TOP MOULDING (CONSISTENT)	NOT NECESSARY	55.00	-
1	FRONT WINDSCREEN INNER SEAL (CONSISTENT)	NOT NECESSARY	52.00	-
1	REAR RH QUARTER GLASS MOULDING & SEA ASSY (CONSISTENT)	NECESSARY	309.00	309.00
1	REAR RH CUSHION TOP (CONSISTENT)	DEFORMED	699.00	699.00
1	REAR RH CUSHION COVER (CONSISTENT)	DEFORMED	95.00	95.00
1	DASH BOARD (CONSISTENT)	BENT / MTG DEFORMED	918.00	918.00
1	RH FRONT ABSORBER (CONSISTENT)	BENT	392.00	392.00
1	RH FRONT ABSORBER MOULDING (CONSISTENT)	NOT NECESSARY	135.00	-
1	RH FRONT KNUCKLE ARM (CONSISTENT)	DISTORTED / BENT	382.00	382.00
1	RH FRONT KNUCKLE HUP & BEARING (CONSISTENT)	DAMAGED	573.00	573.00
1	STEERING RACK ASSY (CONSISTENT)	DAMAGED	1,027.00	1,027.00
1	RH FRONT WHEEL SENSOR (CONSISTENT)	NOT NECESSARY	158.00	-
1	RH LOWER ARM (FRONT) (CONSISTENT)	DISTORTED	472.00	472.00
2	RH REAR ABSORBER RH/LH @ \$278.00 (CONSISTENT)	O/S DISTORTED / N/S NOT NECESSARY	556.00	278.00
2	RH REAR ABSORBER MOUNTING RH/LH @ \$149.00 (CONSISTENT)	NOT NECESSARY	298.00	-
1	RH REAR AXLE (CONSISTENT)	DISTORTED	1,235.00	1,235.00
2	RH REAR KNUCKLE HUP BEARING & SENSOR @ \$487.00 (CONSISTENT)	O/S DAMAGED / N/S NOT NECESSARY	974.00	487.00
1	AIR PRESSURE SENSOR (O/S REAR) (CONSISTENT)	DAMAGED	199.00	199.00
1	BRAKE OIL (CONSISTENT)	NOT NECESSARY	90.00	-
4	WHEEL MUDFLAP @ \$59.00 (CONSISTENT)	O/S FRONT/REAR / N/S REAR CUT	236.00	177.00
	LESS 20% DISCOUNT		-	-9,084.50
			53,680.03	36,338.00

Report Ref No. CC4/ASM19005049/Dpb3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>SPECIAL NETT ITEMS</b>				
20	FRONT BUMPER CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	110.00	30.00
10	RH FENDER PROTECTOR CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	20.00
10	RH FRONT DOOR PROTECTOR CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	20.00
10	RH DOOR BOARD CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	20.00
1	RH DOOR INNER SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	20.00
10	RH REAR DOOR BOARD CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	30.00
10	RH CENTRE LOCAL PANEL CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	20.00
10	REAR FENDER PROTECTOR CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	20.00
10	REAR FENDER DUST GARNISH CLIPS @ \$5.50 (SN) (CONSISTENT)	NECESSARY	55.00	20.00
4	SPORT RIM (17") @ \$33.00 (SN) (CONSISTENT)	O/S FRONT / REAR CUT	1,320.00	660.00
4	TYRE (215 X 55 X R17) @\$355.00 (@ \$710.00 80%) (SN) (CONSISTENT)	O/S FRONT / REAR PUNCTURE	1,420.00	568.00
1	SET FRONT NUMEBR PLATE & BOX (SN) (CONSISTENT)	BENT	60.00	45.00
			3,375.00	1,473.00
<b>LABOUR</b>				
TO CHECK WIRING, CHECK SRS, AIR-BAG & ERASE FAULT CODING & CODING & CENTRE LOCK WIRING.			800.00	350.00
TO REMOVE AND REFIT WINDSCREEN & QUARTER GLASS.			280.00	180.00
TO REMOVE & REFIT INTERIOR CARPET GARNISH, ROOF LINING, CUSHION & ALL ACCIDENT AFFECTED AREA & CLEANING.			900.00	300.00
TO REMOVE AND REFIT FRONT & REAR UNDER CARRIAGE DAMAGE AFFECTED AREA.			1,800.00	800.00
TO REMOVE & RENEW SPORT RIM, TYRE & REBALANCING.			200.00	80.00
TO KNOCKING, WELDING, STRAIGHTENING ALL ACCIDENT DAMAGE AFFECTED AREA.			3,000.00	2,600.00
TO RESRAY PAINTING ON ALL ACCIDENT AFFECTED AREA.			2,400.00	1,900.00

Report Ref No. CC4/ASM19005049/Dpb3s2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOF ALL ACCIDENT AFFECTED AREA.	NOT NECESSARY	400.00	150.00
	TO PRESS WHEEL HUP BEARING.		200.00	-
	TO ADJUST COMPUTER WHEEL ALIGNMENT & TEST DRIVE.		280.00	80.00
	TO REMOVE AND REFIT AIR-CON CONDENSER & TURBO COOLER & TOP-UP GAS & OIL.		280.00	120.00
	TO REMOVE & REFIT & RENEW DASH BOARD.		800.00	180.00
			11,340.00	6,740.00
GRAND TOTAL			68,395.03	44,551.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				35,500.00

Report Ref No. CC4/ASM19005049/Dpb3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.