




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19005049/Dpb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG		Date : 26-08-2019		
		Code : ASM		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SS 333P	Veh. Inspected	SLZ 9083Y	
Policy No.	GA310756/1	Coverage (\$)	0.00	
Claim No.	S9M01HIF	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	20/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI KONA	c.c	998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHK3811LJU094455	Colour	GREY	
Odometer	12635	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S FRONT PORTION, O/S BODY, O/S REAR PORTION AND REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/03/2019	Inspection Date	28/03/2019	
Survey held at	GOH LEE HWA AUTOMOBILE BLK 5033, #01-255 AVENUE 3 ANG MO KIO IND. PARK 2 SINGAPORE 569536			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>25 Working Days</b>		