



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGB 905X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	R/R DOOR TRIM FRONT R/R SUCH PANEL (WCP) (CONSISTENT)	NO SUCH PARTS	55.00	-
1	REAR BUMPER (WCP) (CONSISTENT)	BROKEN	480.00	480.00
1	REAR BUMPER SPOILER (WCP) (CONSISTENT)	CUT	180.00	180.00
1	R/R TOWING LUG COVER (WCP) (CONSISTENT)	CUT	15.00	15.00
1	L/R BUMPER GUIDE S/HOLDER	BROKEN	18.00	18.00
1	R/R BUMPER GUIDE (WCP) (CONSISTENT)	BROKEN	18.00	18.00
1	REAR BUMPER SUPPORT REIN (WCP) (CONSISTENT)	* CHECK	265.00	-
1	RR BUMPER MOULDING FOAM (WCP) (CONSISTENT)	* CHECK	50.00	-
1	RR BUMPER CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	15.00	-
1	REAR PANEL (WCP) (CONSISTENT)	BENT	430.00	430.00
1	CROSSMEMBER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R OUTER SENSOR (WCP) (CONSISTENT)	SERVICEABLE	85.00	-
1	R/R OUTER SENSOR (WCP) (CONSISTENT)	BROKEN	85.00	85.00
1	L/R INNER SENSOR (WCP) (CONSISTENT)	SERVICEABLE	85.00	-
1	R/R INNER SENSOR (WCP) (CONSISTENT)	SERVICEABLE	85.00	-
1	L/R OUT SENSOR BRKT (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	R/R OUT SENSOR BRKT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R INNE SENSOR BRKT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R INN SENSOR BRKT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	APPLICATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	2-COMP ADHESIVE SENS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R REFLECTOR (WCP) (CONSISTENT)	BROKEN	30.00	30.00
1	R/SIDE PANEL R/R FENDER (WCP) (CONSISTENT)	NO SUCH PARTS	480.00	-
1	RR LOCK CARRIER TRIM GARNISH. T(WCP) (CONSISTENT)	NOT NECESSARY	75.00	-
	COST PLUS 15%		367.65	188.40
			2,818.65	1,444.40
SPECIAL NETT ITEMS				
1	AUDATEX FEE AUDATEX FEE (SN) (CONSISTENT)		45.00	45.00
			45.00	45.00

Report Ref No. CC4/ASM19005051/Eps3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR ALIGNMENT ALIGNMENT. TOTAL LABOUR. PAINT WORK: LABOUR COST AND INCLUDING MATERIAL.		60.00 1,251.00 634.50 1,945.50	60.00 1,026.00 589.50 1,675.50
GRAND TOTAL			4,809.15	3,164.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$362.25 NETT)				2,500.00

Report Ref No. CC4/ASM19005051/Eps3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.