

**Progressive Car Care Pte Ltd**  
**Blk 3022A Ubi Road 1 #01-46**  
**408716**

Claim Reference: TP 0319 - 5445  
 Assessment number: TP 0319 - 5445  
 Version: 1810  
 Date calculated: 03/19/2019 03:08 PM

the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To inspect damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplemental item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Steve (CLKK) with Napadi 20/3/19  
 8321 8813 L/S 12.00 pm  
 Run AK spray  
 5 days

Full Report  
 Registration: SGB905X  
 Printed: 19/03/2019 3:08 PM

Paint Work

| Code         | Description - TWO COAT PEARL/MICA                                                 | WU   | Price SGD |
|--------------|-----------------------------------------------------------------------------------|------|-----------|
| 53 55 61 00) | ADD/TIME FOR ONE MAIN WORK R/SIDE PANEL NEW PART PAINT STAGE 1                    | 2.0  | 9.00      |
| 51 01 71 13  | PAINTING PREPARATION WORK NEW PART S1 METAL (PART/S FITTED)                       | 19.0 | 85.50     |
| 51 01 71 93  | PREPARATION FOR PAINT (PLASTIC PARTS) (WITH PART(S) REMOVED) (ASSEMBLY OPERATION) | 2.0  | 9.00      |

Total Paint

Hrs 14.10 WU 141.0 Price SGD 634.50

**Spare Parts**

| Code | Description          | Part Number       | Supplier            | prices as at 2015-06-01 | Price SGD |
|------|----------------------|-------------------|---------------------|-------------------------|-----------|
| 1902 | R/R DOOR TRIM FRONT  | 5K6 839 902 B 041 | R/R SUCH PANEL X NN |                         | 55.00     |
| 2583 | REAR BUMPER          | 5K6 807 421 GRU   | BR                  |                         | 480.00    |
| 2605 | REAR BUMPER SPOILER  | 5K6 807 521 M 9B9 | L CAT               |                         | 180.00    |
| 2607 | R/R TOWING LUG COVER | 5K6 807 441 9B9   | CAT                 |                         | 15.00     |
| 2617 | L/R BUMPER GUIDE     | 5K6 807 393 C     | S/HOLDER BR         |                         | 18.00     |
| 2618 | R/R BUMPER GUIDE     | 5K6 807 394 C     | BR                  |                         | 18.00     |
| 2640 | REAR BUMPER SUPPORT  | 5K0 807 305 A     | REIN ?              |                         | 265.00    |
| 2645 | RR BUMPER MOULDING   | 5K6 807 863       | FOAM ?              |                         | 50.00     |
| 2655 | RR BUMPER CLAMP KIT  | 5K6 898 623       | NN                  |                         | 15.00     |
| 2711 | REAR PANEL           | 5K6 813 301       | BT                  |                         | 430.00    |
| 2719 | CROSSMEMBER END      | 1K6 813 309 B     | X NN                |                         | 0.00      |
| 2781 | L/R OUTER SENSOR     | 1S0 919 275 C GRU | X SVC               |                         | 85.00     |
| 2782 | R/R OUTER SENSOR     | 1S0 919 275 C GRU | BR                  |                         | 85.00     |
| 2783 | L/R INNER SENSOR     | 1S0 919 275 C GRU | X SVC               |                         | 85.00     |
| 2784 | R/R INNER SENSOR     | 1S0 919 275 C GRU | X SVC               |                         | 85.00     |
| 2787 | L/R OUT SENSOR BRKT  | 5K0 919 491 B     | X SVC               |                         | 0.00      |

**Progressive Car Care Pte Ltd**  
**Blk 3022A Ubi Road 1 #01-46**  
**408716**

Claim Reference: TP 0319 - 5445  
 Assessment number: TP 0319 - 5445  
 Version: 1810  
 Date calculated: 03/19/2019 03:08 PM

Full Report  
 Registration: SGB905X  
 Printed: 19/03/2019 3:08 PM

| Code             | Description          | Part Number       | Supplier        | Price SGD                |
|------------------|----------------------|-------------------|-----------------|--------------------------|
| 2788             | R/R OUT SENSOR BRKT  | 5K0 919 491 B     | nn              | 0.00                     |
| 2789             | L/R INN SENSOR BRKT  | 5K0 919 491 C     | nn              | 0.00                     |
| 2790             | R/R INN SENSOR BRKT  | 5K0 919 492 C     | nn              | 0.00                     |
| 2798             | APPLICATOR           | D 009 500 25      | nn              | 0.00                     |
| 2799             | 2-COMP ADHESIVE SENS | 180 KU2 A1        | nn              | 0.00                     |
| 3318             | R/R REFLECTOR        | 5K0 945 106 G     | OR              | 30.00                    |
| 3482             | R/SIDE PANEL         | 5K4 809 844       | R/R FENDER X NS | 480.00                   |
| 4985             | RR LOCK CARRIER TRIM | 1K6 863 459 R 82V | GARNISH-T. X NN | 75.00                    |
| f: OEM Parts     |                      |                   |                 | Savings 0.00             |
| n: Non-OEM Parts |                      |                   |                 | Subtotal 2,451.00        |
| u: Used parts    |                      |                   |                 | Addition(+15.00%) 367.65 |
| <b>Total</b>     |                      |                   |                 | <b>2,818.65</b>          |

**Extras**

| Code                | Description             | Price SGD     |
|---------------------|-------------------------|---------------|
| 1000                | AUDATEX FEE AUDATEX FEE | 45.00*        |
| 1001                | ALIGNMENT ALIGNMENT     | 60.00*        |
| <b>Total Extras</b> |                         | <b>105.00</b> |

**Progressive Car Care Pte Ltd**  
**Blk 3022A Ubi Road 1 #01-46**  
**408716**

Claim Reference: TP 0319 - 5445  
Assessment number: TP 0319 - 5445  
Version: 1810  
Date calculated: 03/19/2019 03:08 PM

**Full Report**  
**Registration: SGB905X**  
**Printed: 19/03/2019 3:08 PM**

**Final Calculation**

|                                       | SGD                          | SGD             |
|---------------------------------------|------------------------------|-----------------|
| <b>Parts</b>                          | 2,451.00                     |                 |
| Addition(+15.00%)                     | 367.65                       |                 |
| <b>Total Parts</b>                    |                              | <b>2,818.65</b> |
| <b>Labour Time Base 10 WU/h</b>       |                              |                 |
| Total 278.0 WU X 45.00 SGD/h          | <del>1,251.00</del> 1,026.00 |                 |
| <b>Total of Labour</b>                |                              | <b>1,251.00</b> |
| <b>Total Of Extras</b>                |                              | <b>105.00</b> ✓ |
| <b>Paint Work Time Base 10 WU/h</b>   |                              |                 |
| Labour Cost 141.0 WU X 45.00 SGD/h    | <del>634.50</del> 589.50     |                 |
| <b>Total Paint Including Material</b> |                              | <b>634.50</b>   |
| <b>Repair Cost Excludes GST</b>       |                              | <b>4,809.15</b> |
| GST (+7.00%)                          |                              | <b>336.64</b>   |
| <b>Repair Cost Included GST</b>       |                              | <b>5,145.79</b> |

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS