

22/03/2002

ASS. REC. BY:

REF: CS / SPF 19005080 / Gnd 302

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Perry HE

of

SPF

Date/Time:

15/3/19 @ 11:02am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 7522

Insured:

at Workshop m/s

Indeco

Tel:

9787 7084

of

39 Defn June 12

Policy No:

Claim No:

MHA SPF 0300000113

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA

☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:11am @ 15/3/19

Person Contacted:

Mike

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 7522 - X

21/3/19 @ 4.14pm revert to Perry by email.

Material = £3387.60 ; Man hours = 53.5 hrs

Surveyor

60

REF: SPF

ASSIGNMENT

From: Date: 20/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 752 Z
at Workshop m/s Indeco
of 39 DeFu lene 12

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Mike 09787 7084

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBC7528 Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 3.0

Make: Nissan URVAN c.c 2953

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 19428 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1TG4E 258 0789711

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 20-03-19

Survey held at w/s 2330pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/3 Finalized \$53.5 Hr with Anson.

Do Not Finalise

21/3/2019

RECEIVED 09 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

180

180

Nivitha (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 15 March 2019 11:02 AM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - GBC752Z

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contract rate.

Ref: MHASPF0300000113

GBC752Z

Parts:

- 1 Scope Of Repairs
- 1.1 TAILGATE
- 1.2 TAILGATE HINGE RH
- 1.3 TAILGATE HINGE LH
- 1.4 TAILGATE LOCK
- 1.5 TAILGATE LOCK CATCH
- 1.6 TAILGATE TRIM BOARD
- 1.7 TAILGATE DAMPER RH
- 1.8 TAILGATE DAMPER LH
- 1.9 TAILLAMP RH
- 1.10 TAILLAMP PANEL RH
- 1.11 TAILGATE WEATHER STRIP
- 1.12 REAR BUMPER
- 1.13 REAR BUMPER CENTER BRACKET
- 1.14 REAR BUMPER CLIP 85071-01N00
- 1.15 REAR BUMPER CLIP 01553-10721
- 1.16 REAR BUMPER CLIP 85099-VW000
- 1.17 REAR BUMPER CLIP 85221-VW000
- 1.18 REAR PILLAR LOWER GARNISH RH 76939
- 1.19 REAR WINDSCREEN MOULDING
- 1.20 SEALANT
- 1.21 REAR END PANEL ASSY
- 1.22 FUEL TANK PIPE 17221-VZ90B
- 1.23 FUEL DOOR INNER 17221-VX50A
- 1.24 FUEL TANK PIPE MOUNTING
- 1.25 FUEL DOOR LOCK
- 1.26 FUEL DOOR LOCK CATCH
- 1.27 REVERSE SENSOR

Labour:

TO REPLACE AND RESPRAY TAILGATE	4 hrs
TO REMOVE AND REFIX REAR WINDSCREEN	6 hrs
TO REPLACE AND RESPRAY REAR END PANEL	6 hrs
TO APPLY TUFF KOTE ON END PANEL	1 hr
TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK	2 hrs

TO REMOVE AND REFIX REAR SEATS TO ASSIST WORK	2 hrs
TO REPAIR AND RESPRAY LHR BODY PANEL	8 hrs
TO REMOVE AND REFIX FUEL TANK TO ASSIST WORK	2 hrs
TO REPLACE AND RESPRAY REAR BUMPER	5 hrs
TO REFIX SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER	0.5 hr
TO REPAIR AND RESPRAY RHR WHOLE BODY PANEL	12 hrs
TO REPAIR AND RESPRAY FLOOR STEEL CHECKER PLATE AFFECTED AREA	5 hrs

Thank you.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Shiau Chan (LKKAuto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Monday, 8 April 2019 3:17 PM
To: Shiau Chan (LKKAuto); assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - GBC752Z

OK, thanks.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, 8 April 2019 3:16 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - GBC752Z

Dear Perry,

Kindly advise whether we can submit our report to you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 21 March 2019 4:14 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - GBC752Z

Dear Perry,

Please find the attachment of vehicle GBC 752Z.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 March 2019 4:14 PM
To: 'Perry HE (SPF)'; assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - GBC752Z
Attachments: GBC752 photo.pdf; GBC 752Z.xls

Dear Perry,

Please find the attachment of vehicle GBC 752Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 15 March 2019 11:02 AM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - GBC752Z

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO, with new contract rate.

Ref: MHASPF0300000113

GBC752Z

Parts:

- 1 Scope Of Repairs
- 1.1 TAILGATE
- 1.2 TAILGATE HINGE RH
- 1.3 TAILGATE HINGE LH
- 1.4 TAILGATE LOCK
- 1.5 TAILGATE LOCK CATCH
- 1.6 TAILGATE TRIM BOARD
- 1.7 TAILGATE DAMPER RH
- 1.8 TAILGATE DAMPER LH
- 1.9 TAILLAMP RH
- 1.10 TAILLAMP PANEL RH
- 1.11 TAILGATE WEATHER STRIP
- 1.12 REAR BUMPER
- 1.13 REAR BUMPER CENTER BRACKET
- 1.14 REAR BUMPER CLIP 85071-01N00
- 1.15 REAR BUMPER CLIP 01553-10721



**Scope Of Work
Home Team Agency**

SCOPE OF WORK

I To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :		UNIT :	GC	Reference No. MHA/SPF/2019/03-0015 1100020179
VEH NO :	GBC752Z	MB		REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL	NISSAN URVAN			Mileage:	194128	

JNIT 646 2580789711

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	TAILGATE / <i>huc</i>	1000.00	1	20%	1200.00	1200.00
1.2	TAILGATE HINGE RH <i>X</i>	50.00	1	20%	60.00	60.00
1.3	TAILGATE HINGE LH <i>X</i>	50.00	1	20%	60.00	60.00
1.4	TAILGATE LOCK <i>X BT</i>	290.00	1	20%	348.00	348.00
1.5	TAILGATE LOCK CATCH <i>X</i>	20.00	1	20%	24.00	24.00
1.6	TAILGATE TRIM BOARD <i>/ CAA</i>	180.00	1	20%	216.00	216.00
1.7	TAILGATE DAMPER RH <i>X</i>	120.00	1	20%	144.00	144.00
1.8	TAILGATE DAMPER LH <i>X</i>	120.00	1	20%	144.00	144.00
1.9	TAILLAMP RH <i>/ PIS</i>	45.00	1	20%	54.00	54.00
1.10	TAILLAMP PANEL RH <i>/ huc</i>	250.00	1	20%	300.00	300.00
1.11	TAILGATE WEATHER STRIP <i>/ huc</i>	100.00	1	20%	120.00	120.00
1.12	REAR BUMPER <i>/ PIS</i>	120.00	1	20%	144.00	144.00
1.13	REAR BUMPER CENTER BRACKET <i>/ BT</i>	90.00	1	20%	108.00	108.00
1.14	REAR BUMPER CLIP 85071-01N00 <i>/ huc</i>	4.00	2	20%	4.80	9.60
1.15	REAR BUMPER CLIP 01553-10721 <i>/ huc</i>	3.00	6	20%	3.60	21.60
1.16	REAR BUMPER CLIP 85099-VW000 <i>/ huc</i>	5.00	2	20%	6.00	12.00
1.17	REAR BUMPER CLIP 85221-VW000 <i>/ huc</i>	8.00	4	20%	9.60	38.40
1.18	REAR PILLAR LOWER GARNISH RH 76939 <i>/ CAA</i>	320.00	1	20%	384.00	384.00
1.19	REAR WINDSCREEN MOULDING <i>/ huc</i>	70.00	1	20%	84.00	84.00
1.20	SEALANT <i>/ huc</i>	20.00	2	20%	24.00	48.00
1.21	REAR END PANEL ASSY <i>/ huc</i>	150.00	1	20%	180.00	180.00
1.22	FUEL TANK PIPE 17221-VZ90B <i>/ ?</i>	180.00	1	20%	216.00	216.00
1.23	FUEL DOOR INNER 17221-VX50A <i>/ ?</i>	80.00	1	20%	96.00	96.00
1.24	FUEL TANK PIPE MOUNTING <i>/ ?</i>	NO USE	1			
1.25	FUEL DOOR LOCK <i>/ ?</i>	100.00	1	20%	120.00	120.00
1.26	FUEL DOOR LOCK CATCH <i>/ ?</i>	15.00	1	20%	18.00	18.00
1.27	REVERSE SENSOR <i>/ PIS</i>	100.00	1	20%	120.00	120.00
Remarks:		BY AIR SUBJECT TO PART AVAILABILITY			Parts Total:	\$ 4,269.60

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO REPLACE AND RESPRAY TAILGATE	61.80	4	247.20
1.2	TO REMOVE AND REFIX REAR WINDSCREEN	61.80	6	370.80
1.3	TO REPLACE AND RESPRAY REAR END PANEL	61.80	6	370.80
1.4	TO APPLY TUFF KOTE ON END PANEL	61.80	1	61.80
1.5	TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK	61.80	2	123.60
1.6	TO REMOVE AND REFIX REAR SEATS TO ASSIST WORK	61.80	2	123.60
1.7	TO REPAIR AND RESPRAY LHR BODY PANEL	61.80	8	494.40
1.8	TO REMOVE AND REFIX FUEL TANK TO ASSIST WORK	61.80	2	123.60
1.9	TO REPLACE AND RESPRAY REAR BUMPER	61.80	5	309.00
1.10	TO REFIX SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER	61.80	0.5	30.90
1.11	TO REPAIR AND RESPRAY RHR WHOLE BODY PANEL	61.80	12	741.60
1.12	TO REPAIR AND RESPRAY FLOOR STEEL CHECKER PLATE AFFECTED AREA	61.80	5	309.00
2	Additional Services			
			53.5	
		Labour Total:		\$ 3,306.30
		GRAND TOTAL:		\$ 7,575.90

Contractor shall complete the entire repair within 50 working days upon quotation approved date.

*Amo @ i ang (LKK)
8288 0282
Not Authorized.
20/3/19.*

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	TAILGATE	1	BUCKLED	\$1,200.00	\$1,200.00	
1.2	TALGATE HINGE RH	1	NOT NECESSARY	\$60.00	\$0.00	
1.3	TALGATE HINGE LH	1	NOT NECESSARY	\$60.00	\$0.00	
1.4	TAILGATE LOCK	1	BENT	\$348.00	\$348.00	
1.5	TAILGATE LOCK CATCH	1	NOT NECESSARY	\$24.00	\$0.00	
1.6	TAILGATE TRIM BOARD	1	CRACKED	\$216.00	\$216.00	
1.7	TAILGATE DAMPER RH	1	NOT NECESSARY	\$144.00	\$0.00	
1.8	TAILGATE DAMPER LH	1	NOT NECESSARY	\$144.00	\$0.00	
1.9	TAILLAMP RH	1	DISTORTED	\$54.00	\$54.00	
1.10	TAILLAMP PANEL RH	1	BUCKLED	\$300.00	\$300.00	
1.11	TAILGATE WEATHER STRIP	1	TWISTED	\$120.00	\$120.00	
1.12	REAR BUMPER	1	DISTORTED	\$144.00	\$144.00	
1.13	REAR BUMPER CENTER BRACKET	1	BENT	\$108.00	\$108.00	
1.14	REAR BUMPER CLIP 85071-01N00	2	NECESSARY	\$4.80	\$9.60	
1.15	REAR BUMPER CLIP 01553-10721	6	NECESSARY	\$3.60	\$21.60	
1.16	REAR BUMPER CLIP 85099-VW000	2	NECESSARY	\$6.00	\$12.00	
1.17	REAR BUMPER CLIP 85221-VW000	4	NECESSARY	\$9.60	\$38.40	
1.18	REAR PILLAR LOWER GARNISH RH 76939	1	CRACKED	\$384.00	\$384.00	
1.19	REAR WINDSCREEN MOULDING	1	NECESSARY	\$84.00	\$84.00	
1.20	SEALANT	2	NECESSARY	\$24.00	\$48.00	
1.21	REAR END PANEL ASSY	1	BUCKLED	\$180.00	\$180.00	
1.22	FUEL TANK PIPE 17221-VZ90B	1	UNCONFIRM	\$216.00	\$216.00	
1.23	FUEL DOOR INNER 17221-VX50A	1	UNCONFIRM	\$96.00	\$96.00	
1.24	FUEL TANK PIPE MOUNTING	NO USE				
1.25	FUEL DOOR LOCK	1	UNCONFIRM	\$120.00	\$120.00	
1.26	FUEL DOOR LOCK CATCH	1	UNCONFIRM	\$18.00	\$18.00	
1.27	REVERSE SENSOR	1	DISTORTED	\$120.00	\$120.00	
	COSTING		TOTAL PARTS COST		\$3,837.60	

2	SCOPE OF REPAIRS				
2.1	TO REPLACE AND RESPRAY TAILGATE				4
2.2	TO REMOVE AND REFIX REAR WINDSCREEN				6
2.3	TO REPLACE AND RESPRAY REAR END PANEL				6
2.4	TO APPLY TUFF KOTE ON END PANEL				1
2.5	TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK				2
2.6	TO REMOVE AND REFIX REAR SEATS TO ASSIST WORK				2
2.7	TO REPAIR AND RESPRAY LHR BODY PANEL				8
2.8	TO REMOVE AND REFIX FUEL TANK TO ASSIST WORK				2
2.9	TO REPLACE AND RESPRAY REAR BUMPER				5
2.10	TO REFIX SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER				0.5
2.11	TO REPAIR AND RESPRAY RHR WHOLE BODY PANEL				12
2.12	TO REPAIR AND RESPRAY FLOOR STEEL CHECKER PLATE AFFECTED AREA				5
COSTING		TOTAL MAN-HOUR			53.50




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19005080/Gqd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : PERRY HE		Date : 24-04-2019		
		Code : SPF		
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	GBC 752Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No. MHASPF0300000113	Excess (\$)	0.00	
	Assign From PERRY HE	Assign Date	15/03/2019	
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN URVAN 3.0	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JN1TG4E25Z0789711	Colour	BLUE
	Odometer	194128	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	5 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	5 mm
	R/H Rear Tyre	195 R15	BRIDGESTONE	5 mm
	L/H Rear Tyre	195 R15	BRIDGESTONE	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	Inspection Date	20/03/2019	
	Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		
5a. Remarks				



Registration No. GBC 752Z

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	TAILGATE	1	BUCKLED	\$1,200.00	\$1,200.00	
1.2	TALGATE HINGE RH	1	NOT NECESSARY	\$60.00	\$0.00	
1.3	TALGATE HINGE LH	1	NOT NECESSARY	\$60.00	\$0.00	
1.4	TAILGATE LOCK	1	BENT	\$348.00	\$348.00	
1.5	TAILGATE LOCK CATCH	1	NOT NECESSARY	\$24.00	\$0.00	
1.6	TAILGATE TRIM BOARD	1	CRACKED	\$216.00	\$216.00	
1.7	TAILGATE DAMPER RH	1	NOT NECESSARY	\$144.00	\$0.00	
1.8	TAILGATE DAMPER LH	1	NOT NECESSARY	\$144.00	\$0.00	
1.9	TAILLAMP RH	1	DISTORTED	\$54.00	\$54.00	
1.10	TAILLAMP PANEL RH	1	BUCKLED	\$300.00	\$300.00	
1.11	TAILGATE WEATHER STRIP	1	TWISTED	\$120.00	\$120.00	
1.12	REAR BUMPER	1	DISTORTED	\$144.00	\$144.00	
1.13	REAR BUMPER CENTER BRACKET	1	BENT	\$108.00	\$108.00	
1.14	REAR BUMPER CLIP 85071-01N00	2	NECESSARY	\$4.80	\$9.60	
1.15	REAR BUMPER CLIP 01553-10721	6	NECESSARY	\$3.60	\$21.60	
1.16	REAR BUMPER CLIP 85099-VW000	2	NECESSARY	\$6.00	\$12.00	
1.17	REAR BUMPER CLIP 85221-VW000	4	NECESSARY	\$9.60	\$38.40	
1.18	REAR PILLAR LOWER GARNISH RH 76939	1	CRACKED	\$384.00	\$384.00	
1.19	REAR WINDSCREEN MOULDING	1	NECESSARY	\$84.00	\$84.00	
1.20	SEALANT	2	NECESSARY	\$24.00	\$48.00	
1.21	REAR END PANEL ASSY	1	BUCKLED	\$180.00	\$180.00	
1.22	FUEL TANK PIPE 17221-VZ90B	1	UNCONFIRM	\$216.00	\$216.00	
1.23	FUEL DOOR INNER 17221-VX50A	1	UNCONFIRM	\$96.00	\$96.00	
1.24	FUEL TANK PIPE MOUNTING	NO USE				
1.25	FUEL DOOR LOCK	1	UNCONFIRM	\$120.00	\$120.00	
1.26	FUEL DOOR LOCK CATCH	1	UNCONFIRM	\$18.00	\$18.00	
1.27	REVERSE SENSOR	1	DISTORTED	\$120.00	\$120.00	
	COSTING		TOTAL PARTS COST		\$3,837.60	

2	SCOPE OF REPAIRS					
2.1	TO REPLACE AND RESPRAY TAILGATE					4
2.2	TO REMOVE AND REFIX REAR WINDSCREEN					6
2.3	TO REPLACE AND RESPRAY REAR END PANEL					6
2.4	TO APPLY TUFF KOTE ON END PANEL					1
2.5	TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK					2
2.6	TO REMOVE AND REFIX REAR SEATS TO ASSIST WORK					2
2.7	TO REPAIR AND RESPRAY LHR BODY PANEL					8
2.8	TO REMOVE AND REFIX FUEL TANK TO ASSIST WORK					2
2.9	TO REPLACE AND RESPRAY REAR BUMPER					5
2.10	TO REFIX SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER					0.5
2.11	TO REPAIR AND RESPRAY RHR WHOLE BODY PANEL					12
2.12	TO REPAIR AND RESPRAY FLOOR STEEL CHECKER PLATE AFFECTED AREA					5
COSTING		TOTAL MAN-HOUR				53.50

Registration No. GBC 752Z

Vehicle Inspected By

ONG HWEE JIE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



Registration No. GBC 752Z

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	TAILGATE	1	BUCKLED	\$1,200.00	\$1,200.00	
1.2	TALGATE HINGE RH	1	NOT NECESSARY	\$60.00	\$0.00	
1.3	TALGATE HINGE LH	1	NOT NECESSARY	\$60.00	\$0.00	
1.4	TAILGATE LOCK	1	BENT	\$348.00	\$348.00	
1.5	TAILGATE LOCK CATCH	1	NOT NECESSARY	\$24.00	\$0.00	
1.6	TAILGATE TRIM BOARD	1	CRACKED	\$216.00	\$216.00	
1.7	TAILGATE DAMPER RH	1	NOT NECESSARY	\$144.00	\$0.00	
1.8	TAILGATE DAMPER LH	1	NOT NECESSARY	\$144.00	\$0.00	
1.9	TAILLAMP RH	1	DISTORTED	\$54.00	\$54.00	
1.10	TAILLAMP PANEL RH	1	BUCKLED	\$300.00	\$300.00	
1.11	TAILGATE WEATHER STRIP	1	TWISTED	\$120.00	\$120.00	
1.12	REAR BUMPER	1	DISTORTED	\$144.00	\$144.00	
1.13	REAR BUMPER CENTER BRACKET	1	BENT	\$108.00	\$108.00	
1.14	REAR BUMPER CLIP 85071-01N00	2	NECESSARY	\$4.80	\$9.60	
1.15	REAR BUMPER CLIP 01553-10721	6	NECESSARY	\$3.60	\$21.60	
1.16	REAR BUMPER CLIP 85099-VW000	2	NECESSARY	\$6.00	\$12.00	
1.17	REAR BUMPER CLIP 85221-VW000	4	NECESSARY	\$9.60	\$38.40	
1.18	REAR PILLAR LOWER GARNISH RH 76939	1	CRACKED	\$384.00	\$384.00	
1.19	REAR WINDSCREEN MOULDING	1	NECESSARY	\$84.00	\$84.00	
1.20	SEALANT	2	NECESSARY	\$24.00	\$48.00	
1.21	REAR END PANEL ASSY	1	BUCKLED	\$180.00	\$180.00	
1.22	FUEL TANK PIPE 17221-VZ90B	1	UNCONFIRM	\$216.00	\$216.00	
1.23	FUEL DOOR INNER 17221-VX50A	1	UNCONFIRM	\$96.00	\$96.00	
1.24	FUEL TANK PIPE MOUNTING	NO USE				
1.25	FUEL DOOR LOCK	1	UNCONFIRM	\$120.00	\$120.00	
1.26	FUEL DOOR LOCK CATCH	1	UNCONFIRM	\$18.00	\$18.00	
1.27	REVERSE SENSOR	1	DISTORTED	\$120.00	\$120.00	
	COSTING		TOTAL PARTS COST		\$3,837.60	

2	SCOPE OF REPAIRS					
2.1	TO REPLACE AND RESPRAY TAILGATE					4
2.2	TO REMOVE AND REFIX REAR WINDSCREEN					6
2.3	TO REPLACE AND RESPRAY REAR END PANEL					6
2.4	TO APPLY TUFF KOTE ON END PANEL					1
2.5	TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK					2
2.6	TO REMOVE AND REFIX REAR SEATS TO ASSIST WORK					2
2.7	TO REPAIR AND RESPRAY LHR BODY PANEL					8
2.8	TO REMOVE AND REFIX FUEL TANK TO ASSIST WORK					2
2.9	TO REPLACE AND RESPRAY REAR BUMPER					5
2.10	TO REFIX SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER					0.5
2.11	TO REPAIR AND RESPRAY RHR WHOLE BODY PANEL					12
2.12	TO REPAIR AND RESPRAY FLOOR STEEL CHECKER PLATE AFFECTED AREA					5
COSTING		TOTAL MAN-HOUR				53.50

Registration No. GBC 752Z

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.